PRINT DATE: 05/06/96

PAGE: 1

FAILURE MODES EFFECTS ANALYSIS (FMEA) - CIL HARDWARE NUMBER: 05-6MA-2011 -X

SUBSYSTEM NAME: EPD&C - ELEC PWR GENERATION: FUEL CELL (04-1A)

		REVISION: 0 U3/30/89	
PART DATA			
	PART NAME VENDOR NAME	PART NUMBER VENDOR NUMBER	
LRU	: MID PGA 1	V070-76440D	
LRU	; MID PCA 2	V070-764430	
LRU	; MID PCA 3	V070-764450	
SRU	: FUSE	ME451-0018-0300	

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:

FUSE, 3 AMP - FUEL CELL CONTROL POWER

REFERENCE DESIGNATORS:

40V76A25F6 40V76A26F5 40V76A27F5

QUANTITY OF LIKE ITEMS: 3

THREE, 1/EACH FOP CONTROL POWER CIRCUIT

FUNCTION:

EACH FUSE CONDUCTS INPUT CONTROL POWER AND PROVIDES CIRCUIT PROTECTION FOR ITS ASSOCIATED FUEL CELL POWER PLANT (FCP) NO. 1, 2, OR 3 CONTROL POWER CIRCUIT.

FAILURE MODES EFFECTS ANALYSIS FMEA -- CIL FAILURE MODE

NUMBER: 05-8MA-2011-01

REVISION#: 0

04/16/96

SUBSYSTEM NAME: EPD&C - ELEC PWR GENERATION:FUEL CELL (04-1A)

LRU: MID PCA 1 ITEM NAME: FUSE CRITICALITY OF THIS

FAILURE MODE: 1R2

FAILURE MODE:

FAILS OPEN, FAILS TO CONDUCT

MISSION PHASE:

LO LIFT-OFF

VEHICLE/PAYLOAD/KIT EFFECTIVITY:

102 COLUMBIA

103 DISCOVERY 104 ATLANTIS 105 ENDEAVOUR

CAUSE:

STRUCTURAL FAILURE, CONTAMINATION, MECHANICAL SHOCK, VIBRATION, PROCESSING ANOMALY, THERMAL STRESS

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

REDUNDANCY SCREEN

A) PASS

B) PASS

C) PASS

PASS/FAIL RATIONALE:

A)

B)

Ç)

- FAILURE EFFECTS -

(A) SUBSYSTEM:

LOSS OF ASSOCIATED FUEL CELL CONTROL POWER

(B) INTERFACING SUBSYSTEM(S):

PAGE: 3 PRINT DATE: 04/17/96

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL FAILURE MODE
NUMBER: 05-6MA-2011- 01

LOSS OF POWER TO COOLANT PUMP AND H2 PUMP LEADING TO FCP OVERHEATING/ FLOODING AND OUTPUT VOLTAGE DEGRADATION. REQUIRES CREW ACTION TO SHUTDOWN FCP. TIME CRITICAL

(C) MISSION:

NO EFFECT - MINIMUM DURATION FLIGHT. LOSS OF FUEL CELL REDUNDANCY (CAPABILITY EXISTS FOR SAFE RETURN ON ONE OF THREE FCP).

(D) CREW, VEHICLE, AND ELEMENT(S):

FIRST FCP LOSS NO EFFECT - SECOND FCP SHUTDOWN DURING ASCENT LOSES CRITICAL FUNCTIONS AND MAY RESULT IN CREW/VEHICLE LOSS. FAILURE TO REMOVE LOAD FROM AFFECTED FCP WITHIN 9 MINUTES MAY RESULT IN OVERTEMP AND SUBSEQUENT EXTERNAL REACTANT LEAKAGE.

(E) FUNCTIONAL CRITICALITY EFFECTS:

FIRST FCP LOSS NO EFFECT - SECOND FCP SHUTDOWN DURING ASCENT LOSES CRITICAL FUNCTIONS AND MAY RESULT IN CREW/VEHICLE LOSS. FAILURE TO REMOVE LOAD FROM AFFECTED FCP WITHIN 9 MINUTES MAY RESULT IN OVERTEMP AND SUBSEQUENT EXTERNAL REACTANT LEAKAGE.

-DISPOSITION RATIONALE-

(A) DESIGN:

REFER TO APPENDIX D. ITEM NO. 4 - FUSE, PLUG-IN TYPE

(B) TEST:

GROUND TURNAROUND TEST

ANY TURNAROUND CHECKOUT TESTING IS ACCOMPLISHED IN ACCORDANCE WITH OMRSD.

(C) INSPECTION:

REFER TO APPENDIX D. ITEM NO. 4 - FUSE, PLUG-IN TYPE

(D) FAILURE HISTORY:

CURRENT DATA ON TEST FAILURES, FLIGHT FAILURES, UNEXPLAINED ANOMALIES, AND OTHER FAILURES EXPERIENCED DURING GROUND PROCESSING ACTIVITY CAN BE FOUND IN THE PRACA DATA BASE. THE FAILURE HISTORY DATA PROVIDED IN APPENDIX D IS NO LONGER BEING KEPT UP-TO-DATE.

FAILURE MODES EFFECTS ANALYSIS (FMEA) - CIL FAILURE MODE

NUMBER: 05-6MA-2011-01

(E) OPERATIONAL USE:

CREW ACTION REQUIRED TO SHUTDOWN AFFECTED FCP DURING FLIGHT. ONBOARD PROCEDURES MANAGE POWER FOR LOSS OF ONE FCP.

- APPROVALS -

PAE MANAGER

PRODUCT ASSURANCE ENGR

DESIGN ENGINEERING EDITORIALLY APPROVED

TECHNICAL APPROVAL

: P. STENGER-NGUYEN

: J. NGUYEN

: T. D. NGUYEN

: JSC

: VIA APPROVAL FORM : 95-CIL-012_05-M6A