

PAGE: 1

PRINT DATE: 09/03/93

**FAILURE MODES EFFECTS ANALYSIS (FMEA) – CRITICAL HARDWARE
NUMBER: 05-6N-2042-X**

SUBSYSTEM NAME: EPD&C - AUXILIARY POWER UNIT

REVISION: 1 08/30/93

	PART NAME VENDOR NAME	PART NUMBER VENDOR NUMBER
LRU	: PANEL R2	V070-730277
SRU	: SWITCH, TOGGLE	ME452-0102-7301

PART DATA

**EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:
SWITCH, TOGGLE, 3 POLE 2 POSITION - AUXILIARY POWER UNIT (APU) AUTO
SHUTODWN INHIBIT CONTROL CIRCUIT**

**REFERENCE DESIGNATORS: 32V73A2S22
32V73A2S60
32V73A2S61**

**QUANTITY OF LIKE ITEMS: 3
THREE**

**FUNCTION:
PROVIDES INHIBIT/ENABLE COMMAND SELECTION FOR APU AUTO SHUTDOWN INHIBIT
CONTROL CIRCUIT**

**FAILURE MODES EFFECTS ANALYSIS (FMEA) - CRITICAL FAILURE MODE
NUMBER: 05-6N-2042-01**

SUBSYSTEM NAME: EPD&C - AUXILIARY POWER UNIT
LRU: PANEL R2
ITEM NAME: SWITCH, TOGGLE

REVISION# 1 06/30/93
CRITICALITY OF THIS
FAILURE MODE: 1R3

FAILURE MODE:
SHORT-TO-GROUND (GROUND), FAILS OPEN

MISSION PHASE:
PL PRELAUNCH
LO LIFT-OFF
DO DE-ORBIT
LS LANDING SAFING

VEHICLE/PAYLOAD/KIT EFFECTIVITY: 102 COLUMBIA
103 DISCOVERY
104 ATLANTIS
105 ENDEAVOUR

CAUSE:
PIECE PART STRUCTURAL FAILURE, CONTAMINATION, VIBRATION, MECHANICAL
SHOCK, PROCESSING ANOMALY

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

REDUNDANCY SCREEN A) PASS
B) FAIL
C) PASS

PASS/FAIL RATIONALE:

A)

B)

FIRST FAILURE NOT DETECTABLE IN FLIGHT SINCE THE OPERATIONAL STATUS OF
THIS SWITCH IS NOT MONITORED WITH SWITCH SCANS.

C)

- FAILURE EFFECTS -

(A) SUBSYSTEM:

INABILITY TO PROVIDE POWER TO APU AUTO SHUTDOWN INHIBIT CONTROL CIRCUIT.

(B) INTERFACING SUBSYSTEM(S):

NO EFFECT - FIRST FAILURE. LOSS OF ABILITY TO OVERRIDE OVERSPEED/
UNDERSPEED PROTECTION ON APU AFTER TWO FAILURES.

(C) MISSION:

NO EFFECT - ABORT DECISION REQUIRED AFTER TWO FAILURES DUE TO LOSS OF
ONE APU.

**FAILURE MODES EFFECTS ANALYSIS (FMEA) - CRITICAL FAILURE MODE
NUMBER: 05-6N-2042-01**

(D) CREW, VEHICLE, AND ELEMENT(S):
NO EFFECT - FIRST FAILURE

(E) FUNCTIONAL CRITICALITY EFFECTS:
POSSIBLE LOSS OF VEHICLE AND CREW AFTER TWO OTHER FAILURES (FALSE
OVERSPEED/UNDERSPEED INDICATION ON APU, LOSS OF SECOND APU) DUE TO LOSS
OF TWO OF THREE APUS.

-DISPOSITION RATIONALE-

(A) DESIGN:
REFER TO APPENDIX A, ITEM NO. 1 - TOGGLE SWITCH

(B) TEST:
REFER TO APPENDIX A, ITEM NO. 1 - TOGGLE SWITCH

GROUND TURNAROUND TEST - APU 1/2/3 CONTROLLER TEST THROUGH GROUND
CONNECTION PERFORMED EVERY FLOW OR AFTER LRU RETEST OF APU ASSEMBLY,
AFTER LRU RETEST OF CONTROLLER ASSEMBLY OR AFTER CIG RETEST.

(C) INSPECTION:
REFER TO APPENDIX A, ITEM NO. 1 - TOGGLE SWITCH

(D) FAILURE HISTORY:
REFER TO APPENDIX A, ITEM NO. 1 - TOGGLE SWITCH

(E) OPERATIONAL USE:
NONE

- APPROVALS -

EDITORIALLY APPROVED : RI
EDITORIALLY APPROVED : JSC
TECHNICAL APPROVAL : VIA CR

Handwritten signature and date: 9/7/93
Handwritten signature and date: 9/7/93
S502/OL