

FAILURE MODES EFFECTS ANALYSIS (FMEA) - CIL HARDWARE  
 NUMBER: 05-6PG-21228 -X

SUBSYSTEM NAME: EPD&amp;C - COMM. &amp; TRACK

REVISION: 0

01/05/88

---

 PART DATA
 

---

	PART NAME	PART NUMBER
	VENDOR NAME	VENDOR NUMBER
LRU	: PNL A1A2	
SRU	: DIODE	JANTXV1N4246

---

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:  
 DIODE, PA POWER DIODE, S-BAND POWER AMPLIFIER POWER CONTROL CIRCUIT

REFERENCE DESIGNATORS: 36V73A1A2A18CR13  
 36V73A1A2A18CR14  
 36V73A1A2A18CR15  
 36V73A1A2A18CR16

QUANTITY OF LIKE ITEMS: 4  
 FOUR

FUNCTION:  
 IN CASE OF SWITCH FAILURE (S11 OR S12) PREVENTS UNWANTED INPUTS TO THE  
 GCIL COMMAND MODE DRIVERS DUE TO REVERSE LEAKAGE CURRENT FLOW  
 THROUGH THE CONTROL BUS AND INTO THE COMMAND DRIVERS.

FAILURE MODES EFFECTS ANALYSIS FMEA - CIL FAILURE MODE

NUMBER: 05-6PG-21228- 02

REVISION#: 1 08/15/87

SUBSYSTEM NAME: EPD&C - C&T: S-BAND COMMUNICATIONS (05-2G)

LRU: PNL A1A2

CRITICALITY OF THIS

ITEM NAME: DIODE

FAILURE MODE: 2R3

FAILURE MODE:

FAILS SHORT CIRCUIT (END TO END).

MISSION PHASE:

LO LIFT-OFF  
OO ON-ORBIT  
DO DE-ORBIT

VEHICLE/PAYLOAD/KIT EFFECTIVITY:

102 COLUMBIA  
103 DISCOVERY  
104 ATLANTIS  
105 ENDEAVOUR

CAUSE:

STRUCTURAL FAILURE, MECHANICAL STRESS, VIBRATION, CONTAMINATION,  
ELECTRICAL STRESS, THERMAL STRESS, PROCESSING ANOMALY.

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

REDUNDANCY SCREEN

A) FAIL  
B) N/A  
C) PASS

PASS/FAIL RATIONALE:

A)

FAILS SCREEN "A" BECAUSE SHORTED DIODES CANNOT BE DETECTED DURING  
GROUND TURNAROUND TESTING.

B)

N/A FOR SCREEN "B" BECAUSE THE SWITCH FAILURE CAN BE DETECTED BY LOSS OF  
SWITCH FUNCTION EVEN THOUGH THE SHORTED DIODES CANNOT BE DETECTED  
DURING FLIGHT.

C)

- FAILURE EFFECTS -

(A) SUBSYSTEM:

**FAILURE MODES EFFECTS ANALYSIS (FMEA) – GIL FAILURE MODE**

**NUMBER: 05-6PG-21228-02**

NO EFFECT ON EPDC. LOSS OF PROTECTION FOR GCIL DRIVERS IN CASE OF SWITCH FAILURE. AFTER A SECOND DIODE FAILURE LOSS OF PROTECTION FOR BOTH GCIL POWER AMP POWER CONTROL DRIVERS.

**(B) INTERFACING SUBSYSTEM(S):**

NO EFFECT

**(C) MISSION:**

NO EFFECT

**(D) CREW, VEHICLE, AND ELEMENT(S):**

NO EFFECT

**(E) FUNCTIONAL CRITICALITY EFFECTS:**

AFTER THREE FAILURES (TWO DIODES AND ONE SWITCH SHORT TO GROUND), LOSS OF USE OF BOTH POWER AMPS. POSSIBLE LOSS OF PRIME MISSION OBJECTIVE DUE TO LOSS OF TDRS COMMUNICATIONS.

---

**-DISPOSITION RATIONALE-**

---

**(A) DESIGN:**

REFER TO APPENDIX F, ITEM #3, DIODE.

**(B) TEST:**

REFER TO APPENDIX F, ITEM #3, DIODE.

**GROUND TURNAROUND TEST**

NO TESTS ARE AVAILABLE TO DETECT SHORTED DIODES DURING GROUND TURNAROUND.

**(C) INSPECTION:**

REFER TO APPENDIX F, ITEM #3, DIODE.

**(D) FAILURE HISTORY:**

CURRENT DATA ON TEST FAILURES, FLIGHT FAILURES, UNEXPLAINED ANOMALIES, AND OTHER FAILURES EXPERIENCED DURING GROUND PROCESSING ACTIVITY CAN BE FOUND IN THE PRACA DATA BASE.

FAILURE MODES EFFECTS ANALYSIS (FMEA) – CIL FAILURE MODE

NUMBER: 05-SPG-21228- 02

(E) OPERATIONAL USE:

CREW CAN USE REMAINING POWER AMP TO MAINTAIN TDRS COMMUNICATION

---

- APPROVALS -

---

EDITORIALLY APPROVED	: BNA	: <u>J. Kashura 8/18/97</u>
EDITORIALLY APPROVED	: JSC	: <u>Adam / Gordon 9/23/97</u>
TECHNICAL APPROVAL	: VIA APPROVAL FORM	: 86-CIL-015_06/SPG /