SHUTTLE CRITICAL ITEMS LIST - ORBITER

SUBSYSTEM : EPD&C - COMM. & TRACK. FMEA NO 05-6PR-51050 -1 REV: 06/28/88

ASSEMBLY : PNL R15

P/N RI :MC454-0026-2150

P/N VENDOR: QUANTITY :1

IONE

•

CRIT. FUNC: 1R CRIT. HDW: 2

VEHICLE 102 103 104 EFFECTIVITY: X X X

PHASE(S): PL LO OO X DO LS

REDUNDANCY SCREEN: A-PASS B-PASS C-PASS
REPARED BY:
APPROVED BY:
APPROVED BY:
APPROVED BY:

DES H D HADDAD REL 40 1-5-47 J Y HARADA

H D HADDAD DES YJ Y HARADA REL OE 8-30-88 RELIEF

Fre Relie Sanda da 18/7

ITEM:

QΕ

CB23, CIRCUIT BREAKER, 15 AMPS. KU-BAND EA-2 POWER AND DA/EA-1 OPERATE COMMAND.

FUNCTION:

CLOSES AND OPENS THE POWER CIRCUITS TO THE KU-BAND ELECTRONIC ASSEMBLY 2: ENERGIZES RELAY K2, WHICH PROVIDES POWER TO DA, THROUGH CONTACT CLOSURE; ACTIVATES RPC53 WHICH PROVIDES POWER TO EA-1 THROUGH MNC. RECEIVES POWER FROM 35 AMP FUSE 40V76A32F18. (FMEA # 05-6-2278). 32V73A15CB23.

FAILURE MODE:

FAILS OPEN. FAILS TO CONDUCT, FAILS TO CLOSE

CAUSE(S):

STRUCTURAL FAILURE, CONTAMINATION, VIBRATION, MECHANICAL SHOCK, PROCESSING ANOMALY, THERMAL STRESS.

EFFECT(S) ON:

(A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE

EFFECTS ON ABILITY TO CONTROL, POSITION, OR LOCK ANTENNA GIMBALS - 1R/2

- (A) NO EFFECT ON EPDC.
- (B) LOSS OF ABILITY TO LOCK GIMBALS, REAL-TIME DECISION REQUIRED TO PERFORM IN-FLIGHT MAINTENANCE PROCEDURE WITH EVA OR JETTISON THE DEPLOYED ASSEMBLY.
- (C,D) POSSIBLE LOSS OF CREW/VEHICLE AFTER TWO FAILURES IF DA CANNOT BE SECURED FOR REENTRY OR JETTISONED. REENTRY WITH GIMEALS UNLOCKED MAY CAUSE DAMAGE TO THE RADIATOR.

EFFECTS ON MISSIONS REQUIRING RU-BAND SYSTEM SUPPORT - 2/2

(A) NO EFFECT ON EPDC.

SHUTTLE CRITICAL ITEMS LIST - ORBITER

SUBSYSTEM : EPO4C - COMM. 4 TRACK. FMEA NO 05-6PR-51050 -1 REV: 06/28/88

(B,C,) LOSS OF ALL MISSION OBJECTIVES REQUIRING RU-RAND COMM DATA PROCESSING OR RENDEZVOUS RADAR.

(D) NO EFFECT.

EFFECTS ON PROVIDING DATA TO MEP FOR STATE VECTOR UPDATE - 1R/3.

(A) NO EFFECT ON EPDC.

(B,C,D) LOSS OF ONE OF THREE REDUNDANT PATHS TO SUPPLY DATA TO MSP FOR STATE VECTOR UPDATE. UHF PROVIDES AN INDEPENDENT PATH FOR STATE VECTOR UPDATE. AFTER FOUR FAILURES POSSIBLE LOSS OF CREW/VEHICLE DUE TO LOSS OF STATE VECTOR UPDATE. NOTE A SINGLE FAILURE OF A KU-BAND SPA DASH NUMBER +4001 CAN CAUSE THE LOSS OF POWER TO BOTH MSP'S, RESULTING IN ONLY ONE REMAINING PATH (UHF) TO UPDATE THE STATE VECTOR. THIS FAILURE CAN OCCUR DURING ANY MISSION PHASE. (KU-BAND POWERED ON OR OFF.)

DISPOSITION & RATIONALE:

- (A) DESIGN (B) TEST (C) INSPECTICK (D) FAILURE HISTORY (E) OPERATIONAL USE
- (A,B,C,D) REFER TO APPENDIX D, ITEM # 1, CIRCUIT BREAKER
- (B) TEST
 GROUND TURNAROUND TEST- PERFORM RADAR SELF-TEST- PERFORMED EVERY FLIGHT.
- (E) OPERATIONAL USE

WORKAROUND TO REGAIN ABILITY TO CONTROL, POSITION, OR LOCK ANTENNA GIMBALS

REAL-TIME DECISION REQUIRED TO PERFORM THE GIMBAL LOCK IN-FLIGHT MAINTENANCE PROCEDURE WITH EVA OR TO JETTISION THE DA.

WORKAROUND TO REGAIN SUPPORT OF MISSION OBJECTIVES
COMM: NONE. RADAR: ATTEMPT RENDEZVOUS WITH ALTERNATE SENSORS. USE BACK-UP RENDEZVOUS PROCEDURES.

WORKAROUND TO PROVIDE THE STATE VECTOR UPDATE
THE STATE VECTOR CAN BE UPDATED VIA THE NORMAL S-BAND COMMUNICATIONS LINK
OR VIA UHF/AUDIO.