

PAGE: 1

PRINT DATE: 09/27/94

FAILURE MODES EFFECTS ANALYSIS (FMEA) - CRITICAL HARDWARE

NUMBER: 05-6WA-2051H-X

SUBSYSTEM NAME: EPD&C- WATER SPRAY BOILER

REVISION: 1 07/26/94

	PART NAME VENDOR NAME	PART NUMBER VENDOR NUMBER
LRU	: PANEL R2	V070-730277
SRU	: SWITCH, TOGGLE	ME452-0102-7303

PART DATA

**EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:
SWITCH, TOGGLE, 3 POLE, 3 POSITION, "APU/HYD BOILER CNTLR/HTR"**

**REFERENCE DESIGNATORS: 32V73A2S41
32V73A2S42
32V73A2S43**

**QUANTITY OF LIKE ITEMS: 3
THREE**

**FUNCTION:
PROVIDES POWER TRANSFER CONTROL FOR THE WATER SPRAY BOILER (WSB)
CONTROLLERS AND RESPECTIVE HEATERS (WATER TANK, SPRAY BOILER AND STEAM
OUTLET HEATERS ON CONTROLLERS "A" AND "B", AND INLET LINE HEATER ON
CONTROLLER "A" ONLY) FOR WSB NO'S 1, 2 AND 3.**

PAGE: 4

PRINT DATE: 00/01/95

FAILURE MODES EFFECTS ANALYSIS (FMEA) - NONCRITICAL FAILURE MODE
 NUMBER: 05-6WA-2051H-02

REVISION# 05/25/95

SUBSYSTEM NAME: EPD&C-WATER SPRAY BOILER

LRU: PANEL R2

CRITICALITY OF THIS

ITEM NAME: SWITCH, TOGGLE

FAILURE MODE: 1R3

FAILURE MODE:

PREMATURE CLOSURE, INTERNAL SHORTS, INADVERTENT CLOSURE

MISSION PHASE:

LO LIFT-OFF

DO DE-ORBIT

VEHICLE/PAYLOAD/KIT EFFECTIVITY: 102 COLUMBIA
 103 DISCOVERY
 104 ATLANTIS
 105 ENDEAVOUR
 EFFECTIVE FOR WSB INLET LINE ELECTRICAL
 HEATER MOD ONLY

CAUSE:PIECE-PART STRUCTURAL FAILURE, CONTAMINATION, MECHANICAL SHOCK, VIBRATION
 PROCESSING ANOMALY, THERMAL STRESS

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

REDUNDANCY SCREEN A) PASS
 B) N/A
 C) PASS

PASS/FAIL RATIONALE:

A)

B)

SCREEN IS N/A SINCE CLOSED IS THE NORMAL SWITCH POSITION WHEN THE WSB IS IN
 USE. THIS FAILURE WILL NOT BE DETECTED UNTIL THE SWITCH IS TRANSFERRED
 FROM POSITION "A" TO "B" (OR "B" TO "A") AND IT IS DETERMINED THAT THE SWITCHED
 "ON" CONTROLLER IS NOT POWERED.

C)

CORRECTING ACTION:ASCENT - SHUT DOWN AFFECTED APU/HYD SYSTEM AT AN APPROPRIATE TIME BASED
 ON FLIGHT PHASE AND SYSTEM TEMPERATURE.ENTRY - SHUT DOWN AFFECTED APU/HYD SYSTEM OR DELAY APU START IF FAILURE
 IS KNOWN PRIOR TO DEORBIT.**REMARKS/RECOMMENDATIONS:**

NONE

PAGE: 5

PRINT DATE: 06/01/95

**FAILURE MODES EFFECTS ANALYSIS (FMEA) - NONCRITICAL FAILURE MODE
NUMBER: 05-6WA-2051H-02**

- FAILURE EFFECTS -

(A) SUBSYSTEM:

SWITCH CONTACTS 1 AND 2 (OR 3 AND 4) FAILED CLOSED WILL CAUSE A CONTINUOUS ENABLE OF ONE OF TWO SERIES REMOTE POWER CONTROLLERS (RPC'S), RPC 22 (RPC 19), FOR CONTROLLER "A" ("B") AND LOSS OF ABILITY TO ENABLE ONE OF TWO SERIES RPC'S: RPC 19 (RPC 22) FOR CONTROLLER "B" ("A").

(B) INTERFACING SUBSYSTEM(S):

LOSS OF ABILITY TO SWITCH FROM CONTROLLER "A" TO "B" ("B" TO "A").

(C) MISSION:

NO EFFECT - FIRST FAILURE

(D) CREW, VEHICLE, AND ELEMENT(S):

NO EFFECT - FIRST FAILURE

(E) FUNCTIONAL CRITICALITY EFFECTS:

POSSIBLE LOSS OF CREW AND VEHICLE AFTER THREE FAILURES: 1) THIS FAILURE RESULTING IN THE CONTINUOUS ENABLE OF RPC 22 (RPC 19) OF CONTROLLER "A" ("B") AND THE LOSS OF ABILITY TO ENABLE RPC 19 (RPC 22) OF CONTROLLER "B" ("A"), (2) CONTROLLER "A" ("B") FAILURE WHICH REQUIRES SWITCHING TO REDUNDANT CONTROLLER (LOSS OF WSB), AND (3) LOSS OF SECOND APU/HYDRAULIC SUBSYSTEM.

- APPROVALS -

PRODUCT ASSURANCE ENGR : T. K. KIMURA
DESIGN ENGINEERING : G. J. SCHWARTZ

J. Kimura 6/1/95
G. J. Schwartz 6-1-95