PRINT DATE: 11/07/88

SENTILE CRITICAL ITEMS LIST + ORBITER

MUMBER: 06-131-0301-X

SUBSTITUTE TAME: ARE COOLING

REVISION :

11/07/88

CLASSIFICATION

PART BUMBER

LRU SRU CABIN FAN & DEERIS TRAP

MC621-0008-0311

8V755527

QUARTITY OF LIFE ITEMS: 2

DESCRIPTION/FUNCTION: PAN AND DEBRIS TRAP ASSY - CABIN AIR REVITALIZATION

TWO INDEPENDENTLY CONTROLLED PANS LOCATED IN A COMMON FAN PACKAGE TO CIRCULATE CREW CABIN AIR FOR CO2 AND HUMIDITY REMOVAL, TEMPERATURE CONTROL AND FLIGHT DECK AVIONICS COOLING DURING GROUND AND ORBITAL OPERATIONS. ONE FAN PROVIDES THE REQUIRED FLOW DURING MORNAL OPERATIONS.

5.5 PRINT DATE: 11/C PAGE: 3 SEUTTLE CEITICAL ITEMS LIST - ORBITRE MUMBER: 06-131-0101-01 PEAITION: 11/07/88 SUSSYSTEM: ARS COOLING LRG : CABIN FAN & DEBRIS TRAP CHITICALITY OF THIS ITEK MAKE: FAN FAILURE MODE: 1R2 FAILURE MCDE: LOSS OF CUTFUT AIR FLOW, INCLUDING REDUCED FLOW MISSION PRASE: LO LIFT-OFF 00 ON-ORBIT DO DE-CREIT VEHICLE/PAYLOAD/RIT REFECTIVITY: 102 103 DISCOVERY 104 ATLANTIS CAUSE: PHYSICAL BINDING/JAMMING, LOSS OF ELECTRICAL POWER, CONTANTNATION CHITICALITY 1/1 DURING ANY MISSION PRASE OR ABORT? N REDUNDANCE SCREEN 1) PASS 3) N/A C) PASS A) SCREEN B IS W/A BECAUSE REDUNDANT FAN IS IN STANDBY. - FAILURE EFFECTS -

PRINT DATE: 11/07/8

SEUTTLE CRITICAL ITEMS LIST - ORBITER MUMBER: 05-121-0201-01

- (A) GURGISTEM: LOSS OF ONE REDUNDANT FAM. INTERRUPTION OF AIR FLOW.
- (B) INTERPACING SUBSTITUTE (B): UNTIL CORRECTING ACTION IS IMPLEMENTED, AIR FIGH LOSS RESULTS IN AIR QUALITY DEGRADATION (INCREASED CABIN TEMP, REDUCED COZ AND WATER REMOVAL), LOSS OF FLIGHT DECK AVIONICS COOLING, AND POSSIBLE LOSS OF SMORE DETECTION CAPABILITY.
- (C) MISSIDE: POSSIBLE EARLY MISSION TERMINATION.
- (D) CREW, VERICLE, AND RESIDENT(S): NO EFFECT.

PATIONALS FOR CRITICALITY: FUNCTIONAL CRITICALITY EFFECT - SECOND ASSOCIATED PAILURE (LOSS OF REDUNDANT FAM) WILL CAUSE LOSS OF AVIONICS COOLING AND MAY RESULT IN OVERHEATING AND PAILURE OF FLIGHT DECK AVIONICS, POTENTIALLY CAUSING LOSS OF CREW/VEHICLE.

- DISPOSITION RATIONALE -

(A) DESIGN: FAN IS AYIAL FLOW TYPE DRIVEN BY A 3 PHASE, 400 HZ, 115 VOLTS/PHASE INDUCTION TYPE ELECTRIC MOTOR. FAM HAS A CYLINDRICAL ALUMINUM HOUSING AND ALUMINUM IMPELLER. THE DESIGN OPERATING LIFE IS 20,000 HOURS MINIMUM. THE PARS ARE RUN TO FAILURE. BEARINGS ARE PRECISION BALL BEARINGS OF THE DEEP GROOVE TYPE AND ARE PRELOADED IN SUCH A MANDIER AS TO MINIMIZE THE RFFECTS OF INDUCED ENVIRONMENTS UPON PERFORMANCE OF THE FAM. THE BINDING OF ROTATING PARTS PAILURE CAUSE IS MINIMIZED BY BEARING SELECTION, UPSTREAM FILTRATION AND CLEARANCES BETWEEN ROTATING AND STATIONARY PARTS. THE BEARINGS SELECTED ARE FROM A FAMILY OF BEARINGS WHICH HAVE BEEN OPERATED FOR 120,000 HOURS AND 904 WERE STILL OPERATING AT THE END OF THE TEST (B10 LIFE). BEARING WEAR IS MINIMIZED BY BALANCING THE ROTATING ASSEMBLY ON ITS OWN. BEARING TO A REQUIREMENT OF 200 KICRO OUNCE INCHES AND USE OF HIGH LUBRICITY, RICH TEMPERATURE TOLERANT GREASE, ERYTOI 240AC. THE UPSTREAM FILTER IS 40/70 MICRON WHILE CLEARANCES BETWEEN ROTATING AND STATIONARY PARTS ARE 0.004 INCHES (127 MICRONS). THE MOTOR IS DESIGNED TO MEET A 55C TEMPERATURE RISE. MOTOR WILL CONTINUE TO OFERATE ON TWO PHASES. THE ELECTRICAL DISTRIBUTION SYSTEM DYNAMIC COMPONENTS ARE DERATED BEE PARTS. THE CONNECTORS ARE FER MIL-C-38999.

PRINT DATE: 11/6.,00

SECTILE CRITICAL ITEMS LIST - ORRITER MUMBER: 06-131-0101-01

(B) TEST:

DURING MANUFACTURING BUILDUP DIELECTRIC WITHSTANDING TEST IS PERFORMED.

ACCEPTANCE TEST - EACH FAN IS BURNED-IN FOR AT LEAST SIX HOURS. DURING ATP THE POWER IMAIN AND POWER FACTOR ARE MEASURED. INSULATION RESISTANCE 100 NEGORM MINIMUM WITH 500 VDC APPLIED. PAN PERFORMANCE IS VERIFIED FOR AIRFLOW AND DELTA-P WITH THREE PHASE AND TWO PHASE POWER SUPPLY.

QUALIFICATION TEST - FAN PACKAGE ASSEMBLY SUBJECTED TO RANDOM VIBRATION SPECTRUM ENVELOPE OF 20 TO 150 HZ INCREASING AT 6 DB/OCTAVE TO 0.09 G**2/HZ AT 150 HZ, CONSTANT AT 0.09 G**2/HZ FROM 150 TO 900 HZ. DECREASING AT 9 DB/OCTAVE FROM 900-2000 HZ FOR 48 MINUTES PER AXIS IN THREE ORTHOGORAL AXES. DESIGN SHOCK - THREE TERMINAL SANTOOTH PULSES OF 20 G PEAK AMPLITUDE AND 11 MS DURATION APPLIED IN BOTH DIRECTIONS ALONG EACH OF THREE ORTHOGONAL AXES. SALT SPRAY TEST WITH SOLUTION OF FIVE PARTS OF SALT BY WEIGHT AND BOR RH FOR 120 HOURS, CYCLED BETWEEN 60 AND 120F.

IN-VEHICLE TESTING - FAN PERFORMANCE (ON/OFF) IS VERIFIED IN BOTH MANUAL AND REMOTE MODES, AND DELTA-P IS VERIFIED. THREE PHASE OPERATION IS VERIFIED. FAN WITH LOWER FLOW RATE IS USED TO VERIFY SUPPLY DUCT AIR- FLOW. DELTA-P IS CONTINUALLY MONITORED WHEN VEHICLE IS POWERED UP.

OMRSD - PERFORMANCE OF THE CABIN FAMS IS VERIFIED DURING PACH TURNAROUND. THE CABIN FAN DEERIS TRAP IS INSTALLED ANYTIME THE CABIN FANS ARE OPERATED AND IS CLEANED DURING EVERY TURNAROUND.

(C) IMSPECTION: - RECEIVING INSPECTION

RAW MATERIAL VERIFIED.

CONTAMINATION CONTROL

CORROGION PROTECTION PROVISIONS AND CONTAMINATION CONTROL PLAN VERIFIED BY INSPECTION.

ASSEMBLY/INSTALLATION

PARTS PROTECTION, MANUFACTURING PROCESS, INSTALLATION AND ASSEMBLY VERIFIED BY INSPECTION. TORQUE VERIFIED BY INSPECTION. INBRIGANT APPLICATION VERIFIED BY INSPECTION.

HONDESTRUCTIVE EVALUATION

DYE PENETRANT AND X-RAY OF WELDS IS VERIFIED BY INSPECTION.

CRITICAL PROCESSES

ELECTRICAL TERMINATION VERIFIED BY INSPECTION. WELDING IS VERIFIED BY

PAGE: 6 FRINT DATE: 11/07/1

SKUTTLE CRITICAL ITEMS LIST - ORBITER MUMBER: 06-181-0201-01

INSPECTION.

TESTING

PERFORMANCE TEST AND CLEANLINESS VERIFICATION CONDUCTED.

HANDLING/PACKAGING

HANDLING AND PACKAGING REQUIREMENTS VERIFIED BY INSPECTION.

(D) FAILURE MISTORY: THREE FAN FAILURES HAVE OCCURRED:

- (1) CAR AZES6-010, 4-6-76. ONE FAN DID NOT START DURING OV101 ALT CHECKOUT. TWO OF THE THREE CIRCUIT BREAKERS IN THE POWER DISTRIBUTION SYSTEM WERE FOUND TO HAVE TRIPPED. THE MALFUNCTION WAS ATTRIBUTED TO SOME PROBLEM WHICH CAUSED ONE POWER PHASE TO TRIP. THEN WHEN THE PAN WAS ACTIVATED THE TWO CIRCUIT BREAKERS RECEIVING POWER TRIPPED. THE ANOMALY DISAPPEARED DURING TROUBLESHOOTING AND THE PAN SUBSEQUENTLY OPERATED PROPERLY. NO CORRECTIVE ACTION; UNEXPLAINED ANOMALY.
- AFTER STS-3, FAN B WAS FOUND TO BE NOISY. DEERIS WAS FOUND IN THE FAN HOUSING, NICKS WERE FOUND IN THE IMPELIER BLADE TIPS. THE BEARING ON THE IMPELLER END OF THE SHAFT WAS LIGHTLY BRINELLED. BEARING GREASE WAS ADEQUATE IN AMOUNT AND CONSISTENCY. CAUSE OF THE BRINELLING WAS CONSIDERED TO BE ASSEMBLY DAMAGE AND SHOCK LOADING ON THE BEARING WHEN SOLID DEERIS PASSED THROUGH THE FAN. BRINELLING OF THE BRARING AND UNBALANCE CAUSED BY DEERIS BUILDUP ON THE ROTATING PARTS RESULTED IN THE INCREASE IN FAN MOISE, WHICH WAS AMPLIFIED BY THE EFFECTS OF AIR DUCTS AND MOUNTINGS. CORRECTIVE ACTION NONE; EXISTING FAN MOTOR ASSEMBLY PROCEDURES WERE CONSIDERED ADEQUATE, AND DEERIS TRAP CLEANING PROCEDURE WAS ADEQUATE. AFTER CAR CLOSEOUT, FILTERS WERE RESIZED (FROM JOO MICRON TO 40/70 MICRON), PRECLUDING CONTAMINATION.
- (3) CAR ADO353-010, 10-10-85. DURING OV-099 CHECKOUT, FAN B EXHIBITED ABNORMAL MOISE AND VIERATION THROUGH ADJACENT STRUCTURE.
 INVESTIGATION REVEALED IMPELIER BLADE DAMAGE CAUSED BY THE INTRODUCTION OF A POREIGN OBJECT INTO THE FAN HOUSING. THE OBJECT WAS NEVER FOUND. THE IMPELIER HAD RUBBED A 90 DEGREE ARC ON THE HOUSING. AN ACCUMULATION OF LINT AND OTHER NATERIALS WAS FOUND ON THE INSIDE OF THE IMPELLER BLADE HUB. CORRECTIVE ACTION NCR 11258 WAS ISSUED TO ESTABLISE CONTAINATION CONTROL FRACTICE AND PROCEDURES.

(E) OPERATIONAL CEE:

1. CREW ACTION
FAN PERFORMANCE DEGRADATION TROUBLESHOOTING AND APPROPRIATE FOLLOW
ON PROCEDURES (POWERDOWN).

2. TRAINING

A. CURRENT ECLSS TRAINING COVERS THE GENERIC EFFECT OF THIS FAILURE.

PRINT DATE: 11/07/86

SHUTTLE CRITICAL ITEMS LIST - ORBITER MUMBER: 06-131-0301-01

B. CURRENT FOF CONTAINS APPLICABLE CONTINGENCY PROCEDURES FOR THE REFECT OF THE FAILURE.

- 3. OPERATIONAL CONSIDERATIONS
 - A. REAL TIME DATA SYSTEM ALLOWS FOR GROUND MONITORING.
 - B. REFERENCE CURRENT LOSS/FAILURE FLIGHT RULES.
 - C. POTENTIAL LOSS OF CO2 COSTROL; USE OF LES MAY BE REQUIRED.

REMARKS:

- APPROVALS -

RELIABILITY ENGINEERING: W. L. STEISSLINGER
DESIGN ENGINEERING : H. K. DUONG ELL
OUALITY ENGINEERING : D. R. STOICA DRS
NASA RELIABILITY :
NASA DESIGN :
NASA OUALITY ASSURANCE :