

**FAILURE MODES EFFECTS ANALYSIS (FMEA) - CRITICAL HARDWARE**  
**NUMBER: M5-6MR-8004-X**

SUBSYSTEM NAME: ORBITER DOCKING SYSTEM

REVISION: 1      SEPT 1, 1995

	PART NAME VENDOR NAME	PART NUMBER VENDOR NUMBER
LRU	ENERGIA POWER PANEL RSC-E	MC621-0087-0009 CJMKD.488.312.001
SRU	PUSH BUTTON SWITCH	PKZ-8 (AGO.360.212.TU)

---

**PART DATA**


---

**EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:**  
 PUSH-BUTTON SWITCHES(TWO DOUBLE POLE SWITCHES UNDER A SINGLE COVER  
 CAP.) TWO POLE, MOMENTARY - APDS "RING-OUT" COMMAND.

**REFERENCE DESIGNATORS:** 36V73A&A3SB1-B5  
 36V73A&A3SB1-B6

**QUANTITY OF LIKE ITEMS:** 2  
 (TWO)

**FUNCTION:**  
 PROVIDE THE "RING OUT" COMMAND STIMULI TO CLOSE THE APPROPRIATE CONTACTS  
 IN THE DSCU TO ENABLE THE TRANSMITTAL OF THE "RING OUT" COMMAND TO THE  
 DMCU. THE DMCU ENABLES POWER TO THE RING MOTORS (M4 & M5) FOR RING  
 EXTENSION AND RETRACTION FUNCTIONS.

M5-6MR - 119

RSC  
Energia**Proprietary Data**

## FAILURE MODES EFFECTS ANALYSIS (FMEA) - CIL FAILURE MODE

NUMBER: M5-6MR-B004- D1

REVISION# 1      SEPT 1, 1995

SUBSYSTEM NAME: ORBITER DOCKING SYSTEM

LRU: MC821-0087-0009

ITEM NAME: PUSH BUTTON SWITCH

CRITICALITY OF THIS

FAILURE MODE: 2R3

## FAILURE MODE:

FAILS OPEN (MULTIPLE CONTACTS WITHIN ONE SWITCH)

## MISSION PHASE:

OO      ON-ORBIT

VEHICLE/PAYLOAD/KIT EFFECTIVITY: 104 ATLANTIS

## CAUSE:

A) PIECE PART FAILURE, B) CONTAMINATION, C) VIBRATION, D) MECHANICAL SHOCK, E) PROCESSING ANOMALY, F) THERMAL STRESS

CRITICALITY 1M DURING INTACT ABORT ONLY? NO

CRITICALITY 1R2 DURING INTACT ABORT ONLY (AVIONICS ONLY)? NO

## REDUNDANCY SCREEN

A) PASS

B) N/A

C) FAILS

## PASS/FAIL RATIONALE:

A)

B)

N/A

C)

REDUNDANT FUNCTIONS ROUTED THROUGH THE SAME CONNECTOR.

## METHOD OF FAULT DETECTION:

NONE.

## MASTER MEAS. LIST NUMBERS:

NONE

## - FAILURE EFFECTS -

## (A) SUBSYSTEM:

PARTIAL LOSS OF SWITCH CONTROL CAPABILITY FOR THE APDS "RING-OUT" COMMAND.

## (B) INTERFACING SUBSYSTEM(S):

FIRST FAILURE - NO EFFECT. LOSS OF COMMAND REDUNDANCY.

## (C) MISSION:

FIRST FAILURE - NO EFFECT.

RSC  
Energia

Proprietary Data

FAILURE MODES EFFECTS ANALYSIS (FMEA) - GIL FAILURE MODE  
NUMBER: MS-6MR-0004-01

(D) CREW, VEHICLE, AND ELEMENT(S):  
NO EFFECT.

(E) FUNCTIONAL CRITICALITY EFFECTS:  
FIRST FAILURE (ONE OF TWO ASSOCIATED SWITCHES FAILS OPEN) - DISABLES ONE OF THREE PANEL COMMAND SIGNALS. NO EFFECT.  
SECOND FAILURE (FAILURE OF ASSOCIATED SWITCH DISABLES THE REMAINING TWO PANEL COMMAND CHANNEL INPUTS TO THE DSCU) - INABILITY TO EXTEND THE DOCKING RING TO ITS INITIAL DOCKING POSITION USING NOMINAL PROCEDURES.

DESIGN CRITICALITY (PRIOR TO OPERATIONAL DOWNGRADE, DESCRIBED IN F): 2R3

(F) RATIONALE FOR CRITICALITY CATEGORY DOWNGRADE:  
~~THIRD FAILURE (INABILITY TO PERFORM IFM TO DRIVE RING MOTORS) - LOSS OF ALL RING CONTROL RESULTING IN LOSS OF CAPABILITY TO PERFORM DOCKING. LOSS OF MISSION OBJECTIVES WITH INABILITY TO PERFORM DOCKING. NA~~

-DISPOSITION RATIONALE-

(A) DESIGN:  
REFER TO APPENDIX C, ENERGIA HARDWARE.

(B) TEST:  
REFER TO APPENDIX C, ENERGIA HARDWARE.

APDS PANEL OPERATION IS VERIFIED DURING GROUND CHECKOUT. ANY TESTING IS ACCOMPLISHED IN ACCORDANCE WITH OMRSD.

(C) INSPECTION:  
REFER TO APPENDIX C, ENERGIA HARDWARE.

(D) FAILURE HISTORY:  
REFER TO APPENDIX C, ENERGIA HARDWARE.

(E) OPERATIONAL USE:  
AFTER SECOND FAILURE, IN-FLIGHT MAINTENANCE PROCEDURES DEVELOPED TO DRIVE THE RING MOTORS DIRECTLY FROM THE FEED-THROUGH CONNECTORS IN THE EXTERNAL AIRLOCK, USING THE ORBITER BREAKOUT BOX.

- APPROVALS -

PRODUCT ASSURANCE ENGR : M. NIKOLAYEVA  
DESIGN ENGINEER : B. VAKULIN  
NASA SS/MA :  
NASA SUBSYSTEM MANAGER :  
  
NASA EPD&C SUBSYSTEM MANAGER :

*[Handwritten signatures and dates]*  
9/21/95  
9/22/95  
9/21/95



RSC  
Energia Proprietary Data