

**FAILURE MODES EFFECTS ANALYSIS (FMEA) - CRITICAL HARDWARE
NUMBER: M5-6MR-8024-X**

SUBSYSTEM NAME: ORBITER DOCKING SYSTEM

REVISION: 1 SEPT 1, 1995

	PART NAME VENDOR NAME	PART NUMBER VENDOR NUMBER
LRU	DMCU RSC-E	MC621-0087-0005 33Y.6212.D11

PART DATA

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:
LINE REPLACEABLE UNIT (LRU) DOCKING MECHANISM CONTROL UNIT (DMCU) -
DOCKING RING MOTORS (M/M5) LOGIC AND POWER CONTROL.

REFERENCE DESIGNATORS: 40V53A1A3

QUANTITY OF LIKE ITEMS: 1
(ONE)

FUNCTION:

THE DMCU IS DESIGNED TO RECEIVE COMMANDS FROM THE DOCKING SYSTEM CONTROL UNIT (DSCU.) IT IMPLEMENTS DOCKING RING CONTROL DURING THE AUTOMATIC AND THE PANEL CONTROLLED OPERATIONAL MODES. THE UNIT CONTROLS THE TWO DOCKING MECHANISM (RING) ELECTROMOTORS. THE UNIT RECEIVES THE FOLLOWING COMMANDS FROM THE CONTROL PANEL THROUGH THE DSCU: 1) RING RETRACT, 2) STOP RING RETRACTION, 3) RING EXTEND, AND 4) STOP RING EXTENSION. THE UNIT PROVIDES ONE TELEMETRY SIGNAL TO THE DATA COLLECTION UNITS (DCUs) FOR MONITORING THE RING MOTOR ACTUATION.

OUTPUT FUNCTIONS:

- 1) MOTOR CONTROL \pm 27 V RING DEPLOY/RETRACT POWER FOR M/M5 MOTORS (TWO POSITIVE AND TWO NEGATIVE POWER OUTPUTS PER MOTOR.)
- 2) TELEMETRY INFORMATION (ONE DISCRETE) TO THE DCU-1.

RSC
Energia**Proprietary Data**

**FAILURE MODES EFFECTS ANALYSIS (FMEA) - CIL FAILURE MODE
NUMBER: M5-6MR-B024-01**

**SUBSYSTEM NAME: ORBITER DOCKING SYSTEM
LRU: MC621-0067-0005
ITEM NAME: DMCU**

REVISION# 1 SEPT 1, 1985

**CRITICALITY OF THIS
FAILURE MODE: 2R3**

**FAILURE MODE:
LOSS OF M4/M5 MOTOR CONTROL SIGNAL (ONE OF THREE) FOR RING EXTENSION OR
RETRACT.**

**MISSION PHASE:
OO ON-ORBIT**

VEHICLE/PAYLOAD/KIT EFFECTIVITY: 104 ATLANTIS

**CAUSE:
INTERNAL COMPONENT FAILURE(S)**

CRITICALITY 1H DURING INTACT ABORT ONLY? NO

CRITICALITY 1R2 DURING INTACT ABORT ONLY (AVIONICS ONLY)? NO

**REDUNDANCY SCREEN A) PASS
 B) FAILS
 C) FAILS**

**PASS/FAIL RATIONALE:
A)**

**B)
SINGLE RELAY FAILURE NOT DETECTABLE.**

**C)
REDUNDANT FUNCTIONS ROUTED THROUGH THE SAME CONNECTOR.**

**METHOD OF FAULT DETECTION:
RING WOULD STOP AFTER SECOND FAILURE.**

MASTER MEAS. LIST NUMBERS: NONE

- FAILURE EFFECTS -

**(A) SUBSYSTEM:
DEGRADATION OF REDUNDANCY FOR CONTROLLING RING DRIVE MOTORS.**

**(B) INTERFACING SUBSYSTEM(S):
NO EFFECT.**

**(C) MISSION:
FIRST FAILURE - NO EFFECT.**



**RSC
Energie**

Proprietary Data

FAILURE MODES EFFECTS ANALYSIS (FMEA) - CIL FAILURE MODE

NUMBER: M5-6MR-2024-01

(D) CREW, VEHICLE, AND ELEMENT(S):
NO EFFECT.

(E) FUNCTIONAL CRITICALITY EFFECTS:

FIRST FAILURE (LOSS OF ONE OF THREE INTERNAL CONTROL SIGNALS OF RING DRIVE LOGIC CIRCUIT) - DEGRADED RING DRIVE CONTROL REDUNDANCY.
 SECOND FAILURE (LOSS OF SECOND ASSOCIATED INTERNAL CONTROL SIGNAL) - LOSS OF ALL RING CONTROL RESULTING IN LOSS OF CAPABILITY TO PERFORM DOCKING.
 LOSS OF MISSION OBJECTIVES WITH INABILITY TO PERFORM DOCKING.

DESIGN CRITICALITY (PRIOR TO OPERATIONAL DOWNGRADE, DESCRIBED IN F): 2R3

(F) RATIONALE FOR CRITICALITY CATEGORY DOWNGRADE:

N/A (THERE ARE NO WORKAROUNDS TO CIRCUMVENT THIS FAILURE) 2DISPOSITION RATIONALE.

(A) DESIGN:

REFER TO APPENDIX E, ENERGIA HARDWARE.

(B) TEST:

REFER TO APPENDIX E, ENERGIA HARDWARE.

RING DEPLOYMENT CONTROL OPERATION IS VERIFIED DURING GROUND CHECKOUT.
 ANY TESTING IS ACCOMPLISHED IN ACCORDANCE WITH OMRSD.

(C) INSPECTION:

REFER TO APPENDIX E, ENERGIA HARDWARE.

(D) FAILURE HISTORY:

REFER TO APPENDIX E, ENERGIA HARDWARE.

(E) OPERATIONAL USE:

AFTER THIRD FAILURE, CREW COULD PERFORM AN IN-FLIGHT MAINTENANCE TO DRIVE THE RING MOTORS DIRECTLY FROM THE FEED-THROUGH CONNECTORS IN THE EXTERNAL AIRLOCK, USING THE ORBITER BREAKOUT BOX. HOWEVER, WORST CASE, CREW WOULD ABORT DOCKING SINCE THIS WORKAROUND REQUIRES A GREAT DEAL OF TIME TO PERFORM.

- APPROVALS -

PRODUCT ASSURANCE ENGR : M. NIKLAYEVA
 DESIGN ENGINEER : B. VAKULIN
 NASA SS/MA :
 NASA SUBSYSTEM MANAGER :
 NASA EPD/C SUBSYSTEM MANAGER :

[Handwritten signatures and dates]
 9/21/95
 9/22/95
 9/21/95

RSC
Energia

Proprietary Data