

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- NON-CIL HARDWARE
NUMBER:M5-6SS-0108 -X

SUBSYSTEM NAME: ISS DOCKING SYSTEM

REVISION: 0 02/27/98

PART DATA

	PART NAME	PART NUMBER
	VENDOR NAME	VENDOR NUMBER
LRU	:PANEL A6A3	V828-730150
SRU	:TOGGLE SWITCH	ME452-0102-7801

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:
 SWITCHES, TOGGLE, 3 POLE 2 POSITION, MAINTAINED ON - PSU POWER MAIN A AND B CONTROL CIRCUIT.

REFERENCE DESIGNATORS: 38V73A7A3S9
 38V73A7A3S10

QUANTITY OF LIKE ITEMS: 2
 TWO

FUNCTION:
 THE SWITCHES PROVIDE MANUAL ACTIVATION OF PANEL PSU POWER MAIN A AND MAIN B POWER CIRCUITS.

REFERENCE DOCUMENTS: 1) VS70-953103, INTEGRATED SCHEMATIC - 53G, MAIN A/MAIN B SUPPLY BUS POWER DISTRIBUTION

FAILURE MODES EFFECTS ANALYSIS FMEA -- NON-CIL FAILURE MODE

NUMBER: M5-6SS-0108-02

REVISION#: 0 02/27/98

SUBSYSTEM NAME: ISS DOCKING SYSTEM

LRU: PANEL A6A3

ITEM NAME: TOGGLE SWITCH

CRITICALITY OF THIS

FAILURE MODE: 1R3

FAILURE MODE:

FAILS CLOSED IN "ON" POSITION, CONTACT-TO-CONTACT SHORT

MISSION PHASE: OO ON-ORBIT

VEHICLE/PAYLOAD/KIT EFFECTIVITY:	103	DISCOVERY
	104	ATLANTIS
	105	ENDEAVOUR

CAUSE:

A) PIECE PART STRUCTURAL FAILURE, B) CONTAMINATION, C) VIBRATION, D) MECHANICAL SHOCK, E) PROCESSING ANOMALY, F) THERMAL STRESS

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

CRITICALITY 1R2 DURING INTACT ABORT ONLY (AVIONICS ONLY)? NO

REDUNDANCY SCREEN	A) PASS
	B) N/A
	C) PASS

PASS/FAIL RATIONALE:

A)

B)

"B" SCREEN IS N/A SINCE FAILURE OF AT LEAST TWO REMAINING PATHS ARE DETECTABLE IN FLIGHT.

C)

METHOD OF FAULT DETECTION:

THE FAILURE WOULD BE DETECTED DURING SYSTEM POWER DOWN.

MASTER MEAS. LIST NUMBERS:	V53X0777E
	V53X0778E
	V53X0779E

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- NON-CIL FAILURE MODE
 NUMBER: M5-6SS-0108-02

V53X0780E
 V53X0786E
 V53X0787E
 V53X0788E
 V53X0789E

CORRECTING ACTION: MANUAL

CORRECTING ACTION DESCRIPTION:

CREW CAN OPEN ASSOCIATED PANEL A7A2 SWITCHES.

REMARKS/RECOMMENDATIONS:

EACH PACU IS SUPPLIED WITH POWER BY BOTH MAIN A AND B. ONE MOTOR FOR GROUP 1(2) IS POWERED BY MAIN A AND THE OTHER MOTOR FOR GROUP 1(2) IS POWERED BY MAIN B.

- FAILURE EFFECTS -

(A) SUBSYSTEM:

LOSS OF SWITCH CONTROL CAPABILITY FOR THE AFFECTED PSU POWER CIRCUIT.

(B) INTERFACING SUBSYSTEM(S):

ONE PSU POWER CIRCUIT CONTINUOUSLY ENERGIZED.

(C) MISSION:

NO EFFECT

(D) CREW, VEHICLE, AND ELEMENT(S):

FIRST FAILURE - NO EFFECT

(E) FUNCTIONAL CRITICALITY EFFECTS:

POSSIBLE LOSS OF CREW/VEHICLE AFTER EIGHT FAILURES:

- 1) "PSU POWER" SWITCH FAILS CLOSED.
- 2) ONE OF TWO ASSOCIATED "UNDOCKING" SWITCHES (PANEL A7A2) FAILS CLOSED.
- 3) ONE OF TWO ASSOCIATED "POWER ON" SWITCHES (PANEL A7A2) FAILS CLOSED.
- 4) ONE OF TWO ASSOCIATED "APDS CIRC PROT OFF" SWITCHES (PANEL A7A2) FAILS CLOSED.
- 5,6) TWO "APDS POWER" (PANEL A7A2) CIRCUIT BREAKERS FAILED CLOSED.
- 7,8) TWO APDS "CONTROL PANEL POWER" (PANEL A7A2) CIRCUIT BREAKERS FAIL CLOSED RESULTING IN ALL HOOKS INADVERTENTLY OPENING. POSSIBLE LOSS OF HABITABLE ENVIRONMENT.

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- NON-CIL FAILURE MODE
NUMBER: M5-6SS-0108-02

- TIME FRAME -

TIME FROM FAILURE TO CRITICAL EFFECT: DAYS

TIME FROM FAILURE OCCURRENCE TO DETECTION: HOURS

TIME FROM DETECTION TO COMPLETED CORRECTING ACTION: HOURS

IS TIME REQUIRED TO IMPLEMENT CORRECTING ACTION LESS THAN TIME TO EFFECT?
YES

RATIONALE FOR TIME TO CORRECTING ACTION VS TIME TO EFFECT:
TO REMOVE POWER TO THE FAILED CLOSED "PSU POWER" SWITCH, THE CREW CAN
OPEN THE ASSOCIATED "UNDOCKING" SWITCH ON PANEL A7A2.

HAZARD REPORT NUMBER(S): ORBI 511

HAZARD(S) DESCRIPTION:
LOSS OF HABITABLE ENVIRONMENT IN ODS/CREW MODULE

- APPROVALS -

SS&PAE
DESIGN ENGINEERING

: T. K. KIMURA
: C. J. ARROYO

J. Kimura 4-13-98
C. Arroyo