PAGE: 1 PRINT DATE: 04/11/98

### FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL HARDWARE NUMBER: M5-6SS-0114 -X

SUBSYSTEM NAME: ISS DOCKING SYSTEM

REVISION: 0

02/27/98

PART DATA

PART NAME

**VENDOR NAME** 

PART NUMBER

VENDOR NUMBER

LRU :MID PCA-1

VQ70-764400

SRU

:GENERAL PURPOSE RELAY

MC455-0129-0004

**EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:** 

GENERAL PURPOSE RELAY, 25 AMP - PYRO POWER MAIN A +Y1 LOGIC BUS SIGNAL

REFERENCE DESIGNATORS: 40V76A25A2K2

QUANTITY OF LIKE ITEMS: 1

ONE

FUNCTION:

THE CONTACTOR PROVIDES POWER DISTRIBUTION AND ACTIVATION FOR ONE OF THE TWO LOGIC BUSES IN THE PFCU.

REFERENCE DOCUMENTS:

1) VS70-953103, INTEGRATED SCHEMATIC - 53PA, PFCU

POWER DISTRIBUTION CONTROL CIRCUIT

PAGE 5 PRINT DATE: 04/11/98

FAILURE MODES EFFECTS ANALYSIS FMEA - NON-CIL FAILURE MODE

NUMBER: M5-6SS-0114-02

REVISION#: 0

02/27/98

SUBSYSTEM NAME: ISS DOCKING SYSTEM

LRU: MID PCA-1

ITEM NAME: GENERAL PURPOSE RELAY

**CRITICALITY OF THIS** 

FAILURE MODE: 1R3

FAILURE MODE:

CLOSED, FAILS TO OPEN, PREMATURELY CLOSES, SHORTS CONTACT-TO-CONTACT

MISSION PHASE:

OO ON-ORBIT

VEHICLE/PAYLOAD/KIT EFFECTIVITY:

103 DISCOVERY

104 ATLANTIS

105 ENDEAVOUR

CAUSE:

A) PIECE PART FAILURE, B) CONTAMINATION, C) VIBRATION, D) MECHANICAL SHOCK, E) PROCESSING ANOMALY, F) THERMAL STRESS

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

CRITICALITY 1R2 DURING INTACT ABORT ONLY (AVIONICS ONLY)? NO

REDUNDANCY SCREEN

A) PASS

B) N/A

C) PASS

PASS/FAIL RATIONALE:

A)

N/A - PYROTECHNIC SEPARATION IS CLASSIFIED AS STANDBY REDUNDANCY.

C)

## METHOD OF FAULT DETECTION:

TELEMETRY CAN BE USED TO VERIFY POWER ON OR OFF FOR THE PSU 20 AMP BUSES. "PYROTECHNIC BUS STATUS (AP. 8P, AND CP)" AND "PYRO CIRCUIT PROTECT CIRCUIT OFF" INDICATIONS IN THE APDS D&C PANEL

MASTER MEAS. LIST NUMBERS: V53X0765E

PAGE: 6 PRINT DATE: 04/11/98

## FAILURE MODES EFFECTS ANALYSIS (FMEA) -- NON-CIL FAILURE MODE NUMBER: M5-6SS-0114-02

V53X0766E V53X0797E V53X0798E V53X0796E

CORRECTING ACTION: NONE

### CORRECTING ACTION DESCRIPTION:

DESIGN FAULT TOLERANCE: "PYRO CIRCUIT PROTECTION OFF" SWITCHES PROVIDE REDUNDANCY AGAINST INADVERTENT PROTECHNIC SEPARATION.

#### - FAILURE EFFECTS -

## (A) SUBSYSTEM:

DEGRADATION OF REDUNDANCY AGAINST INADVERTENT PYROTECHNIC SEPARATION.

# (B) INTERFACING SUBSYSTEM(S):

FIRST FAILURE - NO EFFECT

#### (C) MISSION:

FIRST FAILURE - NO EFFECT.

# (D) CREW, VEHICLE, AND ELEMENT(S):

FIRST FAILURE - NO EFFECT.

# (E) FUNCTIONAL CRITICALITY EFFECTS:

POSSIBLE LOSS OF CREW/VEHICLE AFTER SIX FAILURES:

- RELAY FAILS CLOSED.
- 2) ONE OF TWO "PYRO CIRCUIT PROTECTION OFF" SWITCHES FAILS CLOSED (MULTIPLE CONTACTS) - UNWANTED "PYRO CIRCUIT PROTECTION OFF" COMMAND TO THE PFCU. DEGRADED PROTECTION AGAINST ACCIDENTAL PYROTECHNIC SEPARATION.
- ONE RPC IN THE PYRO POWER CIRCUITRY FAILS ON.
- 4,5) TWO OF THREE PYROTECHNIC POWER CIRCUIT BREAKERS FAILS CLOSED.
- 6) ONE "ACTIVE" OR "PASSIVE" HOOKS FIRING SWITCH FAILS CLOSED (MULTIPLE CONTACTS). POSSIBLE VEHICLE SEPARATION OR LOSS OF HABITABLE VOLUME DUE TO UNWANTED PYRO "FIRE" COMMAND.

TILLE	ED A NE
- 1464	PRAME

PAGE: 7 PRINT DATE 04/11/98

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- NON-CIL FAILURE MODE NUMBER: M5-688-0114-02

TIME FROM FAILURE TO CRITICAL EFFECT: DAYS

TIME FROM FAILURE OCCURRENCE TO DETECTION: MINUTES

TIME FROM DETECTION TO COMPLETED CORRECTING ACTION: N/A

IS TIME REQUIRED TO IMPLEMENT CORRECTING ACTION LESS THAN TIME TO EFFECT?

RATIONALE FOR TIME TO CORRECTING ACTION VS TIME TO EFFECT:
THE CREW CAN KEEP OPEN THE ASSOCIATED "PYRO CIRCUIT PROTECTION OFF"
SWITCH OR PROTECHNIC POWER CIRUIT BREAKER AS PROTECTION AGAINST
ACCIDENTAL PYROTECHNIC SEPARATION.

HAZARD REPORT NUMBER(\$): ORBI 511

HAZARD(S) DESCRIPTION:

LOSS OF HABITABLE ENVIRONMENT IN ODS/CREW MODULE.

- APPROVALS -

5S&PAE

DESIGN ENGINEERING

: T. K. KIMURA

: C. J. ARROYO