PAGE: 1

PRINT DATE: 03.12.96

FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL HARDWARE

NUMBER: M5-6\$\$-8002-X

SUBSYSTEM NAME: E - DOCKING SYSTEM

REVISION:

Ð

DEC. 1996

PART NAME

VENDOR NAME

PART NUMBER VENDOR NUMBER

LRU

SRU

: ENERGIA POWER PANEL

ASC-E

: PUSH BUTTON SWITCH

MC621-0087-0009

SLIYU.468312.001

PKZ-6 (AGO.360.212.TU)

PART DATA

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:
PUSH-BUTTON SWITCHES (TWO DOUBLE POLE SWITCHES UNDER A SINGLE COVER CAP.) TWO POLE, MOMENTARY - APDS "POWER-ON" COMMAND.

REFERÊNCE DESIGNATORS: 36V73A8A3S81-81

36V73A8A3SB1-B2

QUANTITY OF LIKE ITEMS: 2

(CWO)

FUNCTION:

PROVIDE THE "TURN-ON" COMMAND TO THE POWER SWITCHING UNIT (PSU.) THE PSU PROVIDES THE LOGIC BUSES TO THE DSCU. DMCU, PACU, AND THE LACU. THESE LOGIC BUSES ARE REQUIRED TO IMPLEMENT ALL DOCKING AND UNDOCKING OPERATIONS.

PRINT DATE: 10.02.97

PAGE: 2

FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL FAILURE MODE NUMBER: MS-555-8002-01

> REVISION 0 FEBRUSC, 19976

SUBSYSTEM NAME: E - DOCKING SYSTEM

LRU: MC621-0087-0009 ITEM NAME: PUSH BUTTON SWITCH CRITICALITY OF THIS

FAILURE MODE: 183

FAILURE MODE:

FAILS OPEN (MULTIPLE CONTACTS WITHIN ONE SWITCH)

MISSION PHASE:

ON-ORBIT

103 DISCOVERY VEHICLE/PAYLOAD/KIT EFFECTIVITY:

> 104 ATLANTIS 105 ENDEAVOUR

CAUSE:

A) PIECE PART STRUCTURAL FAILURE, B) CONTAMINATION, C) VIBRATION, D) MECHANICAL SHOCK, E) PROCESSING ANOMALY, F) THERMAL STRESS

CRITICALITY 1/1 DURING INTACT ABORT DILLY? NO

CRITICALITY 1R2 DURING INTACT ABORT ONLY (AVIONICS ONLY)? NO

REDUNDANCY SCREEN

A) PASS

B) N/A

C) PASS

PASS/FAIL RATIONALE:

A)

N/A - AT LEAST-TWO REMAINING PATHS ARE DETECTABLE IN FLIGHT.

C)

METHOD OF FAULT DETECTION:

NONE.

MASTER MEAS, LIST NUMBERS:

NONE

CORRECTING ACTION:

WORKAROUNDS ARE AVAILABLE TO SEPARATE THE ORBITER FROM ISS:

1) IFM TO DRIVE HOOKS OPEN;

2) INITIATION OF PYROBOLT SEPARATION:

32) PERFORM EVA TO REMOVE 96 BOLTS FROM THE DOCKING BASE.

PRINT DATE: 03.12.96

FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL FAILURE MODE NUMBER: M5-65S-B002-01

- FAILURE EFFECTS .

(A) SUBSYSTEM:

PARTIAL LOSS OF SWITCH CONTROL CAPABILITY FOR THE APDS "POWER-ON" COMMAND.

(B) INTERFACING SUBSYSTEM(S):

FIRST FAILURE - NO EFFECT, LOSS OF COMMAND REDUNDANCY.

(C) MISSION:

NO EFFECT.

(D) CREW, VEHICLE, AND ELEMENT(S):

FIRST FAILURE - NO EFFECT.

(E) FUNCTIONAL CRITICALITY EFFECTS:

WORST CASE, SHUTTLE MECHANISM CONTROL: POSSIBLE LOSS OF CREW OR VEHICLE AFTER THREE FAILURES.

1) ONE OF TWO ASSOCIATED SWITCHES FAILS OPEN. DISABLES ONE OF THREE PANEL COMMAND SIGNALS. NO EFFECT. 2) FAILURE OF ASSOCIATED SWITCH DISABLES REMAINING TWO PANEL COMMAND CHANNEL INPUTS TO THE PSU. LOSS OF NOMINAL UNDOCKING CAPABILITY. 3) ONE PYROBOLT FAILS TO INITIATE RESULTING IN LOSS OF CAPABILITY TO IMPLEMENT PYROTECHNIC SEPARATION. LOSS OF NOMINAL AND PYROTECHNIC SEPARATION CAPABILITY.

DESIGN CRITICALITY (PRIOR TO OPERATIONAL DOWNGRADE, DESCRIBED IN F):

(F) RATIONALE FOR CRITICALITY CATEGORY DOWNGRADE:
ALTHOUGH THE CRITICALITY REMAINS UNCHANGED AFTER WORKAROUNDS
CONSIDERATION (ALLOWED PER CR \$050107W), THEY ARE PROVIDING ADDITIONAL

FAULT TOLEPANCE TO THE SYSTEM.

AFTER THE SECOND FAILURE. THE CREW WOULD PERFORM IFM TO DRIVE THE HOOKS OPEN. IF UNABLE TO PERFORM THE IFM (THIRD FAILURE) THEN IMPLEMENT THE PYROTECHNIC SEPARATION. IF UNABLE TO PERFORM THE PYROTECHNIC SEPARATION (FOURTH FAILURE) THEN PERFORM EVA TO REMOVE 96 BOLTS TO CIRCUMVENT THE WORST CASE 'DESIGN CRITICALITY' EFFECT. IF UNABLE TO PERFORM EVA (FIFTH FAILURE), POSSIBLE LOSS OF CREWNEHICLE DUE TO LOSS OF ALL UNDOCKING CAPABILITY.

- TIME FRAME -

TIME FROM FAILURE TO CRITICAL EFFECT: DAYS

TIME FROM FAILURE OCCURRENCE TO DETECTION: MINUTES

TIME FROM DETECTION TO COMPLETED CORRECTIVE ACTION: HOURS

TIME REQUIRED TO IMPLEMENT CORRECTIVE ACTION LESS THAN TIME TO EFFECT? YES

PAGE: 4

PRINT DATE: 03.12.96

Failure modes effects analysis (fmea) - Non-Cil Failure mode

NUMBER: M5-6SS-8002-01

HATIONALE FOR TIME TO CORRECTING ACTION VS TIME TO EFFECT: CREW WOULD HAVE SUFFICIENT TIME TO USE OR PERFORM EVA.

HAZAROS REPORT NUMBER(S): ORBI 401A

HAZARD DESCRIPTION: INABILITY TO SEPARATE ORBITER AND ISS.

- APPROVALS .

PRODUCT ASSURANCE ENGR DESIGN ENGINEER

: M. NIKOLAYEVA

: B. VAKULIN