

FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL HARDWARE  
NUMBER: M5-655-B010-X

SUBSYSTEM NAME: E - DOCKING SYSTEM

REVISION: 0 DEC, 1996

	PART NAME VENDOR NAME	PART NUMBER VENDOR NUMBER
LRU	: ENERGIA POWER PANEL RSC-E	MC621-0067-0009 SLYUJ.468312.001
SRU	: PUSH BUTTON SWITCH	PKZ-2 (AGO.360.212.TU)

## PART DATA

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:  
PUSH-BUTTON SWITCHES (TWO DOUBLE POLE SWITCHES UNDER A SINGLE COVER CAP.) TWO POLE, MOMENTARY - APDS "UNDOCKING" COMMAND.

REFERENCE DESIGNATORS: 36V73A8A3SB3-B1  
36V73A8A3SB3-B2

QUANTITY OF LIKE ITEMS: 2  
(TWO)

## FUNCTION:

PROVIDE THE 'UNDOCKING' COMMAND STIMULI TO CLOSE THE APPROPRIATE CONTACTS IN THE DSCU TO IMPLEMENT THE 'UNDOCKING' FUNCTION. THE 'UNDOCKING' SIGNAL IS ROUTED BY THE DSCU TO THE PACU-1 AND PACU-2 TO ENABLE THE MOTORS (M6, M7, M8, AND M9) WHICH IMPLEMENT THE OPENING OF THE STRUCTURAL LATCHES (HOOKS 1 & 2) FOR SEPARATION FROM THE ISS. ~~INOMINAL UNDOCKING IS NOT PLANNED TO FULL ASSEMBLY.~~ THIS COMMAND CAN ONLY BE IMPLEMENTED AFTER THE 'APDS CIRCUIT PROTECTION OFF' SWITCH IS ENABLED AND THE APDS CONTROL COMMAND PROTECTIVE COVER IS REMOVED.

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- NON-CIL FAILURE MODE  
NUMBER: M5-6SS-B010-02

REVISION# 0 DEC, 1996

SUBSYSTEM NAME: E - DOCKING SYSTEM  
LRU: MC621-0087-0009  
ITEM NAME: PUSH BUTTON SWITCH

CRITICALITY OF THIS  
FAILURE MODE: 1R3

FAILURE MODE:  
FAILS CLOSED (MULTIPLE CONTACTS WITHIN ONE SWITCH,) SHORTS TO GROUND

MISSION PHASE:  
OO ON-ORBIT

VEHICLE/PAYLOAD/KIT EFFECTIVITY: 103 DISCOVERY  
104 ATLANTIS  
105 ENDEAVOUR

CAUSE:  
A) PIECE PART FAILURE, B) CONTAMINATION, C) VIBRATION, D) MECHANICAL SHOCK, E)  
PROCESSING ANOMALY, F) THERMAL STRESS

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

CRITICALITY 1R2 DURING INTACT ABORT ONLY (AVIONICS ONLY)? NO

REDUNDANCY SCREEN A) PASS  
B) N/A  
C) PASS

PASS/FAIL RATIONALE:

A)

B)

N/A - AT LEAST TWO REMAINING PATHS ARE DETECTABLE IN FLIGHT.

C)

METHOD OF FAULT DETECTION:  
NONE

MASTER MEAS. LIST NUMBERS: NONE

CORRECTING ACTION:

FOR CASE 1, THE CREW CAN DISABLE ONE OF THE THREE APDS LOGIC BUSES TO  
PREVENT IMPLEMENTATION OF AN UNWANTED COMMAND.

FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL FAILURE MODE  
 NUMBER: M5-6SS-B010-02

- FAILURE EFFECTS -

## (A) SUBSYSTEM:

LOSS OF SWITCH CONTROL CAPABILITY FOR THE APDS "UNDOCKING" CIRCUITS.

## (B) INTERFACING SUBSYSTEM(S):

UNWANTED "UNDOCKING" COMMAND TO THE DSCU.

## (C) MISSION:

FIRST FAILURE - NO EFFECT.

## (D) CREW, VEHICLE, AND ELEMENT(S):

NO EFFECT.

## (E) FUNCTIONAL CRITICALITY EFFECTS:

## CASE 1: (2R3 - PPP)

SHUTTLE OR PMA1 MECHANISM CONTROL: POSSIBLE LOSS OF MISSION AFTER THREE FAILURES.

1) ONE OF TWO ASSOCIATED SWITCHES FAILS CLOSED. ENABLES TWO OF THREE PANEL COMMAND SIGNALS. TEMPORARY UNWANTED "UNDOCKING" COMMAND TO THE DSCU. CREW WOULD PERFORM AN APDS LOGIC BUS DROP TO RECOVER DOCKING FUNCTIONS. 2) REMAINING ASSOCIATED SWITCH FAILS CLOSED RESULTING IN UNWANTED "UNDOCKING" COMMAND TO THE DSCU. 3) ONE OF TWO "APDS CIRC PROT OFF" SWITCHES FAILS CLOSED. UNWANTED "UNDOCKING" COMMAND TO THE APDA RESULTING IN POSSIBLE PREMATURE UNDOCKING PRIOR TO CREW INGRESS.

## CASE 2: (1R3 - PNP)

WORST CASE, SHUTTLE MECHANISM CONTROL: POSSIBLE LOSS OF CREW OR VEHICLE AFTER EIGHT FAILURES.

1) ONE OF TWO ASSOCIATED "UNDOCKING" SWITCHES FAILS CLOSED. 2) ONE OF TWO ASSOCIATED "POWER ON" SWITCHES FAILS CLOSED. 3) ONE OF TWO ASSOCIATED "APDS CIRC PROT OFF" SWITCHES FAILS CLOSED. 4, 5) TWO APDS POWER (A7&A3) CIRCUIT BREAKERS FAIL CLOSED. 6, 7) TWO APDS CONTROL PANEL POWER (A8A3) CIRCUIT BREAKERS FAIL CLOSED. 8) ONE PSU MAIN POWER RPC FAILS ON RESULTING IN ALL HOOKS OPENING INADVERTENTLY. POSSIBLE LOSS OF HABITABLE ENVIRONMENT.

DESIGN CRITICALITY (PRIOR TO OPERATIONAL DOWNGRADE, DESCRIBED IN F):

## (F) RATIONALE FOR CRITICALITY CATEGORY DOWNGRADE:

N/A

- TIME FRAME -

TIME FROM FAILURE TO CRITICAL EFFECT: DAYS

TIME FROM FAILURE OCCURRENCE TO DETECTION: HOURS

TIME FROM DETECTION TO COMPLETED CORRECTIVE ACTION: MINUTES

PAGE: 7

PRINT DATE: 06.12.96

FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL FAILURE MODE  
NUMBER: M5-6SS-B010-02

TIME REQUIRED TO IMPLEMENT CORRECTIVE ACTION LESS THAN TIME TO EFFECT?  
YES

RATIONALE FOR TIME TO CORRECTING ACTION VS TIME TO EFFECT:  
FOR CASE 1: CREW WOULD HAVE SUFFICIENT TIME TO DISABLE THE LOGIC BUSES.

HAZARDS REPORT NUMBER(S): ORBI 511


HAZARD DESCRIPTION:  
LOSS OF PRESSURE IN HABITABLE VOLUME.

---

• APPROVALS •

---

PRODUCT ASSURANCE ENGR : M. NIKOLAYEVA  
DESIGN ENGINEER : B. VAKULIN

  
\_\_\_\_\_