PAGE: 1 PRINT DATE: 06/17/97

FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL HARDWARE

NUMBER: M5-6SS-8020-X

SUBSYSTEM NAME: E - DOCKING SYSTEM

REVISION:

Ð

DEC, 1996

PART NAME VENDOR NAME

PART NUMBER VENDOR NUMBER

LRU

: ENERGIA POWER PANEL

MC821-0087-0009

RSC-E

SLIYU.468312.001

SRU

: CIRCUIT BREAKER

Az2-2 (\$\in\$3.619.242 TU)

PART DATA

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:

PNL ASA3, CIRCUIT BREAKER (4.2 AMPS TRIPPING CURRENT,) APDS (+Ap, +Bp, +Cp) PFCU LOGIC BUS CONTROL.

REFERENCE DESIGNATORS: 35V73A8A3F2

36V73A8A3F6 36V73A8A3F10

QUANTITY OF LIKE ITEMS: 3

(THREE)

FUNCTION:

PROVIDE PROTECTION, CONTROL, AND DISTRIBUTION FOR THE APDS PYROTECHNIC SEPARATION LOGIC BUSES (+Ap. +Bp. +Cp). THESE BUSES ARE PROVIDED TO THE PYROTECHNIC EIRING CONTROL UNIT (PFCU). WITHIN THE PFCU, THE BUSES ARE DISTRIBUTED TO CONFIGURE THE PYROTECHNIC SEPARATION ELEMENTS (ACTIVE AND PASSIVE HOOKS). IN ADDITION, THE BUSES ARE ENERGIZED WHEN PYROTECHNIC CIRCUIT CHECKOUT IS REQUIRED.

PRINT DATE: 06/17/97

PAGE: 2

FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL FAILURE MODE NUMBER: MS-655-8020-01

REVISION# D

DEC, 1996

SUBSYSTEM NAME: E - DOCKING SYSTEM

LRU: MC621-0087-0009

CRITICALITY OF THIS

ITEM NAME: CIRCUIT BREAKER

FAILURE MODE: 1R3

FAILURE MODE:

FAILS OPEN, FAILS TO CONDUCT, INADVERTENTLY OPENS, FAILS TO TRANSFER

MISSION PHASE:

00

ON-ORBIT

VEHICLE/PAYLOAD/KIT EFFECTIVITY: 103 DISCOVERY

104 ATLANTIS

105 ENDEAVOUR

CAUSE:

 A) PIECE PART FAILURE, B) CONTAMINATION, C) VIBRATION, D) MECHANICAL SHOCK, E) PROCESSING ANOMALY, F) THERMAL STRESS

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

CRITICALITY 1R2 DURING INTACT ABORT ONLY (AVIONICS ONLY)? NO

REDUNDANCY SCREEN

A) PASS

B) N/A

C) PASS

PASS/FAIL RATIONALE: -

A}

B١

PYROTECHNIC SEPARATION SYSTEM IS CONSIDERED STAND-BY.

C)

METHOD OF FAULT DETECTION:

DISPLAYS AND TELEMETRY DATA. "PYROTECHNIC BUS STATUS (+Ad, +Bp, +Cp) " AND "PYRO CIRCUIT PROTECTION OFF" INDICATIONS IN THE D&C PANEL.

MASTER MEAS, LIST NUMBERS:

V53X0796E

V53X0797E

V53X0798E

CORRECTING ACTION:

CREW WOULD PERFORM EVA TO REMOVE 96 BOLTS FROM THE DOCKING BASE TO SEPARATE THE ORBITER FROM ISS.

FAILURE MODES EFFECTS ANALYSIS (FMEA) — NON-CIL FAILURE MODE NUMBER: M5-688-8020-01

- FAILURE EFFECTS -

(A) SUBSYSTEM:

DISABLES PROTECTION, CONTROL AND DISTRIBUTION FOR ONE OF THREE APDS PYROTECHNIC BUSES (+Ap, +Bp, +Cp)

(B) INTERFACING SUBSYSTEM(S):

DEGRADED PYROTECHNIC BUS REDUNDANCY.

(C) MISSION:

NO EFFECT.

(D) CREW, VEHICLE, AND ELEMENT(S):

FIRST FAILURE - NO EFFECT.

(E) FUNCTIONAL CRITICALITY EFFECTS:

SHUTTLE MECHANISM CONTROL: POSSIBLE LOSS OF CREW OR VEHICLE AFTER THREE FAILURES.

1) ONE OF THREE CIRCUIT BREAKERS FAILS OPEN. DEGRADED PYROTECHNIC BUS REDUNDANCY. 2) ONE OF TWO REMAINING ASSOCIATED CIRCUIT BREAKERS FAILS OPEN. DISABLES TWO OF THREE PYROTECHNIC BUSES. LOSS OF CAPABILITY TO IMPLEMENT PYROTECHNIC SEPARATION. 3) ONE OF TWELVE HOOKS FAILS TO OPEN (REF. M8-1SS-BM001-D4.). LOSS OF CAPABILITY TO IMPLEMENT NOMINAL SEPARATION.

DESIGN CRITICALITY (PRIOR TO OPERATIONAL DOWNGRADE, DESCRIBED IN F):

(F) RATIONALE FOR CRITICALITY CATEGORY DOWNGRADE:

ALTHOUGH THE CRITICALITY REMAINS UNCHANGED AFTER WORKARDUNDS CONSIDERATION (ALLOWED PER CR \$050107W), THEY ARE PROVIDING ADDITIONAL FAULT TOLERANCE TO THE SYSTEM.

AFTER THE THIRD FAILURE, THE CREW WOULD PERFORM EVA TO REMOVE 96 BOLTS TO CIRCUMVENT THE WORST CASE "DESIGN CRITICALITY" EFFECT. IF UNABLE TO PERFORM EVA (FOURTH FAILURE), POSSIBLE LOSS OF CREWVEHICLE DUE TO LOSS OF ALL UNDOCKING CAPABILITY.

- TIME FRAME -

TIME FROM FAILURE TO CRITICAL EFFECT: DAYS

TIME FROM FAILURE OCCURRENCE TO DETECTION: HOURS

TIME FROM DETECTION TO COMPLETED CORRECTIVE ACTION: HOURS

TIME REQUIRED TO IMPLEMENT CORRECTIVE ACTION LESS THAN TIME TO EFFECT? YES

PAGE: 4

PRINT DATE: 11,12,96

FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL FAILURE MODE NUMBER: MS-655-8020-01

"RATIONALE FOR TIME TO CORRECTING ACTION VS TIME TO EFFECT: CREW WOULD HAVE SUFFICIENT TIME TO PERFORM EVA.

HAZARDS REPORT NUMBER(S): ORBI 401A

HAZARD DESCRIPTION:

INABILITY TO SEPARATE ORBITER AND ISS.-

· APPROVALS -

PRODUCT ASSURANCE ENGR : M. NIKOLAYEVA

DESIGN ENGINEER

: B. VAKUUN