PAGE: 1 PRINT DATE: 01/07/98

FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL HARDWARE NUMBER: M8-1\$\$-E035 -X

SUBSYSTEM NAME: ECLSS - ARPCS

REVISION: 1 10/22/97

PART DATA

PART NAME VENDOR NAME PART NUMBER **VENDOR NUMBER**

LRU

:VALVE, PURGE ISO

CARLETON TECHNOLOGIES

MC250-0004-0011 2765-0001-5

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:

CREW CABIN PURGE ISO VALVE

QUANTITY OF LIKE ITEMS: 1

ONE

FUNCTION:

PROVIDES CAPABILITY FOR VENTING CREW CABIN PRESSURE OVERBOARD VIA A VACUUM VENT LINE. THE VALVE IS A BUTTERFLY VALVE THAT HAS TWO FLOW POSITIONS FIXED BY DETENTS IN THE ACTUATION MECHANISM. THIS VALVE IS MANUALLY OPERATED WITHIN THE CREW CABIN.

REFERENCE DOCUMENTS:

VS28-643001

V828-643222

M072-643401

PAGE 5 PRINT DATE: 01/07/98

FAILURE MODES EFFECTS ANALYBIS FMEA - NON-CIL FAILURE MODE

NUMBER: M8-1SS-E035-02

REVISION#: 0

SUBSYSTEM NAME: ECLSS - ARPCS

LRU: VALVE, CREW CABIN PURGE ISO ITEM NAME: VALVE, CREW CABIN PURGE ISO

CRITICALITY OF THIS FAILURE MODE: 1R3

04/08/97

FAILURE MODE:

FAILS TO CLOSE, INTERNAL LEAKAGE

MISSION PHASE:

OO ON-ORBIT

VEHICLE/PAYLOAD/KIT EFFECTIVITY:

109 DISCOVERY 104 ATLANTIS

105 ENDEAVOUR

CAUSE:

CORROSION, CONTAMINATION, PHYSICAL BINDING/JAMMING, EXCESSIVE VIBRATION. MECHANICAL SHOCK, MATERIAL DEFECT, FATIGUE, POROSITY

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

REDUNDANCY SCREEN

A) PASS

B) N/A

C) PASS

PASS/FAIL RATIONALE:

A)

N/A - ALL REDUNDANCY IS IN STANDBY UNTIL REQUIRED.

C)

METHOD OF FAULT DETECTION:

PHYSICAL OBSERVATION - VALVE DOES NOT CLOSE WHEN MANUALLY OPERATED. INSTRUMENTATION - LOSS OF PRESSURE WITHIN CREW CABIN WHEN BOTH CREW CABIN PURGE VALVE AND ECLSS BAY VACUUM VENT ISO VALVE ARE OPEN.

CORRECTING ACTION: MANUAL

CORRECTING ACTION DESCRIPTION:

CREW COULD UTILIZE CREW CABIN PURGE VALVE OR ECLSS BAY VACUUM VENT ISO VALVE TO CONTROL CREW CABIN PRESSURE VENTING. EXTERNAL LEAKAGE OF

PAGE: 6 PRINT DATE: 01/07/98

FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL FAILURE MODE NUMBER: M8-15S-E035-02

PRESSURE FOLLOWING THIRD FAILURE CAN BE ISOLATED FROM CREW CABIN BY PERFORMING AN IN-FLIGHT MAINTENANCE TO SEAL LEAK USING DUCT TAPE OR ANY OTHER AVAILABLE MATERIAL.

REMARKS/RECOMMENDATIONS:

CREW CABIN PURGE VALVE, CREW CABIN PRESSURE BLEED VALVE, AND ECLSS BAY VACUUM VENT ISO VALVE ARE ALL IN SERIES. ALL THREE MUST BE OPENED BEFORE THERE CAN BE A LOSS OF CREW CABIN PRESSURE TO THE OUTSIDE.

- FAILURE EFFECTS -

(A) SUBSYSTEM:

LOSS OF ISOLATION BETWEEN CREW CABIN PURGE VALVE AND ECLSS BAY VACUUM VENT ISO VALVE.

(B) INTERFACING SUBSYSTEM(S):

NO EFFECT FIRST FAILURE. A FAILED OPEN CONDITION ON BOTH THE CREW CABIN PURGE VALVE AND ECLSS BAY VACUUM VENT ISO VALVE WILL RESULT IN EXCESS LOSS OF CONSUMABLES WITHIN CREW CABIN.

(C) MISSION:

NO EFFECT FIRST FAILURE. LOSS OF MISSION IF SECOND SERIES VALVE (CREW CABIN PURGE VALVE) AND THIRD SERIES VALVE (ECLSS BAY VACUUM VENT ISO VALVE) INTERNALLY LEAK OR FAIL TO CLOSE.

(D) CREW, YEHICLE, AND ELEMENT(S):

NO EFFECT FIRST FAILURE. LOSS OF CREW/VEHICLE IF A FAILED OPEN CONDITION ON BOTH THE CREW CABIN PURGE VALVE AND ECLSS BAY VACUUM VENT ISO VALVE OCCURS AND CREW CABIN PRESSURE CANNOT BE MAINTAINED.

(E) FUNCTIONAL CRITICALITY EFFECTS:

FIRST FAILURE (CREW CABIN PURGE ISO VALVE INTERNALLY LEAKS OR FAILS TO CLOSE) - NO EFFECT.

SECOND FAILURE (CREW CABIN PURGE VALVE INTERNALLY LEAKS OR FAILS TO CLOSE) - NO EFFECT; LOSS OF SERIES REDUNDANCY.

THIRD FAILURE (ECLSS BAY VACUUM VENT ISO VALVE INTERNALLY LEAKS OR FAILS TO CLOSE) - LOSS OF PRESSURE WITHIN CREW CABIN. SAFETY OF CREW AND VEHICLE JEOPARDIZED UPON LOSS OF CONSUMABLES. - CRITICALITY 1R3 CONDITION. POSSIBLE LOSS OF PRESSURE IN SPACE STATION IF THIRD FAILURE OCCURS WHILE 576 BULKHEAD HATCH AND EXTERNAL AIRLOCK UPPER HATCH ARE OPEN.

DESIGN CRITICALITY (PRIOR TO DOWNGRADE, DESCRIBED IN (F)): 183

PAGE: 7 PRINT DATE: 01/07/98

FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL FAILURE MODE NUMBER: M8-19S-E035-02

(F) RATIONALE FOR CRITICALITY DOWNGRADE:
PERFORMING A WORKAROUND TO SEAL EXTERNAL LEAKAGE OF PRESSURE WHEN
ALL THREE SERIES VALVES FAIL IN THE OPEN POSITION DOES NOT IMPACT THE 1R3
CRITICALITY OF THIS FAILURE MODE.

- TIME FRAME -

TIME FROM FAILURE TO CRITICAL EFFECT: DAYS

TIME FROM FAILURE OCCURRENCE TO DETECTION: MINUTES

TIME FROM DETECTION TO COMPLETED CORRECTING ACTION: SECONDS

IS TIME REQUIRED TO IMPLEMENT CORRECTING ACTION LESS THAN TIME TO EFFECT? YES

RATIONALE FOR TIME TO CORRECTING ACTION VS TIME TO EFFECT:
CREW HAS ENOUGH TIME TO UTILIZE CREW CABIN PURGE VALVE OR ECLSS BAY
VACUUM VENT ISO VALVE TO CONTROL DEPRESSURIZATION OR SEAL LEAK TO
PREVENT EXTERNAL LEAKAGE OF CREW CABIN PRESSURE BEFORE PROBLEM
BECOMES CATASTROPHIC.

HAZARD REPORT NUMBER(\$): ORBI 611

HAZARD(S) DESCRIPTION:

LOSS OF HABITABLE PRESSURE IN CREW CABIN HABITABLE VOLUME

- APPROVALS -

SS & PAE

DESIGN ENGINEER

M. W. GUENTHER

K. J. KELLY