

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL HARDWARE

NUMBER: 03-1-0304 -X

SUBSYSTEM NAME: MAIN PROPULSION

REVISION: 2 11/07/00

PART DATA

	PART NAME	PART NUMBER
	VENDOR NAME	VENDOR NUMBER
LRU	: LH2 TOPPING VALVE, 2.0 INCH, NC, TYPE 1 VACCO INDUSTRIES	MC284-0395-0051 1397-513

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:

LH2 TOPPING VALVE, 2 INCH, NORMALLY CLOSED, PNEUMATICALLY ACTUATED OPEN.

VALVE WAS ORIGINALLY DESIGNED AND MANUFACTURED BY VACCO INDUSTRIES (EATON). THE UNITED SPACE ALLIANCE-NSLD IS A CERTIFIED REPAIR DEPOT BUT HAS NOT YET BEEN CERTIFIED AS AN ALTERNATE PRODUCTION AGENCY.

REFERENCE DESIGNATORS: PV13

QUANTITY OF LIKE ITEMS: 1

FUNCTION:

PROVIDES CONTROL OF REPLENISH/TOPPING OF LH2 DURING COMPLETION OF PROPELLANT LOADING. OPENED AT THE START OF LH2 SLOW FILL. CLOSED FOR LH2 TANK PREPRESSURIZATION AND DRAINBACK OF LH2 FILL LINE. REMAINS CLOSED DURING ENGINE OPERATION. OPENED DURING DUMP/INERTING OPERATIONS.

FAILURE MODES EFFECTS ANALYSIS FMEA -- CIL FAILURE MODE**NUMBER: 03-1-0304-08****REVISION#:** 2 11/07/00**SUBSYSTEM NAME:** MAIN PROPULSION**LRU:** LH2 TOPPING VALVE, PV13**ITEM NAME:** LH2 TOPPING VALVE, PV13**CRITICALITY OF THIS****FAILURE MODE:** 1R3**FAILURE MODE:**

RUPTURE/LEAKAGE OF THE VALVE ACTUATOR DURING ASCENT

MISSION PHASE: PL PRE-LAUNCH
LO LIFT-OFF

VEHICLE/PAYLOAD/KIT EFFECTIVITY:

102	COLUMBIA
103	DISCOVERY
104	ATLANTIS
105	ENDEAVOUR

CAUSE:

FATIGUE, MATERIAL DEFECT, DAMAGED/DEFECTIVE ACTUATOR SEALS

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

REDUNDANCY SCREEN

- A) PASS
- B) FAIL
- C) PASS

PASS/FAIL RATIONALE:

A)

B)

FAILS B SCREEN BECAUSE ACTUATOR FAILURE CANNOT BE DETECTED DURING FLIGHT;
THE ACTUATOR IS UNPRESSURIZED DURING ASCENT.

C)

- FAILURE EFFECTS -**(A) SUBSYSTEM:**

LOSS OF CAPABILITY TO OPEN OR MAINTAIN OPEN LH2 TOPPING VALVE (PV13) FOR TOPPING, DUMP AND INERTING OPERATIONS (REFERENCE FMEA/CIL 03-1-0304-01). ACTUATOR IS LOCATED ON HELIUM PNEUMATIC LEG UPSTREAM OF CHECK VALVE CV9 (NON-ACCUMULATOR LEG). LEAKAGE MAY BE DETECTABLE ON GROUND USING HAZARDOUS GAS DETECTION SYSTEM (HGDS).

**FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL FAILURE MODE
NUMBER: 03-1-0304-08**

(B) INTERFACING SUBSYSTEM(S):

SAME AS A.

(C) MISSION:

FOR FAILURE OCCURRENCE ON GROUND, LAUNCH SCRUB.

(D) CREW, VEHICLE, AND ELEMENT(S):

SAME AS C.

(E) FUNCTIONAL CRITICALITY EFFECTS:

1R/3 3 SUCCESS PATHS. TIME FRAME - ASCENT.

- 1) LH2 TOPPING VALVE (PV13) ACTUATOR RUPTURES.
- 2) PREMATURE ACTUATION OF TOPPING VALVE OPENING SOLENOID (LV39).
- 3) CHECK VALVE (CV9) FAILS TO REMAIN CLOSED.

CAUSES LOSS OF PNEUMATIC ACTUATION PRESSURE RESULTING IN THE INABILITY TO CLOSE LO2 PREVALVES AT MECO. THIS RESULTS IN FAILURE TO MAINTAIN INJECTED GHE AND LO2 PRESSURE AT THE SSME PUMP, RESULTING IN POSSIBLE PUMP OVERSPEED AND EXPLOSION. POSSIBLE AFT COMPARTMENT OVERPRESSURIZATION AND FIRE/EXPLOSION HAZARD. ENGINE PURGE HELIUM RESIDUALS ARE TRANSFERRED TO VALVE ACTUATION SUPPLY AT MECO BY SOFTWARE COMMAND, WHICH MAY NOT ACTUATE LO2 PREVALVES CLOSED. POSSIBLE LOSS OF CREW/VEHICLE.

-DISPOSITION RATIONALE-

(A) DESIGN:

FACTORS OF SAFETY: PROOF - 2.0; BURST - 4.0. DURING CERTIFICATION TESTING, ACTUATOR WAS BURST TESTED TO 3400 PSIG. ACTUATOR OPERATING PRESSURE IS 850 PSIG. BOTH THE ACTUATOR BODY AND END CAP ARE MANUFACTURED FROM ALUMINUM ALLOY. STRUCTURAL ANALYSIS INDICATES POSITIVE MARGINS OF SAFETY FOR ALL CONDITIONS OF VALVE OPERATION; FRACTURE /FATIGUE ANALYSES SHOW THAT ALL CRITICAL PARTS ARE SATISFACTORY FOR FOUR TIMES EXPECTED LIFE.

EXTERNAL LEAKAGE FROM THE ACTUATOR END CAP IS PREVENTED BY THE USE OF A CREEVEY-TYPE SEAL (TEFLON COVER OVER A SANDVIK SPRING) AND A KEL-F STATIC SEAL. EXTERNAL LEAKAGE FROM THE ACTUATOR PISTON IS PREVENTED BY USE OF A KEL-F LIP SEAL.

(B) TEST:

ATP

EXAMINATION OF PRODUCT

**FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL FAILURE MODE
NUMBER: 03-1-0304-08**

AMBIENT PROOF:

VALVE BODY - 195 PSIG, VALVE OPEN AND CLOSED

ACTUATOR - 1700 PSIG

VALVE RESPONSE TIMES - AMBIENT AND CRYO (-300 DEG F AND -423 DEG F):

VALVE: 55 PSIG

ACTUATOR: 500 AND 740 PSIG

EXTERNAL LEAKAGE - AMBIENT AND CRYO (-300 DEG F AND -423 DEG F):

VALVE BODY: 130 PSIG

ACTUATOR: 740 PSIG

INTERNAL LEAKAGE - AMBIENT AND CRYO (-300 DEG F AND -423 DEG F):

INLET-TO-OUTLET @ 55 PSIG

OUTLET-TO-INLET @ 40 PSIG

ACTUATOR: 740 PSIG

POSITION INDICATION: VERIFICATION OF OPERATION

ELECTRICAL CHARACTERISTICS - CONTACT RESISTANCE; INSULATION RESISTANCE; AND DIELECTRIC STRENGTH.

CERTIFICATION

LIFE -

CRYO - 500 CYCLES AT -400 DEG F

AMBIENT - 1500 CYCLES

RANDOM VIBRATION TESTS - IN ALL THREE AXES

13.3 HOURS IN EACH AXIS WHILE PRESSURIZED TO 35 PSIG AND AT -300 DEG F.

DESIGN SHOCK (ALL THREE AXES) - 18 SHOCKS OF 15G EACH, THREE IN EACH DIRECTION.

THERMAL CYCLE TESTS - PERFORMED THREE TIMES

70 DEG F TO -400 DEG F TO 70 DEG F TO 275 DEG F TO 150 DEG F

VALVE RESPONSE TIMES - AMBIENT AND CRYO (-300 DEG F AND -423 DEG F):

VALVE: 55 PSIG

ACTUATOR: 500 AND 740 PSIG

EXTERNAL LEAKAGE - AMBIENT AND CRYO (-300 DEG F AND -423 DEG F):

VALVE BODY: 130 PSIG

ACTUATOR: 740 PSIG

INTERNAL LEAKAGE - AMBIENT AND CRYO (-300 DEG F AND -423 DEG F):

INLET-TO-OUTLET @ 55 PSIG

OUTLET-TO-INLET @ 40 PSIG

ACTUATOR: 740 PSIG

**FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL FAILURE MODE
NUMBER: 03-1-0304-08**

ELECTRICAL CHARACTERISTICS - CONTACT RESISTANCE; INSULATION RESISTANCE; AND DIELECTRIC STRENGTH.

ELECTRICAL BONDING - LESS THAN 100 MILLIOHMS

BURST - 260 PSIG VALVE BODY, 3400 PSIG ACTUATOR

GROUND TURNAROUND TEST

ANY TURNAROUND CHECKOUT IS ACCOMPLISHED IN ACCORDANCE WITH OMRSD.

(C) INSPECTION:

RECEIVING INSPECTION

RAW MATERIAL VERIFIED BY INSPECTION FOR MATERIAL AND PROCESS CERTIFICATION. TEST REPORTS REQUIRED ON CAST MATERIAL. COMPLETION OF HOT ISOSTATIC PRESSING (HIP) PROCESS IS VERIFIED. CAST HOUSING (ROUGH MACHINED) IS INSPECTED FOR POROSITY.

CONTAMINATION CONTROL

CONTAMINATION CONTROL PROCESS AND CORROSION PROTECTION PROVISIONS ARE VERIFIED. THE INTERNAL WETTED SURFACES ARE CLEANED TO LEVEL 400A AND VERIFIED BY INSPECTION.

ASSEMBLY/INSTALLATION

ALL DETAIL PARTS ARE INSPECTED FOR CRITICAL DIMENSIONS, SURFACE FINISH, BURRS, DAMAGE, AND CORROSION. CRITICAL POPPET AND SLEEVE SURFACES ARE LAPPED AND INSPECTED WITH 40X MAGNIFICATION. TORQUES ARE VERIFIED TO BE IN ACCORDANCE WITH DRAWING REQUIREMENTS. PRIOR TO INSTALLATION, SEALS ARE VISUALLY EXAMINED WITH 10X MAGNIFICATION FOR DAMAGE AND CLEANLINESS. ALL SPRINGS ARE LOT TRACEABLE AND LOAD TESTED AT THE PIECE PART LEVEL. MANDATORY INSPECTION POINTS ARE INCLUDED IN THE ASSEMBLY PROCEDURE.

CRITICAL PROCESSES

HEAT TREATMENT OF THE VALVE BALL AFTER MACHINING IS VERIFIED. PART PASSIVATION AND HARD ANODIZING ARE VERIFIED. CERTIFICATION OF WELDING, POTTING, AND SOLDERING IS VERIFIED. PAINTING (ON BODY), ELECTRICAL BONDING, AND DRY FILM LUBRICANT ARE VERIFIED BY INSPECTION. ALL CASTINGS ARE SUBJECTED TO A HIP PROCESS.

NONDESTRUCTIVE EVALUATION

PRIOR TO FINAL MACHINING, THE HOUSING IS X-RAYED, ETCH AND DYE PENETRANT INSPECTED, AND LEAK CHECKED AT PROOF PRESSURE. ALL WELDS ON THE ELECTRICAL CONNECTOR ARE DYE PENETRANT INSPECTED AND VERIFIED BY INSPECTION.

TESTING

ATP VERIFIED BY INSPECTION.

PACKAGING/HANDLING

HANDLING, PACKAGING, STORAGE, AND SHIPPING REQUIREMENTS ARE VERIFIED BY INSPECTION.

**FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL FAILURE MODE
NUMBER: 03-1-0304-08**

(D) FAILURE HISTORY:

ATP

DURING ATP PROOF PRESSURE TEST, EXCESSIVE LEAKAGE PAST THE ACTUATOR SEAL WAS NOTED (REF CAR A9705). TEARDOWN REVEALED A SCRATCH ON THE PISTON SEAL. THE SEAL WAS REPLACED AND ACTUATOR MET LEAKAGE REQUIREMENTS. CORRECTIVE ACTION WAS TO INCORPORATE A MANDATORY INSPECTION POINT OF THE SEALS PRIOR TO INSTALLATION.

QUALIFICATION

DURING QUALIFICATION TEST, ACTUATOR LEAKAGE WAS OBSERVED (REF CAR A9894). X-RAY OF THE ACTUATOR REVEALED A BROKEN RACK/PISTON SPRING. UPON TEARDOWN, A BROKEN STATIC SEAL WAS ALSO FOUND. FAILURE ANALYSIS OF THE SPRING DETERMINED THAT THE SPRING FAILED FROM IMPACT EMBRITTLEMENT. THE ACTUATOR SPRING MATERIAL WAS CHANGED FROM TITANIUM TO ELGILOY AND REDUNDANT ACTUATOR STATIC SEALS WERE ADDED. THE QUAL UNIT WAS REWORKED AND SUCCESSFULLY RETESTED.

DURING QUALIFICATION TEST AT CRYO TEMPERATURE, THE ACTUATOR SHAFT SEAL LEAKAGE WAS 400 SCIM, MAX ALLOWABLE IS 100 SCIM (REF CAR AC6963). THE CAUSE ATTRIBUTED TO NORMAL INTERNAL WEAR IN COMBINATION WITH MIGRATING LUBRICANT. THE SPECIFICATION FOR MAXIMUM ACTUATOR SHAFT SEAL LEAKAGE WAS REVISED TO 500 SCIM (TYPE II VALVES ONLY), TO BE MEASURED AFTER EXPOSURE TO QUALIFICATION VIBRATION TEST.

DURING CRYOGENIC QUAL TESTING, ACTUATOR PISTON SEAL LEAKAGE OF 130 SCIM WAS NOTED. MAX ALLOWABLE IS 100 SCIM (REFERENCE CAR AB1806). THE LEAKAGE WAS DUE TO METALLIC PARTICLE GENERATION DURING ASSEMBLY FROM IMPROPERLY CLEANED PARTS CAUSING GALLING DURING ASSEMBLY. SUPPLIER ACTUATOR ASSEMBLY PROCEDURE PS-352M WAS CHANGED TO ADD CAUTION AND INSPECTION NOTE.

DURING QUALIFICATION TESTING, ACTUATOR PISTON SEAL LEAKAGE OF 200 SCIM WAS DETECTED. MAX ALLOWABLE IS 100 SCIM. LEAKAGE WAS DUE TO METALLIC PARTICLES GENERATED DURING ASSEMBLY WITH AN INADEQUATE ASSEMBLY TOOL. REDESIGNED TOOL ELIMINATED THE PROBLEM (REFERENCE CAR AB0197).

DURING QUALIFICATION TESTING, LEAKAGE AT THE ACTUATOR PISTON SEAL RETAINER INTERFACE WAS 560 SCIM. MAX ALLOWABLE IS 100 SCIM (REFERENCE ARE AB0088). LEAKAGE WAS DUE TO INSUFFICIENT SEAL RETAINER TORQUE OF 70 FT-LBS. ASSEMBLY TORQUE WAS INCREASED TO 95 - 100 FT-LBS WITH REPEAT APPLICATIONS AT 5 MINUTE INTERVALS UNTIL SUB-ASSEMBLY STOPS MOVING. IMPLEMENTED OV-102 AND SUBS.

FIELD

DURING MPTA CHECKOUT, HELIUM WAS LEAKING THROUGH THE VENT PORT OF THE ACTUATOR CAUSING THE VALVE TO FAIL TO REMAIN OPEN (REF CAR A9630). DURING DISASSEMBLY, IT WAS FOUND THAT THE STATIC SEAL WAS PROTRUDING OUTSIDE ITS RETAINER AREA AND THAT THE SEAL RETAINER TORQUE WAS LOW. IT WAS CONCLUDED THAT THE ACTUATOR STATIC SEAL RETAINER TORQUE RELAXES EITHER FROM SEAL

**FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL FAILURE MODE
NUMBER: 03-1-0304-08**

MATERIAL COLD FLOW OR RETAINER BACKING OFF. THE VALVE WAS REDESIGNED TO ADD REDUNDANT ACTUATOR SEALS AND LOCKTITE IS APPLIED TO THE RETAINER TO PREVENT TORQUE RELAXATION AND A SERIES OF RETORQUING TO MINIMIZE COLD FLOW. THE VALVE WAS REWORKED AND PASSED SUBSEQUENT LEAKAGE TESTS.

AT PALMDALE ACTUATOR LEAKAGE OCCURRED FROM UNDER THE ENDCAP OF THE ACTUATOR (REFERENCE CAR AD2446). THE ORIGIN OF THE LEAK WAS DUE TO TWO DAMAGED GASKETS P/N 1397-60 AND A SEAL P/N 1397-29-2. THE FAILURE WAS DUE TO A FAILURE TO BACK UP THE END CAP ON THE ACTUATOR WHILE TURNING A LINE FITTING DURING THE INSTALLATION OF THE VALVE. GASKETS AND SEAL REPLACED. NO FURTHER ACTION REQUIRED.

DURING CHECKOUT AT PALMDALE ON OV-099, THE ACTUATOR END CAP LEAKED EXCESSIVELY (REFERENCE CAR AC2152). NEW SEALS AND END CAP WERE INSTALLED ON THE VEHICLE BY THE SUPPLIER AND PASSED SUBSEQUENT LEAK TEST. CAUSE FOR LEAKAGE WAS NOT DETERMINED.

CURRENT DATA ON TEST FAILURE, FLIGHT FAILURE, UNEXPLAINED ANOMALIES, AND OTHER FAILURES EXPERIENCED DURING GROUND PROCESSING ACTIVITY CAN BE FOUND IN THE PRACA DATABASE.

(E) OPERATIONAL USE:

HELIUM BOTTLE PRESSURE IS ON DISPLAY IN COCKPIT. CREW ACTION CAN CLOSE PNEUMATIC ISOLATION VALVES (LV7,8) DURING ASCENT. PRIOR TO MECO, THE ISOLATION VALVES CAN BE REOPENED OR THE LEFT ENGINE LOW PRESSURE GHE CROSSOVER VALVE (LV10) CAN BE OPENED.

- APPROVALS -

S&R ENGINEERING	: W.P. MUSTY	: /S/ W. P. MUSTY
S&R ENGINEERING ITM	: P. A. STENGER-NGUYEN	: /S/ P. A. STENGER-NGUYEN
DESIGN ENGINEERING	: EARL HIRAKAWA	: /S/ EARL HIRAKAWA
MPS SUBSYSTEM MGR.	: TIM REITH	: /S/ TIM REITH
MOD	: BILL LANE	: /S/ BILL LANE
USA SAM	: MIKE SNYDER	: /S/ MIKE SNYDER
USA ORBITER ELEMENT	: SUZANNE LITTLE	: /S/ SUZANNE LITTLE
NASA SR&QA	: ERICH BASS	: /S/ ERICH BASS