

FAILURE MODES EFFECTS ANALYSIS (FMEA) - CIL HARDWARE  
 NUMBER: 04-1A-0101 -X

SUBSYSTEM NAME: ELECTRICAL POWER GENERATION: FUEL CELL  
 REVISION: 3 03/27/96

---

PART DATA

---

	PART NAME	PART NUMBER
	VENDOR NAME	VENDOR NUMBER
LRU	: FUEL CELL POWERPLANT IFC	MC464-0115-3020 807100
LRU	: FUEL CELL POWERPLANT IFC	MC464-0115-3021 808100
LRU	: FUEL CELL POWERPLANT IFC	MC464-0115-3030 814100
LRU	: FUEL CELL POWERPLANT. IFC	MC464-0115-3031 815100

---

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:  
 FCP NO. 1, 2, 3

REFERENCE DESIGNATORS: 40V45A100  
 40V45A200  
 40V45A300

QUANTITY OF LIKE ITEMS:  
 TWO-RH  
 ONE-LH

FUNCTION:  
 THREE POWER SOURCES FOR MAIN ELECTRICAL POWER.

PRINT DATE: 02/16/89

SHUTTLE CRITICAL ITEMS LIST - ORBITER

NUMBER: 04-1A-0101-09

S50230Y

ATTACHMENT -

REVISION: 0 02/16/89 W Page 26 of 120

SUBSYSTEM: ELECTRICAL POWER GENERATION: FUEL CELL

LOW FUEL CELL POWERPLANT

ITEM NAME: FUEL CELL POWERPLANT

CRITICALITY OF THIS

FAILURE MODE: 1/1

**FAILURE MODE:**

INTERNAL LEAKAGE OF REACTANTS THROUGH CELL MATRIX OR SEPARATOR PLATE

**MISSION PHASE:**

FL PRELAUNCH  
LO LIFT-OFF  
CO ON-ORBIT  
DO DE-ORBIT  
LS LANDING SAFING

VEHICLE/PAYLOAD/KIT EFFECTIVITY: 102 COLUMBIA  
: 103 DISCOVERY  
: 104 ATLANTIS

**CAUSE:**

DRYOUT DUE TO INSUFFICIENT ELECTROLYTE, LATENT DEFECT OF MATRIX, OR MAGNESIUM SEPARATOR PLATES. EXCESSIVE DELTA PRESSURE DUE TO FAILED REGULATOR.

CRITICALITY 1/1 DURING IMPACT ABORT ONLY? Y

REDUNDANCY SCREEN A) N/A  
B) N/A  
C) N/A

**PASS/FAIL RATIONALE:**

A)

B)

C)

**- FAILURE EFFECTS -**

**(A) SUBSYSTEM:**

LOSS OF REDUNDANCY - CREW IS REQUIRED TO SHUTDOWN FCP IMMEDIATELY TO PREVENT POSSIBLE VEHICLE OR FCP DAMAGE. LOW LEVEL LEAKAGE WILL IMMEDIATELY REACT DUE TO CATALYST ACTION PRECLUDING REACTANT ACCUMULATION TO AN EXPLOSIVE MIXTURE. UNDETECTED GROSS LEAKAGE CAN RESULT IN REACTANT MIXING AND POTENTIAL FIRE. INCREASED LOCAL TEMPERATURE AND DECREASED VOLTAGE IN AFFECTED CELL.

**(B) INTERFACING SUBSYSTEM(S):**

PRINT DATE: 02/16/89

SHUTTLE CRITICAL ITEMS LIST - CREWITER NUMBER: 04-1A-0101-09

S50230Y  
ATTACHMENT -  
Page 27 of 120

DEGRADATION OF INTERFACE FUNCTION - REDUCED ELECTRICAL POWER SUPPLY TO EPD&C.

(C) MISSION:

NO EFFECT AFTER LOSS OF ONE FUEL CELL. MINIMUM DURATION MISSION INVOKED.

(D) CREW, VEHICLE, AND ELEMENT(S):

CREW IS REQUIRED TO SHUTDOWN AND SAFE AFFECTED PCP WHEN DETECTED. POSSIBLE LOSS OF CREW/VEHICLE IF GROSS LEAKAGE IS UNDETECTED.

(E) FUNCTIONAL CRITICALITY EFFECTS

---

- DISPOSITION RATIONALE -

---

(A) DESIGN:

INTERNAL LEAKAGE (REACTANT CROSSOVER) IS THE WEAROUT FAILURE MODE OF THE INDIVIDUAL CELLS. HOWEVER, THIS IS EXPECTED TO OCCUR IN THE 3000 TO 5000 HOUR TIME PERIOD RATHER THAN THE 2000 TO 2500 HOUR OPERATING LIFE OF THE FUEL CELL POWER SECTION.

THEREFORE, THE TENDENCY IF THIS FAILURE MODE WERE TO OCCUR WOULD BE FOR A TOLERABLE LOW LEVEL OR "PINHOLE" LEAK TO OCCUR LATE IN THE LIFE OF THE UNIT. HOWEVER, LATENT DEFECTS IN A CELL OR SEPARATOR PLATE COULD ESCAPE THE SCREENING PROCESS RESULTING IN A CROSSOVER LEAK EARLIER IN THE LIFE CYCLE OF THE FUEL CELL.

TO AID IN DETECTION OF THIS FAILURE MODE, CELL PERFORMANCE MONITOR INSTRUMENTATION HAS BEEN ADDED INCLUDING ALARM LEVELS SET SUFFICIENTLY LOW TO PERMIT SHUTDOWN AND ISOLATION PRIOR TO INCURRING FUEL CELL OR VEHICLE DAMAGE.

THE CELL ELECTROLYTE MATRIX IS DESIGNED TO WITHSTAND PRESSURES 8 TO 10 TIMES GREATER THAN OPERATING CONDITIONS. THE SEPARATOR PLATES ARE MAGNESIUM WITH A NICKEL PLATING FOR CORROSION PROTECTION AND AN OUTER GOLD PLATING TO MINIMIZE ELECTRICAL CONTACT RESISTANCE.

THE THERMAL CONTROL SYSTEM IS DESIGNED WITH A GREATER THAN 20 DEG F CONDENSER EXIT TEMPERATURE MARGIN FOR CONTROLLING ELECTROLYTE DRYOUT.

THE PRESSURE REGULATOR IS DESIGNED TO PRECLUDE PRESSURE IMBALANCE SUFFICIENT TO OVERCOME BUBBLE PRESSURE OF MATRIX. EXCESSIVE PRESSURE DETECTABLE BY COOLANT PRESSURE MEASUREMENT ON EACH PCP. VENT SYSTEM RELIEF FLOW CAPABILITY IS GREATER THAN SUPPLY FLOW CAPABILITY.

(B) TEST:

CELL ASSEMBLY AND SEPARATOR PLATE ARE HELIUM LEAK CHECKED AT 8 PSID (NORMAL PRESSURE 4-6 PSID). INDIVIDUAL SEPARATOR PLATE INTEGRITY IS TESTED AT 100 PSI PLUS X-RAY AND VISUALLY INSPECTED TO STANDARDS PRIOR TO ASSEMBLY.

PRINT DATE: 02/16/89

SHUTTLE CRITICAL ITEMS LIST - ORBITER NUMBER: 04-1A-0101-09

S50230Y  
ATTACHMENT  
Page 28 of 120

EACH CELL IS EVALUATED FOR ELECTRICAL PERFORMANCE AT ASSEMBLY. POWER SECTION EXTERNAL LEAKAGE DECAY TEST AT SYSTEM PRESSURE (QUALIFICATION AND ATP).

ATP VERIFIES PROPER THERMAL CONTROL TO ASSURE ADEQUATE ELECTROLYTE VOLUME MAINTENANCE. INDIVIDUAL CELLS ARE WEIGHED DURING MANUFACTURE TO ASSURE PROPER ELECTROLYTE FILL.

CMPSD: N2 DIAGNOSTIC TEST IS PERFORMED DURING TURNAROUND TO DETECT LOW-LEVEL CROSSOVER UP TO SEVERAL HUNDRED HOURS PRIOR TO REACHING SIGNIFICANT LEVELS WHICH MIGHT AFFECT PERFORMANCE OR SAFETY. FUEL CELL PERFORMANCE VERIFIED DURING PRELAUNCH ONLOAD OPERATIONS.

(C) INSPECTION:

RECEIVING INSPECTION

DIMENSIONAL INSPECTIONS ARE PERFORMED DURING RECEIVING, IN-PROCESS, AND ACCEPTANCE SEQUENCES. MATERIAL LOT SAMPLES ARE FORWARDED TO A TEST LAB FOR CERTIFICATION ANALYSIS. WELD FILLER METAL IS CERTIFIED BY LAB TESTING AND MATERIAL CONTROL LAB SPECIFICATIONS.

CONTAMINATION CONTROL

DETAIL PARTS AND ASSEMBLIES ARE SOLVENT CLEANED PER APPROVED PROCEDURES AND DOUBLE BAGGED AS REQUIRED TO PREVENT CONTAMINATION. ASSEMBLY OPERATIONS ARE PERFORMED UNDER CONTROLLED CONDITIONS USING PROCEDURES WHICH MAINTAIN CLEANLINESS AND WHICH SPECIFY APPROPRIATE HANDLING PRECAUTIONS. CLEANLINESS OF OPERATING/TEST FLUIDS IS MAINTAINED THROUGH SAMPLING AND/OR FILTRATION. THE ASSEMBLED FUEL CELL UTILIZES CAPS OR CLOSURES ON ALL FLUID FITTINGS AND THE SHIPMENT/STORAGE OF THE FUEL CELL IS IN A NITROGEN PRESSURIZED METAL SHIPPING CONTAINER.

ASSEMBLY/INSTALLATION

CELL FILLING AND POWERSECTION ASSEMBLY ARE PERFORMED IN AN ATMOSPHERICALLY CONTROLLED CHAMBER USING FEED-THRU GLOVES. STACKING AND TORQUING OPERATIONS UTILIZE A FIXTURE FOR ALIGNMENT AND HYDRAULIC PRESSURE CONTROL FOR ESTABLISHING PROPER CONTACT PRESSURE (COMPRESSIVE LOAD) PRIOR TO THERMOC INSTALLATION. ALL CRITICAL ASSEMBLY OPERATIONS WITNESSED AND VERIFIED BY QC.

NONDESTRUCTIVE EVALUATION

CELL ELECTROLYTE MATRIX IS LIGHT BOX AND VISUALLY INSPECTED PRIOR TO ASSEMBLY. SEPARATOR PLATES ARE X-RAYED AND VISUALLY INSPECTED.

TESTING

CELL PERFORMANCE REQUIREMENTS ARE VERIFIED DURING ATP.

(D) FAILURE HISTORY:

CAR NO. AC9940-010 SUPPLIER, RE-ATP

CELL NUMBERS 22 AND 23 EXHIBITED SUBSTANDARD PERFORMANCE. THE CAUSE WAS A RESULT OF A LEAK PATH WITHIN A COMBO SEPARATOR WHICH WAS LOCATED BETWEEN THE TWO CELLS. A COMBINATION OF POROSITY AND/OR INCLUSION

PRINT DATE: 02/16/89

550230Y

ATTACHMENT -

Page 29 of 12.

SHUTTLE CRITICAL ITEMS LIST - ORBITER

NUMBER: 04-1A-0101-09

WITHIN THE MAGNESIUM BASE ALLOY AND MICRO CRACKS IN THE PROTECTIVE NICKEL PLATING PROVIDED THE LEAK PATH.

THE PROBLEM WAS CLOSED AS "EXPLAINED" WITH THE FOLLOWING RATIONALE: LOW LEVEL CROSSOVER LEAKAGE WILL IMMEDIATELY REACT DUE TO CATALYST ACTION PRECLUDING REACTANT ACCUMULATION. THIS WILL RESULT IN A DEGRADATION OF CELL VOLTAGE WHICH IS DETECTABLE BY THE CELL PERFORMANCE MONITOR PRIOR TO AND DURING A FLIGHT. IN ADDITION, A FUEL CELL POWERPLANT DIAGNOSTIC TEST WHICH IS CAPABLE OF DETECTING VERY MINUTE LEVELS OF REACTANT CROSSOVER IS PERFORMED ON ALL POWERPLANTS PRIOR TO EVERY FLIGHT.

CAR NO. AC9841-010 SUPPLIER, RE-ATP

CELL #31 EXHIBITED UNSATISFACTORY NITROGEN DECAY CHARACTERISTICS. THE CAUSE WAS A RESULT OF CROSS LEAKAGE AT CELL #31 DUE TO A THIN SPOT IN THE ASBESTOS MATRIX OF THE UNTILIZED ELECTRODE ASSEMBLY. THE THIN SPOT IS BELIEVED TO HAVE BEEN A RESULT OF A MANUFACTURING DEFECT NOT DETECTED DURING VISUAL EXAMINATIONS.

CORRECTIVE ACTION INCLUDED INCORPORATION OF A PREFLIGHT DIAGNOSTIC TEST INTO THE OMRSD. THIS TEST WILL EFFECTIVELY SCREEN ANY POWERPLANTS EXHIBITING REACTANT CROSSOVER LEAKAGE. THE SUBCONTRACTOR IS ALSO INVESTIGATING THE USE OF AN OPTICAL SCANNER WHICH HAS BEEN FOUND TO BE EFFECTIVE AT DETECTING FLAWS WITHIN NEWLY MANUFACTURED ASBESTOS MATRICES.

(E) OPERATIONAL USE:

CELL PERFORMANCE MONITOR PROVIDES CREW ALERT FOR EARLY DETECTION OF THIS FAILURE. CREW ACTION IS REQUIRED TO SHUTDOWN AND SAFE AFFECTED FUEL CELL. ONBOARD PROCEDURES MANAGE POWER FOR LOSS OF ONE PCP.

- APPROVALS -

RELIABILITY ENGINEERING: G. M. FIKUS  
DESIGN ENGINEERING : J. F. WILLIAMS  
QUALITY ENGINEERING : J. COURSEN  
NASA RELIABILITY :  
NASA SUBSYSTEM MANAGER :  
NASA QUALITY ASSURANCE :

: *[Signature]*  
: *J. F. Williams 2-17-89*  
: *J. Courson 2-21-89*  
: *[Signature]*  
: *[Signature]*  
: *[Signature] 3/17/89*