SHUTTLE CRITICAL IDEMS LIST - ORBIDER

SUBSYSTEM : AUXILIARY POWER (APUS) FMEA NO 04-2 -516A -2 REV:02/26/88

ASSEMBLY :FUEL SUPPLY

CRIT. FUNC: 15.

P/N RI :ME360-0017-0008

CRIT. HEW:

P/N VENDOR:SDC P/N 975-0399-008

102 103 104

QUANTITY : 6

VEHICLE EFFECTIVITY: х

:1 FOR PRIM HTR ELEM

PL X LO X CO X DO X LS PHASE(5):

: (S16B FOR SEC HTR ELFM)

PREPARED BY:

REDUNDANCY SCREEN: APPROVED BY

A-PASS E-PASS C-FASS

DES

R STEDMAN DES APPROVED 與X_(MASA): SSM W

REL QE,

T R BOLTZ WEREL

W J SMITH

REL / OE /2-

ITEM:

THERMOSTAT, FUEL SERVICING LINES (FILL AND TEST LINE).

QΕ

FUNCTION:

TO PROVIDE A CLOSED ELECTRICAL CIRCUIT, AT 55 DEG F AND AN OPEN CIRCUIT AT 65 DEG F (PLUS OR MINUS 5 DEG F). THE THERMOSTAT CONTROLS THE PRIMARY ELEMENTS OF THE FUEL SERVICING AND TEST LINE HEATERS. BOTH THE PRIMARY AND SECONDARY THERMOSTATS AND HEATERS ARE ACTIVATED PRIOR TO CRYO LOADING THROUGH LAUNCH. HEATERS ARE OFF FOR ASCENT AND ONLY ONE HEATER ELEMENT WILL BE ACTIVATED DURING THE REMAINDER OF THE FLIGHT (REFERENCE FREA 04-2-MR116).

FAILURE MODE:

FAILS TO OPEN, (FAILS CLOSED)

CAUSE(S):

SHORT, WELDED CONTACTS

EFFECT(S) ON:

- (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE
- (A) NO EFFECT WHEN APU IS RUNNING AND FUEL IS FLOWING.
- (B,C) IF HEATER PANEL SWITCH FAILS AND CREW UNABLE TO TURN HEATER OFF, POSSIBLE DECOMPOSITION OF HYDRAZINE COULD OCCUR RESULTING IN 1055 OF MISSION.
- (O.E) NO EFFECT UNLESS APU IS SHUT DOWN AND HEATER IS NOT TURNED OFF. IF NOT, POSSIBLE LOSS OF CREW/VEHICLE OR APU.

DISPOSITION & RATIONALE:

(A)DESIGN (B)TEST (C)INSPECTION (D)FAILURE HISTORY (E)OPERATIONAL USE

(A) DESIGN

THE ELECTRICAL SYSTEM IS DESIGNED WITH (3) DRIVERS THROUGH (RPC) TO TURN ON THE HEATER. A (3) POLE SWITCH WHICH HAS (1) POLE TO EACH DRIVER ENERGIZES THE CIRCUIT. ANY TWO DRIVERS WILL ENERGIZE A HEATER; ONE DRIVER FAILING ON WILL NOT DELIVER POWER TO THE HEATER.

SHUTTLE CRITICAL ITIMS LIST - CREITER

SUBSYSTEM : AUXILIARY FOWER (APUS) FMEA NO 04-2 -516A -2 REV:00, 26, 6

SWITCH IS DESIGNED TO MEET THE REQUIREMENTS OF MIL-5-24206. IT IS ALL WELDED CONSTRUCTION, VIERATION, AND CORROSION RESISTANT, SIMPLY, SNAP-ACTING THERMAL SWITCH, REPMETICALLY SEALED WITH DRY NITROGEN. IT RATED AT 5 AMPS AND WILL ONLY CARRY MILLIAMPS.

(B) TEST

PART ACCEPTANCE TEST INCLUDES CONTACT RESISTANCE, SEAL TEST, CREEP, AND 250 CYCLE RUN-IN.

IT IS QUALIFIED BY SIMILARITY TO LIKE MIL-5-24236 SWITCHES BUILT BY SUNDSTRAND DATA CONTROL. THE SWITCH WAS QUALIFICATION TESTED.

OMRSD: APU 1/2/3 HEATER TEST BY COCKPIT COMMAND VERIFIES THERMOSTATS FOR FIRST FLIGHT AND ON A CONTINGENCY BASIS THEREAFTER ANY TIME THE LINE, INSULATION, OR HEATER IS DISTURBED. THERMOSTATS ARE VERIFIED OPERATIONS EVERY FLIGHT.

(C) INSPECTION

RECEIVING INSPECTION

RAW MATERIALS ARE CERTIFIED AND VERIFIED BY INSPECTION.

CONTAMINATION CONTROL

CLIANLINESS REQUIREMENTS ARE VERIFIED BY INSPECTION.

ASSEMBLY/INSTALLATION

MANUFACTURING OPERATIONS ARE VERIFIED BY INSPECTION.

NONDESTRUCTIVE EVALUATION

PARTICLE IMPACT NOISE DETECTION (PIND) IS VERIFIED BY INSPECTION. FLUOROCARBON LEAK CHECK IS VERIFIED BY INSPECTION.

CRITICAL PROCESSES

WELDING PER SPECIFICATION REQUIREMENTS IS VERIFIED BY INSPECTION.

TEST1HG

TEST EQUIPMENT CALIBRATION AND CERTIFICATION ARE VERIFIED BY INSPECTION: BURN-IN CYCLING IS VERIFIED BY INSPECTION. ATP IS WITNESSED AND VERIFIED BY INSPECTION.

HANDLING/PACKAGING

HANDLING, FACKAGING, STORAGE, AND SHIPPING PROCEDURES ARE VERIFIED.

(D) FAILURE HISTORY

CAR 24F011: THERMOSTAT FAILED CLOSED. NO CORRECTIVE ACTION AS OF NOW. THE PROBLEM WAS THOUGHT AT FIRST TO BE CAUSED BY "SLOW CREEP," BUT THE POSSIBILITY THAT THE FAILURE MAY HAVE BEEN CAUSED BY EXCESSIVE VISRATIC IS BEING ADDRESSED. CORRECTIVE ACTION WILL BE DECIDED FOLLOWING INVESTIGATION. HOWEVER, NO FAILURES OF THIS TYPE HAVE OCCURRED ON VEHICLE LINES. THESE THERMOSTATS ARE NOT LOCATED ON THE APU AS IN CAR 24F011. CONSEQUENTLY THE VIBRATION ENVIORMENT IS MUCH MORE BENIGN.

(E) OPERATIONAL USE

MANUALLY SWITCH TO ALTERNATE HEATER.