

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL HARDWARE

NUMBER: 04-2-S17C-IM-X

SUBSYSTEM NAME: AUXILIARY POWER UNIT (APU)

REVISION : 3 11/21/91

SOS027L
ATTACHMEN
PAGE 28 G

	PART NAME VENDOR NAME	PART NUMBER VENDOR NUMBER
■ LRU :	AUXILIARY POWER UNIT (APU)	MC201-0001-04XX
■	SUNOSTRAND	X742211X
■ SRU :	THERMOSTAT	5908109
■	SUNOSTRAND DATA CONTROLS	975-0478-003

PART DATA

- EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:
THERMOSTAT, OVERTEMPERATURE, APU FUEL PUMP/VALVE (GGVM)/FUEL LINES
(FEED, BYPASS, REFERENCE)
SUPPLY
- QUANTITY OF LIKE ITEMS: 6
1 FOR HEATER ELEMENT A
AND ONE FOR HEATER ELEMENT B, 2 PER APU
- FUNCTION:
TO PROVIDE A CLOSED ELECTRICAL CIRCUIT AT A MINIMUM OF 120 DEG F AND AN
OPEN CIRCUIT AT A MAXIMUM OF 140 DEG F. DIFFERENTIAL BETWEEN OPENING
AND CLOSING TEMPERATURE IS REQUIRED TO BE AT LEAST 7 DEG F. EACH
OVERTEMPERATURE THERMOSTAT (~~S17C/S17D~~) CONTROLS ONE OF THE REDUNDANT
ELEMENTS (HEATER A/HEATER B) OF THE APU FUEL PUMP, GGVM AND FUEL
LINE HEATERS (REFERENCE FMEA 04-2-HR17) IN THE EVENT THAT THE CONTROL
THERMOSTAT (~~S17A/S17B~~) FAILS CLOSED.

S17A/S17B

S17C/S17D

PAGE: 6

PRINT DATE: 11/21/91

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL FAILURE MODE

NUMBER: 04-2-S17C-IM-02

SC5027
ATTACH
PAGE 33 C

SUBSYSTEM: AUXILIARY POWER UNIT (APU)
LRU :AUXILIARY POWER UNIT (APU)
ITEM NAME: THERMOSTAT

REVISION# 3 11/21/91 R

CRITICALITY OF THIS
FAILURE MODE:1R3

- FAILURE MODE:
FAILS TO OPEN (FAILS CLOSED).

MISSION PHASE:

PL	PRELAUNCH
LO	LIFT-OFF
OO	ON-ORBIT
DO	DE-ORBIT

- VEHICLE/PAYLOAD/KIT EFFECTIVITY: 102 COLUMBIA
: 103 DISCOVERY
: 104 ATLANTIS
: 105 ENDEAVOUR

- CAUSE:
INTERNAL PIECE-PART FAILURE, VIBRATION, BIMETAL DISC CRACK OR FATIGUE,
LOSS OF HERMETIC SEAL, CONTAMINATION.

- CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

- REDUNDANCY SCREEN A) PASS
- B) FAIL
- C) FAIL

PASS/FAIL RATIONALE:

- A)
THERMOSTAT OPENING CAN BE VERIFIED DURING TURNAROUND.
- B)
OVERTEMPERATURE THERMOSTAT FAILURE NOT DETECTABLE UNTIL CONTROL
THERMOSTAT FAILS CLOSED.
- C)
FIX BY MS 9
VIBRATION OF THE MOUNTING LINES ON THE APU COULD CAUSE FAILURE OF
CONTROL AND OVERTEMPERATURE THERMOSTATS ON BOTH HEATER SYSTEMS
A AND B.

- MASTER MEAS. LIST NUMBERS: V46TOX12A
: V46TOX28A

PAGE: 7

PRINT DATE: 11/21/91

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL FAILURE MODE
 NUMBER: 04-2-517C-IM-02

SOS02
 ATTACHME
 PAGE 34

: V46T0X71A 1X71A
 : V46T0X72A 1X72A
 : V46T0X92A

 - FAILURE EFFECTS -

- (A) SUBSYSTEM:
 NO EFFECT ON APU OPERATION. LOSS OF HEATER REDUNDANCY IF CONTROL THERMOSTAT (S17A/S17B) FAILS.
- (B) INTERFACING SUBSYSTEM(S):
 NO EFFECT
 (S17A/S17B)
- (C) MISSION:
 NO EFFECT AS OVERTEMPERATURE THERMOSTAT FAILURE IS NOT DETECTABLE.
- (D) CREW, VEHICLE, AND ELEMENT(S):
 NO EFFECT UNLESS FUEL LINE OVERHEATS AND FUEL IGNITES. POSSIBLE LOSS OF CREW/VEHICLE.
- (E) FUNCTIONAL CRITICALITY EFFECTS:
 1ST FAILURE - OVERTEMPERATURE THERMOSTAT FAILED CLOSED HAS NO EFFECT.
 2ND FAILURE - FAILURE OF CONTROL THERMOSTAT (OPEN OR CLOSED) WILL BE DETECTED BY FDA AND RESULT IN CREW SELECTING THE REDUNDANT HEATER SYSTEM.
 3RD FAILURE - FAILURE OF THE REDUNDANT SYSTEM OR COCKPIT SWITCH CAN CAUSE FAILED ON HEATER OR FAILED OFF HEATER. FAILED ON HEATER WOULD RESULT IN FUEL IGNITION IF HEATER POWER IS NOT REMOVED. FAILED OFF HEATER CAN CAUSE FUEL FREEZING AND LINE RUPTURE (HYDRAZINE LEAKAGE) UPON THAWING.

 - DISPOSITION RATIONALE -

- (A) DESIGN:
 THE ELECTRICAL SYSTEM IS DESIGNED WITH (3) DRIVERS THROUGH (RPC) TO TURN HEATERS ON OR OFF. A (3) POLE SWITCH WHICH HAS (1) POLE TO EACH DRIVER WHICH ENERGIZES THE CIRCUIT. ANY ONE DRIVER FAILED OFF WILL TURN OFF A HEATER; ONE DRIVER FAILING ON WILL NOT DELIVER POWER TO THE HEATER.

SWITCH IS DESIGNED TO MEET THE REQUIREMENTS OF MIL-S-24236, IT IS ALL WELDED CONSTRUCTION, CORROSION RESISTANT, SIMPLE, SNAP-ACTING THERMAL SWITCH, HERMETICALLY SEALED WITH DRY NITROGEN, IT IS RATED AT 5 AMPS, BUT

CARRIES MILLAMPS.

PAGE: 8

PRINT DATE: 11/21/91

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL FAILURE MODE
 NUMBER: 04-2-517G-IM-02

50502
 ATTACH
 PAGE 35 OF

■ (B) TEST:

PART ACCEPTANCE TEST INCLUDES CONTACT RESISTANCE, SEAL TEST, CREEP, AND 250 CYCLE RUN-IN.

IT IS QUALIFIED BY SIMILARITY TO LIKE MIL-S-24236 SWITCHES BUILT BY SUNDSTRAND DATA CONTROL. THE SWITCH WAS QUALIFICATION TESTED.

ALL NOT DETECTABLE UNLESS CONTROL FLUID THERMOSTAT FAILS CLOSED. MAY NOT BE BETA IN APT CO DURING CRYO LOW DUE TO LOW TEMPERATURE

OMRSD: APU 1/2/3 HEATER TEST BY COCKPIT COMMAND VERIFIES THERMOSTATS FOR FIRST FLIGHT AND ON A CONTINGENCY BASIS THEREAFTER ANY TIME THE LINE, INSULATION, OR HEATER IS DISTURBED.

ENTER SYSTEM BOTH

OVERTEMPERATURE THERMOSTAT IS VERIFIED FUNCTIONAL FOR FIRST FLIGHT AND EVERY FIFTH FLIGHT THEREAFTER. A AND B CONTROL THERMOSTATS/HEATER SYSTEMS ARE VERIFIED OPERATIONAL IN-FLIGHT EVERY FLIGHT.

(SYSTEMS)

■ (C) INSPECTION:

RECEIVING INSPECTION:

RAW MATERIALS ARE CERTIFIED AND VERIFIED BY INSPECTION. 1ST AND 20TH RECEIVED SHIPMENTS ARE VERIFIED BY OUT-PLANT ANALYSIS. OTHER SHIPMENTS ARE ACCEPTED ON VENDOR-SUPPLIED CERTIFICATION.

CONTAMINATION CONTROL:

ALL CLEANING OPERATIONS ARE PERFORMED AND INSPECTED PER DOCUMENTED CLEANLINESS REQUIREMENT PROCEDURES. MICROPARTICLE ANALYSIS PERFORMED ON A SAMPLE. PRECAP INSPECTION IS PERFORMED FOR EVERY UNIT.

ASSEMBLY/INSTALLATION:

ALL MANDATORY INSPECTION POINTS FOR MANUFACTURING OPERATIONS ARE VERIFIED AND DOCUMENTED.

NONDESTRUCTIVE EVALUATION:

GROSS LEAK CHECK IS DONE IN FC43 FLUORINERT AND IS VERIFIED BY QUALITY ASSURANCE INSPECTION FOR EVERY UNIT. PARTICLE NOISE IMPACT DETECTION (PIND) TESTING IS PERFORMED AT THE LOWER MODULE ASSEMBLY LEVEL (NOT ATP) FOR EVERY UNIT.

CRITICAL PROCESSES:

VERIFICATION OF CASE WELD IS DONE BY HELIUM LEAK CHECK FOR EVERY UNIT.

TESTING:

TEST EQUIPMENT CALIBRATION IS PER MIL-STD-45662. BURN-IN CYCLING AND ATP ARE PERFORMED AND VERIFIED FOR EVERY UNIT BY INSPECTION.

HANDLING/PACKAGING:

HANDLING, PACKAGING, STORAGE, AND SHIPPING PROCEDURES ARE VERIFIED BY PERIODIC SYSTEM AUDITS.

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL FAILURE MODE
 NUMBER: 04-2-517C-IM-02

S050270
 ATTACH
 PAGE 36

■ (D) FAILURE HISTORY:

CAR 34RF11:
 BASELINE APU IN-FLIGHT VIBRATION LEVELS EXCEED SWITCH DESIGN LIMITS AND HAVE RESULTED IN FAILED ON CONDITION, BUT IT COULD ALSO LEAD TO A FAILED OFF CONDITION.

CORRECTIVE ACTION: A STUDY TO REPLACE THESE SWITCHES ON THE IAPU WITH A VIBRATION INSENSITIVE DEVICE IS IN WORK.

■ (E) OPERATIONAL USE:

MANUALLY SWITCH TO ALTERNATE HEATER IF CONTROL THERMOSTAT AND OVERTEMP THERMOSTAT FAIL. IF ALTERNATE HEATER FAILS ON, CREW MUST REMOVE POWER FROM HEATER THEN MANUALLY CYCLE HEATER (IF POSSIBLE). IF ALTERNATE HEATER FAILS OFF, CREW MUST ORIENT VEHICLE TO PREVENT FUEL FREEZING.

- APPROVALS -

RELIABILITY ENGINEERING: D. R. ATAPATTU
 DESIGN ENGINEERING : J. R. MUNROE
 QUALITY MANAGER : O. J. BUTTNER
 NASA RELIABILITY : *Amey/12/92*
 NASA SUBSYSTEM MANAGER :
 NASA QUALITY ASSURANCE :

Zabala, Orlan
[Signature]
[Signature]
[Signature]
 1-24-92
[Signature]