PAGE: 1

PRINT: DATE: 4/16/96

FAILURE MODES EFFECTS ANALYSIS (FMEA) — CIL HARDWARE NUMBER: 05-5-817-1 -X

SUBSYSTEM NAME: DATA PROCESSING SYSTEM (DPS)

REVISION: 7

04/15/96

PART DATA

PART NAME VENDOR NAME PART NUMBER

YENDOR NUMBER

LRU

: PANEL OF

V070-730389

ಽನ೮

: SWITCH, GPC MODE

ME452-0102-7361

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:

SWITCH, MODE TOGGLE, 3P3P, "RUN-STBY-HALT" LEVER LOCKED SWITCH

REFERENCE DESIGNATORS:

33V73A6S46

33V73A6S47 33V73A6S48 33V73A6S49

33V73A6S50

QUANTITY OF LIKE ITEMS: 5

FIVE ON PANEL OF

FUNCTION:

PROVIDE MEANS FOR CHANGING THE GENERAL PURPOSE COMPUTER (GPC) MODES IN "RUN" MODE THE GPC IS IN THE OPERATIONAL STATUS, IN "STANDBY" THE GPC ACTIVITY DEPENDS ON SOFTWARE. IN "HALT" THE GPC IS INACTIVE AND CAPABLE OF INITIAL PROGRAM LOAD (IPL). NORMAL POSITION DURING MISSION IS "RUN".

PAGE 2

.. PRINT DATE: 04/16/98

FAILURE MODES EFFECTS ANALYSIS FMEA - CIL FAILURE MODE

NUMBER: 05-5-817-1-01

- REVISION#: 8

04/08/96

SUBSYSTEM NAME: DATA PROCESSING SYSTEM (DPS)

LRU: PANEL O6

CRITICALITY OF THIS

ITEM NAME: SWITCH, TOGGLE

FAILURE MODE: 1R2

FAILURE MODE:

PREMATURE AND ERRONEOUS OPERATION.

MISSION PHASE:

PL PRE-LAUNCH LO LIFT-OFF

OO ON-ORBIT DO DE-ORBIT

LS LANDING/SAFING

VEHICLE/PAYLOAD/KIT EFFECTIVITY:

102 COLUMBIA

103 DISCOVERY 104 ATLANTIS

105 ENDEAVOUR

CAUSE:

CONTAMINATION, MECHANICAL SHOCK, VIBRATION, PROCESSING ANOMALY, PIECE PART STRUCTURAL FAILURE.

CRITICALITY 1/1 DURING INTACT ABORT ONLY? YES

AGA — ABORT ONCE AROUND RETURN TO LAUNCH SITE RTLS

TAL TRANS-ATLANTIC LANDING

REDUNDANCY SCREEN

A) PASS

B) FAIL

C) PASS

PASS/FAIL RATIONALE:

A)

B)

FAILS SCREEN BISINCE ONLY ONE OF THREE OF THE REDUNDANT CONTACTS IS CSTRUMENTED

C١

- FAILURE EFFECTS -

PAGE: 3 PRINT DATE: 04/16/96

FAILURE MODES EFFECTS ANALYSIS (FMEA) — CIL FAILURE MODE NUMBER: 05-5-B17-1-01

(A) SUBSYSTEM:

GPC WILL BE REMOVED FROM ACTIVE USE AND PLACED IN STANDBY OR HALT.

FAILURE EFFECTS FOR EACH MODE ARE AS FOLLOWS:

1) RUN TO STANDBY:

PRIMARY AVIONICS SOFTWARE SYSTEM (PASS): GPC IS EJECTED FROM REDUNDANT SET AND IS INEFFECTIVE UNTIL THE SET IS REFORMED.
BACKUP FLIGHT SYSTEM (BFS): GPC IS UNABLE TO CONTROL (PAYLOAD) PL1 & 2 BUSES. ABILITY TO ENGAGE BFS IS NOT AFFECTED.
2) STANDBY TO HALT:
PASS OR BFS. GPC STOPS PROCESSING.
3) HALT TO STANDBY:
BFS/PASS GPC IPL-INCOMPLETE: LOSS OF THE GPC WITH THE MODE SWITCH.

PROBLEM. IPL MUST BE PERFORMED IN THE HALT MODE.

BFS/PASS GPC POST IPL: NO EFFECT. GPC IS NOW UNDER SOFTWARE CONTROL

MONITORING FOR MODE SWITCH TRANSITION TO THE RUN MODE.

BEST NO EFFECT. HOWEVER, IF THE PASS GPC'S ARE IN OPS1 OR 3, THE BES CAN

WORST CASE FOR ALL MODES IS EQUIVALENT TO LOSS OF OUTPUT FROM ONE GPC.

(B) INTERFACING SUBSYSTEM(S):

TRACK THE FLIGHT CRITICAL STRINGS.

LOSS OF STRINGS (DATA BUSES) ASSIGNED TO FAILED GPC.

(C) MISSION:

LOSS OF ONE GPC NO EFFECT. TWO GPC'S RESULT IN MINIMUM DURATION FLIGHT. THREE GPC'S NEXT PRIMARY LANDING SITE.

(D) CREW, VEHICLE, AND ELEMENT(S):

NO EFFECT FIRST FAILURE.

(E) FUNCTIONAL CRITICALITY EFFECTS:

CRITICALITY 1R2 BECAUSE OF THE FOLLOWING REASONS:

FOR ASCENT/ENTRY: THIS FAILURE COUPLED WITH AN UNDETECTED FLIGHT CONTROL SYSTEM (FCS) FAILURE IN THE NULL (ZERO OUTPUT) POSITION (E.G., IN THE AEROSURFACE AMPLIFIER (ASA) OR ASCENT THRUST VECTOR CONTROLLER (ATVC)). COULD RESULT IN THE TWO HEALTHY PATHS BEING VOTED OUT. THIS COULD RESULT IN A VOTING DILEMMA IN THE FCS (E.G., "FORCE FIGHT" IN THE SERVO ACTUATORS. REFERENCE FMEA 05-1-FC6042-1 AND '05-1-FC6542-1).

PAGE: 4 PRINT DATE: 04/16/96

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL FAILURE MODE NUMBER: 05-5-B17-1-91

FOR ASCENT:

DURING INTACT ABORT (RTLS, TAL, AOA), CRITICALITY 1 IF UNABLE TO PURGE AFT FUSELAGE COMPARTMENTS OF POST MECO GAS MIXTURE (BY OPENING HELIUM BLOW DOWN VALVE) RESULTING IN POSSIBLE FIRE/EXPLOSION AND MAY RESULT IN LOSS OF VEHICLE & CREW ((FLIGHT AFT) FA3 OR FA4 MULTIPLEXER DEMULTIPLEXER (MDM)).

ALL PHASES:

LOSS OF OUTPUT FROM ONE INERTIAL MEASUREMENT UNIT (IMU) OR A FLIGHT FORWARD (FF) MDM CHANNEL PROCESSING IMU DATA, FOLLOWED BY FAILURE OF ANOTHER IMU OR FF MDM WITH ERRONEOUS OUTPUT SUCH THAT THE AVERAGE OF THE TWO REMAINING CHANNELS IS CORRUPTED, WILL LEAD TO INCORPORATION OF FAULTY IMU DATA BY ALL COMPUTERS AND POSSIBLE LOSS OF VEHICLE/CREW.

FOR BFS:

AFTER LOSS OF PASS DUE TO GENERIC FAILURE(S), BFS ENGAGE IS REQUIRED. ANY SUBSEQUENT FAILURE IN THE BFS LEADS TO INABILITY TO CONTROL THE VEHICLE AND RESULTS IN LOSS OF CREW/VEHICLE

-DISPOSITION RATIONALE-

(A) DESIGN:

REFER TO APPENDIX A, ITEM NO. 1 - TOGGLE SWITCH.

(B) TEST:

REFER TO APPENDIX A, ITEM NO. 1 - TOGGLE SWITCH.

GROUND TURNAROUND TEST: ALL TURNAROUND CHECKOUT TESTING IS ACCOMPLISHED IN ACCORDANCE WITH OMRSD.

(C) INSPECTION:

REFER TO APPENDIX A, ITEM NO. 1 - TOGGLE SWITCH

(D) FAILURE HISTORY:

CURRENT DATA ON TEST FAILURES, FLIGHT FAILURES, UNEXPLAINED ANOMALIES, AND OTHER FAILURES EXPERIENCED DURING GROUND PROCESSING ACTIVITY CAN BE FOUND IN THE PRACA DATABASE

(E) OPERATIONAL USE:

AFTER FAILURE OF A PASS MODE SWITCH, THE REMAINING GPC'S SHOULD BE CONFIGURED ACCORDING TO THE APPROPRIATE FLIGHT DATA FILE GPC FAIL PROCEDURES AND FLIGHT RULE GUIDELINES. PAGE: 5 PRINT DATE: 4/16/96

FAILURE MODES EFFECTS ANALYSIS (FMEA) - CIL FAILURE MODE

NUMBER: 05-5-817-1-01

- APPROVALS -

EDITORIALLY APPROVED EDITORIALLY APPROVED

: RI : JSC

TECHNICAL APPROVAL

: VIA APPROVAL FORM

: 96-CIL-013_05-5