

PAGE: 1

PRINT DATE: 05/27/94

FAILURE MODES EFFECTS ANALYSIS (FMEA) - CRITICAL HARDWARE

NUMBER: 05-6-2010C -X

SUBSYSTEM NAME: ELECTRICAL POWER DISTRIBUTION & CONTROL

REVISION: 7 05/26/94

	PART NAME VENDOR NAME	PART NUMBER VENDOR NUMBER
LRU	: AFT PCA 4, 5, 6	VO70-765280
SRU	: FUSE, HIGH CURRENT	ME451-0016-2150

PART DATA

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:
FUSE F3, 150 AMP, HIGH CURRENT - LOCATED IN AFT PCA 6

REFERENCE DESIGNATORS: 56V76A136F3

QUANTITY OF LIKE ITEMS: 1
ONE

FUNCTION:
CONDUCTS ORBITER MAIN BUS C CURRENT AND PROVIDES OVERCURRENT
PROTECTION FROM AFT POWER CONTROLLER ASSEMBLY (APCA) 6 TO APCA 3.

FAILURE MODES EFFECTS ANALYSIS (FMEA) - CRITICAL FAILURE MODE
NUMBER: 05-6-2010C - 01

REVISION# 7 05/26/94

SUBSYSTEM NAME: ELECTRICAL POWER DISTRIBUTION & CONTROL

LRU: AFT PCA 4, 5, 6

ITEM NAME: FUSE, HIGH CURRENT

CRITICALITY OF THIS

FAILURE MODE: 1R2

FAILURE MODE:

FAILS OPEN, FAILS TO CONDUCT

MISSION PHASE:

LO LIFT-OFF

VEHICLE/PAYLOAD/KIT EFFECTIVITY:

102	COLUMBIA
103	DISCOVERY
104	ATLANTIS
105	ENDEAVOUR

CAUSE:

STRUCTURAL FAILURE, CONTAMINATION, VIBRATION, MECHANICAL SHOCK,
 PROCESSING ANOMALY, THERMAL STRESS

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

REDUNDANCY SCREEN

A) PASS
B) PASS
C) PASS

PASS/FAIL RATIONALE:

A)

A SCREEN PASSES BECAUSE FUSE FAIL OPEN IS DETECTABLE DURING GROUND
 TURNAROUND TEST

B)

B SCREEN PASSES BECAUSE FUSE FAIL OPEN IS DETECTABLE DURING FLIGHT FROM
 AVAILABLE MEASUREMENT INDICATION

C)

C SCREEN PASSES BECAUSE REDUNDANT FUSES ARE PHYSICALLY ISOLATED FROM
 EACH OTHER

- FAILURE EFFECTS -

(A) SUBSYSTEM:

INABILITY TO CONDUCT ORBITER MAIN BUS C POWER FROM APCA 6 TO APCA 3

(B) INTERFACING SUBSYSTEM(S):

LOSS OF POWER REDUNDANCY TO FOUR SRB-RGA'S (1, 2, 3 AND 4).

(C) MISSION:

NO EFFECT - FIRST FAILURE

FAILURE MODES EFFECTS ANALYSIS (FMEA) - CRITICAL FAILURE MODE
NUMBER: 05-6-2010C - 01

(D) CREW, VEHICLE, AND ELEMENT(S):
 NO EFFECT - FIRST FAILURE

(E) FUNCTIONAL CRITICALITY EFFECTS:
 POSSIBLE LOSS OF CREW/VEHICLE AFTER TWO FAILURES:

FIRST FAILURE (FUSE OPENS) WOULD CAUSE LOSS OF BACK UP POWER FROM ORBITER MAIN BUS C TO FOUR SRB-RGA'S.

SECOND FAILURE (FAILING OPEN OF FUEL CELL NO. 2 MOTOR DRIVEN POWER CONTACTOR) CAUSES LOSS OF PRIMARY POWER FROM ORBITER MAIN BUS A. THIS WOULD CAUSE SIMULTANEOUS TOTAL LOSS OF POWER TO SRB-RGA'S 2, 3, AND 4 RESULTING IN LOSS OF THREE OF FOUR SRB-RGA'S.

-DISPOSITION RATIONALE-

(A) DESIGN:
 REFER TO APPENDIX D, ITEM NO. 3 - FUSE, HIGH CURRENT

(B) TEST:
 REFER TO APPENDIX D, ITEM NO. 3 - FUSE, HIGH CURRENT

GROUND TURNAROUND TEST
 ANY GROUND TURNAROUND CHECKOUT TESTING IS ACCOMPLISHED IN ACCORDANCE WITH OMRSD.

(C) INSPECTION:
 REFER TO APPENDIX D, ITEM NO. 3 - FUSE, HIGH CURRENT

(D) FAILURE HISTORY:
 FAILURE HISTORY IS TRACKED IN THE PRACA SYSTEM.

(E) OPERATIONAL USE:
 NONE

- APPROVALS -

PAE MANAGER : K. PRESTON
 PRODUCT ASSURANCE ENGR : T. KIMURA
 DESIGN ENGINEERING : J. GULSBY
 NASA SSMA :
 NASA SUBSYSTEM MANAGER :

K.L. Preston 6/2/94
T. Kimura 6/2/94
J. Gulsby 6/2/94
For NASA 4-11-95
For Flight Act 4-11-95