

SHUTTLE CRITICAL ITEMS LIST - ORBITER

SUBSYSTEM :ELECT POWER DIST & CONT FMEA NO 05-6 -2704 -1 REV:05/03/88

ASSEMBLY :PANEL MA73C CRIT.FUNC: 1R  
P/N RI :RWR80S1211FR CRIT. HDW: 2  
P/N VENDOR:  
QUANTITY :2 VEHICLE 102 103 104  
EFFECTIVITY: X X X  
PHASE(S): PL LC X OO X DO X LS  
: TWO

PREPARED BY: REDUNDANCY SCREEN: A-PASS B-PASS C-PASS  
DES R PHILLIPS APPROVED BY: APPROVED BY (NASA):  
REL M HOVE SSM *J.C. Stary 5/12/88*  
QE J COURSEN REL *W. J. Courson 5/6/88* QE *D. J. ... 5/6/88*

ITEM:

RESISTOR, CURRENT LIMIT, WIRE WOUND, 1.2K OHM - MID MCA 3 AND 2 DC BUS A AND C CONTROL CIRCUIT

FUNCTION:

PROVIDES CURRENT LIMITING/CIRCUIT PROTECTION FOR THE CONTROL CIRCUITS FOR DC BUSES A AND C RELAY LOGIC POWER INPUTS TO MIDBODY MOTOR CONTROL ASSEMBLY #3 AND #2 FOR VENT DOOR, PAYLOAD BAY DOOR LATCH, RADIATOR DEPLOY/LATCH, REMOTE MANIPULATOR LATCH AND KU-BAND ANTENNA STOW/DEPLOY MOTORS. 85V73A129A1R3 AND A4R2

FAILURE MODE:

OPEN

CAUSE(S):

STRUCTURAL FAILURE (VIBRATION, MECHANICAL STRESS), THERMAL STRESS, ELECTRICAL STRESS, PROCESSING ANOMALY

EFFECT(S) ON:

(A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE (E) FUNCTIONAL CRITICALITY EFFECT:

(A) LOSS OF ONE OF TWO MAIN DC BUS RELAY LOGIC POWER INPUTS TO THE ASSOCIATED MID MOTOR CONTROL ASSEMBLY.

(B) LOSS OF INTERFACE REDUNDANCY. NO EFFECT FOR FIRST FAILURE - THE REDUNDANT MOTOR CONTROLLED THROUGH A DIFFERENT RESISTOR COMPLETES THE FUNCTION.

(C) POSSIBLE EARLY MISSION TERMINATION DUE TO LOSS OF REDUNDANCY FOR LATCHING PAYLOAD BAY DOOR CENTERLINE LATCHES.

(D) FIRST FAILURE - NO EFFECT.

SHUTTLE CRITICAL ITEMS LIST - ORBITER

UBSYSTEM :ELECT POWER DIST & CONT FMEA NO 05-6 -2704 -1 REV:05/03/88

EFFECT(S) ON (CONTINUED):

(A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE (E)FUNCTIONAL  
CRITICALITY EFFECT:

(E) POSSIBLE LOSS OF CREW/VEHICLE AFTER SECOND FAILURE (LOSS OF  
REDUNDANT MOTOR OR POWER/CONTROL CIRCUIT) DUE TO INABILITY TO LATCH  
PAYLOAD BAY DOORS (RESULTING IN AERODYNAMIC STRUCTURAL DAMAGE DURING  
ENTRY) AND/OR TO OPEN VENT DOORS DURING DESCENT (DOOR FAILED CLOSED  
RESULTS IN VEHICLE STRUCTURAL DAMAGE DUE TO PRESSURE DIFFERENTIALS).  
LEFT AND RIGHT VENT DOORS ARE NOT CONSIDERED TO BE REDUNDANT TO EACH  
OTHER. "B" SCREEN PASSES SINCE THE FAILURE CAN BE DETECTED BY CREW  
MONITORING MECHANISM OPERATION TIMES OR BY LOSS OF MCA OPERATIONAL  
STATUS MEASUREMENTS AVAILABLE TO GROUND PERSONNEL.

DISPOSITION & RATIONALE:

(A)DESIGN (B)TEST (C)INSPECTION (D)FAILURE HISTORY (E)OPERATIONAL USE

A,B,C,D) DISPOSITION AND RATIONALE

REFER TO APPENDIX E, ITEM NO. 3 - RESISTOR, WIRE WOUND

3) GROUND TURNAROUND TEST

VERIFY MCA OPERATIONAL STATUS INDICATORS ARE "ON" (ALL MOTOR CONTROL  
RELAYS RESET) DURING NO OPERATION OF THE AC MOTOR MECHANISMS. TEST IS  
PERFORMED FOR ALL FLIGHTS.

4) OPERATIONAL USE

CONSIDERATION WILL BE GIVEN TO STOWING MECHANISMS WITH THE LOSS OF  
REDUNDANCY. LOSS OF REDUNDANCY FOR CLOSING CENTERLINE PLBD LATCHES  
INVOKES A MINIMUM DURATION FLIGHT. FOR LOSS OF REDUNDANT VENT DOOR  
OPEN CAPABILITY, OPEN VENT DOORS PRIOR TO ENTRY.