

PAGE: 1

PRINT DATE: 05/17/90

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL HARDWARE
 NUMBER: 05-6EB-2000-X

SUBSYSTEM NAME: EPD&C - PAYLOAD BAY DOORS

REVISION : 2 05/16/90

	PART NAME VENDOR NAME	PART NUMBER VENDOR NUMBER
LRU :	PANEL R13A2	V070-730338
■ SRU :	RESISTOR	RHR80S1211FR

 PART DATA

- EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:
 RESISTOR, WIRE WOUND (1.2K) - PAYLOAD BAY DOOR (PLBD) CONTROL

REFERENCE DESIGNATORS: 32V73A13A2A1R1
 : 32V73A13A2A1R2
 : 32V73A13A2A1R3

- QUANTITY OF LIKE ITEMS: 3
 THREE, ONE PER CONTROL BUS (AB1, BC1, & BC2)
- FUNCTION:
 LIMITS CURRENT BETWEEN CONTROL BUSES AND MDM'S FOR CONTROL OF PAYLOAD BAY DOORS OPENING AND CLOSING FUNCTIONS.

PAGE: 2

PRINT DATE: 05/17/90

1367

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL FAILURE MODE

NUMBER: 05-6EB-2000-01

SUBSYSTEM: EPD&C - PAYLOAD BAY DOORS
LRU :PANEL R13A2
ITEM NAME: RESISTOR

REVISION# 2 05/16/90 R

CRITICALITY OF THIS
FAILURE MODE:1R3

FAILURE MODE:
OPEN

MISSION PHASE:

OO ON-ORBIT
DO DE-ORBIT

VEHICLE/PAYLOAD/KIT EFFECTIVITY: 102 COLUMBIA
: 103 DISCOVERY
: 104 ATLANTIS

CAUSE:

STRUCTURAL FAILURE (MECHANICAL STRESS, VIBRATION), ELECTRICAL STRESS,
THERMAL STRESS, PROCESSING ANOMALY

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

REDUNDANCY SCREEN A) PASS
B) FAIL
C) PASS

PASS/FAIL RATIONALE:

A)

B)

FIRST FAILURE NOT DETECTABLE IN FLIGHT SINCE: 1) OPERATIONAL STATUS OF
THIS RESISTOR IS NOT MONITORED, AND 2) THERE WILL BE NO FUNCTIONAL
EFFECT UNTIL SECOND FAILURE OCCURS AND CAUSES LOSS OF COMPUTER/MDM
COMMANDS.

C)

- FAILURE EFFECTS -

(A) SUBSYSTEM:

FIRST FAILURE - LOSS OF POWER IN ONE OF THREE CONTROL CIRCUITS FOR
PLBDS

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL FAILURE MODE
NUMBER: 05-6EB-2000-01

- (B) INTERFACING SUBSYSTEM(S):
FIRST FAILURE - LOSS OF REDUNDANCY. TWO OF THREE POWER SOURCES ARE REQUIRED TO ENABLE COMPUTER/MDM COMMANDS FOR CONTROL OF PLBD OPERATIONS.
- (C) MISSION:
FIRST FAILURE - NO EFFECT
- (D) CREW, VEHICLE, AND ELEMENT(S):
FIRST FAILURE - NO EFFECT
- (E) FUNCTIONAL CRITICALITY EFFECTS:
POSSIBLE LOSS OF MISSION AND/OR CREW/VEHICLE THROUGH LOSS OF ALL PLBD CONTROL CAPABILITY. FAILURE TO OPEN PLBD WOULD RESULT IN LOSS OF MISSION (2R3). FAILURE TO CLOSE PLBD WOULD RESULT IN UNSAFE CONFIGURATION FOR ENTRY (1R3). REQUIRES TWO OTHER FAILURES (REDUNDANT RESISTOR FAILS OPEN, LOSS OF KEYBOARD WORKAROUND CAPABILITY) BEFORE EFFECT IS MANIFESTED.

- DISPOSITION RATIONALE -

- (A) DESIGN:
REFER TO APPENDIX E, ITEM NO. 3 - RESISTOR
 - (B) TEST:
REFER TO APPENDIX E, ITEM NO. 3 - RESISTOR
- GROUND TURNAROUND TEST
VERIFY CONTROL BUS PATHS BY ACTIVATING ALL CONTROL BUSES, COMMANDING PAYLOAD BAY DOOR SWITCH, AND OBSERVING SWITCH SCAN DATA. TESTS ARE PERFORMED EVERY FLIGHT AND LRU RETEST PER TABLE V37Z00.000.
- (C) INSPECTION:
REFER TO APPENDIX E, ITEM NO. 3 - RESISTOR
 - (D) FAILURE HISTORY:
REFER TO APPENDIX E, ITEM NO. 3 - RESISTOR
 - (E) OPERATIONAL USE:
NO ACTION IS REQUIRED FOR THE FIRST FAILURE. SOFTWARE BYPASS IS AVAILABLE IF HARDWARE SWITCH FAILS. EVA CAPABILITY EXISTS TO CLOSE PAYLOAD BAY DOORS AFTER MULTIPLE FAILURES.

FAILURE MODES EFFECTS ANALYSIS (FMEA) — CRITICAL FAILURE MODE
NUMBER: 05-6EB-2000-01

- APPROVALS -

RELIABILITY ENGINEERING: T. AI
DESIGN ENGINEERING : T. BANHIDY
QUALITY ENGINEERING : W. R. HIGGINS
NASA RELIABILITY :
NASA SUBSYSTEM MANAGER :
NASA QUALITY ASSURANCE :
NASA EPDTC SUBSYS MGR
NASA EPDTC Reliability

: TA McManis 4/24/90
: [Signature]
: [Signature]
: [Signature]
: K.M. Balasubramanian 8/23/90
: [Signature] 1/11/90
: [Signature] for F. Higgins 21 Aug 90
: L. David Capps 8/24/90
: for J. Woodard