PAGE: 1

PRINT DATE: 05/22/91

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL HARDWARE

NUMBER: 05-6ED-2251A-X

SUBSYSTEM NAME: EPD&C - ET UMBILICAL DOORS

REVISION	;	4	05/21/91
----------	---	---	----------

			•
		PART NAME VENDOR NAME	PART NUMBER VENDOR NUMBER
LÆU	:	AFT MCA-1	V070-765410
LRU	:	AFT MCA-2	V070-765420
LRU	:	AFT MCA-3	V070-765430
LRU	:	AFT MCA-3	V070-765600
LRU	: .	AFT MCA-2	V070-765620
LRU	:	AFT MCA-1	V070-755630
SRU	:	30010	JANTXV1N4246
		PART DATA	
		TOTAL DATE	

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS: DIODE, ISOLATION

REFERENCE DESIGNATORS: 54V76A114A2CR38

: 54V76A114A2CR38 : 54V76A114A2CR51 : 54V76A114A2CR52 : 55V76A115A1CR80 : 55V76A115A1CR81 : 56V76A116A2CR39

56V76A116A2CR40

QUANTITY OF LIKE ITEMS: 8

EIGHT

PROVIDES AND ISOLATES REDUNDANT POWER PATH TO CENTERLINE LATCH HYBRID RELAY (STOW) FOR USE DURING MANUAL MODE OPERATION. ALSO, ISOLATES THE LOGIC POWER FROM THE CONTROL POWER, WHICH IS CONTINUOUSLY SUPPLIED BY A DC BUS, TO PREVENT AN INADVERTENT STOW OPERATION OF THE CENTERLINE LATCH.

PAGE: 2		,				PRINT DATE: 05/22	/91
FAILURE MODE	S EFFECTS	AKALY\$1\$	(FME	'A)	CRITICAL FAIL NUMBE	URE MODE R: 05-6ED-2251A-02	
SUBSYSTEM:	FPOAC ~	ET LIMATO	TAI	nnoes	REVISION#	4 05/21/91 R	
LRU :AFT M ITEM NAME:	CA-1 DIODE		-			CRITICALITY OF T FAILURE MODE:1	
FAILURE MOI SHORT (END	DE:						
MISSION PHU LO DO	LIFT-OFF						
VEHICLE/PAY	/LOAD/KIT	EFFECTIVE	:	103 104	COLUMBIA DISCOVERY ATLANTIS ENDEAVOUR		
CAUSE: STRUCTURAL ELECTRICAL	FAILURE (MECHANICA HERMAL ST	L STI	RESS, , PROC	VIBRATION), CO ESSING ANOMALY	ONTAMINATION.	
CRITICALITY	/ 1/1 OURI	NG INTACT	ABO	RT ONL	Y? NO		
REDUNDANCY	SCREEN A)				·	·	
PASS/FAIL 9	PATIONALE:						
8)							
C)					•	.5	
	·					·	
		• FAI			TS -		
(A) SUBSYST FIRST FAILU LATCH		GIZES ONE	OF T	WO SEI		STOW A CENTERLINE	
(6) INTERFA	CING SUBS	YSTEM(S):					

PAGE: 3

PRINT DATE: 05/22/91

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL FAILURE MODE
NUMBER: 05-6ED-2251A-02

(C) MISSION: FIRST FAILURE - NO EFFECT

(0) CREW, VEHICLE, AND ELEMENT(S): FIRST FAILURE - NO EFFECT

(E) FUNCTIONAL CRITICALITY EFFECTS:
AFTER SECOND FAILURE (REDUNDANT DIDDE SHORTS END-TO-END), LOSS/DAMAGE
OF DOOR COULD OCCUR DUE TO PREMATURE STOWING (RELEASING) ONE OF TWO
CENTERLINE LATCHES DURING ASCENT WHICH WOULD SUBJECT THE LESS
RESTRAINED ET DOORS TO THE BOOST ENVIRONMENT OF VIBRATION AND
ATMOSPHERIC WINDAGE. POSSIBLE LOSS OF CREW/VEHICLE DUE TO STRUCTURAL
DAMAGE CAUSED BY THERMAL EFFECTS DURING RE-ENTRY.

- DISPOSITION RATIONALE -

(A) DESIGN:
REFER TO APPENDIX F. ITEM NO. 3 - DIODE

■ (8) TEST: REFER TO APPENDIX F, ITEM NO. 3 - DIODE

GROUND TURNAROUND TEST
PROPER DIODE FUNCTION IS VERIFIED THROUGH ET DOOR CENTERLINE LATCH
UNLOCK/STON MOTOR I & 2 (MANUAL) TEST. MCA OPERATIONAL STATUS IS
VERIFIED ON WHEN NO STON COMMANDS ARE GIVEN. TESTS ARE PERFORMED INFLIGHT AND LRU RETEST PER TABLE V56Z00.000.

- (C) INSPECTION:
 REFER TO APPENDIX F. ITEM NO. 3 DIODE
 - (0) FAILURE HISTORY: REFER TO APPENDIX F, ITEM NO. 3 DIODE
 - (E) OPERATIONAL USE:

U.S. Govit

PAGE: 4

PRINT DATE: 05/22/91

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL FAILURE MODE

NUMBER: 05-6ED-2251A-02

- APPROVALS -

RELIABILITY ENGINEERING: T. AI

DESIGN ENGINEERING : T. POCKLINGTON

QUALITY ENGINEERING : W. R. HIGGINS

NASA RELIABILITY

NASA SUBSYSTEM MANAGER:

NASA EPOSC RELIABILITY :

NASA QUALITY ASSURANCE :

NASA EPO&C SUBSYS MGR :

... III

1. W. Ladder 7.5.91

KO Frent Amber 1/8/72