

**FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL HARDWARE****NUMBER: 05-6J-2056A -X****SUBSYSTEM NAME:** EPD&C - MAIN PROPULSION SYSTEM**REVISION:** 1 08/03/00

---

**PART DATA**

---

	<b>PART NAME</b>	<b>PART NUMBER</b>
	<b>VENDOR NAME</b>	<b>VENDOR NUMBER</b>
LRU	: AFT LCA 2	MC450-0058-0001
SRU	: DIODE	JANTXV1N5551

---

**EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:**

DIODE, BLOCKING (3 AMP) - LH2 OUTBOARD FILL/DRAIN VALVE, MANUAL SWITCH OPEN COMMAND/GROUND OPEN COMMAND.

**REFERENCE DESIGNATORS:** 55V76A122CRJ3(61)**QUANTITY OF LIKE ITEMS:** 1**FUNCTION:**

ISOLATES THE MDM OPEN COMMAND FROM THE MANUAL SWITCH OPEN POSITION. CONDUCTS MANUAL SWITCH OPEN COMMAND AND GROUND OPEN COMMAND TO THE HDC FOR CONTROL OF POWER TO OPEN SOLENOID OF LH2 OUTBOARD FILL/DRAIN VALVE.

**FAILURE MODES EFFECTS ANALYSIS FMEA -- CIL FAILURE MODE**

**NUMBER: 05-6J-2056A-01**

**REVISION#:** 1 08/16/00

**SUBSYSTEM NAME:** EPD&C - MAIN PROPULSION SYSTEM

**LRU:** AFT LCA-2

**CRITICALITY OF THIS**

**ITEM NAME:** LH2 O/B F/D VLV OPEN CMD BLK DIODE (PV11)

**FAILURE MODE:** 1R3

---

**FAILURE MODE:**

OPEN, FAILS OPEN, FAILS TO CONDUCT

**MISSION PHASE:** LO LIFT-OFF

<b>VEHICLE/PAYLOAD/KIT EFFECTIVITY:</b>	102	COLUMBIA
	103	DISCOVERY
	104	ATLANTIS
	105	ENDEAVOUR

**CAUSE:**

PIECE PART STRUCTURAL FAILURE, MECHANICAL SHOCK, VIBRATION, THERMAL STRESS

**CRITICALITY 1/1 DURING INTACT ABORT ONLY?** NO

---

<b>REDUNDANCY SCREEN</b>	A) PASS
	B) FAIL
	C) PASS

**PASS/FAIL RATIONALE:**

A)

B)

DIODE FAILS BE SCREEN SINCE MDM OPEN COMMAND AND GROUND OPEN COMMAND ARE LOAD SHARING AND CANNOT BE DISTINGUISHED.

C)

---

**- FAILURE EFFECTS -**

---

**(A) SUBSYSTEM:**

NO EFFECT FIRST FAILURE. REDUDANT MDM OPEN COMMAND WILL MAINTAIN OPEN SOLENOID POWER.

**(B) INTERFACING SUBSYSTEM(S):**

SAME AS A.

**FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL FAILURE MODE  
NUMBER: 05-6J-2056A-01**

**(C) MISSION:**  
SAME AS A.

**(D) CREW, VEHICLE, AND ELEMENT(S):**  
SAME AS A.

**(E) FUNCTIONAL CRITICALITY EFFECTS:**  
1R/3 3 SUCCESS PATHS. TIME FRAME – ASCENT.  
1) DIODE FAILS OPEN.  
2) LOSS OF OPEN MDM COMMAND RESULTING IN OPEN SOLENOID (LV32)  
DEACTUATION. BISTABLE FEATURE MAINTAINS FILL/DRAIN VALVE IN OPEN  
POSITION.  
3) PREMATURE ACTUATION OF CLOSE SOLENOID (LV33) RESULTING IN PREMATURE  
CLOSURE OF LH2 OUTBOARD FILL/DRAIN VALVE.

RESULTS IN TERMINATION OF PROPELLANT LOADING OR DETANKING WHICH MAY CAUSE A  
PRESSURE SPIKE AND POSSIBLE RUPTURE OF ORBITER FILL LINE, FEED LINE AND/OR GSE  
INTERFACE/FACILITY LINES. POSSIBLE AFT COMPARTMENT OVERPRESSURIZATION AND  
FIRE/EXPLOSION HAZARD. POSSIBLE LOSS OF ADJACENT CRITICAL FUNCTIONS DUE TO  
CRYO EXPOSURE.

REF. CIL 03-1-0302-06.

---

**-DISPOSITION RATIONALE-**

---

**(A) DESIGN:**  
REFER TO APPENDIX F, ITEM NUMBER 4 - DIODE.

**(B) TEST:**  
REFER TO APPENDIX F, ITEM NUMBER 4 - DIODE.

GROUND TURNAROUND TEST  
ANY TURNAROUND CHECKOUT IS ACCOMPLISHED IN ACCORDANCE WITH OMRSD.

**(C) INSPECTION:**  
REFER TO APPENDIX F, ITEM NUMBER 4 - DIODE.

**(D) FAILURE HISTORY:**  
REFER TO APPENDIX F, ITEM NUMBER 4 - DIODE.

**FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL FAILURE MODE  
NUMBER: 05-6J-2056A-01**

CURRENT DATA ON TEST FAILURE, FLIGHT FAILURE, UNEXPLAINED ANOMALIES, AND OTHER FAILURES EXPERIENCED DURING GROUND PROCESSING ACTIVITY CAN BE FOUND IN THE PRACA DATABASE.

**(E) OPERATIONAL USE:**  
NO CREW ACTION CAN BE TAKEN.

---

**- APPROVALS -**

---

S&R ENGINEERING	: W. P. MUSTY	:/S/ W.P. MUSTY
S&R ENGINEERING ITM	: P. A. STENGER-NGUYEN	:/S/ P.A. STENGER-NGUYEN
DESIGN ENGINEERING	: ANDY RIZVI	:/S/ ANDY RIZVI
MPS SYBSYSTEM MGR.	: TIM REITH	:/S/ TIM REITH
EPD&C SUBSYSTEM MGR.	: R. L. PHAN	:/S/ RICHARD PHAN
MOD	: WILLIAM LANE	:/S/ WILLIAM LANE
USA SAM	: MICHAEL SNYDER	:/S/ MICHAEL SNYDER
USA ORBITER ELEMENT	: SUZANNE LITTLE	:/S/ SUZANNE LITTLE
NASA SR&QA	: BILL PRINCE	:/S/ BILL PRINCE