5RB CRITICAL ITEMS LIST

SUBSYSTEM: ELECTRICAL AND INSTRUMENTATION

ITEM NAME: SRB OF Waterlight Reusable Cable X02W4R J1/P2, X02W6R J1/P2, X02W10R J1/P2 and

X02W11R J1/P2 or SRB OF Throwaway Cable X02W4 31/P2, X02W6 J1/P2, X02W10 J1/P2, and

X02W11 J1/P2. (TVC A. B. C. D Rock Position Commands and Delta Ps)

PART NO.: 10400-0006, 10400-0656 FM CODE: A07, A08, A09, A10

10400-0008, 10400-0658 10400-0011, 10400-0661 10400-0012, 10400-0662

ITEM CODE: 50-04-X02 REVISION: Basic

CRITICALITY CATEGORY: IR REACTION TIME: Immediate

NO. REQUIRED: 1 each DATE: March 1, 1995

CRITICAL PHASES: Boost SUPERCEDES: March 1, 1994

FMEA PAGE NO.: D-636, D-638, D-639, D-641 ANALYST: R. Smith/A. Craft

SHEET 1 OF 3 APPROVED: P. Kalia

FAILURE MODE AND CAUSES: (a) Loss of three of four Rock/Tilt position commands and/or secondary DP in three out of four cables due to: or (b) loss of two of four Rock/Tilt position commands and or Secondary DP two out of four connectors simultaneously due to:

For (a);

- One pin or wire open caused by: open solder, open wire, broken/bent pin, corroded pin.
- One pin or wire short to ground caused by: bent pin, contamination in connector, insulation breakdown, frayed shielding, abraded or cut insulation.
- Loss of connector caused by: connector not fully mated, improperly safety wired, improperly torqued, defective threads, mechanical overstress.
- o For (b):
- Two pins or wires open caused by: open solder, open wire, broken/bent pin, corroded pin.
 - Two pins or wires short to ground caused by: bent pin, contamination in connector, insulation breakdown, frayed shielding, abraded or cut insulation.

DR Document: RA-21

FM Code: 50-04-X02-A07, A08, A09, A10

FAILURE EFFECT SUMMARY: Loss of three of four Position commands and/or secondary DP in three out of four cables or two of four Position commands simultaneously to Rock actuator resulting in loss of TVC leading to loss of mission, vehicle and crew. Two success paths remain after the first failure. Operation is not affected until all three paths are lost except in the case of simultaneous loss.

Date: March 1, 1995

REDUNDANCY SCREENS AND MEASUREMENTS:

- 1) Pass All cables are system tested during ground turnaround sequence.
- 2) Pass Rock A, B, C, and D secondary delta pressure measurements B58P1311A through B58P1314A.
- Pass No credible causes.

RATIONALE FOR RETENTION:

- A. DESIGN Per Appendix A Section # [& III
- B. TESTING
 - 1) VENDOR RELATED Per Appendix B Section # IA & IB
 - 2) KSC RELATED Per Appendix B Section # IIA
 - SYSTEM UNIQUE FUNCTIONAL

Cables are tested during Assembly Checkout Operations (ACO) (Actua- tor Null, Linearity, and Potarity) per 10REQ-0021, para. 2.3.14.1. (Open, Short or Loss of Connector)

Cables are again tested during hottire operations per IOREQ-0021, para. 2.3.16.

After transfer to SPC, Cables are tested during Shuttle flight control integration test per OMRSD File II, Vol. 1, requirement numbers \$00000.650, .670, .680, .720, and .750 (SRH Actuator Tests).

The last time cables are tested is during final countdown per OMRSD File II, Vol. 1, requirement number S00FS0.030 (SRB Gimbal Test). (Open, Short or Loss of Connector)

50 - 194

Supercedes: March 1, 1994 DR Document: RA-21

FM Code: 50-04-X02-A07, A08, A09, A10

March 1, 1994

C. INSPECTION

- 1) VENDOR RELATED Per Appendix C Section # [(Soldered Connector)
- 2) KSC RELATED Per Appendix C Section # HA
- D FAILURE HISTORY

Failure Histories may be obtained from the PRACA database.

E. OPERATIONAL USE

Not applicable to this failure mode.

Supercedes: March 1, 1994 DR Document: RA-21