

**SSME FFA/CIL
REDUNDANCY SCREEN**

Component Group: Fuel Turbopumps
 CIL Item: B600-04
 Part Number: RS007801
 Component: Low Pressure Fuel Turbopump
 FMEA Item: B600
 Failure Mode: Loss of head rise.

Prepared: F. Cromwell
 Approved: T. Nguyen
 Approval Date: 11/1/99
 Change #: 1
 Directive #: CCBD ME3-01-5249

Page: 1 of 1

Phase	Failure / Effect Description	Criticality Hazard Reference
S 4.1	<p>Reduced LPFTP pump output results in reduced pressure and flow delivered to the HPFTP. The controller senses the increased HPFTP demand and increases the fuel preburner oxidizer flow. In the event of HPFTP cavitation, excessive turbine discharge temperatures may result in a premature engine shutdown. Mission scrub if detected by redline. Loss of vehicle due to HPFTP turbine failure may result if not detected.</p> <p>Redundancy Screens: TURBOPUMP SYSTEM - SENSOR SYSTEM: UNLIKE REDUNDANCY</p> <p>A: Pass - Redundant hardware items are capable of checkout during normal ground turnaround. B: Pass - Loss of a redundant hardware items is detectable during flight. C: Pass - Loss of redundant hardware items could not result from a single credible event.</p>	1R ME-D1S,M
M 4.1	<p>Reduced LPFTP pump output results in reduced pressure and flow delivered to the HPFTP. The controller senses the increased HPFTP demand and increases the fuel preburner oxidizer flow. In the event of HPFTP cavitation, excessive turbine discharge temperatures may result in a premature engine shutdown. Mission abort if detected by redline. Loss of vehicle due to HPFTP turbine failure may result if not detected.</p> <p>Redundancy Screens: TURBOPUMP SYSTEM - SENSOR SYSTEM: UNLIKE REDUNDANCY</p> <p>A: Pass - Redundant hardware items are capable of checkout during normal ground turnaround B: Pass - Loss of a redundant hardware items is detectable during flight. C: Pass - Loss of redundant hardware items could not result from a single credible event.</p>	1R ME-D1S,M

B - 547

**SSME FMEA/CIL
DESIGN**

Component Group: Fuel Turbopumps
CIL Item: B600-04
Part Number: RS007601
Component: Low Pressure Fuel Turbopump
FMEA Item: B600
Failure Mode: Loss of head rise.

Prepared: F. Cromwell
Approved: T. Nguyen
Approval Date: 11/1/99
Change #: 1
Directive #: CCBD ME3-01-5249

Page: 1 of 1

Design / Document Reference

FAILURE CAUSE: A: Fracture, distortion of inducer vane.

THE PUMP INDUCER (1) INCORPORATES FOUR FULL VANES AND FOUR LONG PARTIAL VANES WHICH ARE HYDRODYNAMICALLY SHAPED TO PROVIDE THE REQUIRED HEAD RISE TO THE HPFTP PUMP INLET AND MEET THE ICD MINIMUM NET POSITIVE SUCTION PRESSURE (NPSP) REQUIREMENTS. THE INDUCER WAS DESIGNED TO MAINTAIN A CONTROLLED OPERATING CLEARANCE WITH THE PUMP HOUSING (2) TO MAXIMIZE PUMP EFFICIENCY. THE INDUCER IS MATED TO THE SHAFT (3) BY INVOLUTE SPLINES. A RETAINING NUT (4) IS INSTALLED AND LOCKED (5) TO SECURE THE INDUCER. THE INDUCER HUB PROVIDES JOURNALS FOR THE TURBINE-END (6) AND PUMP-END BEARINGS (7). FOUR HOLES LOCATED IN THE INDUCER HUB NEAR THE VANE LEADING EDGES ALLOW THE BEARING COOLANT TO RETURN TO THE MAIN FLOW STREAM. THE INDUCER VANE FILLETS ARE RADIUSSED TO REDUCE STRESS RISERS. THE INDUCER IS MANUFACTURED UTILIZING FORGED 5AL-2.5SN (ELI) TITANIUM ALLOY (8). THIS MATERIAL WAS SELECTED FOR ITS TOUGHNESS AND MECHANICAL AND FATIGUE PROPERTIES AT CRYOGENIC TEMPERATURES. THIS ALLOY IS NOT SUSCEPTIBLE TO HYDROGEN ENVIRONMENT EMBRITTLEMENT AT OPERATING TEMPERATURES. THE MATERIAL IS ANNEALED TO IMPROVE PROPERTIES. THE ROTATING ASSEMBLY HAS BEEN DESIGN VERIFICATION TESTED FOR VIBRATION CHARACTERISTICS (9). THE INDUCER HAS BEEN DESIGN VERIFICATION TESTED FOR VIBRATION CHARACTERISTICS (10).

(1) RS007604 (2) RS007632 R0019854; (3) RS007628; (4) RSC07619; (5) RS007620; (6) RS007606; (7) RS007605; (8) RSS-8577; (9) RSS-402; (10) RSS-402

FAILURE CAUSE: B: Fracture, distortion of diffuser vane.

THE HOUSING VOLUTE (1) HAS 13 DIFFUSER VANES TO GUIDE THE FLOW FROM THE INDUCER TUNNEL INTO THE VOLUTE. THE DIFFUSER VANE FILLETS ARE RADIUSSED TO REDUCE STRESS RISERS. THE PUMP VOLUTE IS MANUFACTURED UTILIZING CAST TENS-50 ALUMINUM (2), WHICH WAS SELECTED FOR ITS MECHANICAL PROPERTIES AT CRYOGENIC TEMPERATURES, AND RESISTANCE TO HYDROGEN ENVIRONMENT EMBRITTLEMENT. THE CASTING IS HOT ISOSTATICALLY PRESSED TO IMPROVE MECHANICAL PROPERTIES. THE MATERIAL IS ALSO SOLUTION TREATED AND AGE HARDENED. THE VOLUTE IS ANODIZED FOR CORROSION PROTECTION. THE VOLUTE IS PROOF PRESSURE TESTED TO VERIFY ITS STRUCTURAL INTEGRITY (3). THE FACTOR OF SAFETY ON BURST AND LOW CYCLE FATIGUE LIFE HAS BEEN DEMONSTRATED BY DESIGN VERIFICATION TESTING (4).

(1) R0019854; (2) RSS-8577; (3) RL00408; (4) RSS-402

FAILURE CAUSE: ALL CAUSES

THE HIGH AND LOW CYCLE FATIGUE LIFE FOR THE INDUCER AND VOLUTE HOUSING MEET CEI REQUIREMENTS (1). THE MINIMUM FACTORS OF SAFETY FOR THESE PARTS MEET CEI REQUIREMENTS (2). THE LPFTP INDUCER AND VOLUTE HOUSING PARENT MATERIALS WERE CLEARED FOR FRACTURE MECHANICS/INDE FLAW GROWTH BY CRITICAL INITIAL FLAW SIZE DETECTABILITY (3). THE CONTROLLER SOFTWARE IS CONFIGURED TO DETECT AND RESPOND PROPERLY TO THE FAILURES IDENTIFIED AND COMMAND A SAFE ENGINE STATE (4). REUSE OF PARTS DURING OVERHAUL IS CONTROLLED BY THE REQUIREMENTS OF THE OVERHAUL SPECIFICATION (5).

(1) RL00532 CP320R0003B; (2) RSS-8546, CP320R0003B; (3) NASA TASK 117; (4) CP406R0002 PT 1 3 2.3 5.3; (5) RL00531

B - 548

**SSME FMF OIL
INSPECTION AND TEST**

Component Group: Fuel Turbopumps
 CIL Item: B600 04
 Part Number: RS007601
 Component: Low Pressure Fuel Turbopump
 FMEA Item: B630
 Failure Mode: Loss of head rise.

Prepared: F. Cronwell
 Approved: T. Nguyen
 Approval Date: 11/1/99
 Change #: 1
 Directive #: CCBD ME3-01-5248

Page: 1 of 2

B - 549

Failure Causes	Significant Characteristics	Inspection(s) / Test(s)	Document Reference
A	INDUCER		RS007604
	MATERIAL INTEGRITY	MATERIAL INTEGRITY IS VERIFIED PER SPECIFICATION REQUIREMENTS.	RB0170-152
		INDUCER FORGING IS PENETRANT AND ULTRASONIC INSPECTED PER SPECIFICATION REQUIREMENTS.	RA0115-116 RA0115-012
		INDUCER IS PENETRANT INSPECTED PER SPECIFICATION REQUIREMENTS.	RA0115-116
	ASSEMBLY INTEGRITY	BLADE FILLET RADII, EDGES, AND DEBURRING ARE INSPECTED PER DRAWING REQUIREMENTS.	RS007604
		BLADE COORDINATES ARE VERIFIED PER DRAWING REQUIREMENTS.	
		THE BLADE EDGES ARE VISUALLY INSPECTED AT TURBOPUMP ASSEMBLY PER SPECIFICATION REQUIREMENTS	RL00353
		INDUCER BLADE TIP-TO-HOUSING CLEARANCE IS INSPECTED PER DRAWING REQUIREMENTS.	RS007604 R0019864 RS007632
	LPFTP		RS007501
	ASSEMBLY INTEGRITY	TORQUE CHECKS ARE PERFORMED EACH FLIGHT FLOW TO VERIFY ASSEMBLY INTEGRITY.	CMRSD V41BS0.010
B	VOLUTE HOUSING ASSEMBLY		
	MATERIAL INTEGRITY	MATERIAL INTEGRITY IS VERIFIED PER SPECIFICATION REQUIREMENTS.	RB0170-009
		CASTING HOT ISOSTATIC PRESS IS VERIFIED PER SPECIFICATION REQUIREMENTS.	RI 00372
		HOUSING IS PROOF PRESSURE TESTED PER SPECIFICATION REQUIREMENTS.	RL00408
		CASTING IS RADIOGRAPHIC INSPECTED PER SPECIFICATION REQUIREMENTS	RL10003
		THE PENETRANT AND HIDDEN SURFACE INSPECTIONS ARE PERFORMED ON THE VOLUTE PRIOR TO AND AFTER PROOF PRESSURE TESTING PER DRAWING AND SPECIFICATION REQUIREMENTS	R0019864 RA0115-116 RL00314
	HEAT TREAT	HEAT TREAT IS VERIFIED PER DRAWING REQUIREMENTS.	R0019864
	SURFACE FINISH	THE CAST SURFACE FINISH IS VERIFIED PER DRAWING AND SPECIFICATION REQUIREMENTS.	R0019864 RA0115-007
		VOLUTE ANODIZATION IS VERIFIED PER SPECIFICATION REQUIREMENTS.	RA1609-003
ALL CAUSES	LPFTP		RS007501
	ASSEMBLY INTEGRITY	THE PUMP SUBASSEMBLIES ARE INSPECTED DURING OVERHAUL PER SPECIFICATION REQUIREMENTS. INSPECTIONS INCLUDE: VISUAL, DIMENSIONAL, PENETRANT, AND REPLACEMENT OF USAGE ITEMS AS APPLICABLE PER OVERHAUL CLASSIFICATION.	RL00531 RA0115-116

Component Group: Fuel turbopumps
 CIL Item: B600-04
 Part Number: RS007601
 Component: Low Pressure Fuel Turbopump
 FMEA Item: B600
 Failure Mode: Loss of head rise.

Prepared: n. Greenwald
 Approved: T. Nguyen
 Approval Date: 11/1/99
 Change #: 1
 Directive #: CCBD ME3-01-5248

Page: 2 of 2

Failure Causes	Significant Characteristics	Inspection(s) / Test(s)	Document Reference
ALL CAUSES	ASSEMBLY INTEGRITY	OPERATION/PERFORMANCE IS VERIFIED BY ENGINE HOT-FIRE TESTING AND 2ND E & M TESTS ON INSPECTIONS	RL00050-04 RL00050-06 RL00050-07 RL00461
		DATA FROM PREVIOUS FLIGHT OR HOT-FIRE IS REVIEWED FOR PROPER TURBOPUMP OPERATION/PERFORMANCE. (LAST TEST)	MSFC PLN 1228

Failure History: Comprehensive failure history data is maintained in the Problem Reporting database (PRAMS/PRACA)
 Reference: NASA letter SA21/88/30E and Rocketdyne letter 88RC09761
 Operational Use: Not Applicable.

B - 550

WELDED JOINTS

Component Group: Fuel Turbopumps
 CIL Item: B600
 Part Number: RS007601
 Component: Low Pressure Fuel Turbopump
 FMEA Item: B600

Prepared: F. Cromwell
 Approved: T. Nguyen
 Approval Date: 11/1/99
 Change #: 2
 Directive #: CCBD ME3-01-5248
 Page: 1 of 1

Component	Basic Part Number	Weld Number	Weld Type	Class	Root Side Not Access	Critical Initial Flaw Size Not Detectable		Comments
						HCF	LCF	
MANIFOLD	RS007603	1	EBW	Ia	X			
MANIFOLD	RS007603	2	GTAW	I				
MANIFOLD	RS007603	5,8,10	GTAW	II	X	X		
MANIFOLD	RS007603	9,10	GTAW	II	X			
MANIFOLD	RS007603	13	GTAW	I				
MANIFOLD	RS007603	17	EBW	II	X	X	X	
MANIFOLD	RS007603	18	GTAW	I	X	X	X	

B - 580

SSME FMEA/CIL
FIELD CONFIGURATION VARIANCES FROM CIL RATIONALE

Component Group: Fuel Turbopumps
 Item Name: Low Pressure Fuel Turbopump
 Item Number: B600
 Part Number: RS007601

Prepared: F. Cromwell
 Approved: T. Nguyen
 Approval Date: 11/1/99
 Change #: 3
 Directive #: CCBD ME3-01-5248

Page: 1 of 1

Base Line Rationale	Variance	Change Rationale	Variant Dash Number
1. B600-06. RS007606, RS007605; CAUSE A. THE INNER AND OUTER BEARING RINGS ARE EDDY CURRENT INSPECTED PER RA1615-034.	BEARING RINGS RECEIVED FROM SUPPLIER SPLIT BALL BEARING INCORPORATED RECEIVED NO GENERAL EDDY CURRENT INSPECTION.	GENERAL EDDY CURRENT INSPECTION OF RINGS REPLACES TYPE IVC IN PENETRANT INSPECTION IN DETECTING SURFACE FLAWS. USE AS IS RATIONALE: 1. RINGS ARE SUPPLIED BY SPLIT BALL BEARING INCORPORATED RECEIVED 10X VISUAL AND TYPE IVC PENETRANT INSPECTION INSTEAD OF GENERAL EDDY CURRENT INSPECTION. FLAW DETECTABILITY RELIABILITY LEVELS BETWEEN PENETRANT AND GENERAL EDDY CURRENT INSPECTIONS ARE 0.060 AND 0.057 RESPECTIVELY	SEE DAR 2745 FOR VARIANT PART SERIAL NUMBERS
2. B600-10. THE HOUSING INSULATION IS PROTECTED BY A KEVLAR COMPOSITE SURFACE WITH L-T-80 FIRE RETARDANT ALUMINUM TAPE APPLIED TO THE KEVLAR SURFACE	CERTAIN FLIGHT HOUSINGS HAVE NICKEL PLATED INSULATION WITH COPPER PLATED TIE-IN AREAS.	THE BLOCK I AND PHASE II HAVE NICKEL PLATING TO PROTECT THE INSULATION FROM MECHANICAL DAMAGE AND PROVIDE A MOISTURE BARRIER. THE HOUSING IS COPPER PLATED AT THE INSULATION CLOSE-OUT AREAS TO IMPROVE THE NICKEL BOND. THE MINIMUM FACTORS OF SAFETY FOR THE INSULATED HOUSING MEET C.E.I. REQUIREMENTS. DAR 2068 ADDRESSES THE TIME CONSTRAINTS FOR NICKEL PLATED INSULATION WITH COPPER PLATED TIE-IN CONFIGURATIONS.	RS007632-171, -181, -201, -211
3. B600-05. THE BALLS ARE POSITIONED BY AN FEP COATED ARMALON CAGE. FEP COATING ON CAGES USED TO REDUCE POCKET AND BALL WEAR THUS INCREASING BEARING LIFE.	BLOCK I AND PHASE II PUMPS DO NOT HAVE FEP COATED CAGES.	BLOCK I AND PHASE II CAGES HAVE TEFLON CONTAINED IN THE FIBERGLASS CAGE THAT PROVIDES BEARING LUBRICATION.	RS007605-027 RS007606-007, -025
4. B600-01. BLOCK II NOZZLE ASSEMBLY ALLOWS A MINIMUM OF 12 OF THE 43 NOZZLE PASSAGES TO BE BLOCKED.	BLOCK I PHASE II NOZZLE ASSEMBLY ALLOWS A MINIMUM OF 16 OF THE 43 NOZZLE PASSAGES TO BE BLOCKED	THE BLOCK I PHASE II NOZZLE ASSEMBLY DOES NOT VIOLATE THE REQUIREMENTS OF THE BLOCK II NOZZLE ASSEMBLY. BLOCK I PHASE II NOZZLE MEETS CEI NOZZLE VANE REQUIREMENTS.	R0019793-091
6. B600-02. CAUSE B,C THE SECOND STAGE ROTOR BRAZE JOINT INTEGRITY IS ULTRASONIC INSPECTED PER DRAWING REQUIREMENTS.	CERTAIN SECOND STAGE ROTORS RECEIVED NO ULTRASONIC INSPECTION OF THE BRAZE JOINT.	THE BRAZE JOINTS OF ALL SECOND STAGE ROTORS HAVE RECEIVED A VISUAL AND PENETRANT INSPECTION. ALL PARTS SUSPECTED TO HAVE BRAZE JOINT ANOMALIES HAVE BEEN ADDRESSED.	RS007625-031
6. B600-02. CAUSE D NOZZLE COPPER PLATING ADHESION IS VERIFIED PER DRAWING REQUIREMENTS.	CERTAIN NOZZLES DID NOT RECEIVE A BAKE TEST.	ADHESION BAKE TEST IS NOT REQUIRED FOR NOZZLES WHICH HAVE BEEN PREVIOUSLY HOT FIRE TESTED. THE HOT FIRE ENVIRONMENT ADEQUATELY VERIFIES THE COPPER PLATING ADHESION INTEGRITY.	RS007622-025 R0019793-023
7. B600-02. CAUSE E. THE STATOR COPPER PLATING ADHESION IS VERIFIED PER DRAWING REQUIREMENTS	CERTAIN STATORS DID NOT RECEIVE A BAKE TEST.	ADHESION BAKE TEST IS NOT REQUIRED FOR STATORS WHICH HAVE BEEN PREVIOUSLY HOT FIRE TESTED. THE HOT FIRE ENVIRONMENT ADEQUATELY VERIFIES THE COPPER PLATING ADHESION INTEGRITY	RS007623-031

C - 591