SSME EA/CIL REDUNDANCY SCREEN

Component Group:

Actuators

CIL Item:

E140-11

Part Number:

RES1008-6XXX

Component:

Oxidizer Preburner Oxidizer Valve Actuator

FMEA Item:

E140

Failure Mode: Structural failure. Prepared:

S. Heater

Approved:

T. Nguyen 6/9/00

Approval Date: Change #:

1

Directive #:

CCBD ME3-01-5624

Page:

1 of 1

Phase	Failure / Effect Description	Criticality Hazard Reference
C 4.1	If in pneumatic shutdown, major pneumatic leak preventing proper pneumatic shutdown sequence. Overpressurization aft compartment. Loss of vehicle.	1R ME-A1A,
	Redundancy Screens: PNEUMATIC SYSTEM - ACTUATOR SYSTEM: UNLIKE REDUNDANCY	ME-B4A,C, ME-C1A,C,
	A: Pass - Redundant hardware items are capable of checkout during normal ground turnaround. B: Fail - Loss of a redundant hardware items is not detectable during flight. C: Fail - Loss of redundant hardware items could result from a single credible event.	ME-D1A,C, ME-G10C,D

П 253

SSME FMEA/CIL DESIGN

Component Group: CIL Item:

Actuators E140-11

Part Number:

RES1008-6XXX

Component:

Oxidizer Preburner Oxidizer Valve Actuator

FMEA Item:

E140

Failure Mode:

Structural failure.

Prepared:

S. Heater

Approved:

T. Nguyen 6/9/00

Approval Date: Change #:

1

Directive #:

CCBD ME3-01-5624

Page:

1 of 1

Design / Document Reference

FAILURE CAUSE: A: Structural failure of housing or end caps.

THE ACTUATOR HOUSING IS MACHINED FROM A FORGED 7175 ALUMINUM BILLET, HEAT TREATED TO CONDITION T736 (1). THIS ALLOY WAS SELECTED FOR ITS TENSILE STRENGTH AND FATIGUE STRENGTH. THE EXTERIOR OF THE HOUSING IS SHOT-PEENED TO ENHANCE THE STRESS CORROSION RESISTANCE (1) (2). THE HOUSING IS ANODIZED FOR CORROSION PROTECTION AND THE CYLINDER BORES ARE HARD ANODIZED FOR WEAR RESISTANCE (3). STANDARD LEE PLUGS ARE USED TO CLOSE OFF DRILLED PASSAGE ACCESS HOLES WHERE SECONDARY RETENTION IS AVAILABLE (SUCH AS BOLTING ANOTHER PART OVER THE PLUG). OTHERWISE A "PIN PLUG" IS USED WHICH IS A LEE PLUG WITH THREADS ON THE IN-HOLE END FOR SECONDARY RETENTION (1). LEE PLUGS AND PIN PLUGS ARE ALUMINUM TO PREVENT GALVANIC CORROSION. THE BYPASS VALVE END RESISTANCE TO STRESS CORROSION CRACKING (2). THE MATERIAL IS ANODIZED FOR GENERAL CORROSION PROTECTION. 7075-T73 ALLOY IS USED FOR ITS STRENGTH AND ACTUATOR HOUSING. THE PNEUMATIC CAP (5) AND SEQUENCE VALVE CAP (6) ARE MADE FROM 2024-T6 ALUMINUM ALLOY. THE MATERIAL WAS SELECTED FOR ITS STRENGTH, PNEUMATIC CYLINDER (7) IS MADE FROM 6061-T651 ALUMINUM. THE CYLINDER IS SHOT PEENED TO ENHANCE STRESS CORROSION RESISTANCE AND SIMILARITY TO THE HOUSING'S THERMAL CHARACTERISTICS (2). THE CAP ANODIZING PROVIDES CORROSION PROTECTION. THE CYLINDER IS ANODIZED FOR ADDITIONAL CORROSION PROTECTION. THE MATERIAL WAS SELECTED FOR ITS STRENGTH, THE CYLINDER IS ANODIZED FOR ADDITIONAL CORROSION PROTECTION. THE MATERIAL WAS SELECTED FOR ITS STRENGTH, CORROSION RESISTANCE AND FATIGUE STRENGTH. THE CORROSION CRACKING (2). THE HIGH CYCLE AND LOW CYCLE FATIGUE LIFE OF THE ACTUATOR MEET CEI REQUIREMENTS (8). THE MINIMUM FACTORS OF SAFETY FOR THE ACTUATOR MEET CEI REQUIREMENTS (9). THE ACTUATOR SOME EXPERIENCE CHITICAL PARTS AND EXAMINED. THE ACTUATOR SHOWED NO DETRIMENTAL DEFECTS OR WEAR. THIS ACTUATOR HAD 28 STARTS AND 10,332 SECONDS HOT FIRE TIME, INCLUDING 6,651

(1) 34000657; (2) RSS-8582; (3) 34000694; (4) 34000149; (5) 34001925; (6) 34000319; (7) 34001927; (8) RL00532, CP320R0003B; (9) RSS-8546, CP320R0003B; (10) NASA TASK 117; (11) DVS-SSME-512; (12) RSS-512; (13) SSME-82-2316

- 25

/CIL

Component Group: CIL Item:

Actuators

E140-11

Part Number: Component:

RES1008-6XXX Oxidizer Preburner Oxidizer Valve Actuator

FMEA item:

E140

Failure Mode:

Structural failure.

S. Heater

T. Nguyen . 6/9/00

1

Prepared: Approved: Approval Date: Change #: Directive #:

CCBD ME3-01-5624

		an antarar fariate.	•	
	Failure Causes	Significant Characteristics	Page:	1 of 2 ,
		 	Inspection(s) / Test(s)	Document Reference
4		HOUSING FORGING PVA HOUSING ASSY. PVA HOUSING FORMED END CAP, BYPASS VALVE CAP, PNEUMATIC CYLINDER, PNEUMATIC END CAP, SEQUENCE VALVE	■	34000219 34000694 34000657 34000149 34001925 34001927
		MATERIAL INTEGRITY	MATERIAL INTEGRITY IS VERIFIED PER DRAWING REQUIREMENTS.	34000319
				34000219 34000694 34000657 34000149 34001925 34001927 34000319
		HEAT TREAT	THE HOUSING FORGING IS ULTRASONIC INSPECTED PER DRAWING REQUIREMENTS.	34000219
			HEAT TREAT OF HOUSING IS VERIFIED TO MEET DRAWING REQUIREMENTS.	34000657
			SHOT PEENED HOUSING AND PNEUMATIC CYLINDER EXTERIORS ARE VERIFIED TO MEET DRAWING REQUIREMENTS.	34000657 34001927
			THE HOUSING AND END CAPS ARE PENETRANT INSPECTED AFTER MACHINING.	34000149 34001925 34000319 34000657 34000694 34001927
			ANODIZE OF HOUSING, PNEUMATIC CYLINDER, AND END CAPS IS VERIFIED PER DRAWING REQUIREMENTS.	34000149 34001925 34000319 34000657 34000694 34001927
			PROOF PRESSURE TESTING VERIFIES THE STRUCTURAL INTEGRITY OF THE END CAPS AND HOUSING.	RC1008
		FUNCTIONAL INTEGRITY	HOTFIRE TESTING AND SECOND E & M INSPECTIONS VERIFY SATISFACTORY OPERATION.	RL00050-04 RL00056-06 RL00056-07
			ACTUATOR OPERATION IS VERIFIED PRIOR TO EACH FLIGHT DURING HYDRAULIC SYSTEM CONDITIONING.	OMRSD S00FA0.211
			ACTUATOR OPERATION IS VERIFIED DURING THE ACTUATOR CHECKOUT MODULE PRIOR TO EACH FLIGHT.	OMRSD V41AS0.010

Ш 255 Component Group:

Actuators

CIL Item:

E140-11

Part Number:

RES1008-6XXX

Component:

Oxidizer Preburner Oxidizer Valve Actuator

FMEA Item:

E140

Failure Mode:

Structural failure.

Prepared:

Approved: Approval Date:

T. Nguyen 6/9/00 Change #:

Directive #:

CCBD ME3-01-5624

S. Heater

			Page:	2 of 2			
	Failure Causes	Significant Characteristics	Inspection(s) / Test(s)	Document Reference			
Α		FUNCTIONAL INTEGRITY	ACTUATOR OPERATION IS VERIFIED DURING FLIGHT READINESS CHECKOUT PRIOR TO EACH FLIGHT. (LAST TEST),				

Failure History:

Comprehensive failure history data is maintained in the Problem Reporting database (PRAMS/PRACA)

Reference: NASA letter SA21/88/308 and Rocketdyne letter 88RC09761,

Operational Use: Not Applicable.

 \Box