Rev. B

USA Ground Operations CIL Sheet

Critical Item: Jackscrew NASA Part No: None

AUG 9 2000

Criticality Category: 1 Total Quantity: 14

79K05424 / 104

Mfg/Part No: Duff-Norton / Series 2800

System: Find No. Extensible and Auxiliary Access Platforms

Qtv Area PMN Baseline Drawing / Sheet VAB HB-1 K60-0554 398.01 79K09164 / 175 7 VAB HB-3 K60-0555 398.02

Function:

None

None

Provide mechanical motion to raise and lower platforms.

Failure Mode No. Failure Mode	Failure Cause Failure Effect	Detection Method Time to Effect	Crit
09FY02-006.015	Mechanical wear of drive sleeve beyond operational		Cat
	limits, structural failure, improper maintenance.	Visual	1
Lift screw	I manufacturate transfer maintenance.		Ī
disengagement from	Uncontrolled descent of the platform. Platform would break its hinges and continue to fall causing loss of life and or vehicle.	Immediate	
drive sleeve			

ACCEPTANCE RATIONALE

Design:

- . The jackscrew is rated at 20 tons. It is a ball screw type.
- The platform weight is 1164 lb. yeilding a 34:1 operational safety factor.
- The manufacturer states that the jackscrew is serviceable until the backlash reaches 50% of the screw thread thickness.

Test:

· OMRSD File VI requires performance of an annual backlash test of the jackscrew to determine wear on the mechanism in accordance with KSC-5600-5610, Jackscrew Wear Inspection.

Inspection:

- OMI Q6152 requires a biennial inspection of the lifting screw for damage and application of oil.
- OMI Q6152 requires a biennial adjustment of the clevis to the jackscrew shaft to maintain a clearance of

Failure History:

- Current data on test failures, unexplained anomalies, and other failures experienced during ground processing activities can be found in the PRACA database. The PRACA database was researched and no data was found on this component in the critical failure mode.
- A failure of another jackscrew did occur in the ET Gox Vent Arm Hood an 4/6/98 (PR PV-6-336823). The NASA KSC Malfunction Lab inspected the failed unit (Report #MSL-0422-1998) and attributed its failure to worn out threads on the drive sleeve unit.

Operational Use:

Correcting Action	Timeframe
There is no action which can be taken to mitigate the failure effect.	The state of the s
The second secon	timeframe does not apply.