

MAR 11 1994

B/L: 389.00
SYS: 250-TON
BRIDGE
CRANE, VAB

Critical Item: Synchro Transmitter and Receiver Assembly,
Auxiliary Hoist (2 Total, 1/Crane)
Flnd Number: 2SYNT/2SYNR2
Criticality Category: 2

SAA No: 09FY12-005	System/Area: 250-Ton Bridge Crane (#1 & #2)/VAB
NASA Part No: NA	PMN/ Name: K60-0533, K60-0534/ 250-Ton Bridge Crane (#1 & #2)/VAB
Mfg/ Part No: General Electric/ 2JDA66PA10A, 5PY-5GTY23	Drawing/ Sheet No: 69-K-L-11388/ 20

Function: Provides aux hoist position and motion indication to the operator in the cab. The operator uses this indicator to determine movement distance when required to make small incremental moves for mate/demate operations.

Critical Failure Mode/Failure Mode No: Erroneous Output (Indication)/09FY12-005.085-

Failure Cause: Corrosion, binding mechanism

Failure Effect: Loss of accurate position indication or load motion indication could result in improper load positioning. The worst case would be attempting to mate or demate a critical load (SRB forward assembly), the failure occurring, and the effect being the operator commanding too much movement and the critical load contacting the transporter, work platforms, MLP, or Shuttle Stack resulting possible damage to vehicle system. Time to effect: seconds.

ACCEPTANCE RATIONALE

Design:

<u>Ratings</u>	<u>Actual</u>
115 volts	120 volts

- Totally enclosed nonventilated cast housing.
- Motor-type rotor is the only moving part.
- This item was off-the-shelf hardware selected by the crane manufacturer for this application.

Attachment
S050234CK
Sheet 75 of 147

MAR 11 1994

Test:

- OMRSD file VI requires verification of proper performance of hoist operational test annually.
- OMI Q3008, Operating Instructions, requires all crane systems to be operated briefly in all speeds to verify satisfactory operation before lifting operations.

Inspection:

- OMI Q5003, Maintenance Instructions, requires monthly inspection for quietness and smoothness during operation; monthly inspection of belt drives for worn, frayed or abnormal wear; monthly inspection for broken, bent or badly worn pulleys; monthly verification by examination and manipulation that keys and couplings are securely in place; annual removal and inspection of brushes and replacement of brushes when overall length is 3/8-inch or less.

Failure History:

- The PRACA database was researched and failure data was found on this component in the critical failure mode.
 - The failures occurred on 3/9/91, 10/10/91, and 10/8/92.
 - The failure cause was binding mechanism.
 - The correcting action was to remove and replace the selsyn receiver (3/9/91), or to remove, repair and replace the selsyn receiver (10/10/91 & 10/8/92).

NOTE: The failures did not necessarily occur on these crane drive systems. The failure may have occurred on any one of the four drive systems of one of these two cranes or the VAB 175-Ton Bridge Crane.

- The GIDEP failure data interchange system was researched and no failure data was found on this component in the critical failure mode.

Operational Use:• **Correcting Action:**

- 1) When the failure indication is noticed, the operator can stop all crane operations by returning the Master Control Switch to neutral or pressing the E-Stop button (releasing the brake switch in the float mode).
- 2) Operators are trained and instructed to operate these cranes and know and understand what to do if a failure indication is present.
- 3) During all critical lifts, there is at least one remote Emergency Stop (E-Stop) operator observing the load and can stop the crane if a failure indication is noticed.
- 4) Operationally, the crane must not be operated in the fine speed mode if a critical load is within 10 feet of any structure in the direction of travel.

• **Timeframe:**

- Estimated operator reaction time is 10 to 15 seconds.

Attachment
S050234CK
Sheet 76 of 147