UNIT Remote Control Unit (RCU) DWG NO. 2294824-506. 507 SHUTTLE CCTV FMEA NO. 1.1.19 CRITICAL ITEMS LIST CHITICALITY 2/18 FAILURE EFFECT FATLURE HODE AND RATIONALE FOR ACCEPTANCE ON END ITEM CAUSE DESIGN FEATURES Camera power enable Camera power enable signal. sticks low, camera will Fails low. The RCU is a microprocessor-based command and control unit using an RCA 1802 CMOS not turn on. microprocessor, CMOS RAM, and TTL PROM. Computer I/O circuitry is implemented in Causes: CMOS CO4000 series logic to minimize power dissipation. The design incorporates a Morst Case: Loss of elbow Data register relay on. dual master oscillator (one active, one cold backup). The master oscillator is a PIU motion could prevent Status 1, Component Assy. Temperature Compensated Crystal Oscillator (TCXO) purchased from Vectron to an RCA RMS stowing. AlO. 2294869-503 or specification control drawing (SCD). Decode logic consists of law Power Schottky Status 2, Component Assy TTL, and the sync amplifier design uses manufilthic MES539 wideband up amps, All. 2294869-504. (2) Strobe Circuit Fallure on Parts were required to be JAN reliability level parts or their equivalent. Part VSD Interface Assy selection falls into three categories: A6, 2592386-501 or 2294865-504 JAN or better parts from the Military QPL, Microcomputer Assy. (2) Parts demonstrated to NASA to be equivalent to JAN level via test data A7, 2599298-501 or 2294866-504 (e.g., CO4000/3W series parts), or Parts procured to an RCA spec control drawing which calls out tests and screening to effect JAN equivalency. BARE BOARD DESIGN (ATO, ATT) The design of the associated AlO and All boards is constructed from laminated copper-clad epoxy glass sheets (MEMA G-10) Grade FR-4), PER MIL-P-55617A. Circuit connections are made through printed traces which run from point to point on the board surfaces. Every trace terminates at an annular ring. The annular ring surrounds the hole in which a component lead or terminal is located. This ring provides a footing for the solder, ensuring good mechanical and electrical performance. Its size and shape are governed by HIL-P-55640 as are trace widths, spacing and routing. These requirements are reiterated specifically in drawing

The thru holes are drilled from a drill tape thus eliminating the possibility of human error and allowing tight control over hole and annular ring concentricity, an important reliability criterion. After drilling and etching, All copper cladding is tin-lead plated per MII-SID-1495. This provides for easy and reliable soldering at the time of board assembly, even after periods of prolonged storage.

notes to further assure compliance. Variations between the artwork master and the final product (due to irregularities of the etching process) are also controlled by drawing notes. This prevents making defective boards from good artwork. Holes which house no lead or terminal, but serve only to electrically interconnect the different board layers, contain stitch bars for mechanical support and increased reliability.

1-115 ∞π√-≦ω

REVISEO 5-7-87

			
FMR A NO. 1.1.19		SHUTTLE CCTV CRITICAL TIEMS LIST	UNIT <u>Remote Control Unit (8)</u> DWG NO. <u>2294624-506. 507</u> SHEET2 OF8
	FAILURE EFFECT ON END TIEM Camera power enable sticks low, camera will not turn on. Worst Case: Loss of elbow PTU motion could prevent RMS stowing.	RATIONALE FOR ACCEPTANCE RATIONALE FOR ACCEPTANCE RESIGN FEATURES (Continued) BUAND ASSEMBLY DESIGN (A10, A11) All components are installed in a manner which assures maximum reliability. Component leads are pre-tinned, allowing total wetting of solder joints. All leads are formed to provide stress relief and the bodies of large components are staked. Special mounting and handling instructions are included in each drawing required after final assembly. The board is coated with urethane which protects against humidity and contamination. BOARD PLACEMENT (A6, A7, A10, A11) The A6, A7, A10, and A11 boards are secured in the electronics assembly by gold-plated beryllium copper care guides. Connections are made to the mother board with blind-mated connectors. Disengagement during launch is prevented by a cover which spans the board's free edge. BARE BOARD CONSTRUCTION (A6, A7) The boards are of "we)ded wire" construction. At the bare board level this does not distinguish it from a normal PC board except that holes which will take weld pins generally are not connected to PC traces. Only those pins which bring power and	
		ground potentials to the ICs are on PCs. An annular ring surrounds the hole in the board where each power and ground pin is located. These pins are then soldered to the trace like any other component lead. Aside from this feature, all design & construction techniques used in PC board layout apply. BOARD ASSEMBLY (A6, A7) The drilled and elched board is populated with several hundred solderable or weldable pins. Power and ground pins, as well as connector pins, are soldered in place. Discreet components (resistors, diadas, capacitors) are attached to bifurcated terminals, where they are soldered. Flatpack ICs are welded, load-by-lead, to the tops of the weld pins. After welding, extra lead material is triumed away. Circuit connections are made using #30 AHG nickel weld wire. The wire is welded to the pin surfaces on the board backside. All wire welds are done using a machine which is tape driven, thus eliminating the possibility of miswiring due to operator error. All wiring & circuit performance is tested prior to box-level installation. After successful testing, components are staked as required by drawing notes and the assembly is coated with urethane. The boards is inserted in the box on card-edge guides, in the same manner as the other PC boards.	

FNEA HD. 1.1.19		REVISED 5-7-B/	
		SHUTTLE CCTV DNG NO. 2294874-504 CRITICAL ITEMS LIST SHEET 3 OF 8	<u> 11</u>
FAITURE MODE AND CAUSE Camera power enable signal (a) lata register relay on Status 1, Component Assy A16, 2294869-503 or Status 2, Component Assy A11, 2294869-504- (2) Strobe Circuit failure on VSU Interface Assy A6, 2592386-501 or 2294865-504 (3) Microcomputer Assy A7, 2599298-501 or 2294866-504	FAILURE EFFECT ON END ITEM Camera power enable sticks low, camera will not turn on. Worst Case: Loss of elbow PTO motion could prevent RMS stowing.	QUALIFICATION TEST For Qualification Test flow, see Table 2 located at the front of this book.	

REVISED 5-7-07 UNIT Remote Control Unit (RCU) OMG NO. 2294824-504 SHUTTLE CCTV FMEA NO. 1,1,19 CRITICAL LIENS LIST SHEET 4 CHITICALITY 2/1R FAILURE EFFECT FAITURE HODE AND RATIONALE FOR ACCEPTANCE. ON END THEM CAUSE Camera power enable: ACCEPTANCE TEST Camura power enable signal sticks low, camera will fails low. The CCTV systems' RCU is subjected to the following testing: not turn an. Causes: 3 dB/Oct-rise from 0.01 G^2/Hz to 0.04 G^2/Hz Worst Case: Loss of elbow Vibration: 20-80Hz: (I) Data register relay on 80-350 Hz: 0.04 G²/Hz PTU motion could prevent Status 1. Component Assy 3 dB/Oct-fall to 0.018 G2Hz RHS stowing. 350-750 Hz: A10, 2294869-503 or 0.018 G²/H₂ 750-1000: Status 2, Component Assy 3 d0/Oct-Fall to 0.009 G²/Hz 1000-2000: All. 2294859-504. Test Duration: 1 Hinute per Axis (2) Strobe Circuit Failure on Test Level! 6.6 Grms V50 Interface Assy A6. 2592386-501 or 2294865-504 100° F: Time to stablize equipment plus I hour Itermal: (3) Microcomputer Assy. O" f: Time to stablize equipment plus I hour A7, 2599298-501 or 2294866-504 100° F: Time to stablize equipment plus I hour for Acceptance Test Flow, see Table I located at the front of this bank. OPERATIONAL TEST ... In order to verify that CCTV components are operational, a test must verify the health of all the command related components from the PHS (A7A1) panel switch, through the ACU, through the sync lines to the Camera/PTU, to the Camera/PTU command decoder. The test must also verify the camera's ability to produce video, the VSD's ability to route wideo, and the monitor's ability to display video. A similar test would be performed to verify the MDM command path. <u>Pre-Launch on Orbiter Test/In-Flight Test</u> 1. Power CCTV System. Via the PHS panel, select a monitor as sestimation and the camera under test as source. 3. Send "Camera Power On" command from PHS panel. 4. Select "External Sync" on monitor. 5. Observe video displayed on monitor. Note that If video on munitur is synchronized (i.e., slable raster) then this indicates that the camera

synchronized video.

8. Observe video routed to downlink.

9. Send "Camera Power Off" command via PMS panel.

is receiving composite sync from the RCU and that the camera is producing

Send Pan, Till, Focus, Zoom, ALC, AND Gamma commands and visually (either.

10. Repeat Steps 1 through 9 except issue commands via the MOM command path.

via the monitor or direct observation) verify operation. 7. Select downlink as destination and camera under test as source.

This proves that the CCTV equipment is operational.

	·		REVISED 5-7-B7
TMLA NO. 1.1.19	•	SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT Remote Control Unit (RCU) DWG NO. <u>2294824-506</u> 507 SHEEY <u>5</u> OF <u>B</u>
FAILURE MODE AND	FAILURE EFFECT ON END 17FM	RATIONALE FOR ACCEPTANCE	,
Camera power enable signal fails low.	Camera power enable sticks low, camera will not turn on.	OA/INSPECTION Procurement Control - The RCU EEE parts and hardware it	ems are procured from approved

<u>Worst Case</u>: Loss of elbuw

PTU motion could prevent

AMS stowing.

Causesi

 (1) Data register relay on Status 1, Component Assy Alo, 2294869-503 or Status 2, Component Assy AII, 2294869-504.

(2) Strabe Circuit Failure on VSN Interface Assy A6, 2592386-501 or 2294865-504

(3) Microcomputer Assy. A7, 2599298-501 or 2294866-504

vendors and suppliers, which meet the requirements set forth in the CCTV contract and Quality Plan Work Statement (WS-2593176). Resident BCAS personnel review all procurement documents to establish the need for GSI on selected parts (PAI 517).

Incoming Inspection and Storage - Lacoming Quality inspections are made on all received materials and parts. Results are recorded by lot and retained in file by drawing and control numbers for future reference and traceability. All EEE parts are subjected to incoming acceptance tests as called for in PAI 315 - Incoming Inspection Test Instructions. Incoming flight parts are further processed in accordance with REA 1846684 - Precunditioning and Acceptance Requirements for Electronic Parts, with the exception that OPA and PIND testing is not performed. Mechanical items are inspected per PAI 316 - Incoming Inspection Instructions for Mechanical Items, PAI 305 - Incoming Quality Control Inspection Instruction, and PAI 612 - Procedure for Processing Incoming or Purchased Parts Designated for Flight Use. Accepted items are delivered to Material Controlled Stores and retained under specified conditions until fabrication is required. Monconforming materials are held for Material Review Board (MRB) disposition. (PAI-307, PAI IQC-531.)

<u>Board Assembly & Test - Prior to the start of RCU board assembly, all items are</u> verified to be correct by stock room personnel, as the items are accommitated to form a kit. The items are verified again by the operator who assembles the kit by checking against the as-built-parts-list (ABPL). OCAS Mandatory Inspection Points are designated for printed circuit, wire wrap and welded wire boards, plus harness connectors for soldering wiring, crimping, solder splices and quality workmanship prior to coating of the component side of boards and sleeving of hornesses. Specific REO board assembly and test instructions are provided in drawing notes, and applicable documents are called out in the Fabrication Procedure and Record (FPR-2294824) and parts list PL-2294824. These include wire connection List 2295901, Process Standard RIV-566 2260881, Process Standard - Bonding Veloro Tape 2280889, Specification Soldering 2280749. Specification Name Plate Application 1960167. Specification - Crimping 2200000, Specification - Bonding and Staking 2280878, Specification - Urethane coating 2280877, Specification - Locking Compound 2026][6. Specification Epoxy Adhesive 2010985, Specification - Marking 2280876. Specification - Horkmanship 8030035, Specification Bonding and Staking 2280875.

RCU Assembly and Test - An open box test is performed per TP-IT-2294824, and an Acceptance Test per FP-AT-2294824, including vibration and thermal-vacuum. Isrques are specified and witnessed, traceability numbers are recorded, and calibrated tools are checked prior to use. RCA Quality and DCAS inspections are performed at the completion of specified FPR operations in accordance with PA1-204, PA1-205, PA1-206. and PAI 217. OCAS personnel witness RCU button-up and critical Lorquing. RCA and

'REVISED 5-7-07 UNIT Remote Control Unit (RCU) SHUTTLE CCTV DWG NO. 2294824-506, 507 FMEA NO. 1.1.19 CRITICAL TIEMS LIST CRITICALITY 2/18 SHEET 6 FAILURE MODE AND FAILURE EFFECT RATIONALE FOR ACCEPTANCE ON END ITEM CAUSE QA/INSPECTION (Continued) Camera power enable signal Camera power enable sticks law, camera will fails low. ngt turn on. DCAS personnel monitor acceptance tests and review the test data/results. These personnel also inspect for conformance after all repair, rework and retest. Causes: Data register relay on. Warst Case: Lass of elbow PTU motion could prevent Preparation for Shipment - The RCU is packaged according to 2280746, Process Status 1, Component Assy A10, 2294869-503 or Standard for Packaging and Handling guidelines. All related documentation including RMS stowing. Status 2, Component Assy assembly drawings. Parts List, ABPL, Test Data, etc., is gathered and held in a A11, 2294869-504. documentation folder assigned specifically to each assembly. This folder is retained (2) Strobe Circuit Fallure on for reference. An EIOP is prepared for each RCU in accordance with the requirements VSU Interface Assy of WS-2593)76. RCA QC and OCAS persunnel witness crating, packaging, packing and A6, 2592386-501 or 2294865-504 marking, and review the EIDP for completeness and accuracy. (3) Microcomputer Assy A7, 2599298-501 or 2294866-504

AEVISED 5-7-87 UNIT Remote Control Unit (RCU) DHG NO. 2294824-500, 507____ SHUTTLE CCTV FMEA NO. 1.1.12 _____ CRITICAL ITEMS LEST SHEET 7 OF 8. CHITICALITY 2/1R FAILURE EFFFCT FALLURE NODE AND RAILONALE FOR ACCEPTANCE ON END ITEM_ CAUSE Camera power enable Camera power enable signal. FAILURE HISTORY sticks low, camera will fails low. not turn on. TOR - W4307 - Log #505, -501 S/N 004 Causes: Worst Case: Loss of albow ()) Nata register relay on <u>Description:</u> Prelounch Tast Failure, Box Level, Cold Temperature Environment. PIU motion could prevent Status I, Component Assy Check sum failure at 64°F. RMS stowing. A10, 2294869-503 ur Status 2, Component Assy Cause: Defective PRON 037-A7BD A11, 2294869-504. (2) Strobe Circuit Failure on <u>Corrective Action:</u> U37 PROM replaced per MASA Directive #12. All flight PROMS are to be tested at 40°F and 0°F to check performance. VSU Interface Assy A6, 2592386-501 or 2294865-504 Equipment groups 506 and 507 have been redesigned to use PROM that is (3) Microcomputer Assy less susceptible to temperature failure. A7, 2599298-501 or 2294866-504

		KEA12ED 2-1-B1	
FMEA NO. 1.1.19 CKITICALITY 2/1R		SHUTTLE CCTV CRITICAL ITEM\$ LIST.	UNIT <u>Remate Control Unit {RCU</u> DWG ND. <u>2294824-506, 587</u> SMEET <u>8</u> OF <u>8</u>
FAILURE NODE AND CAUSE Tamera power enable signal ails low. Tauses: 1) Data register relay on Status 1, Component Assy AlO, 2294869-503 or Status 2, Component Assy All, 2294869-504. 2) Strobe Circuit Failure on WSU Interface Assy A6, 2592386-501 or 2294865-504 3) Microcomputer Assy A7, 2599298-501 or 2294866-504	FAILURE EFFECT ON END TIEM Camera power enable slicks low, camera will not turn bo. Worst Case: Loss of elbow PTU motion could prevent RMS stowing.	OPERATIONAL EFFECTS Loss of ability to position the elbow camera. Possible the elbow camera physically interferes with a payload, port payload bay door cannot be closed. Loss of crew an CREW ACTIONS Perform EVA to repusition the elbow camera, use RMS motion jettison the RMS. CREW TRAINING Crew should be trained in contingency EVA and RMS operate MISSION CONSTRAINT Do not manifest elbow camera for any flight where the patcan interfere with each other (for any pan or tilt angle flown do not change the camera position until the interference of the camera position until th	inability to stow the AMS if If RMS cannot be stowed the d vehicle. on to reposition the camera, lons procedures. Lyload and the elbow camera