PMEA NO	 	SHUTTLE CCTV CRITECAL ITEMS LIST	UNIT <u>1YC/MLA</u> DWG NO. 2294819-506.508/ 2294828-502 SWEET <u>1</u> OF <u>9</u>
	CRITICAL ITEMS LIST RATIONALE FOR ACCEPTANCE DESIGN FEATURES The TVC/Lens Assembly is comprised of 16 electrical subtained and fabricated using standard propostruction. The remaining three assemblies, high voltand stepper motors, are vendor supplied components which purchased according to RCA Specification Control Drawin neering and reliability assurance. Specifications per establish the design, performance, test, qualification, for a procured piece of equipment. Parts, materials, processes, and design guidelines for specified in accordance with RCA 2295503. This document ments for selection and tontrol of FFE parts. To the match availability, all parts have been selected from midDAN level, as a minimum. In addition to the overall segmenal purpose preferred parts has been defined by this ment Systems division Standard Parts List. In the case microcircuits, devices are screened and tested to the Morocured under the designations of HI-REL/3NQ and SNC 5 Instruments Corp, respectively. Parts not included in used in the design only after a monstandard item approximated in the design only after a monstandard item approximated in the design only after a monstandard item approximated in the design only after a monstandard item approximated in the MSIAF by NAS Worst-Case Circuit Analyses have been performed and doc designs to demonstrate that sufficient operating margin conditions. The analysis was worst case—in that the vaparameters was set to limits that will drive the output A component application review and analysis was conduct stress on each piece part by the temperature extremes it qualification testing does not exceed the stress deration 2295503. In addition, an objective examination of the design was COR to verify that the TVC/Lens assembly met specificat	assemblies: 13 subassemblies inted-circuit board type of tage power supply, oscillator, heave been specified and gs (SCOs) prepared by engithe SCO are prepared to and acceptance requirements. The Shuttle CCTV program are t defines the program require-aximum extent, and consistent litary specifications at the lection criteria, a subset of s document and the RCA Governof the CHOS and TIL family of IL-SIO-083C equivalent and 4LS from RCA-SSO and Texas the above documents have been all form (ASIAF) has been pre-RAE) and approved for use in A-JSC. umented for all circuit s exist for all operating lue for each of the variable to a maximum (or minimum). ed to verify that the applied dentified with environmental no values identified in RCA performed through a POR and	
,		ments.	•

FMEA NO2.1.1		SHUTTLE COIV CRITICAL ITEMS LIST	UNIT TYC/MLA
FAILURE HODE AND CAUSE a output signal to the VSU. Neither ideo or synchronization information is present. YC 1, 2294888-504 Sync Generator Clock ivider Chain. 2, 2294881-50) Camera Training ogic. A4, 2294884-503 Sync forwalter Video Output Orive. 6, 2294085-501 Power ON/OFF witching Input Voltage Preagulator. Output Voltage Regulator. 7, 2794886-503 OC-DC Converter Prinary Oscillator Orive. Secondary sectifiers/Filters. 13, 2295527-1 Master Oscillator.	FATLURE EFFECT ON END LITM Loss of camera butput depicting scene information within FOV of lens assembly. Worst Case: Loss of mission critical video.	CESEGN FEATURES (Continued) BARE BOARD DESIGN (A1, A6, A7) The design for the associated boards A1, A6, and A7 a copper-clad epoxy glass sheets (NEMA G-10) Grade fR-4 connections are made through priated traces which run board surfaces. Every trace terminates at an annular surrounds the hole in which a component lead or terminates a footing for the solder, ensuring good mech performance. Its size and shape are governed by MIL-spacing and routing. These requirements are reiterat notes to further assure compliance. Variations between final product (due to irregularities of the atching p drawing notes. This prevents making defective boards house no lead or terminal, but serve only to electric board layers, contain stitch bars for mechanical supp. The thru holes are drilled from a drill tape thus elihoman error and allowing tight control over hole and important reliability criterion. After drilling and tim-lead plated per MIL-STD-1495. This provides for the time of board assembly, even after periods of pro-BOARD ASSEMBLY DESIGN (A1, A6, A7) All components are installed in a manner which assure Component leads are pre-tinned, allowing total wetting are formed to provide stress relief and the bodies of Special mounting and handling instructions are includanter final assembly. The board is coaled with ureth humidity and contamination.	re constructed from laminated), PER MIL-P-S5617A. 'Circuit from point to point on the ring. The annular ring nal is located. This ring anital and electrical P-S5640 as are trace widths, ed specifically in drawing en the artwork master and the rocess) are also controlled by from guod artwork. Boles which ally interconnect the different ort and increased reliability. pinating the possibility of annular ring concentricity, an etching, all copper cladding is easy and reliable soldering at donged storage. The maximum reliability. The solder joints are staked. The solder is are staked.
	1		

	· · ·		UNIT TYC/NIA
FMEA ND		SHUTTLE CCTV CRITICAL LIENS LIST	DMG NO. <u>2294819-506.508/</u> <u>2294820-502</u>
			SHEET 3 , OF 9
FATTIME MODE AND CAUSE	FAILURE EFFECT ON END ITEM	RATIONALE FOR ACCEPTANCE	
output signal to the VSD. Neither dec or synchronization information present. (C) (C) (C) (C) (C) (C) (C) (C	Loss of camera output depicting scene informa- tion within FOV of lens assembly. Horst Case: Loss of Mission critical video.	DESIGN FEATURES [Continued] BARE BOARD COMSTRUCTION (A2] The boards are of "melded wire" construction. At the distinguish it from a normal PC board except that holigenerally are not connected to PC traces. Only those ground potentials to the ICs are on PCs. An annular is board where each power and ground pin is located. This the trace like any other component lead. Aside from & construction techniques used in PC board layout app BOARD ASSEMBLY (A2) The drilled and etched boards are populated with sever weldable pins. Power and ground pins, as well as complace. Discreet components (resistors, dindes, capac bifurcated terminals, where they are soldered. Flatplead-by-lead to the tops of the weld pins. After well trimmed away. Circuit connections are made using 834 wire is welded to the pin surfaces on the board backs using a machine which is tape driven, thus eliminating due to operator error. All wiring & circuit performated box-level installation. After successful testing, comby drawing notes and the assembly is coated with urely by drawing notes and the assembly is coated with urely Ine boards. BUARD PLACEMENT The A7-A low voltage power supply board is bolted in perimeter. Four of these mounting screws also pass that A7-A houses a 34-pin connector which brings in power mounted. The A7 module includes these two boards as well as power housing is bent aluminum sheet, comprised of two halve and Q4 are secured to the lower half, and wired togeth put in place. By mounting Qil directly to the aluminum performance is assured. The A1 module beryllium copper card guides. Connection with blind-mated connectors. Disengagement buring la	es which will take weld pins pins which bring power and ring surrounds the hole in the ese pins are then soldered to this feature, all design ly. The real hundred solderable or nector pins, are soldered in iters) are attached to esk ICs are welded, ling, extra lead material is AMS nickel weld wire. The lide. All wire welds are done is tested prior to apponents are staked as required name. The same manner as the other is separated by the standoffs. The separated by the standoffs. The and signals from outside the est screwed together. The module est screwed together. The boards her. Then the upper half is a housing, good thermal its are made to the mother board.

			REVISED 11-3-6
FMEA NO	 	SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT <u>IVC/MLA</u> DWG NO. 2294819-506.508/ 2794820-502 SHEET <u>4</u> OF <u>9</u>
FAILURE MODE AND CAUSE No output signal to the VSU. Neither video or synchronization information is present. IVC Al, 2294800-504 Sync Generator Elock Divider Chain. A2, 2294881-501 Camera Training togic. A4, 2294884-503 Sync Formatter Video Output Drive. A6, 2294065-501 Power ON/OFF Switching Input Voltage Preregulator. Output Voltage Regulator A7, 2294886-503 OC-DC Converter Primary Dscillator Drive. Secondary Rectifiers/Filters. A11, 2295527-1 Master Oscillator.	FAILURE EFFECT DN END ITEM Loss of camera output depicting scene informa- depicting scene informa- tion within fDV of lens assembly. Worst Case: Loss of mission critical wideo.	The Al3 assembly is a temperature compensated volt (TCVCXO) that is purchased to a specification contitue requirements for performance, design, test, an product assurance provisions of the document contaelectronic parts and materials as the Shuttle CCTV approval of RCA and MASA-JSC. Mechanical and electris confirmed by both analysis (design reviews) and QUALIFICATION TEST for Qualification Test Flow, see Table 2 located a	age controlled crystal oscillator rolled drawing that establishes d qualification of the unit. The lateritical requirements for program and must receive the trical integrity of the assembly test (qualification and acceptance).
	I	I	

		ī		I UNIT TYCZNUA
FMFA NO		SHUTTLE CCTV CRITICAL IVEMS LIST		DWG NO. 2294819-596,5087
CRITICALLIY 2/2				SHEET 5 OF 9
FAILURE HODE AND CAUSE	FAILURE EFFECT ON END CLEM		RATIONALE FOR ACCEPTANCE	
TAILURE MODE AND FAILURE EFFECT	might be used in the Vibration: • The TVC/MLA may not for Acceptance Test OPENATIONAL TESTS In order to varify health of all the othrough the ACU, the decoder. The test ability to route vimould be performed Pre-Launch on 1. Power CCTV 2. Via the Photest as so 3. Send "Came	VC/MLA is subjected directly, withouse'r normal installation, to the follows: 20-80Hz: 3 dB/Oct-rise from 80-350 Hz: 0.04 G*/Hz 350-750 Hz: -3 dB/10 Oct-slope Test Duration: 1 Minute per Axis Test Level: 6.1 Grms In a pressure of IXIO-5 Torr, the follows: 125° f: lime to stablize equipment 25° f: lime to stablize equipment 125° f: lime to stablize equipment 125	of vibration isolators which lowing testing: 0.01 G ² /Hz comperature shall be as plus I hour plus I hour plus I hour condition. condition. cont of this book. A test sust verify the CHS (A7AI) panel switch, CTU, to the Camera/PTU command by to produce video, the VSU's splay video. A similar test ation and the camera under	
		5. Observe vi synchroniz is receivi	ternal Sync" on monitor. dec displayed on monitor. Note that ed (i.e., stable raster) then this i ng composite sync from the RCU and t	indicates that the camera
		synchronia ú. Send Pan, vía the mo 7. Select dov	red widen. Tilt, focus, Zoom, DtR. AND Gamma co mitor or direct observation) verify mijnk as destination and camera under deo routed to downlink.	mmands and visually (either operation.
l		9. Send "Caina	era Power Off" command via PHS panel.	

FMEA NO		SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT TYC/MLA DHG NO 2294819-506,508/ 2794820-502 SHEET 6 0F 9
FAILURE MODE AND FAILURE EFFECT ON END ITEM		RATIONALE FOR ACCEPTANCE	
No output signal to the VSU. Neither video or synchronization information is present. IVC A1. 2294880-504 Sync Generator Clock Divider Chain. A2. 2294881-501 Camera Training Logic. A4. 2294884-503 Sync Formatter Video Output Orive. A6. 2294885-501 Power DN/OFF Switching Input Voltage Precegulator. Dutput Voltage Regulator A7. 2294886-503 OC-OC Converter Primary Oscillator Orive. Secondary Rectifiers/filters. A13. 2295527-1 Master Oscillator.	Loss of camera output depicting scene information within FOV of lens assembly. Worst Case: Loss of mission critical video.	Procurement Control — The TVC/MLA EEE Parts and hardwapproved vendors and suppliers, which must the requiremented and Quality Plan Work Statement (NS-2593176) review all procurement documents to establish the need (PAL 517). Incoming Inspection and Storage — Encoming Quality in received materials and parts. Results are recorded to drawing and control numbers for future reference and are subjected to incoming acceptance tests as called Inspection Test Instructions. Incoming flight parts accordance with ACA 1846684 — Preconditioning and Acc Electronic Parts, with the exception that DPA and PIM Mechanical items are inspected per PAL 316 — Incoming machanical items, PAL 305 — Incoming Quality Control PAL 612 — Procedure for Processing Incoming or Purchause. Accepted items are delivered to Material Control Specified conditions until fabrication is required, held for Material Review Board (MRB) disposition. (ABB) disposition. (ABB) disposition against the as-built-parts-list (ABPL), DCA are designated for all printed circuit, wire wrap and tharness connectors for soldering wiring, crimping, st workmanship prior to coating of the component side of harnesses.	rements set forth in the CCTV Resident DCAS personnel of for GSI on selected parts respections are made on all sy lot and retained in file by traceability. All EEE parts for in PAI 315 - Incoming are further processed in reptance Requirements for inspection Instructions for Inspection Instruction, and sed Parts Designated for flight alled Stores and retained under Non-comforming materials are PAI-30), PAI IQC-531.) and assembly, all items as the items are accumulated to rator who assembles the kit by AS Mandatory Inspection Points is welded wire boards, plus older splices and quality
·		IVC Soards	
		Specific TVC board assembly and test instructions are applicable documents are called out in the fabrication (FPR-2294819) and parts list PL2294819. These includes 2593660, Process Standard RTV-566 2280881, Specification Soldering 2280880, Specification - Crimping 22808800, Specification - Urethone coating 2280877, Specification - Urethone coating 2280881, Specification - Urethone Coating 228088	on Procedure and Record de shuttle TVC assembly notes tandard - Bondiny Velcro Tape ion Name Plate Application tion - Bonding and Staking

2026176, Specification Epoxy Adhesive 2010985, Specification - Harking 2280876, Specification - Workmanship 8030035, Specification Bonding and Staking 2280875.

		KFA12FD 10-14-80
	SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT TYC/MLA DWG NB . 2294819-506.508/ 2294820-502 SHEET 7 OF 9
FAILURE EFFECT ON END ITEM Loss of camera output Assisting scene informa-	RATIONALE FOR ACCEPTAN OA/INSPECTION (Continued)	GE
tion within FOV of lens assembly.	<u>IVC Assembly and lest</u>	•
present. tion within FOV of Jens	An open box test is performed per TP-II-2294B19, and an Acceptance Test per IP-AT-2294B19, including vibration and thermal vacuum. Tarques are specified and witnessed, traceability numbers are recorded and calibrated tools are checked prior to use. RCA Quality and DCAS inspections are performed at the completion of specified FPR operations in accordance with PAI-20A, PAI-205, PAI 206 and PAI 217. DCAS personnel witness IVC button-up and critical torquing. IVC/NEA Assembly and Test — After a IVC and an HLA have has been tested individually, they are mated and a final acceptance test is performed per IP-AT-2294B19, including vibration and thermal vacuum environments. RCA and DCAS personnel monitor these tests and review the acceptance test data/results. These personnel also inspect for conformance after all repair, rework and retest. Preparation for Shipment — The TVC and NLA are separated prior to shipment after fabrication and testing is complete. Each is packaged according to CCIV letter 801) and 2280746, Process standard for Packaging and Handling guidelines. All related documentation including assembly drawings, Parts List, ABPL, Test Data, etc., is gathered and held in a documentation folder assigned specifically to each assembly. This folder is retained for reference. An E10P is prepared for each assembly in accordance with the requirements of H5-2593176. RCA QE and DCAS personnel witness cruting, packaging, packing, and marking, and review the E10P for completeness and accordance.	
	ON FND LTEM Loss of camera output depicting scene informa- tion within FOV of lens assembly. Worst Case: toss of wission critical	FAILURE EFFECT ON FND ITEN Loss of camera output depicting scene information within FOV of lens assembly. Worst Case: toss of mission critical video. Marst Case: toss of mission critical video. Marst Case: toss of mission critical video. An open box test is performed per TP-II-2294819, and IP-AT-2294819, including vibration and thermal vacuum vitaessed, traceability numbers are recorded and call to use. RCA Quality and DCAS inspections are perform specified FPR operations in accordance with PAI-204, DCAS personnel witness TVC button-up and critical too IVC/MA Assembly and Test - After a TVC and an HLA had they are mated and a final acceptance test is perform vibration and thermal vacuum environments. RCA and Cand review the acceptance test data/results. These pafter all repair, rework and retest. March Ma

TVC/MLA DHG NO. 2294819-506.508/ SHUTTLE CCTV CRIFICAL ITEMS LIST 2294820<u>-502</u> ___8___ OF CRITICALITY __2/2 FAILURE EFFECT FAILURE MODE AND RATIONALE FOR ACCEPTANCE DN ENO TIEM CAUSE FAILURE HISTORY Loss of camera output No output signal to the VSU. Neither depicting scene informavideo or synchronization information TOR - W2644 - Log #0462, TVC S/N F003-502 tion within FOV of lens is present. IDR - W2640 - Log #0463, FVC S/N F003-502 assembly. <u>Description</u>: Integration Testing Failure Worst Case: Al. 2294880-504 Sync Generator Clock Bux Level loss of mission critical Divider Chain. Thermal-Vac Hot Environment video. A2, 2294881-501 Camera Training No wideo from IVC. +28 volt current at 1.5 Amp limit. (30 minutes into thermal togic. A4, 2294084-503 Sync Forvac hol test cycle -105°F) matter Video Output Drive. Cause: Short in A7 low voltage power supply. (High voltage winding of A6, 2294885-501 Power ON/OFF transformer) Switching Input Voltage Preregulator. Output Voltage Regulator <u>Corrective Action:</u> Removed and replaced transformer (sent to vendor for analysis). A7. 2294886-503 DC-DC Converter Pri-Short due to a pin-hole in magnet wire insulation. mary Oscillator Orive. Secondary Future transformers to be purchased per revised spec control drawing ECN CCTV Rectifiers/Filters. 649(B3**92**B). A13, 2295527-1 Naster Oscillator. 10R - W2/40 - Log #0486 - IVC S/N 008-502<u>Description</u>: Pre-Launch Test failure Box Level Ambient Environment REC: VJCS-2-01-0097 unit returned from KSC. Power was applied to wrong pins. 1+28V). Cause: Incorrect wiring of shuttle craft harness, put +28V to J3-10 and ATN to J1-9. Corrective Action: Miring of shuttle harness to be repaired by responsible organization. Failure analysis performed and corrective action taken on TVC S/N 008. A6 board-failure analysis indicated the following parts are to be changed. Q1, Q3, Q12, CR3, CR6, and R51 were replaced. TOR:- W8024 - Log #0530 - TVC 5/N 007-502 <u>Description</u>: Acceptance Test Failure Bux Level Thermal Vac - Hot Environment. TVC drawing excessive current, >1.5A. Failure occurred at +125°F. Cause: Capacitor CNN on the A6 board was found to be shorted. A large quantity of solder flowed inside from sleeve thro header. Corrective Action: Capacitor ClO removed & replaced, (random part failure).

JYCZMLA

UNIT

SHUTTLE CCSV DWG NO. 2294819-506.508/ FMEA NO. __2.1.1 CRITICAL TIEMS LESS 2294820-502 A8 ÐΕ CRETICALITY _ 2/2 SHEET FAILURE NODE AND FAILURE EFFECT RATIONALE FOR ACCEPTANCE -ON END ITEM CAUSE FALLURE BISTORY No output signal to the VSU. Neither Loss of camera output depicting scene informavideo or synchronization information FOR - N6823 - Log #558 - TVC 5/N 032-502 tion within FOV of lens is present. Y)771 - Log #56B - LVC S/N 009-502 assembly. Y1771 - Lag #568 - TVC S/N 002-502 Y1771 - Lag #568 - TVC S/N 009-502 Al. 2294880-584 Sync Generator Clack **Horst Case:** Y1770 - Log #567 - TVC - \$/N 014-502 Loss of mission critical Divider Chain. Y1770 - Lag #567 - TVC 5/N 010-502 videa. Y1770 - Log #568 - TVC S/H 017-502 Az. 2294881-501 Camera Training M1729 = Log #578 = TVC - S/N 020-502Logic. A4, 2294884-503 Sync Formatter Video Output Drive. <u> Nescription</u>: Flight Failure, Spacecraft Level RHS TV Camera circuit breaker pupped open during flight mission STS-3. A6, 2294885-501 Power DN/OFF Switching Input Voltage Pre-Cause: Camera low voltage supply has erratic syncronization mode at low regulator. Dutput Voltage Regulator temperatura. A7, 2294886-503 OC-OC Converter Priwary Oscillator Orive. Secondary Corrective Action: All flight cameras were returned under CCA35 for rework Rectifiers/filters. and retest to ECN (-1881). ECN (C-1881) to the low voltage power supplies eliminates the erratic syncronization problem. TVC group part no. has been AND, 2295527-1 Haster Dscillator. changed from 2294819-502 to 504 to denote cameras that contain low voltage power supply modification. 108 - 91773 - 109 #0570 - 190 \$/N 008-502<u>Description</u>: flight failure Spacecraft Level (STS-3) IVC not synchronized for approximately 38 minutes. This problem occured at cold temperature. Synchronization was required at 20C. Couse: Loss of phase lock due to thermal assymetry of the 3.58 MHz Phase detector. Corrective Action: CCA 39 has been issued directing BCA to incorporate the heater and sync modifications (ECN CC1 030) to all flight camera's. (VC 008 was madified accordingly. TVC group number has been updated from group 502 to 506. IOR - Y1779 - Eng #576 - IVC S/N 014-502 <u>Description</u>: Flight Failure (STS-3) Spacecraft Level TOR was opened to fullow relay K) - contacts 5 and 8 failure on uss'y 2294885-501 S/N F018.

UNET TYC/MLA_. SHUTTLE CCTV DMG NO. 2294819-506.5082 FMEA NO. __2,1,1 ...___ CRITICAL ITEMS LIST 2294820-502 8B CHITICALITY 2/2 FAILUKÉ NODE AND FALLURE EFFECT ON END TIEM RATIONALE FOR ACCEPTANCE CAUSE FAILURE HISTORY No output signal to the VSU. Neither Loss of camera output depicting scene informavideo ur synchronization information <u>Cause:</u> TVC low unitage power supply has erratic synchronization at low tion within FOV of lens is present. temperature. Relay failure result of excessively high current through contacts assembly. 5 and 8 during reset command. Å1. 2294860-504 Sync Generator Clock **Vorst Case:** Corrective Action: Removed and replaced Ki on the A6 board. Loss of mission critical Divider Chain. Low voltage power supply was reworked to ECN-C1881. wideo. Refer to FDR M6823 for complete history of erratic synchronization problem. A2, 22948B1-501 Camera Training logic. A4, 2294884-503 Sync For-TDR - V1760 - Log #0838 - TVC S/N 026-506 natter Video Output Drive. Ocscription: Flight failure, Spacecraft Level A6. 2294885-501 Power ON/OFF STS-8 Switching Input Voltage Pre-During the flight operations, one time when crew turned camera on they had no renulator. Dutput Voltage Regulator control of ALC and Gamma functions. A7. 2294806-503 DE-DC Converter Pri-Problem resolved itself by recycling power. mary Oscillator Orive. Secondary kectiliers/filters. <u>Cause</u>: After numerous operatons, the reported condition was duplicated on test set. After initial turn on, camera would not except ALC, and Gamma commands. All. 2295527-1 Haster Oscillator. It was found that the output of U33 Pin 6 CMD F.F. reset on A2 board was set in a high state. This should normally have been reset low by either "POR" or bit count 80 pulses, after initial power turn-on. Suspect devices A2 - U26, U66, U67, and U68. Corrective Action: Removed and replaced the following parts on the A2 Board U26, U66, U67, and U60. Lab analysis did not indicated any defect with removed parts. Problem has not recurred after new parts were installed. JDR - A3939 - Log #0954 - TVC S/N 031-506 <u>Oescription</u>: Flight Failure, Spacecraft Level SIS-14 Problem report PV6-004037 No viden mitput Cause: Defective Relay K-1 on the A6 Board. Corrective Action: Cause due to a foreign conductive particle temporarily ladged between relay leads and board P.C. traves. Relay K-1 sent to product assurance lab for analysis, report #A3909. Numerous discrepancies were found, none of which were critical.

		•	KEN1250 11-3-0
FMEA NO2.1.1 CRITICALITY2/2		SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT <u>TYC/HLA</u> DWG NO. 2294819-506,5087 2294820-502 SHEET <u>BC</u> OF <u>9</u>
TAILURE MODE AND CAUSE No output signal to the VSU. Neither video or synchronization information is present. IVE A1, 2294880-504 Sync Generator Clock Divider Chain. A2, 2294881-501 Camera Training Logic. A4, 2294804-503 Sync Formotter Video Output Drive. A0, 2294885-501 Power ON/OFF Switching Input Voltage Preregulator. Output Voltage Regulator A7, 2294886-503 BC-DC Converter Primary Oscillator Brive. Secondary Rectifiers/Filters. A13, 2295527-1 Master Oscillator.	FAILURE EFFECT ON END ITEM Loss of camera output depicting scene information within FOV of lens assembly. Horst Case: Loss of mission critical video.	RAILUNALL FOR ACCEPTANCE FAILURE MISTORY TOR - 8-3527 - Log #1165 - TVC S/N U38-508 Rescription: Acceptance lest Failure	nts and output video information.
		l .	

		HEAT 25 II 10-14-8		
FHEA NO2.3.1		SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT TVC/HLA DWG NO. 2294819-506.508/ 2294820-502 SHEET 9 0F 9	
TAILURE MODE AND CAUSE No output signal to the VSII. Neither video or synchronization information is present. IVC A1, 2294880-504 Sync Generator Clock Divider Chain. A2, 2294881-501 Camera Training Logic. A4, 2294884-503 Sync Formatter Video Output Drive. A6, 2294885-501 Power ON/OFF Switching Enput Voltage Pre-regulator. Output Voltage Regulator A7, 2294886-503 DC-DC Converter Primary Oscillator Drive. Secondary Reclifiers/filters. A13, 2295527-) Master Oscillator.	FAILURE EFFECT ON END ITEM Loss of camera output depicting scene informa- tion within FOV of lens assembly. Horst Cose: Loss of mission critical video.	RATIONAL EFFECTS Loss of video. Possible loss of major mission or other required cameras. CREM ACTIONS If possible, continue RMS operations using alterest JRAINING Crew should be trained to use possible alternate MISSION CONSTRAINT Where possible, procedures should be designed somethic.	EPTANCE objectives due to loss of RMS cameras rnative visual cues.	