

CRITICAL ITEMS LIST

PROJECT: SRMS
 ASS'Y NOMENCLATURE: SERVO POWER AMPLIFIER

SYSTEM: ELECTRICAL SUBSYSTEM
 ASS'Y P/N: 51120FT177

SHEET: 1

FMEA REF.	FMEA REV.	NAME, QTY, & DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	HOWR / FUNC. 2/2 CRITICALITY	RATIONALE FOR ACCEPTANCE SCREENS: N/A
3000	1	CURRENT LIMITER QTY-6 SCHEMATIC 256371B	<p>MODE: MDA BITE SIGNAL FAILS HIGH.</p> <p>CAUSE(S): (1) COMPARATOR CIRCUIT FAILURE.</p>	<p>ABE FAILURE ANNUNCIATION WITHOUT A GENUINE SYSTEM FAULT. CONSISTENCY CHECK FALSE ALARMS MAY OCCUR ESPECIALLY DURING PAYLOAD CAPTURE. AUTO BRAKES MAY BE INITIATED DURING A CAPTURE SEQUENCE. SEQUENCE MAY TAKE LONGER TO COMPLETE.</p> <p>WORST CASE ----- LOSS OF MISSION. LOSS OF COMPUTER SUPPORTED MODES.</p> <p>REDUNDANT PATHS REMAINING ----- N/A</p>	<p>DESIGN FEATURES -----</p> <p>COMPARATORS AND OPERATIONAL AMPLIFIERS ARE STANDARD LINEAR INTEGRATED CIRCUITS WITH MATURE MANUFACTURING TECHNOLOGY. APPLICATION CONSTRAINTS ARE IN ACCORDANCE WITH SPAR-RMS-PA.003.</p> <p>ALL RESISTORS AND CAPACITORS USED IN THE DESIGN ARE SELECTED FROM ESTABLISHED RELIABILITY (ER) TYPES. LIFE EXPECTANCY IS INCREASED BY ENSURING THAT ALL ALLOWABLE STRESS LEVELS ARE DERATED IN ACCORDANCE WITH SPAR-RMS-PA.003. ALL CERAMIC AND ELECTROLYTIC CAPACITORS ARE ROUTINELY SUBJECTED TO RADIOGRAPHIC INSPECTION.</p> <p>THE DESIGN UTILIZES PROVEN CIRCUIT TECHNIQUES AND IS IMPLEMENTED USING CMOS LOGIC DEVICES.</p> <p>CMOS DEVICES OPERATE AT LOW POWER AND HENCE DO NOT EXPERIENCE SIGNIFICANT OPERATING STRESSES. THE TECHNOLOGY IS MATURE, AND DEVICE RELIABILITY HISTORY IS WELL DOCUMENTED. ALL STRESSES ARE ADDITIONALLY REDUCED BY DERATING THE APPROPRIATE PARAMETERS IN ACCORDANCE WITH SPAR-RMS-PA.003. SPECIAL HANDLING PRECAUTIONS ARE USED AT ALL STAGES OF MANUFACTURE TO PRECLUDE DAMAGE/STRESS DUE TO ELECTROSTATIC DISCHARGE.</p>	

RMS/ELEC - 689

PREPARED BY: MFWG

SUPERCEDING DATE: 11 SEP 86

DATE: 24 JUL 91

CIL REV: 1

CRITICAL ITEM# LIST

PROJECT: SRMS
 ASS'Y NOMENCLATURE: SERVO LOWER AMPLIFIER

SYSTEM: ELECTRICAL SUBSYSTEM
 ASS'Y P/N: ST120FT177

SHEET: 2

FMEA REF.	FMEA REV.	NAME, QTY, & DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT OR END ITEM	HOWR / FUNC. 2/2 CRITICALITY	RATIONALE FOR ACCEPTANCE SCREENS: N/A
3000	1	CURRENT LIMITER QTY-6 SCHEMATIC 2563718	<p>MODE: MOA BITE SIGNAL FAILS HIGH.</p> <p>CAUSE(S): (1) COMPARATOR CIRCUIT FAILURE.</p>	<p>ABE FAILURE ANNUNCIATION WITHOUT A GENUINE SYSTEM FAULT. CONSISTENCY CHECK FALSE ALARMS MAY OCCUR ESPECIALLY DURING PAYLOAD CAPTURE. AUTO BRAKES MAY BE INITIATED DURING A CAPTURE SEQUENCE. SEQUENCE MAY TAKE LONGER TO COMPLETE.</p> <p>WORST CASE ----- LOSS OF MISSION. LOSS OF COMPUTER SUPPORTED MODES.</p> <p>REDUNDANT PATHS REMAINING ----- N/A</p>	<p>ACCEPTANCE TESTS ----- THE SPA IS SUBJECTED TO THE FOLLOWING ENVIRONMENTAL TESTING AS AN SRU.</p> <p>O VIBRATION: LEVEL AND DURATION - REFERENCE TABLE 4</p> <p>O THERMAL: PLUS 70 DEGREES C TO -25 DEGREES C DURATION - 1 1/2 CYCLES</p> <p>THE SPA IS THEN TESTED AS PART OF THE JOINTS ACCEPTANCE TESTS (VIBRATION AND THERMAL VACUUM TEST).</p> <p>THE SPA'S/JOINTS UNDERGO RMS SYSTEM TESTS (TP518 RMS STRONGBACK AND TP552 FLAT FLOOR TESTS) WHICH VERIFIES THE ABSENCE OF THE FAILURE MODE.</p> <p>QUALIFICATION TESTS ----- THE SPA IS SUBJECTED TO THE FOLLOWING SRU QUALIFICATION TEST ENVIRONMENTS. THE SPA WAS ALSO TESTED AS PART OF THE JOINT QUALIFICATION TESTS.</p> <p>O VIBRATION: LEVEL AND DURATION - REFERENCE TABLE 4</p> <p>O SHOCK: 20G/11 MS/3 AXES (6 DIRECTIONS)</p> <p>O THERMAL VAC: +81 DEGREES C TO -36 DEGREES C (6 CYCLES) 1X10**6 TORR</p> <p>O HUMIDITY: TESTED WITH THE SHOULDER JOINT</p> <p>O EMC: MIL-STD-461 AS MODIFIED BY SL-E-0002 (TEST CE01, CE03, CS01, CS02, CS06, RE01, RE02 (N/B), RS01)</p> <p>FLIGHT CHECKOUT ----- PDRS OPS CHECKLIST (ALL VEHICLES) JSC 16987</p>	

RMS/ELEC - 690

CRITICAL ITEMS LIST

PROJECT: SMS
ASS'Y NOMENCLATURE: SERVO POWER AMPLIFIER

SYSTEM: ELECTRICAL SUBSYSTEM
ASS'Y P/N: 51140FT177

SHEET: 3

FMEA REF.	FMEA REV.	NAME, QTY & DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	HOWR / FUNC. 2/2 CRITICALITY	RATIONALE FOR ACCEPTANCE SCREENS: N/A
3000	1	CURRENT LIMITER QTY-6 SCHEMATIC 2563716	<p>MODE: MDA BITE SIGNAL FAILS HIGH.</p> <p>CAUSE(S): (1) COMPARATOR CIRCUIT FAILURE.</p>	<p>ABE FAILURE ANNUNCIATION WITHOUT A GENUINE SYSTEM FAULT. CONSISTENCY CHECK FALSE ALARMS MAY OCCUR ESPECIALLY DURING PAYLOAD CAPTURE. AUTO BRAKES MAY BE INITIATED DURING A CAPTURE SEQUENCE. SEQUENCE MAY TAKE LONGER TO COMPLETE.</p> <p>WORST CASE ----- LOSS OF MISSION. LOSS OF COMPUTER SUPPORTED MODES.</p> <p>REDUNDANT PATHS REMAINING ----- N/A</p>	<p>QA/INSPECTIONS -----</p> <p>UNITS ARE MANUFACTURED UNDER DOCUMENTED QUALITY CONTROLS. THESE CONTROLS ARE EXERCISED THROUGHOUT DESIGN PROCUREMENT, PLANNING, RECEIVING, PROCESSING, FABRICATION, ASSEMBLY, TESTING AND SHIPPING OF THE UNITS. MANDATORY INSPECTION POINTS ARE EMPLOYED AT VARIOUS STAGES OF FABRICATION ASSEMBLY AND TEST. GOVERNMENT SOURCE INSPECTION IS INVOKED AT VARIOUS CONTROL LEVELS.</p> <p>EEE PARTS INSPECTION IS PERFORMED AS REQUIRED BY SPAR-RMS-PA.003. EACH EEE PART IS QUALIFIED AT THE PART LEVEL TO THE REQUIREMENTS OF THE APPLICABLE SPECIFICATION. ALL EEE PARTS ARE 100% SCREENED AND BURNED IN, AS A MINIMUM, AS REQUIRED BY SPAR-RMS-PA.003, BY THE SUPPLIER. ADDITIONALLY, EEE PARTS ARE 100% RE-SCREENED IN ACCORDANCE WITH REQUIREMENTS, BY AN INDEPENDENT SPAR APPROVED TESTING FACILITY. DPA IS PERFORMED AS REQUIRED BY PA.003 ON A RANDOMLY SELECTED 5% OF PARTS, MAXIMUM 5 PIECES, MINIMUM 3 PIECES FOR EACH LOT NUMBER/DATE CODE OF PARTS RECEIVED.</p> <p>WIRE IS PROCURED TO SPECIFICATION MIL-W-22759 OR MIL-W-81361 AND INSPECTED AND TESTED TO NASA JSC8000 STANDARD NUMBER 95A.</p> <p>RECEIVING INSPECTION VERIFIES THAT ALL PARTS RECEIVED ARE AS IDENTIFIED IN THE PROCUREMENT DOCUMENTS, THAT NO PHYSICAL DAMAGE HAS OCCURRED TO PARTS DURING SHIPMENT, THAT THE RECEIVING DOCUMENTS PROVIDE ADEQUATE TRACEABILITY INFORMATION AND SCREENING DATA CLEARLY IDENTIFIES ACCEPTABLE PARTS.</p> <p>PARTS ARE INSPECTED THROUGHOUT MANUFACTURE AND ASSEMBLY AS APPROPRIATE TO THE MANUFACTURING STAGE COMPLETED. THESE INSPECTIONS INCLUDE,</p> <p>PRINTED CIRCUIT BOARD INSPECTION FOR TRACK SEPARATION, DAMAGE AND ADEQUACY OF PLATED THROUGH HOLES,</p> <p>COMPONENT MOUNTING INSPECTION FOR CORRECT SOLDERING, WIRE LOOPING, STRAPPING, ETC. OPERATORS AND INSPECTORS ARE TRAINED AND CERTIFIED TO NASA NHB 5300.4(3A) STANDARD, AS MODIFIED BY JSC 0800A.</p> <p>CONFORMAL COATING INSPECTION FOR ADEQUATE PROCESSING IS PERFORMED USING ULTRAVIOLET LIGHT TECHNIQUES.</p> <p>POST P.C. BD. INSTALLATION INSPECTION, CLEANLINESS AND WORKMANSHIP (SPAR/GOVERNMENT REP. MANDATORY INSPECTION POINT)</p> <p>P.C. BD. INSTALLATION INSPECTION, CHECK FOR CORRECT BOARD INSTALLATION, ALIGNMENT OF BOARDS, PROPER CONNECTOR CONTACT MATING, WIRE ROUTING, STRAPPING OF WIRES ETC.,</p> <p>PRE-CLOSURE INSPECTION, WORKMANSHIP AND CLEANLINESS (SPAR/GOVERNMENT REP. - MANDATORY INSPECTION POINT)</p> <p>PRE-ACCEPTANCE TEST INSPECTION, WHICH INCLUDES AN AUDIT OF LOWER TIER INSPECTION COMPLETION, AS BUILT CONFIGURATION VERIFICATION TO AS DESIGN ETC., (MANDATORY INSPECTION POINT).</p>	

RMS/ELEC - 691

CRITICAL ITEMS LIST

PROJECT: SRMS

SYSTEM: ELECTRICAL SUBSYSTEM

ASS'Y NOMENCLATURE: SERVO POWER AMPLIFIER

ASS'Y P/N: 51740F1177

SHEET: 4

FMEA REF.	FMEA REV.	NAME, QTY, & DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	HWDR / FUNC. CRITICALITY RATIONALE FOR ACCEPTANCE SCREENS: N/A
3000	1	CURRENT LIMITER QTY-6 SCHEMATIC 2563710	MODE: MDA BITE SIGNAL FAILS HIGH. CAUSE(S): (1) COMPARATOR CIRCUIT FAILURE.	ABE FAILURE ANNUNCIATION WITHOUT A GENUINE SYSTEM FAULT. CONSISTENCY CHECK FALSE ALARMS MAY OCCUR ESPECIALLY DURING PAYLOAD CAPTURE. AUTO BRAKES MAY BE INITIATED DURING A CAPTURE SEQUENCE. SEQUENCE MAY TAKE LONGER TO COMPLETE. WORST CASE ----- LOSS OF MISSION. LOSS OF COMPUTER SUPPORTED MODES. REDUNDANT PATHS REMAINING ----- N/A	<p>A TEST READINESS REVIEW (TRR) WHICH INCLUDES VERIFICATION OF TEST PERSONNEL, TEST DOCUMENTS, TEST EQUIPMENT CALIBRATION/ VALIDATION STATUS AND HARDWARE CONFIGURATION IS CONVENED BY QUALITY ASSURANCE IN CONJUNCTION WITH ENGINEERING, RELIABILITY, CONFIGURATION CONTROL, SUPPLIER AS APPLICABLE, AND THE GOVERNMENT REPRESENTATIVE, PRIOR TO THE START OF ANY FORMAL TESTING (ACCEPTANCE OR QUALIFICATION).</p> <p>ACCEPTANCE TESTING (ATP) INCLUDES AMBIENT PERFORMANCE, THERMAL AND VIBRATION TESTING, (SPAR/GOVERNMENT REP. - MANDATORY INSPECTION POINT).</p> <p>INTEGRATION OF UNIT TO JOINT SRU - INSPECTIONS INCLUDE GROUNDING CHECKS, CONNECTORS FOR BENT OR PUSHBACK CONTACTS, VISUAL, CLEANLINESS, INTERCONNECT WIRING AND POWER UP TEST TO THE APPROPRIATE JOINT INSPECTION TEST PROCEDURE (ITP) ETC.</p> <p>JOINT LEVEL PRE-ACCEPTANCE TEST INSPECTION, INCLUDES AN AUDIT OF LOWER TIER INSPECTION COMPLETION, AS BUILT CONFIGURATION VERIFICATION TO AS DESIGN ETC.</p> <p>JOINT LEVEL ACCEPTANCE TESTING (ATP) INCLUDES AMBIENT, VIBRATION AND THERMAL-VAC TESTING. (SPAN/GOVERNMENT REP. - MANDATORY INSPECTION POINT).</p> <p>SRMS SYSTEMS INTEGRATION, THE INTEGRATION OF MECHANICAL ARM SUBASSEMBLIES AND THE FLIGHT CABIN EQUIPMENT TO FORM THE SRMS. INSPECTIONS ARE PERFORMED AT EACH PHASE OF INTEGRATION WHICH INCLUDES GROUNDING CHECKS, THRU WIRING CHECKS, WIRING ROUTING, INTERFACE CONNECTORS FOR BENT OR PUSH BACK CONTACTS ETC.</p> <p>SRMS SYSTEMS TESTING - STRONGBACK AND FLAT FLOOR AMBIENT PERFORMANCE TEST. (SPAR/GOVERNMENT REP. - MANDATORY INSPECTION POINT)</p>

RMS/ELEC - 692

PREPARED BY:

HWG

SUPERSEDING DATE: 11 SEP 86

APPROVED BY:

DATE: 24 JUL 91

CIL REV: 1

CRITICAL ITEMS LIST

PROJECT: SRMS
 ASS'Y NOMENCLATURE: SERVO POWER AMPLIFIER

SYSTEM: ELECTRICAL SUBSYSTEM
 ASS'Y P/N: 51140FT177 SHEET: 5

IHEA REF.	IHEA REV.	NAME, QTY & DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT OR END ITEM	HDWR / FUNC. 2/2 CRITICALITY	RATIONALE FOR ACCEPTANCE SCREENS: N/A
3000	1	CURRENT LIMITER QTY-6 SCHEMATIC 2563710	MODE: MDA BITE SIGNAL FAILS HIGH. CAUSE(S): (1) COMPARATOR CIRCUIT FAILURE.	ABE FAILURE ANNUNCIATION WITHOUT A GENUINE SYSTEM FAULT. CONSISTENCY CHECK FALSE ALARMS MAY OCCUR ESPECIALLY DURING PAYLOAD CAPTURE. AUTO BRAKES MAY BE INITIATED DURING A CAPTURE SEQUENCE. SEQUENCE MAY TAKE LONGER TO COMPLETE. WORST CASE ----- LOSS OF MISSION. LOSS OF COMPUTER SUPPORTED MODES. REDUNDANT PATHS REMAINING ----- N/A	FAILURE HISTORY ----- THE FOLLOWING FAILURE ANALYSIS REPORT(S) ARE RELEVANT: FAR 3321: S/W 314 OCT 82 DESCRIPTION ----- SSC-1, MDA BITE ERROR, RANDOM FAILURE OF U25, JM 38510/10304 BHA VOLTAGE COMPARATOR. CORRECTIVE ACTION ----- REPLACED U25	

RMS/ELEC - 693

CRITICAL ITEMS LIST

PROJECT: SRMS

ASS'Y NOMENCLATURE: SERVO POWER AMPLIFIER

SYSTEM: ELECTRICAL SUBSYSTEM

ASS'Y P/N: 512001177

SHEET: 6

FMEA REF.	FMEA REV.	NAME, QTY, & DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	HOWR / FUNC. 2/2 CRITICALITY	RATIONALE FOR ACCEPTANCE SCREENS: N/A
3000	1	CURRENT LIMITER QTY-6 SCHEMATIC 2563718	MODE: MDA BITE SIGNAL FAILS HIGH. CAUSE(S): (1) COMPARATOR CIRCUIT FAILURE.	ABE FAILURE ANNUNCIATION WITHOUT A GENUINE SYSTEM FAULT. CONSISTENCY CHECK FALSE ALARMS MAY OCCUR ESPECIALLY DURING PAYLOAD CAPTURE. AUTO BRAKES MAY BE INITIATED DURING A CAPTURE SEQUENCE. SEQUENCE MAY TAKE LONGER TO COMPLETE. WORST CASE ----- LOSS OF MISSION. LOSS OF COMPUTER SUPPORTED MODES. REDUNDANT PATHS REMAINING ----- N/A	OPERATIONAL EFFECTS ----- IF CONSISTENCY CHECK FALSE ALARM OCCURS DURING CAPTURE/RIGIDIZE SEQUENCE THEN ARM WILL NOT LIMP. ARM JOINTS WILL NOT CONFORM TO PAYLOAD DURING A CAPTURE SEQUENCE. IF THERE IS ANY MISALIGNMENT WITH THE GRAPPLE FIXTURE, THE PAYLOAD WILL CHANGE ITS ATTITUDE DURING A FREE FLYING CAPTURE, OR THE ARM WILL BE PRELOADED IF THE PAYLOAD IS BERTHED. IT MAY TAKE LONGER TO COMPLETE A CAPTURE SEQUENCE. CREW ACTION ----- NONE FOR FREE FLYING CAPTURES. ENTER TEST MODE TO LIMP ARM AFTER COMPLETION OF A BERTHED PAYLOAD CAPTURE. CREW TRAINING ----- CREW SHOULD BE TRAINED TO OBTAIN MINIMUM MISALIGNMENT ERRORS PRIOR TO CAPTURE OF PAYLOAD TO KEEP PRELOAD ON ARM TO A MINIMUM. MISSION CONSTRAINT ----- WHEN CAPTURING A FREE FLYER, THE EE MUST BE FAR ENOUGH AWAY FROM STRUCTURE TO PROHIBIT CONTACT REGARDLESS OF PAYLOAD ROTATIONS. OHRSD OFFLINE ----- VERIFY ON ABE DATA, MDA FLAG IS NOT SET OHRSD ONLINE INSTALLATION ----- NONE OHRSD ONLINE TURNAROUND ----- VERIFY ON ABE DATA, MDA FLAG IS NOT SET	

RMS/ELEC - 694

PREPARED BY:

MFVG

SUPRECEDING DATE: 11 SEP 84

APPROVED BY:

DATE: 24 JUL 91

CIL REV: 1