PROJECT: SRMS
ASS'Y NOMERCLATURE: SERVO FOLER AMPLIFIER SYSTEM: ELECTRICAL SUBSYSTEM
ASS'Y P/N: 51140F1177 SHEFT:

FMEA REF.	FMEA REV.	MAME DTY & DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEN	HDWR / FUNC. RATIONALE FOR ACCEPTANCE  2/18 CRITICALITY SCREENS A-PASS M-PASS C-PASS
SO10	ME	CURRENT LIMITER DIY-6 SCHEMATIC 2563718	MODE: FAILURE OF CURRENT LINIT CCT.  CAUSE(\$): (1) EEE PARTS FAILURE. (U0 FAILURE).	JOINT RUNAWAY WILL OCCUR, FMD/BKD FLAG WILL BE SET TO BKD. BUT MDA BITE WILL BE SET. CONSISTENCY CHECK (ENVELOPE) WILL DETECT. LOSS OF LIMPING DURING END EFFECTOR CAPTURE. WORST CASE UMENPECTED MOTTON. JOINT RUNAWAY. AUTOBRAKES. REDUNDANT PATHS REMAINING AUTOBRAKES	DESIGN FEATURES  COMPARATORS AND OPERATIONAL AMPLIFIERS ARE STANDARD LINEAR INTEGRATED CIRCUITS WITH MATURE MANUFACTURING TECHNOLOGY.  APPLICATION CONSTRAINTS ARE IN ACCORDANCE WITH SPAR-RMS-PA.003.  ALL RESISTORS AND CAPACITORS USED IN THE DESIGN ARE SELECTED FROM ESTABLISHED RELEASELY (ER) TYPES. LITE EMPECTANCY IS INCREASED BY BEUSKING THAT ALL ALLOWABLE STRESS LEVELS ARE DERATED IN ACCORDANCE WITH SPAR MS-PA.003. ALL CERAMIC AND ELECTROLITIC CAPACITORS ARE ROUTIMELY SUBJECTED TO RADIOGRAPHIC INSPECTION.
					DATE: 24 JUL 91 CIL REV: 1

PROJECT: SAMS ASS'Y MOMERCEATURE: SERVO POWER AMPLIFIER SYSTEM: ELECTRICAL SUBSYSTEM ASS'Y P/R: 5114071177 SHEET: \_\_Z THEA **FMEA** DRAUING REF. FATLURE MODE FAILURE EFFECT HDWR / FUNC. RAFJONALE FOR ACCEPTANCE REF. REV. AND 2/1R DESIGNATION CAUSE END ITEM CRITICALITY SCREENS: A-PASS, B-PASS, C-PASS 3010 1 CURRENT HODE: JOINT RUNAWAY ACCEPTANCE TESTS WILL OCCUR. LIHITER FAILURE OF 011-6 CURRENT FWD/BKD FLAG THE SPA IS SUBJECTED TO THE FOLLOWING ENVIRONMENTAL TESTING AS SCHEMATIC LIMIT CCT. WILL BE SET TO 2563718 BKD. BUT MOA CAUSE(S): BITE WILL BE O VISRATION: LEVEL AND DURATION - REFERENCE TABLE 4 (1) EEE SE1. PARTS CONSISTENCY O THERMAL: PLUS 70 DEGREES C TO -25 DEGREES C DURATION -FALLURE. CHECK 1 1/2 CYCLES (80) (ENVELOPE) WILL FAILURE). THE SPA IS THEN TESTED AS PART OF THE JOINTS ACCEPTANCE TESTS (VIBRATION AND THERMAL VACUUM TEST). DETECT. LOSS OF LIMPING DURING END EFFECTOR THE SPA'S/JOINTS UNDERGO RMS SYSTEM TESTS (TP518 RMS CAPTURE. STRONGBACK AND TP552 FLAT FLOOR TESTS) WHICH VERIFIES THE WORST CASE ABSENCE OF THE FAILURE MODE. UNEXPECTED QUALIFICATION TESTS HOTION, JOINT RUNAVAY. THE SPA IS SUBJECTED TO THE FOLLOWING SRU QUALIFICATION TEST AUTOBRAKES. ENVIRONMENTS. THE SPA WAS ALSO TESTED AS PART OF THE JOINT QUALIFICATION TESTS. REDUNDANT PATHS REMAINING O VISRATION: LEVEL AND DURATION - REFERENCE TABLE 4 AUTOBRAKES O SHOCK: 20G/11 MS/3 AKES (6 DIRECTIONS) O THERMAL VAC: +81 DEGREES C TO -36 DEGREES C (6 CYCLES) 1X10\*\*6 TORR O HUMIDITY: TESTED WITH THE SHOULDER JOINT MIL-STO-461 AS MODIFIED BY SL-E-0002 (TEST CEO1, CEO3, CSO1, CSO2, CSO6, REO1, REO2 (M/B), RSO1) O EMC: FLIGHT CHECKOUT PORS OPS CHECKLIST (ALL VEHICLES) JSC 16987

PREPARED BY: HFUG SUPERCEDING DATE: 11 SEP 86 APPROVED BY: DATE: 24 JUL 91 CIL REV: 1

PROJECT: SRMS
ASS'Y NONENCLATURE: SERVO POUER AMPLIFIER
SYSTEM: ELECTRICAL SUBSYSTEM
ASS'Y P/R: SITURETTY
SHEET:

tur a	****	HAMP		·	SERVU PUMER AMPLIFIER ASS'Y P/A: STTAUFTTY SHEET:
FMEA REF.	FHEA REV,	NAME, DIY, A DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	HDUR / FUNC. RATIONALE FOR ACCEPTANCE
3010	•	CURRENT LIMITER OTY-6 SCHEMATIC 2563718	MODE: FAILURE OF CURRENT LIMIT CCT.  CAUSE(\$): (1) EEE PARIS FAILURE. (UB FAILURE).	JOINT RUNAWAY WILL OCCUR. FWD/BKD FLAG WILL BE SET TO BKO. BUT POA BITE WILL BE SET. CONSISTENCY CHECK (ENVELOPE) WILL DETECT. LOSS OF LIMPING DURING END EFFECTOR CAPTURE.  WORST CASE UMEXPECTED HOTION, JOINT RUNAWAY, AUTOBRAKES.  REDUMDANT PATHS REMAINING AUTOBRAKES	CRITICALITY  SCREENS: A-PASS, B-PASS, C-PASS  OA/IMSPECTIONS  UNITS ARE MANUFACTURED UNDER DOCUMENTED COVALITY CONTROLS. THESE COMPROLS ARE EXECUSED THROUGHOUT DESIGN PROCUREMENT, PLANNING, RECEIVING, PROCESSING, FABRICATION, ASSENBLY, TESTING AND SHIPPING PROCURENTY, ESTING AND SHIPPING THE UNITS. MANDATORY IMSPECTION POINTS ARE ENCLOYED AT VARIOUS STACES OF FABRICATION ASSENBLY AND TEST. GOVERNMENT SOURCE INSPECTION IS INVOKED AT VARIOUS CONTROL LEVELS.  EEE PARTS INSPECTION IS PERFORMED AS REQUIFIED BY SPAR-RHS-PA, DOJ. EACH EEE PART IS QUALIFIED BY THE PART LEVEL TO THE REQUIREMENTS OF THE APPLICAN ESPECIFICATION. ALL EEE PARTS ARE TOOK SCREENED AND BURNED IN SPECIFICATION. ALL EEE PARTS ARE TOOK SCREENED AND BURNED IN SPECIFICATION. ALL EEE PARTS ARE TOOK RE-SCREENED IN ACCORDANCE WITH REQUIREMENTS, BY AN INDEPENDENT SAMPONDED TEST. ADDITIONALLY, EEE PARTS ARE TOOK RE-SCREENED IN ACCORDANCE WITH REQUIREMENTS, BY AN INDEPENDENT SAMPONDED TEST. AND THOMALLY, EEE PARTS ARE TOOK RE-SCREENED IN ACCORDANCE WITH REQUIREMENTS, BY AN INDEPENDENT SAMPONDED TEST ARE ARROUNDLY SELECTED SX OF PARTS, MANIMUM SPROUDE BY PA, DOS DIN A RANDOMLY SELECTED SX OF PARTS, MANIMUM SPROUDE BY PA, DOS DIN A RANDOMLY SELECTED SX OF PARTS, MANIMUM SPROUDE BY THE RECEIVED ARE AND INSPECTED AND TESTED TO MASA JSCHOORD STANDARD NUMBER YSA.  PRECEIVING INSPECTION VERTIFIES THAT ALL PARTS RECEIVED ARE RECEIVING INSPECTION WERTFIES THAT ALL PARTS RECEIVED ARE AS IDENTIFIED IN THE PROCUMENENT DOCUMENTS. THAT HOP PHYSICAL DAMAGE MAS OCCURRED TO PARTS DURING SHIPPENT THESE TO THE MANUFACTURING STAGE COMPLETED. THESE THIS PARTS ARE INSPECTED THROUGHOUT MANUFACTURE AND ASSEMBLY AS APPROPRIATE TO THE MANUFACTURING STAGE COMPLETED. THESE THIS PECTION SHOULDE.  PRINTED CIRCUIT BOARD INSPECTION FOR TRACK SEPARATION, DAMAGE AND ADEQUACY OF PLATED THROUGH HOLES,  COMPONENT MOUNTING INSPECTION FOR TRACK SEPARATION, DAMAGE AND ADEQUACY OF PLATED THROUGH HOLES,  CONFORMED MUSTING ULTRAVIOLET LIGHT TECHNIOUS.  POST P.C. BD. INSTALLATION INSPECTION CHECK
PREPARED BY:	. MFL	nc	SUPERCEDING DATE	. 11 CED 84	ADDIDOUGH BY.

PREPARED BY:

SUPERCEDING DATE: 11 SEP 86

APPROVED BY:

DATE: 24 JUL 91

CRITI . ITCHE LIST

ASS'T NUMBER CLATURE: STRVO POWER AMPLIFIER SYSTEM: ELECTRICAL SUBSYSTEM
ASS'Y P/N: 51140F1177 SHEET: 4

	FMFA HAME OTT, R PTV, DRAWING REF. DESTGNATION	FAILURE MODE AND CAUSE	FATLURE EFFECT ON END ITEM	HDUR / FUNC. RATIONALE FOR ACCEPTANCE 2/1R CRITICALITY SCREENS: A-PASS, B-PASS, C-PASS
3010	T CURRENT LIMITER DIT-6 SCHEMATIC 2563718	MODE: fAILURE OF CURRENT LIMIT CCT.  CAUSE(8): (1) EEE PARTS FAILURE. (U8 FAILURE).	JOINT RUNAWAY WILL OCCUR. FWD/BKD FLAG WILL BE SEI TO BKD. BUT MDA BITE WILL BE SET. CONSISTENCY CHECK (ENYELOPE) WILL DETECT. LOSS OF LIMPING DURING END EFFECTOR CAPTURE. WORST CASE UMENPECTED MOTION JOINT RUNAWAY. AUTOBRAKES. REDUNDANT PATHS REMAINING	A TEST READINESS REVIEW (IRR) MHICH INCLUDES VERIFICATION OF TEST PERSONNEL, TEST DOCUMENTS, TEST EQUIPMENT CALIBRATION/ VALIDATION STATUS AND MARDLARE CONFIGURATION IS CONVENED BY QUALITY ASSUMANCE IN COMJUNCTION WITH MEDITERERING, RELIABILITY, CONFIGURATION CONTROL, SUPPLIER AS APPLICABLE, AND THE GOVERNMENT REPRESENTATIVE, PRIOR TO THE START OF ANY FORMAL TESTING (ATP) INCLUDES AMBIENT PERFORMANCE, THERMAL AND VIBRATION TESTING, (SPAR/GOVERNMENT REP MANDATORY INSPECTION POINT).  INTEGRATION OF UNIT TO JOINT SRU - INSPECTIONS INCLUDE GROUNDING CHECKS, CONNECTORS FOR BEHT OR PUSHBACK CONTACTS, VISUAL, CLEANLINESS, INTERCONNECT WIRING AND POWER UP TEST TO THE APPROPRIÂTE JOINT INSPECTION TEST PROCEDURE (1TP) ETC.  JOINT LEVEL PRE-ACCEPTANCE TEST INSPECTION, INCLUDES AN AUDIT OF LOWER TIEN INSPECTION COMPLETION, AS BUILT COMPTOURATION VERTFICATION TO AS DESIGN ETC.  JOINT LEVEL ACCEPTANCE TESTING (ATP) INCLUDES AMBINET, VISRATION AND THERRAL-VAC TESTING.  (SPAR/GOVERNMENT REP MANDATORY INSPECTION POINT).  SRMS SYSTEMS INTEGRATION, THE INTEGRATION OF MECHANICAL ARM SUPASSEMBLIES AND INE FILIGHT CABIN GOUPPENT TO FORM THE SMMS. INSPECTIONS ARE PERFORMED AT EACH PHASE OF INTEGRATION WHICH INCLUDES GROUNDING CHECKS, THRU MIRTING CHECKS, MIRTING ROUTING, INTERFACE CONNECTORS FOR BENT OR PUSH BACK CONTACTS ETC.  SRMS SYSTEMS TESTING - STRONGBACK AND FLAT FLOOR AMBIENT PERFORMANCE TEST. (SPAR/GOVERNMENT REP NANDATORY INSPECTION POINT)

PROJECT: SRMS ASS'Y MOMENCLATURE: SERVO POWER AMPLIFIER

SYSTEM: ELECTRICAL SUBSYSTEM ASS'Y P/N: \$1140F1177

		······································	SS'Y NOMENCLATURE: 5	RVO POWER AMPLIFIER ASSIV P.W. STRUCT STORES
FMEA REF.	FMEA NAME OTY REV. DRAWING RE DESIGNATIO	A FAILURE HODE	FAILURE EFFECT ON END ETEM	HDWR / FUNC. RATIONALE FOR ACCEPTANCE 2/1R CRETICALITY SCREENS: A-PASS, B-PASS, C-PASS
3010	1 CURRENT LINITER DIY-6 SCHEMATIC 2563718	MODE: FAILURE OF CURRENT LIMIT CCT.  CAUSE(9): (1) EFE PARTS FAILURE. (UB FAILURE).	JOINT RUNAWAY WILL DCCUR. FND/BKD FLAG WILL SE SET TO BKD. BUT MDA BITE WILL SE SET. CONSISTENCY CHECK (ENVELOPE) WILL DETECT. LOSS OF LIMPING DURING END EFFECTOR CAPTURE. WORST CASE UNEXPECTED MOTION. JOINT RUNAWAY, AUTOBRAKES. REDUNDANT PATHS REMAINING AUTOBRAKES	THERE HAVE BEEN NO FAILURES ASSOCIATED WITH THIS FAILURE MODE ON THE SRMS PROGRAM.
EPARED BY:	MFWG	SUPERCEDING DATE:	11 CED 84	

SUPERCEDING DATE: 11 SEP 86

DATE: 24 JUL 91

PROJECT: SAMS
ASSIV HOMENCLATURE: SERVO FOMER AMPLIFIER
ASSIV PURE STRUCTURE: SERVO FOMER AMPLIFIER
ASSIV PURE STRUCTURE: 6

TOTAL TOTAL PROPERTY OF CONTROL O		RATIONALE LIPLANCE SCREENS: A-PASS, B-PASS, C-PASS	HDVR / FUNC. 2/18	FAILURE ETFECT OM END LIEM	FAILURE MODE AND EAUSE	HAME OIT & DRAWING REF. DESIGNATION	FMEA REV.	THER REF.
NOME  OMRSD ONLINE TURNAROUND  FOR EACH JUINT IN SINGLE MODE  VERIFY TACHO SIGNATURE FOR BOTH DERECTIONS.	OF TECTED RED. S RAKES, THE HODING ENG ALL	TRESPOND PROPERLY TO HAND CONTROLLER COMMAN ICES. AUTOBRAKES. CANNOT USE PRIMARY MODES OF ARM WILL NOT STOP AUTOMATICALLY IF AN UNDETER THE AUTOBRAKES SYSTEM HAS PREVIOUSLY OCCURREN BE APPLIED MANUALLY.  IS, SELECT BACKUP, ING ILL BE TRAINED TO OBSERVE WHETHER THE ARM IS PROPERLY TO COMMANDS. IF IT ISN'T, APPLY BRAIN ISTRAINT	OPERATIONAL E  ARM DDES HOT AUTO SEQUENCE OPERATION. AR FAILURE OF THE BRAKES CAN BE CREW ACTION  APPLY BRAKES.  CREW TRAINING  THE CREW WILL RESPONDING PR  MISSION CONST  OPERATE UNDER OPERATION MUST PROPERLY TO CARM OPERATION  OMRSD OFFLINE  IN COMPUTER COVERIFY MOTOR	END ITEM  JOINT RUNAWAY WILL OCCUR. FWD/BKD FLAG WILL BE SET TO BKD. BUT MDA BITE WILL BE SET. CONSISTENCY CHECK (ENVELOPE) WILL DETECT. LOSS OF LIMPING DURING END EFFECTOR CAPTURE.  WORST CASE UNEXPECTED MOTION, JOINT RUNAWAY. AUTOBRAKES. REDUNDANT PATHS REMAINING	CAUSE  MODE: FASLURE OF CURRENT LIMIT CCT.  CAUSE(S): (1) EEE PARTS FAILURE. (UB	DESTONATION  CURRENT LIMITER OTT-6 SCHEMATIC		
FOR EACH JOINT IN SINGLE MODE VERIFY TACHO SIGNATURE FOR BOTH DERECTIONS.		······································	HOME					
VERIFY TACHO SIGNATURE FOR BOTH DIRECTIONS.		E TURNAROUND	OMRSD ONLINE			,		
					<b> </b> ;			

PREPARED BY:

HFUG

SUPERCEDING DATE: 11 SEP 86

DATE: 24 JUL 91