PROJE	C1: SRMS (·S MOMENCLATORE	MCIU INSTALLED)
		ATT ATT ATT OF THE PARTY OF THE

ICA F.	FHEA REV.	NAME OFF B DRAWING BEF, DESIGNATION	FAILURE MODE	FAILURE EFFECT	HOME JENE. HOME JENE. HOME JENE. RATIONALE FOR ACCEPTANCE
156	0	SPA INTER-	HODE:	LOSS OF ABILITY	CRITICALIST SCREENS: A-PASS, B-PASS, C-PASS
		CONFEITON DIAGRAM 2563716.	LOSS OF 28V TO SPA. CAUSE(S): (1) IMPUT FRENER S.C.	IO DRIVE JOINT IN PRINE MODE. SPA FUSES WILL BLOW. JOINT FAILS FREE. AUTOBRAKES ARE APPLIED. ARM COMES TO REST. LOSS OF COMPUTER SUPPORTED MODES. JMD/BRO FLAG DEPENDENT OM MOTOR DERECTION ONLY. LOSS OF LIMPING DURING END	DESIGN FEATURES ALL RESISIORS AND CAPACITORS USED IN THE DESIGN ARE SELECTED FROM ESTABLISHED RELIABILITY (ER) TYPES, LIFE EXPECIANCY IS INCREASED BY ENSURING THAT ALL ALLOWABLE STRESS LEVELS ARE DERRITED IN ACCORDANCE WITH SPAR-BMS-PA.DOT. ALL CERAMIC AND ELECTROL PITC CAPACITORS ARE ROUTINELY SUBJECTED TO RADIOGRAPHIC INSPECTION. TRANSFORMERS AND INDUCTORS ARE DESIGNED SPECIFICALLY FOR THE APPLICATION, THESE ARE TOROID - MOUND AND UTILIZE A FERRITE, COME MATERIALS ENSURE THAT THE DERATING REQUIREMENTS OF SPAR-RMS-PA.DOT ARE NET. DISCRETE SEMICOMODUCION DEVICES SPECIFIED TO ATTERAST THE TX LEVEL OF MILES-1950O, ALL DEVICES ARE SUBJECTED TO
				GRECTOR CAPTUME. MORST CASE FREE JOINT. UNEMPECTED MOTION, AUTOBRAKES.	RE-ECREENING BY AN INDEPENDANT IEST HOUSE. SAMPLES OF ALL PROCURED LOTS/DATE CODES ARE SUBJECTED TO DESTRUCTIVE PHYSICAL AMALTSIS LOPA) TO VERTEY THE INTEGRITY OF THE MAMUFACTURING PROCESSES. DEVICE STRESS LEVELS ARE, DERALDE IN ACCORDANCE WITH SPAR-RMS-PA.DO3 AND VERTIFIED BY DESIGN REVIEW.
				REDUNDANT PATHS REMARKING ?) AUTOBRAKES (10 SAFE THE SYSTEM) 2) SACK-UP DATVE AND END EFFECTOR MANUAL DRIVE MIDES (?D SECURE ORREITER),	

DATE: 11 JUE 91

CIL REV: 0

MEA FMEA	NAME, Q17, & DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END FIFM	HOWR / FUNC. 2/1R	ASS'Y P/R: STEOFTS77 SHEE RATIONALE FOR ACCEPTANCE
3156 0	SPA INTER-CONNECTION DIAGRAM 2563716.	CAUSE MODE: LOSS OF 28V 10 SPA. CAUSE(S): (1) IMPUT FILTER S.C.	END TIEM LOSS OF ABILITY 10 DRIVE JOINT IN PRIME MODE. SPA FUSES WILL BLOW, JOINT FAILS FRE. AUTOBRAKES ARE APPLIED. ARM COMES TO REST. LOSS OF COMPUTER SUPPORTED MODES, FMD/BKD FLAG DEPENDENT ON MOTOR DIRECTION CONLY, LOSS OF LIMPING DURING END EFFECTOR CAPTURE. WORST CASE FREE JOINT, UNEMPECIED MOTION, AUTOBRAKES, REDUMDANT PATHS REMAINING 1) AUTOBRAKES (TO SAFE THE SYSTEM) 2) BACK UP DRIVE AND END EFFECTOR MAMDAL DRIVE MODES (TO SECURE ORBITER).	ACCEPTANCE TE THE SPA IS SUI AN SRU. O VIBRATION: O PHERMAL: THE SPA IS THE (VIBRATION AND STRONGBACK AND ABSENCE OF THE QUALIFFICATION THE SPA IS SUB ENVIRONMENTS. QUALIFFICATION O VIBRATION: O SHOCK: O THERMAL VAC O MUNICITY: O EMC:	SCREENS: A PASS, B PASS, C PASS SIS BJECTED TO THE FOLLOWING ENVIRONMENTAL TESTING AS LEVEL AND DURATION REFERENCE TABLE 4 PLUS 70 DEGREES C TO 25 DEGREES C DURATION 1 1/2 CTCLES IN TESTED AS PART OF THE JOINTS ACCEPTANCE TESTS INTERMAL VACUUM TEST). ITS UNDERGO RMS SYSTEM TESTS (1P518 RMS) 1P552 FLAT FLOOR TESTS) WHICH VERTIFIES THE FAILURE MODE. TESTS JECTED TO THE FOLLOWING SRU QUALIFICATION TESTINE SPA WAS ALSO TESTED AS PART OF THE JOINT THE SPA WAS ALSO TESTED AS PART OF THE JOINT THE STATE AND DURATION REFERENCE TABLE 4 20G/11 MS/3 AXES (6 DIRECTIONS) 1810**6 TORR TESTED WITH THE SHOULDER JOINT MIL-SID-461 AS MODIFIED BY SL-E-0002 (TESTICEOT, CEOT, CSOT, CSOT, CSOZ, CSD6, REOT, REOZ (N/B), RSOT)

CRIT	LICI	AL 1	TEHB	LI8T

	r	t	<u> </u>	22 1 MONEUCCATORE: 26	RVO POUER AMPLITIER SYSTEM: ELECTRICAL SUBSYSTEM ASS'T PAR: STEEPTITY SHEE
FMEA REF.	FMEA REV.	DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FATLURE EFFECT ON END ITEM	HOWR / FUNC. RATIONALE FOR ACCEPTANCE 2/18
3156	0	SPA INTER- CONNECTION DIACRAM 2563716.	MODE: LOSS OF 28V 10 SPA. CAUSE(\$): (1) INPUT FILTER \$.C.	LOSS OF ABILITY TO DRIVE JOINT IN PRIME MODE, SPA FUSES WILL BLOW, JOINT FAILS FREE, AUIOBRAKES ARE APPLIED. ARM COMES TO REST. LOSS OF COMPUTER SUPPORTED MCDES. FMD/BKP FLAG DEPENDENT ON MOTOR DIRECTION ONLY, LOSS OF LIMPING DURING END EFFECTION CAPTURE.	CRITICALITY SCREENS: A-PASS, B-PASS, C-PASS QA/INSPECTIONS UNITS ARE MANUFACTURED UNDER DOCUMENTED QUALITY CONTROLS. THESE CONTROLS ARE EXERCISED THROUGHOUT DESIGN PROCUREMENT, PLANNING, RECEIVING, PROCESSING, FABRICATION, ASSEMBLY, TESTING AND SHIPPING OF THE UNITS. MANDATORY INSPECTION POINTS ARE EMPLOYED AT VARIOUS STAGES OF FABRICATION ASSEMBLY AND TEST. GOVERNMENT SOURCE INSPECTION IS INVOKED AT VARIOUS CONTROL LEVELS. EEE PARTS INSPECTION IS PERFORMED AS REQUIRED BY SPAR-MMS-PA.003. EACH EEE PART IS QUALIFIED AT THE PART LEVEL TO THE REQUIREMENTS OF THE APPLICABLE SPECIFICATION. ALL EEE PARTS ARE 100% SCREENED AND BURNED IN, AS A MINIMUM, AS REQUIRED BY SPAR-MMS-PA.003, BY THE SUPPLIER. ADDITIONALLY, EEE PARTS ARE 100% RE-SCREENED IN ACCORDANCE WITH REQUIREMENTS, BY AN INDEPENDENT SPAR APPROVED TESTING FACILITY. OPA IS PERFORMED AS REQUIRED BY PA.003 ON A RANDOHLY SELECTED 5% OF PARTS, MAXEMUM S PIECES MINIMUM S PIECES FOR EACH LOT NUMBER/DATE CODE OF PARTS RECEIVED.
				MORST CASE FREE JOINT. JUNEMPECTED MOTIOM. AUTOBRAKES. REDUNDANT PATHS REMAINING 1) AUTOBRAKES (TO SAFE THE SYSTEM) 2) BACK-UP DRIVE AND END EFFECTOR MANUAL DRIVE MODES (TO SECURE ORBITER).	WIRE IS PROCURED TO SPECIFICATION MIL-W-22759 OR MIL-W-81381 AND INSPECIED AND TESTED TO NASA JSCH8080 STANDARD NUMBER 95A. RECEIVING INSPECTION VERIFIES THAT ALL PARTS RECEIVED ARE AS IDENTIFIED IN THE PROCUREMENT DOCUMENTS, THAT NO PHYSICAL DAMAGE MAS OCCURRED TO PARTS DURING SHIPMENT. THAT THE RECEIVING DOCUMENTS PROVIDE ADEQUATE TRACEABILITY INFORMATION AND SCREENING DATA CLEARLY IDENTIFIES ACCEPTABLE PARTS. PARTS ARE INSPECTED THROUGHOUT MANUFACTURE AND ASSEMBLY AS APPROPRIATE TO THE MANUFACTURING STAGE COMPLETED. THESE INSPECTIONS INCLUDE, PRINTED CIRCUIT BOARD INSPECTION FOR TRACK SEPARATION, DAMAGE AND ADEQUACY OF PLATED THROUGH HOLES, COMPONENT MOUNTING INSPECTION FOR CORRECT SOLDERING MIRE LODPING, STRAPPING, ETC. OPERATORS AND INSPECTORS ARE TRAINED AND CERTIFIED TO NASA WHB 5300.4(3A) STANDARD, AS MODIFIED BY JSC 08800A. CONFORMAL COATING INSPECTION FOR ADEQUATE PROCESSING IS PERFORMED USING ULTRAVIOLET LIGHT TECHNIQUES. POST P.C. BD. ENSTALLATION INSPECTION, CLEANLINESS AND MORKMANSHIP (SPAR/GOVERNMENT REP. MANDATORY INSPECTION POINT) P.C. BD. INSTALLATION INSPECTION, CHECK FOR CORRECT BOARD INSTALLATION. ALIGNMENT OF BRADES.
					INSTALLATION, ALIGNMENT OF BOARDS, PROPER CONNECTOR CONTACT MATING, WIRE ROUTING, STRAPPING OF WIRES ETC., PRE CLOSURE INSPECTION, WORKMANSHIP AND CLEANLINESS (SPAR/GOVERNMENT REP. MANDATORY INSPECTION POINT) PRE ACCEPTANCE TEST INSPECTION, WHICH INCLUDES AN AUDIT OF LUMER TIER INSPECTION CONPLETION, AS BUILT CONFIGURATION VERIFICATION TO AS DESIGN ETC., (MANDATORY INSPECTION POINT)

PREPARED BY:

MFWG

HEA REF.	THEA REV.	NAME, Q17, & DRAWING REF. DESIGNATION	FATLURE MODE AND Cause	FAILURE EFFECT ON END ITEM	HOUR / FUNC. RATIONALE FOR ACCEPTANCE Z/1R CRITICALITY SCREEN: A-PARE R-PARE CARE
3156	0	SPA INTER- CONNECTION DIAGRAM 2563716.	CAUSE HODE: LOSS OF 28V FO SPA. CAUSE(S): (1) IMPUT FILTER S.C.	LOSS OF ABILITY 10 ORIVE JOINT IN PRIME MODE. SPA FUSES WILL BLOW, JOINT FAILS FREE. AUTOBRAKES ARE APPLIED. ARM COMES TO REST. LOSS OF COMPUTER SUPPORTED MODES, FMD/BKD FLAG DEPENDENT OM MOTOR DIRECTION ONLY. LOSS OF LIMPING DURRING EFFECTOR CAPTURE. WORST CASE FREE JOINT. LUMEXPECTED MOTION, AUTOBRAKES, REDUNDANT PATHS REMAINING 13 AUTOBRAKES [10 SAFE INE SYSTEM] 23 BACK-UP DRIVE AND END EFFECTOR MANUAL DRIVE MODES (TO SECURE	
				ORDITER).	
					•

SUPERCEDING DATE: MONE

DATE: 11 JUE 91

EII REV: 0

ret :

PRIPARED BY:

HING

THEA	ENEA	1 want of a i	ALLURE HODE	ROJECI: SRNS (S MC) SS'Y NOMENCLATURE: SE	RYU PUMEN AMPLIFIER	SYSTEM: ELECTRICAL SUBSYSTEM ASS'Y P/R: STIZOFTI77	SHEE
REF.	AEV.	HAME OFF & DRAWING MEE DESIGNATION	AND	FAILURE EFFECT	HDWR / FUNC. 2/1r	RATIONALE FOR ACCEPTANCE	
3156	,		CAUSE	END ITEM	TRITICALITY	SCREENS: A PASS, B PASS, C PASS	
3156		SPA INTER CUNNECTION DIAGRAM 25637%6.	MEDE: LOSS OF 28V TO SPA. EAUSE(S): (1) THPUT FILTER S.C.	LOSS OF ABILITY TO DAIVE JOINT IN PRIME MODE SPA FUSES WILL BLOM, JOINT FAILS FREE. AUTOGRAKES ARE APPLIED. ARM COMES TO REST. LOSS OF COMPUTER SUPPORTED MODES, FIND/BKD FLAG DEPENDENT ON MOTOR DIRECTION ONLY. LOSS OF LIMPING DURING END EFFECTOR CAPTURE.	FAILURE HIST	ORY	
				FREE JOINT. UNEXPECIED MOTION, AUTOBRAKES, REDUNDANT PATHS REMAINING 1) AUTOBRAKES (TO SAFE THE SYSTEM) 2) BACK-UP DRIVE AND END EFFECTOR MANUAL DRIVE MODES (TO SECURE ORBITER).			

SUPERCEDING DATE: NOME

DATE: 11 JUN 91

CII REV: U

PREPARED BY:

MFWG

SUPERCEDING DATE: NUME

CRITICAL ITEMS LIST

	ROJECT: SRMS (5 MC) SS'Y NOMENCLATURE: \$2			SYSTEM: ELECTRICAL SUBSYSTEM	
DE	FAILURE EFFECT ON END TTEN	HOWR / FUNC. 2/1R	RAI	IONALE FOR ACCEPTANCE	SHEET

IMEA REF.	PHEA REV.	NAME OIT & DRAWING REF.	FAILURE MODE	FAILURE EFFECT	AVO POURA AMPLITIER SYSTEM ASS'Y P/A: STEEDITTY SHEET:
1164		DESIGNATION	CAUSE	MO TIEM	2/18 MATTUMALE FOR ACCEPTANCE
3156	0	SPA INTER- CONNECTION DIACRAM 2563716.	HODE: LOSS OF 28V TO SPA, CAUSE(S): (1) IMPUT FILTER S.C.	LOSS OF ABILITY 10 DRIVE JOINT 1N PRIME MODE. SPA FUSES WILL BLOM. JOINT FAILS FREE. AUTOBRAKES ARE APPLIED. ARM COMES 10 REST. LOSS OF COMPUTER SUPPORTED MODES. FMO/SKD FLAG DEPENDENT ON MOTOR DIRECTION ONLY. LOSS OF LINPING DUNING END EFFECTION CAPTURE.	OPERATIONAL EFFECTS COMPUTER SUPPORTED MODES CANNOT BE USED TO COMPLETE THE MISSION. DIRECT DRIVE AND BACK UP MODES REMAIN. IF PAYLOAD ATTACHED, THE ARM SHOULD BE MANEUVERED TO A SAFE POSITION FOR PAYLOAD RELEASE. LOSS OF MENT REDUNDANT PATH RESULTS TH BEING DNE FAILURE AWAY FROM MABILITY TO CRADLE ARM. IF MITH SUBSEQUENT FAILURES ALL DRIVE MODES ARE LOST, THE ARM MAY BE JETTISONED. CREW HAS ABILITY TO OVERRIDE A SINGLE FAILURE. CREW ACTION SELECT BACKUP.
				FREE JOINT. UNEXPECTED HOTION AUTOBRAKES. REDUNDANT PATHS REMAINING 1) AUTOBRAKES (TO SAFE THE SYSTEM) 2) BACK-UP DRIVE AND END EFFECTOR MANUAL DRIVE MODES (TO SECURE ORBITER).	CREW TRAINING THE CREW WILL BE TRAINED TO OBSERVE WHETHER THE ARM IS RESPONDING PROPERLY TO COMMANDS. MISSION CONSTRAINT OPERATE UNDER VERNIER RATES WITHIN TO FT OF STRUCTURE. THE OPERATOR MUST BE ABLE TO DETECT THAT THE ARM IS RESPONDING ARM OPERATIONS. AUTO TRAJECTORIES MUST BE DESIGNED TO COME NO CLOSER THAN 5 FT OMES STRUCTURE. OMASO DEFLINE VERSEY LACK OF 28V FAIL FLAG IN ABE DATA. OHRSD ONLINE INSTALLATION
					NONE OMRSO ONLINE TURNAROUND VERIFY LACK OF 28V FAIL FLAG IN ABE DATA.

SOCCESTA ATTACHMENT : PAGE 149 OF LT:

DATE: 11 JUL 91

CIT REV: $\underline{0}$