

# CRITICAL ITEMS LIST

ASSY NOMENCLATURE: OXYGEN MANIFOLD

ASSY P/N: 10030-01

SYSTEM: CREW ESCAPE SYSTEM

SUBSYSTEM: LAUNCH ENTRY SUIT

REVISION:

PAGE 13 OF 60

FMEA		NAME, QTY & DRAWING REF DESIGNATION	CRITY	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	RATIONALE FOR ACCEPTANCE
REF	REV					
3.3.2		OXYGEN MANIFOLD (1), 18951G-B2	2/IR	3.3.2 Mode: Orbiter O <sub>2</sub> supply on/off valve fails closed  Cause: • defective material • piece part failure	No Orbiter O <sub>2</sub> supply to suit if unable to reconnect Orbiter O <sub>2</sub> supply hose to the EOS connection	<p>1. DESIGN FEATURES TO MINIMIZE FAILURE MODE</p> <ul style="list-style-type: none"> <li>a. The housing is constructed of aluminum.</li> <li>b. The diverter valve is manually actuated with a guard to retain the valve lever position.</li> <li>c. The valve (hole) is lubricated with Braycote.</li> <li>d. The valve actuation is such that when the lever is moved to the "On" position it acts as a fulcrum, forcing the valve to open.</li> <li>e. The spring is centered around the valve stem, preventing any jamming of the valve by the spring.</li> <li>f. The valve stem is made of 303 stainless steel.</li> </ul> <p>2. TEST OR ANALYSIS TO DETECT FAILURE MODE</p> <ul style="list-style-type: none"> <li>a. <u>Acceptance Testing</u> <ul style="list-style-type: none"> <li>(1) Leak test, pressurize manifold to 150 <math>\pm</math> 10 psig with manifold lever in the "On" position.</li> <li>(2) Proof test, pressurize manifold to 300 <math>\pm</math> 10 psig for 5 minutes with manifold lever in the "On" position.</li> <li>(3) Leak test, pressurize manifold to 150 <math>\pm</math> 5 psig with manifold lever in the "Off" position.</li> </ul> </li> <li>b. <u>Certification Test</u> <ul style="list-style-type: none"> <li>(1) High altitude chamber test, Brooks Air Force Base.</li> <li>(a) Unmanned testing series.           <ul style="list-style-type: none"> <li>1 Gradual ascent/descent to 100,000 feet.</li> <li>2 Rapid decompression to 90,000 feet.</li> <li>3 Entrance runs rapid decompression to 100,000 feet for 10 minutes.</li> </ul> </li> </ul> </li> </ul>

PREPARED BY: R. L. ALLISON

SUPERSEDING DATE

APPROVED BY: E. O. SCHLOSSER

DATE:

CEE/LES-13

SP02100  
PAGE 13 OF 60  
ATTACHMENT II  
17

# CRITICAL ITEMS LIST

ASSY NOMENCLATURE: OXYGEN MANIFOLD

ASSY P/N: 10030-01

SYSTEM: CREW ESCAPE SYSTEM

REVISION:

SUBSYSTEM: LAUNCH ENTRY SET

PAGE 14 OF 60

FMEA		NAME, QTY & DRAWING REF DESIGNATION	CMT/V	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	RATIONALE FOR ACCEPTANCE
REF	REV					
3.3.2		OXYGEN MANIFOLD (1), 1B951G-02	Z/R	<p><b>3.3.2</b>  <b>Mode:</b>  Orbiter O<sub>2</sub> supply on/off valve fails closed</p> <p><b>Cause:</b>  • defective material  • piece part failure</p>	<p>No Orbiter O<sub>2</sub> supply to suit if unable to reconnect Orbiter O<sub>2</sub> supply hose to the EDS connection</p>	<p>(b) Manned testing series.</p> <ol style="list-style-type: none"> <li>1 Gradual ascent/descent to 100,000 feet.</li> <li>2 Rapid decompression to 90,000 feet</li> <li>3 Endurance runs rapid decompression to 100,000 feet for 37 minutes.</li> </ol> <p>c Turnaround Test. (In accordance with PIA 23033)</p> <ol style="list-style-type: none"> <li>(1) Leak test, pressurize manifold to 150 ± 10 psig with manifold lever in the "On" position.</li> <li>(2) Proof test, pressurize manifold to 300 ± 10 psig for 5 minutes with manifold lever in the "On" position.</li> <li>(3) Leak test, pressurize manifold to 150 ± 5 psig with manifold lever in the "Off" position</li> </ol> <p>3. INSPECTION</p> <ol style="list-style-type: none"> <li>a. Visual inspection of parts for defects</li> <li>b. One hundred percent inspection during assembly</li> <li>c. Verify seats are properly seated</li> <li>d. Verify manifold is cleaned to level 100A in accordance with JSCM 5322.</li> <li>e. Visual inspection after proof test for any anomalies.</li> <li>f. Verify leakage is within specification</li> </ol> <p>Turnaround Inspection (In accordance with PIA 23033)</p> <ol style="list-style-type: none"> <li>a. Visual inspection of parts for defects.</li> <li>b. Verify seats are properly seated.</li> </ol>

PREPARED BY: R. E. ALLISON

SHIP BUILDING DATE:

APPROVED BY: J.O. SCHLOSSER

DATE:

CEE/LES-14

SH0100  
ATTACHMENT II  
PAGE 71 OF 117

# CRITICAL ITEMS LIST

ASSY NOMENCLATURE: OXYGEN MANIFOLD

ASSY P/N: 10030-02

SYSTEM: CREW ESCAPE SYSTEM

SUBSYSTEM: LAUNCH ENTRY SUIT

REVISION:

PAGE 15 OF 60

FMEA		NAME, QTY & DRAWING REF DESIGNATION	CRIT'Y	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	RATIONALE FOR ACCEPTANCE
REF	REV					
3.3.2		OXYGEN MANIFOLD (1). 1B951G-02	Z/T/H	<p>3.3.2 Mode: Orbiter O<sub>2</sub> supply on/off valve fails closed</p> <p>Cause:            • defective material            • piece part failure</p>	<p>No Orbiter O<sub>2</sub> supply to suit if unable to reconnect Orbiter O<sub>2</sub> supply hose to the EOS connection</p>	<ul style="list-style-type: none"> <li>c. Verify manifold is cleaned to level 100A in accordance with JSCM 5322.</li> <li>d. Verify leakage is within specification.</li> </ul> <p>4. FAILURE HISTORY</p> <p>None. This manifold is a new item.</p> <p>5. OPERATIONAL USE</p> <ul style="list-style-type: none"> <li>a. Operational Effect of Failure. (Note: This failure mode applies only to loss of ship-supplied O<sub>2</sub>, due to O<sub>2</sub> manifold failing closed. Design precludes loss of emergency O<sub>2</sub> due to manifold failure.) Possible loss of crewmember if cabin atmosphere is contaminated during flight and O<sub>2</sub> manifold cannot be bypassed.</li> <li>b. Crew Action - Disconnect Orbiter O<sub>2</sub> supply hose and emergency O<sub>2</sub> hose from O<sub>2</sub> manifold, attach Orbiter O<sub>2</sub> hose to emergency O<sub>2</sub> inlet on manifold. Note: This should be considered a hazardous procedure, performed as a last resort only</li> <li>c. Crew Training - The crew is trained to perform this procedure if necessary.</li> <li>d. Mission Constraints - None. Mission would be terminated prior to emergency use of O<sub>2</sub> manifold.</li> <li>e. In-Flight Checkout - None. Visual inspection would not reveal failure; crew cannot disassemble, repair, or replace a defective manifold.</li> </ul>

PREPARED BY: R. L. AZZISON

SUPERSEDED DATE:

APPROVED BY: J. O. SCHLOSSER

DATE

CEE/LES-15

SH02100  
ATTACHMENT  
Page 72 of 117