PROJECT: SAMS ASS'Y MONENCEATURE: SHOULDER

SYSTEM: MECHANICAL ARM SUBSYSTEM ASS'Y P.W. 3114011210

EET:

AEF. REV.	DRAWING AEF. DESIGNATION	AND CAUSE	PATEURE EFFECT ON END ITEM	NOUN 7 TUNE. 2/2 CRITICALITY RATIONALE FOR ACCEPTANCE
4190 0	SHOULDER BRACE GTY-† P/N 511400+107	MODE: FAILURE TO RELEASE. CAUSE(\$): (1) SEIZURE OF ACTUATOR. (2) LOSS OF POWER.	SHOULDER BRACE CANNOT BE RELEASED. ARM CAUNOT BE DEPLOYED. MORST CASE LOSS OF MISSION. A OSS OF SHOULDER BRACE RELEASE. REDIMDANT PATHS REMAINING M/A	THE LIMEAR ACTUATOR IS A MAJOR BOUGHT-OUT-PART LAHICH IS SUPPLIED BY SPERRY CORPORATION, AEROSPACE AND MARINE GROUP AND MEETS OR EXCEEDS THE REQUIREMENTS OF SPECIFICATION SPAR-SG.515. MATERIALS SELECTION AND USAGE COMPORMS TO SPAR-SG.368 UNION IS EQUIVALENT TO THE BUSAS MATERIALS USAGE REQUIREMENTS. THE BEARING ANALYSIS USES ULTIMATE LOADS TO DETERMINE THE MARIGINS OF SAFETY OF THE LUGRICANT. THE FACIOR BETWEEN MORKING LOADS AND ULTIMATE IS 1.4. THE LUGRICANT FAILURE STRESSES ARE COME THAN THE BRINGELING STRESS. LIFE FOR ALL GEARINGS IS GREATER THAN 400 MISSIONS BASED UPON THE ABOVE CRITERIA. THE ALLOWABLE CONTACT STRESS FOR THE LUBRICANT IS ABOUT 1/51M THE ALLOWABLE CONTACT STRESS FOR THE LUBRICANT STRESMES AS A RESULT ARE TOTALLY LOADED AND SURPACE FAFTICURE IN THE BEARINGS AS A RESULT ARE TOTALLY LOADED AND SURPACE FAFTICURE IN THE BEARING ARSULT ARE TOTALLY LOADED AND SURPACE FAFTICURE IN THE BEARING ARE ACCUSED IN MOM-DEBRIS PRODUCING AREA OF ASSEMBLY. THE BEARINGS ARE PROCURED AND SUPPLIED TO SPERRY BY SPAR, AND MEET OR EXCEED THE REQUIREMENTS OF SPECIFICATION SPAR-SG. 593. THE LIBERAR ACTUATOR DESIGN UTILIZES THREE DIFFERENT BEARINGS, FOUR OF DUE DESIGN AND THO EACH OF THE OFFICE THE DUBY CRITERIAL THEY AND ARE PERMANENTLY LUBRICANT SUSTEM USED IS LUBRICO 905. THE SOLID FILM LUBRICANT SYSTEM USED IS LUBRICO 905. THE SOLID FILM LUBRICANT SYSTEM USED IS LUBRICO 905. THE SOLID FILM LUBRICANT SYSTEM USED IS LUBRICO 905. THE SOLID FILM LUBRICANT SYSTEM USED IS LUBRICANT SKALE TO PER SPAR PPS 20:14. THE LUBRICANT ON ALL BEARINGS AND RUM IN PER SPAR PPS 20:14. THE LUBRICANT ON ALL BEARINGS IS GOOD FOR OVER ADOUTED TO PER PPS-20:114. THE LUBRICANT ON ALL BEARINGS IS GOOD FOR OVER ADOUTE ACOUNT ADD WITH ADD ALL BEARING SIGNOR FOR THE THAT HE POSSIBILITY OF A LOBS OF HEAVILLE LUBRICANT ON ALL BEARINGS IS GOOD FOR OVER ADOUTE ADOUT AND ALL BEARINGS IS GOOD FOR OVER ADOUTE ADOUT AND THE PROPERTY LOAD WILL HOT FREITH LOAD SIMBLE THE APPLIED LOAD WILL HOT RESULT IN TOOTH FAILURE. ALL SHMS GEARS ARE DESIGNATE

PROJECT: SRMS ASS'Y MOMENCLAYURE: SKRULDER

SYSTEM: MECHANICAL ARM SUBSYSTEM
ASS'V P/H: 51140J12TV SHEET: 2

REF.	REV.	CRAVING REF. DESIGNATION	FATLURE MODE AND CAUSE	FATLURE EFFECT ON END ITEM	POINT / FUNC. 2/2 RATIONALE FOR ACCEPTANCE CRITICALITY
4190	•	SHOULDER BRACE GTY-1 PAN 5114001107	MODE: FAILURE TO RELEASE. CAUSE(S): (1) SEIZURE OF ACTUATOR. (2) LOSS OF POWER.	SHOULDER BRACE CAMMOT BE RELEASED. ARM CAMMOT BE DEPLOYED. WORST CASE LOSS OF RISSION. LOSS OF SHOULDER BRACE RELEASE. REDUMDANT PATHS REMATHING N/A	ACCEPTANCE TESTS THE SHOULDER, ELBOW AND WRIST JOINTS ARE SUBJECTED TO THE FOLLOWING ACCEPTANCE ENVIRONMENTAL TESTING. O VIBRATION: LEVEL AND DURATION - REFERENCE TABLES 9, 10 AND 11. O THERMAL: +70 DEGREES C TO -25 DEGREES C (2 CYCLES) 1 X 10**6 TORR. THE JOINTS ARE INTEGRATED INTO THE RMS SYSTEM (PPER TP532) WHICH IS FURTHER TESTED IN (TP518 RMS STRONGBACK AND 1P52 FLAT FLOOR). THESE TESTS VERIFIES THE ABSENCE OF THE FAILURE MODE. GUALIFICATION TESTS THE SHOULDER AND WRIST JOINTS WERE SUBJECTED TO THE LISTED BELOW ENVIRONMENTS. THE ELBOW JOINTS WAS NOT EXPOSED THE GUALIFICATION ENVIRONMENTS WAS CERTIFIED BY SIMILARITY TO THE SHOULDER JOINT. O VIBRATION: LEVEL AND DURATION REFERENCE TABLES 9 AND 10 O SHOCK: 20g/11 MS -3 AKES (6 DIRECTIONS) O THERMAL VACUAM: +81 DEGREES C TO -36 DEGREES C (6 CYCLES) 1 X 10**6 TORR. O EMC: HIL-SID-461 AS MODIFIED BY SLE-0002 (TESTS CEO), CEO3, CS01, CS02, CS06, RE02 (M/B). O MUDIFITY: ONLY SHOULDER JOINT WAS TESTED, 95X RM (55 DEGREES C NATINITATIVED FOR 6 MS.), (05 DEGREES C TO 30 DEGREES C IN 16 HRS.) 10 CYCLES 240 HRS. O LOAD TEST: SHOULDER JOINT STRUCTURAL LOAD TEST REFERENCE TABLE 12. NOTE: ELBOW JOINT (S/N 302 AND UP) INCORPORATES NON-WELDED TRANSITIONS WHICH WAS LOAD TESTED TO LOAD IN REFERENCE TABLE TEST. FLIGHT CHECKOUT

PREPARED BY: MFMG SUPERCEDING DATE: 11 SEP 86 APPROVED BY:

RMS/MECH - 324

PROJECT: SRMS ASS'Y NOMENCLATURE: SHOULDER

SYSTEM: MECHANICAL ARM SUBSYSTEM
ASS'Y P/N: STEEDIZED SHEET: 1

REF.	REV.	DRAVING REF. DESIGNATION	FATEUME MODE AND CAUSE	FAILURE EFFECT ON END ITEM	HOUR / FUNC. 2/2 RATIONALE FOR ACCEPTANCE CRITICALITY
4190		SHOULDER BRACE GTY-1 P/N 5114001107	MODE: FAILURE TO RELEASE. CAUSE(S): (1) SEIZURE OF ACTUATOR. (2) LOSS OF POWER.	SHOULDER BRACE CANNOT BE RELEASED. ARM CANNOT BE DEPLOYED. WORST CASE LOSS OF MISSION. LOSS OF SHOULDER BRACE RELEASE. REDUNDANT PATHS REMAINING M/A	UNITS ARE MAJOR BOUGHT OUT PARTS, MAMUFACTURED, ASSEMBLED AND TESTED TO SPAR DRAWINGS AND SPECIFICATIONS UNDER DOCUMENTED GUALITY CONTROLS. THESE CONTROLS ARE EXERCISED THROUGHOUT DESTEAM PROCUREMENT PLANNING, PROCESSING, FABRICATION, ASSEMBLY COLLEGE AND HOLD ASSEMBLY COLLEGE AND HOLD ASSEMBLY COLLEGE ASSEMBLY AND TEST. SPAR/GOVERNMENT SOURCE INSPECTION INSPECTION POINTS ARE EMPLOYED AS APPROPRIATE AT VARIOUS LEVELS OF ASSEMBLY AND TEST. SPAR/GOVERNMENT SOURCE INSPECTION IS ENVOKED ON THE SUPPLIER. MIRE 3S PROCURED TO SPECIFICATION MIL-W-22759 OR MIL-W-81381 AND INSPECTED AND TESTED TO MASA JSCHBORD STANDARD MIMBER 95A. RECEIVING INSPECTION VEVILLS THAT THE NARDWARE RECEIVED IS AS IDENTIFIED IN THE PROCUMENT, AND THAT APPROPRIATE DATA MAS BEEN OCCURRED UNION SHOPMENT, AND THAT APPROPRIATE DATA MAS BEEN RECEIVED UNICH PROVIDES ADEQUATE TRACEABILITY INFORMATION AND IDENTIFIES ACCEPTABLE PARTS. PARTS ARE INSPECTED THROUGHOUT NAMUFACTURE AND ASSEMBLY AS APPROPRIATE TO THE MANUFACTURING STAGE COMPLETED. THESE INSPECTIONS INCLUDE, MAGNET WIRE 13 PROCURED TO MIL-W-583 AND CHECKED AT INCOMING INSPECTION PROFITED TO MASA MHSSOO.4(43) STANDARD, AS DISECTION. FUR HORES, RIBBIES, AND CRACKS IN THE INSULATION. ALL SOLDERING IS ACCOMPLISHED BY DEPOTION. BEARINGS RECEIVE DIMENSIONAL INSPECTION AT THE SUPPLIER AND VERIFICATION BY SPAR RECEIVING INSPECTION. PROFITED TO MASA MHSSOO.4(43) STANDARD, AS MODIFIED BY JSC OBBOOA. BEARINGS RECEIVE DIMENSIONAL INSPECTION AT THE SUPPLIER FOR PRICE OF UNIFICATION, RUPL THESE CIRCULARITY OF BALL TRACKS AND INSPECTION BY SPAR RECEIVING INSPECTION FOR THE PROFILE FOR PRICE OF THE PROFILE FOR THAT THE FOR THE TRACKS AND THE PROFILEMENT OF BALL TRACKS. FOR THE PROFILEMENT OF BALL TRACKS. FOR THE PROFILEMENT OF BALL TRACKS AND THE PROFILEMENT OF BALL TRACKS. FOR THE PROFILEM

PREPARED BY: MFWG SUPERCEDING DATE: 11 SEP 86 APPROVED BY:

____ DATE: ____

PROJECT: SAMS ASS'Y NOMENCEATURE: SHOULDER

SYSTEM: MECHANICAL ARM SUBSYSTEM
ASS'Y P/M: 5114011219 SHEET: 4

REF. RI	DRAVING REF.	FATEURE HODE AND CAUSE	FATLURE EFFECT ON END ITEN	RUSH / FUNC. 2/2 RATIONALE FOR ACCEPTANCE CRITICALITY
4190	SHOUR DER BRACE GTY-1 P/N 5114001107	MODE: FAILURE TO RELEASE. CAUSE(8): (1) SEIZURE OF ACTUATOR. (2) LOSS OF POMER.	SHOULDER BRACE CAMNOT BE RELEASED. ARM CANNOT BE DEPLOYED. WORST CASE LOSS OF HISSION. LOSS OF SHOULDER BRACE RELEASE. REDUNDANT PATHS REMAINING M/A	RUM-IN, CLEANED AND VISUALLY INSPECTED. LINEAR ACTUATOR UNITS ARE FUNCTIONAL TESTED AFTER INTEGRATION TO SNOULDER JOINT PRIOR TO ACCEPTANCE TESTING IN ACCORDANCE WITH INSPECTION IEST PROCEDURE ITP251A (SMOULDER JOINT POWER UP TESTS). JOINT LEVEL PRE-ACCEPTANCE TEST INSPECTION, INCLUDES AN AUDIT OF LOWER THER INSPECTION COMPLETION, AS BUILT CONFIGURATION VERIFICATION TO AS DESIGN ETC. A TEST RESONNEL TEST DOCUMENTS, IEST EQUIPMENT CALIBRATION OF TEST PERSONNEL TEST DOCUMENTS, IEST EQUIPMENT CALIBRATION/VALIDATION STATUS AND HARDWARE CONFIGURATION IS CONVEMED BY QUALITY ASSUMANCE IN CONJUNCTION WITH ENGINEERING, RELIABILITY, CONFIGURATION CONTROL, SUPPLIER AS APPLICABLE, AND THE GOVERNMENT REPRESENTATIVE, PRIOR TO THE START OF ANY FORMAL TESTING (ACCEPTANCE OR QUALIFICATION). JOINT LEVEL ACCEPTANCE TESTING (ATP) INCLUDES AMBINET, VIBRATION AND THERMAL-VAC TESTING. (SPARJGOVERNMENT REP MANDATORY INSPECTION POINT). SRMS SYSTEMS INTEGRATION, THE INTEGRATION OF MECHANICAL ARM SUPPLED AND THE FLIGHT CARDIN COUNTRY TO FORM THE SRMS. INSPECTIONS ARE PERFORMED AT EACH PHASE OF INTEGRATION MICH INCLUDES GROUNDING CHECKS, THRU MIRTING CHECKS, MIRTING ROTTING, INTERFACE CONNECTORS FOR BENT OR PUSH BACK CONTACTS ETC. SRMS SYSTEMS TESTING - STRONGBACK AND FLAT FLOOR AMBIENT PERFORMANCE TEST. (SPAR/GOVERNMENT REP MANDATORY INSPECTION POINT)

PREPARED BY: MFMG

SUPERCEDING DATE: 11 SEP 86

APPROVED BY: ___ RMS/MECH - 326

CR.	ITI	CAL	IT	BH	9 L	18	7
							_

PROJECT: SRMS

SYSTEM: MECHANICAL ARM SUBSYSTEM
ASS'Y MOMENCIATURE: SHOULDER

SHEET:

SHEET:

FIREA REF.	REV.	DESIGNATION	FATLURE WIBE AND CAUSE	FATLUME EFFECT ON END 1TEN	HUSIR / FUNC. 2/2 Criticality	RATIONALE FOR ACCEPTANCE	- -
4190	•	SHOULDER BRACE GTY-1 P/N 51140D1107	NODE: FAILURE TO RELEASE. CAUSE(\$): (1) SEIZURE OF ACTUATOR. (2) LOSS OF POMER.	SHOULDER BRACE CAMHOT BE RELEASED, ARM CAMHOT BE DEPLOYED. WORST CASE LOSS OF MISSION, LOSS OF SHOULDER BRACE RELEASE. REDMANNER	FAILURE HISTORY THERE HAVE BEEN MODE ON THE SAN	MO FAILURES ASSOCIATED DEED THE EASIERS	
i				REMAINING N/A		,	
				ļ	,		
	ì					·	
į					•		
PARED BY;	MEWG	SUPE	RCEDING DATE: 11 S	EP B6 APPROVE		1E:	

RMS/MECH - 327

PROJECT: SRMS ASS'Y NOMENCLATURE: SHOULDER

SYSTEM: MECHANICAL ARM SUBSYSTEM
ASS'Y P/N: 5T140J1219 SHEET: 6

FHEA REF.	REV.	DRAWING RÉF. DESIGNATION	FATLURE HODE AND CAUSE	FATEURE EFFECT ON END ITEM	ROUR / FUNC. 2/2 RATIONALE FOR ACCEPTANCE CRITICALITY
4190		SHOULDER BRACE GTY-1 P/N 5114001107			OPERATIONAL EFFECTS CANNOT RELEASE SHOULDER BRACE. CANNOT UNCRADLE ARM TO PERFORM MISSION. CREW ACTION PERFORM EVA TO RELEASE SHOULDER BRACE. CREW TRAINING NONE MISSION CONSTRAINTS RELEASE THE SHOULDER BRACE AS EARLY IN THE MISSION AS POSSIBLE TO AVOID ANY THERMALLY INDUCED FAILURES TO RELEASE. SCREEN FAILURES M/A OMRSD OFFLINE OPERATE SHOULDER BRACE TO LATCH, UNLATCH. VERIFY FLAG STATUS. OMRSD ONLINE INSTALLATION HOME
					OPERATE SHOULDER BRACE TO UNLATCH. VERIFY FLAG STATUS.

PREPARED BY: MENG

SUPERCEDING DATE: 11 SEP 86

APPROVED BY:

RMS/MECH - 328