

ITEM NO. <u>4.3.1</u>	CRITICALITY <u>2/2</u>	SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT <u>TVC/WIA</u> DRG NO. <u>2294819-506, 508/</u> <u>2302D80-503</u> SHEET <u>1</u> OF <u>9</u>
FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	NATIONALE FOR ACCEPTANCE	DESIGN FEATURES
No output signal to the VSU. Neither video nor synchronization information is present.	Loss of camera output depicting scene information within FOV of lens assembly. Worst Case: Loss of mission critical video.	The TVC/lens Assembly is comprised of 16 electrical subassemblies; 13 subassemblies are RCA Astro designed and fabricated using standard printed-circuit board type of construction. The remaining three assemblies, high voltage power supply, oscillator, and stepper motors, are vendor supplied components which have been specified and purchased according to RCA Specification Control Drawings (SCDs) prepared by engineering and reliability assurance. Specifications per the SCD are prepared to establish the design, performance, test, qualification, and acceptance requirements for a procured piece of equipment.	Parts, materials, processes, and design guidelines for the Shuttle CCTV program are specified in accordance with RCA 2295503. This document defines the program requirements for selection and control of EEE parts. To the maximum extent, and consistent with availability, all parts have been selected from military specifications at the JAN level, as a minimum. In addition to the overall selection criteria, a subset of general purpose preferred parts has been defined by this document and the RCA Government Systems Division Standard Parts List. In the case of the CMOS and TTL family of microcircuits, devices are screened and tested to the MIL-STD-883C equivalent and procured under the designations of HI-REL/3HQ and SNC 54LS from RCA-SSD and Texas Instruments Corp., respectively. Parts not included in the above documents have been used in the design only after a nonstandard item approval form (NSIAF) has been prepared, submitted to Reliability Assurance Engineering (RAE) and approved for use in the specific application(s) defined in the NSIAF by NASA-JSC.
A1 Sync Generator Clock Divider Chain. 2294880-504			Worst-Case Circuit Analyses have been performed and documented for all circuit designs to demonstrate that sufficient operating margins exist for all operating conditions. The analysis was worst case-in that the value for each of the variable parameters was set to limits that will drive the output to a maximum (or minimum).
A2 Camera Timing Logic 2294881-501			A component application review and analysis was conducted to verify that the applied stress on each piece part by the temperature extremes identified with environmental qualification testing does not exceed the stress derating values identified in RCA 2295503.
A3 Sync Formatter, Video Output Drive. 2294884-503			In addition, an objective examination of the design was performed through a PDR and CDR to verify that the TVC/Lens assembly met specification and contractual requirements.
A4 Power On/Off Switching, Input Voltage Preregulators, Output Voltage Regulators. 2294885-501			
A5 DI-DI Converters			
Primary Oscillator Driver, Secondary Rectifiers/Filters. 2294886-503			
A6 Master Oscillator 2295527-1			

ITEM ID: 4.3.1		SHUTTLE CCIV CRITICAL ITEMS LIST		UNIT TVC/WIA DWG NO. 2294019-506 5007 2301088-503	SHEET 2 OF 9
CRITICALITY 2/2					
FAILURE MODE AND CAUSE		FAILURE EFFECT ON END ITEM		RATIONALE FOR ACCEPTANCE	
No output signal to the VSOU. Neither video nor synchronization information is present.		Loss of camera output depicting scene information within FOV of lens assembly.		DESIGN FEATURES (Continued)	
A1 Sync Generator Clock Divider Chain. 2294080-504		Hazard Case: Loss of mission critical video.		BARE BOARD DESIGN (A1, A4, A6, A7)	
A2 Camera Timing Logic 2294081-501				The design of the associated A1, A4, A6, A7 boards is constructed from laminated copper-clad epoxy glass sheets (NEMA G-10) Grade FR-4, PER MIL-P-55617A. Circuit connections are made through printed traces which run from point to point on the board surfaces. Every trace terminates at an annular ring. The annular ring surrounds the hole in which a component lead or terminal is located. This ring provides a fooling for the solder, ensuring good mechanical and electrical performance. Its size and shape are governed by MIL-P-55640 as are trace widths, spacing and routing. These requirements are reiterated specifically in drawing notes to further assure compliance. Variations between the artwork master and the final product (due to irregularities of the etching process) are also controlled by drawing notes. This prevents making defective boards from good artwork. Holes which house no lead or terminal, but serve only to electrically interconnect the different board layers, contain stitch bars for mechanical support and increased reliability.	
A3 Sync Formatter, Video Output Drive. 2294084-503				The thru holes are drilled from a drill tape thus eliminating the possibility of human error and allowing tight control over hole and annular ring concentricity, an important reliability criterion. After drilling and etching, all copper cladding is tin-lead plated per MIL-STO-1495. This provides for easy and reliable soldering at the time of board assembly, even after periods of prolonged storage.	
A4 Power On/Off Switching, Input Voltage Preregulators, Output Voltage Regulators. 2294085-501				BOARD ASSEMBLY DESIGN (A1, A4, A5, A6, A7)	
A5 DC/DC Converters Primary Oscillator Driver. Secondary Rectifiers/Filters. 2294086-503				All components are installed in a manner which assures maximum reliability. Component leads are pre-tinned, allowing total wetting of solder joints. All leads are formed to provide stress relief and the bodies of large components are staked. Special mounting and handling instructions are included in each drawing required after final assembly. The board is coated with urethane which protects against humidity and contamination.	
A6 Master Oscillator 2294087-1				BOARD PLACEMENT (A1, A2, A4, A6)	
				The A1, A2, A4, and A6 boards are secured in the electronics assembly by gold-plated beryllium-copper card guides. Connections are made to the mother board with blind-mated connectors. Disengagement during launch is prevented by a cover which spans the board's free edge.	

EMFA NO. <u>4.3.1</u>	CRITICALITY <u>2/2</u>	SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT <u>IVCAVIA</u> DNG NO. <u>2294819-506, 500Z</u> <u>2307088-503</u> SHEET <u>3</u> OF <u>9</u>
FAILURE MODE AND CAUSE No output signal to the VSD. Neither video nor synchronization information is present. <u>A1</u> Sync Generator Clock Divider Chain. 2294880-504 <u>A2</u> Camera Timing Logic 2294881-501 <u>A3</u> Sync Formatter, Video Output Drive. 2294884-501 <u>A4</u> Power On/Off Switching, Input Voltage Preregulators. Output Voltage Regulators. 2294885-501 <u>A5</u> DC-DC Converters Primary Oscillator Driver, Secondary Rectifiers/filters. 2294886-503 <u>A6</u> Master Oscillator 2295527-1	FAILURE EFFECT ON END ITEM Loss of camera output depicting scene information within FOV of lens assembly. <u>MarsLCam:</u> Loss of mission critical video.	DESIGN FEATURES (Continued) BARE BOARD CONSTRUCTION (A2) <p>The A2 board is of "welded wire" construction. At the bare board level this does not distinguish it from a normal PC board except that holes which will take weld pins generally are not connected to PC traces. Only those pins which bring power and ground potentials to the ICs are on PCs. An annular ring surrounds the hole in the board where each power and ground pin is located. These pins are then soldered to the trace like any other component lead. Aside from this feature, all design & construction techniques used in PC board layout apply.</p> BOARD ASSEMBLY (A2) <p>The drilled and etched board is populated with several hundred solderable or weldable pins. Power and ground pins, as well as connector pins, are soldered in place. Discrete components (resistors, diodes, capacitors) are attached to bifurcated terminals, where they are soldered. Flatpack ICs are welded, lead-by-lead, to the tops of the weld pins. After welding, extra lead material is trimmed away. Circuit connections are made using #30 AWG nickel weld wire. The wire is welded to the pin surfaces on the board backside. All wire welds are done using a machine which is tape driven, thus eliminating the possibility of miswiring due to operator error. All wiring & circuit performance is tested prior to box-level installation. After successful testing, components are staked as required by drawing notes and the assembly is coated with urethane.</p> <p>The board is inserted in the box on card-edge guides, in the same manner as the other PC boards.</p> <p>The A7-A low voltage power supply board is bolted in place at 6 points around its perimeter. Four of these mounting screws also pass through and tie down the smaller A7-B board. These two boards are mounted face-to-face, separated by the standoffs. Electrical interconnections are achieved by jumper wires between the two boards. The A7-A houses a 34-pin connector which brings in power and signals from outside the module.</p> <p>The A2 module includes these two boards as well as power transistor Q4. The module housing is bent aluminum sheet, comprised of two halves screwed together. The boards and Q4 are secured to the lower half, and wired together. Then the upper half is put in place. By mounting Q4 directly to the aluminum housing, good thermal performance is assured.</p>	

INFA NO. <u>4.3.1</u>		SHUTTLE CCTV CRITICAL ITEMS LIST	LINE1 <u>FVC/HIA</u> DWG NO. <u>2294819-506, 508/</u> <u>2307088-503</u> SHEET <u>4</u> OF <u>9</u>
FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	RATIONALE FOR ACCEPTANCE	
No output signal to the VSH. Neither video nor synchronization information is present.	Loss of camera output depicting scene information within FOV of lens assembly. Worst Case: loss of mission critical video.	The A13 assembly is a temperature compensated voltage controlled crystal oscillator (TCVCO) that is purchased to a specification controlled drawing that establishes the requirements for performance, design, test, and qualification of the unit. The product assurance provisions of the document contain the identical requirements for electronic parts and materials as the Shuttle CCTV program and must receive the approval of RCA and NASA-JSC. Mechanical and electrical integrity of the assembly is confirmed by both analysis (design reviews) and test (qualification and acceptance).	QUALIFICATION JESE For Qualification Test Flow, see Table 2 located at the front of this book.
A1 Sync Generator Clock Divider Chain. 2294880-504			
A2 Camera Timing Logic 2294881-501			
A4 Sync Formatter, Video Output Drive. 2294884-503			
A6 Power On/Off Switching, Input Voltage Preregulators, Output Voltage Regulators. 2294885-501			
A7 DC-DC Converters Primary Oscillator Driver, Secondary Rectifiers/Filters. 2294886-503			
A13 Master Oscillator 2295527-1			

EMEA NO. <u>4.3.1</u>		SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT <u>TVC/HIA</u> DNG NO. <u>2290019-508</u> , <u>5087</u> SHEET <u>5</u> OF <u>9</u>
CRITICALITY <u>2/2</u>			
FAILURE MODE AND CAUSE	FAILURE EFFECT ON ENCL ITEM		RAIONABLE FOR ACCEPTANCE
No output signal to the VSU. Neither video nor synchronization information is present.	Loss of camera output depicting scene information within FOV of lens assembly.	<u>ACCEPTANCE TEST</u> The CCTV systems' WIA is subjected directly, without vibration isolators which might be used in their normal installation, to the following testing:	
A1 Sync Generator Clock Divider Chain, 2294880-504	Worst Case: Loss of mission critical video.	<ul style="list-style-type: none"> • Vibration: 20-80Hz: 3 dB/Oct-rise from 0.01 G²/Hz 80-350 Hz: 0.04 G²/Hz 350-750 Hz: -3 dB/10 Oct-slope Test Duration: 1 Minute per Axis Test Level: 6.1 Grms 	
A2 Camera Timing Logic 2294081-501		<ul style="list-style-type: none"> • Thermal Vacuum: In a pressure of 1×10^{-5} Torr, the temperature shall be as follows: <ul style="list-style-type: none"> 125° F: Time to stabilize equipment plus 1 hour 25° F: Time to stabilize equipment plus 1 hour 125° F: Time to stabilize equipment plus 1 hour 	
A3 Sync Formatter, Video Output Drive, 2294884-503			The WIA may not have been subjected to the vacuum condition.
A4 Power On/Off Switching, Input Voltage Preregulators, Output Voltage Regulators, 2294885-501			For Acceptance Test Flow, See Table I located at the front of this book.
A5 DC-DC Converters Primary Oscillator Driver, Secondary Rectifiers/Filters, 2294886-503			
A6 Master Oscillator 2295521-1			
		<u>OPERATIONAL TESTS</u> In order to verify that CCTV components are operational, a test must verify the health of all the command related components from the PHS (A7AII panel switch, through the RCU, through the sync lines to the Camera/PTU, to the Camera/PTU command decoder. The test must also verify the camera's ability to produce video, the VSU's ability to route video, and the monitor's ability to display video. A similar test would be performed to verify the HDM command path.	
			<u>Pre-Launch on Orbiter Test/In-Flight Test</u>
			<ol style="list-style-type: none"> 1. Power CCTV System. 2. Via the PHS panel, select a monitor as destination and the camera under test as source. 3. Send "Camera Power On" command from PHS panel. 4. Select "External Sync" on monitor. 5. Observe video displayed on monitor. Note that if video on monitor is synchronized (i.e., stable raster) then this indicates that the camera is receiving composite sync from the RCU and that the camera is producing synchronized video. 6. Send Pan, Tilt, Focus, Zoom, DLR, AND Gamma commands and visually (either via the monitor or direct observation) verify operation. 7. Select downlink as destination and camera under test as source. 8. Observe video routed to downlink. 9. Send "Camera Power Off" command via PHS panel. 10. Repeat Steps 3 through 9 except issue commands via the MIM command path. This proves that the CCTV equipment is operational.

FMEA NO. <u>4.3.1</u>	SHUTTLE CCFTV CRITICAL ITEMS LIST	UNIT <u>TVC/HLA</u> DWG NO. <u>2294819-500, 500/</u> <u>2307000-503</u> SHEET <u>6</u> OF <u>9</u>
Criticality <u>2/2</u>		
FAILURE MODE AND CAUSE No output signal to the VSD. Neither video nor synchronization information is present.	FAILURE EFFECT ON END ITEM Loss of camera output depicting scene information within FOV of lens assembly. <u>Worst Case:</u> Loss of mission critical video.	QA/INSPECTION <u>Procurement Control</u> - The TVC/HLA EEE Parts and hardware items are procured from approved vendors and suppliers, which meet the requirements set forth in the CCTV contract and Quality Plan Work Statement (HS-25911/u). Resident DCAS personnel review all procurement documents to establish the need for GSI on selected parts (PAI St7).
A1 Sync Generator Clock Divider Chain. 2294880-504		RATIONALE FOR ACCEPTANCE <u>Incoming Inspection and Storage</u> - Incoming Quality inspections are made on all received materials and parts. Results are recorded by lot and retained in file by drawing and control numbers for future reference and traceability. All EEE parts are subjected to incoming acceptance tests as called for in PAI 315 - Incoming Inspection Test Instructions. Incoming flight parts are further processed in accordance with RGA 18466B4 - Preconditioning and Acceptance Requirements for Electronic Parts, with the exception that DPA and PIND testing is not performed. Mechanical items are inspected per PAI 316 - Incoming Inspection Instructions for mechanical items, PAI 305 - Incoming Quality Control Inspection Instruction, and PAI 612 - Procedure for Processing Incoming or Purchased Parts Designated for Flight Use. Accepted items are delivered to Material Controlled Stores and retained under specified conditions until fabrication is required. Non-conforming materials are held for Material Review Board (MRB) disposition. (PAI 307, PAI IQC 531).
A2 Camera Timing Logic 2294081-501		
A3 Sync Formatter, Video Output Drive. 2294884-503		
A4 Power On/Off Switching, Input Voltage Preregulators, Output Voltage Regulators. 2294885-501		
A5 DC-DC Converters Primary Oscillator Driver, Secondary Rectifiers/Filters. 2294886-503		
A6 Master Oscillator 2295527-1		
		<u>Board Assembly & Test</u> - Prior to the start of TVC board assembly, all items are verified to be correct by stock room personnel, as the items are accumulated to form a kit. The items are verified again by the operator who assembles the kit by checking against the as-built-parts-list (ABPL). DCAS Mandatory Inspection Points are designated for all printed circuit, wire wrap and welded wire boards, plus harness connectors for soldering wiring, crimping, solder splices and quality workmanship prior to coating of the component side of boards and sleeving of harnesses.
		TVC Boards Specific TVC board assembly and test instructions are provided in drawing notes, and applicable documents are called out in the Fabrication Procedure and Record (FPR-2294819) and parts list PL2294819. These include shuttle TVC assembly notes 2593610, Process Standard RTV-S66 2280881, Process Standard - Bonding Velcro Tape 2280089, Specification Soldering 2280749, Specification Name Plate Application 1960167, Specification - Crimping 2280800, Specification - Bonding and Staking 2280070, Specification - Urethane coating 2280877, Specification - Locking compound 2026110, Specification Epoxy Adhesive 2010985, Specification - Marking 2280876, Specification - Workmanship 8030035, Specification Bonding and Staking 2280875.

FMEA NO. 4.3.1CRITICALITY 222

FAILURE MODE AND

CAUSE

No output signal to the VSIU.
Neither video nor synchronization information is present.

A1 Sync Generator
Clock Divider Chain.
2294880-504

A2 Camera Timing Logic
2294881-501

A3 Sync Formatter,
Video Output Drive,
2294884-503

A4 Power On/Off Switching,
Input Voltage Preregulators,
Output Voltage Regulators,
2294885-501

A5 DC-DC Converters
Primary Oscillator Driver,
Secondary Rectifiers/Filters,
2294886-503

A6 Master Oscillator
2295271

FAILURE EFFECT
ON END ITEM

Loss of camera output depicting scene information within FOV of lens assembly.

Worst Case:
Loss of mission critical video.

SHUTTLE COTV
CRITICAL ITEMS LISTUNIT TVC/WIADWG NO. 2294019-506, 5087
2302088-503SHEET 7 OF 9

RATIONALE FOR ACCEPTANCE

QA/INSPECTION (Continued)

TVC Assembly and Test - An open box test is performed per TP-IT-2294819, and an Acceptance Test per TP-AT-2294819, including vibration and thermal vacuum. Torques are specified and witnessed, traceability numbers are recorded and calibrated tools are checked prior to use. RCA Quality and DCAS inspections are performed at the completion of specified FPR operations in accordance with PAI 204, PAI 205, PAI 206 and PAI 217. DCAS personnel witness TVC button-up and critical torquing.

WIA Assembly and Test - An open box test is performed per TP-IT-2307088, Acceptance Test per TP-AT-2307088. Torques are specified and witnessed, traceability numbers are recorded and calibrated tools are checked prior to use. RCA Quality and DCAS inspections are performed at the completion of specified FPR operations in accordance with PAI 204, PAI 205, PAI 217 and PAI 402. DCAS personnel witness WIA button-up and critical torquing.

TVC/WIA Assembly and Test - After a TVC and a WIA have been tested individually, they are mated and a final acceptance test is performed per TP-AT-2294819, including vibration and thermal vacuum environments. RDA and UCAS personnel monitor these tests and review the acceptance test data/results. These personnel also inspect for conformance after all repair, rework and retest.

Preparation for Shipment - The TVC and WIA are separated prior to shipment after fabrication and testing is complete. Each is packaged according to CCIV letter 0011 and 2280746, Process standard for Packaging and Handling guidelines. All related documentation including assembly drawings, Parts List, ABPL, Test Data, etc., is gathered and held in a documentation folder assigned specifically to each assembly. This folder is retained for reference. An EIDP is prepared for each assy in accordance with the requirements of NS-259317b. RCA QC and DCAS personnel witness crating, packaging, packing and marking, and review the EIDP for completeness and accuracy.

ITEM NO. <u>4.3.1</u> CRITICALITY <u>2/2</u>		SHUTTLE CCIV CRITICAL ITEMS LIST	UNIT <u>IVC/VIA</u> DWG NO. <u>2294819-506, 508/ 2307008-503</u> SHEET <u>B</u> OF <u>9</u>				
<table border="1"> <thead> <tr> <th>FAILURE MODE AND CAUSE</th> <th>FAILURE EFFECT ON END ITEM</th> <th>RATIONALE FOR ACCEPTANCE</th> </tr> </thead> <tbody> <tr> <td>No output signal to the VSO. Neither video nor synchronization information is present.</td> <td>Loss of camera output depicting scene information within FOV of lens assembly.</td> <td> <p>FAILURE HISTORY</p> <p>IDR - W2644 - Log #0462, IVC S/N F003-502 IDR - W2640 - Log #0463, IVC S/N F003-502</p> <p>Description: Integration Testing Failure Box Level Thermal-Vac Hot Environment</p> <p>No video from IVC. +28 volt current at 1.5 Amp limit. (30 minutes into thermal vac hot test cycle -105°F)</p> <p>Cause: Short in A7 low voltage power supply. (High voltage winding of transformer)</p> <p>Corrective Action: Removed and replaced transformer (sent to vendor for analysis). Short due to a pin-hole in magnet wire insulation. Future transformers to be purchased per revised spec control drawing ECR (CCIV 64038028).</p> <p>IDR - W2740 - Log #0486 - IVC S/N 008-502</p> <p>Description: Pre-Launch Test Failure Box Level Ambient Environment</p> <p>REF: VOES-2-01-0097 unit returned from KSC. Power was applied to wrong pins. (+28V).</p> <p>Cause: Incorrect wiring of shuttle craft harness, put +28V to J1-10 and RTN to J1-9.</p> <p>Corrective Action: Wiring of shuttle harness to be repaired by responsible organization. Failure analysis performed and corrective action taken on IVC S/N 008. As board-failure analysis indicated the following parts are to be changed. Q1, Q3, Q12, CR3, CR6, and R51 were replaced.</p> <p>IDR - W8024 - Log #0530 - IVC S/N 007-502</p> <p>Description: Acceptance Test Failure Box Level Thermal Vac - Hot Environment. IVC drawing excessive current, >1.5A. Failure occurred at +125°F.</p> <p>Cause: Capacitor C10 on the A6 board was found to be shorted. A large quantity of solder flowed inside from sleeve thru header.</p> <p>Corrective Action: Capacitor C10 removed & replaced. (random part failure).</p> </td> </tr> </tbody> </table>	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	RATIONALE FOR ACCEPTANCE	No output signal to the VSO. Neither video nor synchronization information is present.	Loss of camera output depicting scene information within FOV of lens assembly.	<p>FAILURE HISTORY</p> <p>IDR - W2644 - Log #0462, IVC S/N F003-502 IDR - W2640 - Log #0463, IVC S/N F003-502</p> <p>Description: Integration Testing Failure Box Level Thermal-Vac Hot Environment</p> <p>No video from IVC. +28 volt current at 1.5 Amp limit. (30 minutes into thermal vac hot test cycle -105°F)</p> <p>Cause: Short in A7 low voltage power supply. (High voltage winding of transformer)</p> <p>Corrective Action: Removed and replaced transformer (sent to vendor for analysis). Short due to a pin-hole in magnet wire insulation. Future transformers to be purchased per revised spec control drawing ECR (CCIV 64038028).</p> <p>IDR - W2740 - Log #0486 - IVC S/N 008-502</p> <p>Description: Pre-Launch Test Failure Box Level Ambient Environment</p> <p>REF: VOES-2-01-0097 unit returned from KSC. Power was applied to wrong pins. (+28V).</p> <p>Cause: Incorrect wiring of shuttle craft harness, put +28V to J1-10 and RTN to J1-9.</p> <p>Corrective Action: Wiring of shuttle harness to be repaired by responsible organization. Failure analysis performed and corrective action taken on IVC S/N 008. As board-failure analysis indicated the following parts are to be changed. Q1, Q3, Q12, CR3, CR6, and R51 were replaced.</p> <p>IDR - W8024 - Log #0530 - IVC S/N 007-502</p> <p>Description: Acceptance Test Failure Box Level Thermal Vac - Hot Environment. IVC drawing excessive current, >1.5A. Failure occurred at +125°F.</p> <p>Cause: Capacitor C10 on the A6 board was found to be shorted. A large quantity of solder flowed inside from sleeve thru header.</p> <p>Corrective Action: Capacitor C10 removed & replaced. (random part failure).</p>	
FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	RATIONALE FOR ACCEPTANCE					
No output signal to the VSO. Neither video nor synchronization information is present.	Loss of camera output depicting scene information within FOV of lens assembly.	<p>FAILURE HISTORY</p> <p>IDR - W2644 - Log #0462, IVC S/N F003-502 IDR - W2640 - Log #0463, IVC S/N F003-502</p> <p>Description: Integration Testing Failure Box Level Thermal-Vac Hot Environment</p> <p>No video from IVC. +28 volt current at 1.5 Amp limit. (30 minutes into thermal vac hot test cycle -105°F)</p> <p>Cause: Short in A7 low voltage power supply. (High voltage winding of transformer)</p> <p>Corrective Action: Removed and replaced transformer (sent to vendor for analysis). Short due to a pin-hole in magnet wire insulation. Future transformers to be purchased per revised spec control drawing ECR (CCIV 64038028).</p> <p>IDR - W2740 - Log #0486 - IVC S/N 008-502</p> <p>Description: Pre-Launch Test Failure Box Level Ambient Environment</p> <p>REF: VOES-2-01-0097 unit returned from KSC. Power was applied to wrong pins. (+28V).</p> <p>Cause: Incorrect wiring of shuttle craft harness, put +28V to J1-10 and RTN to J1-9.</p> <p>Corrective Action: Wiring of shuttle harness to be repaired by responsible organization. Failure analysis performed and corrective action taken on IVC S/N 008. As board-failure analysis indicated the following parts are to be changed. Q1, Q3, Q12, CR3, CR6, and R51 were replaced.</p> <p>IDR - W8024 - Log #0530 - IVC S/N 007-502</p> <p>Description: Acceptance Test Failure Box Level Thermal Vac - Hot Environment. IVC drawing excessive current, >1.5A. Failure occurred at +125°F.</p> <p>Cause: Capacitor C10 on the A6 board was found to be shorted. A large quantity of solder flowed inside from sleeve thru header.</p> <p>Corrective Action: Capacitor C10 removed & replaced. (random part failure).</p>					

FMEA NO. 4.3.1	SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT TVC/HIA DWG NO. 2294819-506, 508/ 2307000-503 SHEET BA OF 9
CRITICALITY 2/2		
FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	RATIONALE FOR ACCEPTANCE
No output signal to the VSU. Neither video nor synchronization information is present.	Loss of camera output depicting scene information within FOV of Lens assembly.	<u>FAILURE HISTORY</u> TDR - W2644 - Log #0462, TVC S/N F003-502 TDR - W2640 - Log #0463, TVC S/N F003-502 <u>Description:</u> Integration Testing failure Box Level Thermal-Vac Hot Environment <u>Cause:</u> No video from TVC. +28 volt current at 1.5 Amp limit. (30 minutes into thermal vac hot test cycle ~105°F) <u>Corrective Action:</u> Removed and replaced transformer (sent to vendor for analysis). Short due to a pin-hole in magnet wire insulation. Future transformers to be purchased per revised spec control drawing ECN CCTV 649(D302B). TDR - W2740 - Log #0486 - TVC S/N 008-502 <u>Description:</u> Pre-launch Test failure Box Level Ambient Environment REF: VJCS-2-01-0097 unit returned from KSC. Power was applied to wrong pins. (+28V). <u>Cause:</u> Incorrect wiring of shuttle craft harness; put +28V to J1-10 and RIN to J1-9. <u>Corrective Action:</u> Wiring of shuttle harness to be repaired by responsible organization. Failure analysis performed and corrective action taken on TVC S/N 008. Ab board-failure analysis indicated the following parts are to be changed. Q1, Q3, Q12, CR3, CR6, and R51 were replaced. TDR - W0024 - Log #0530 - TVC S/N 007-502 <u>Description:</u> Acceptance Test failure Box Level Thermal Vac - Hot Environment TVC drawing excessive current, >1.5A. Failure occurred at ~125°F. <u>Cause:</u> Capacitor C10 on the Ab board was found to be shorted. A large quantity of solder flowed inside from sleeve thru header. <u>Corrective Action:</u> Capacitor C10 removed & replaced. (random part failure).
Failure Mode and Cause	Failure Effect on End Item	Failure History
A1 Sync Generator Clock Divider Chain. 2294800-504	Loss of camera output depicting scene information within FOV of Lens assembly.	TDR - W2644 - Log #0462, TVC S/N F003-502 TDR - W2640 - Log #0463, TVC S/N F003-502 <u>Description:</u> Integration Testing failure Box Level Thermal-Vac Hot Environment <u>Cause:</u> No video from TVC. +28 volt current at 1.5 Amp limit. (30 minutes into thermal vac hot test cycle ~105°F) <u>Corrective Action:</u> Removed and replaced transformer (sent to vendor for analysis). Short due to a pin-hole in magnet wire insulation. Future transformers to be purchased per revised spec control drawing ECN CCTV 649(D302B). TDR - W2740 - Log #0486 - TVC S/N 008-502 <u>Description:</u> Pre-launch Test failure Box Level Ambient Environment REF: VJCS-2-01-0097 unit returned from KSC. Power was applied to wrong pins. (+28V). <u>Cause:</u> Incorrect wiring of shuttle craft harness; put +28V to J1-10 and RIN to J1-9. <u>Corrective Action:</u> Wiring of shuttle harness to be repaired by responsible organization. Failure analysis performed and corrective action taken on TVC S/N 008. Ab board-failure analysis indicated the following parts are to be changed. Q1, Q3, Q12, CR3, CR6, and R51 were replaced. TDR - W0024 - Log #0530 - TVC S/N 007-502 <u>Description:</u> Acceptance Test failure Box Level Thermal Vac - Hot Environment TVC drawing excessive current, >1.5A. Failure occurred at ~125°F. <u>Cause:</u> Capacitor C10 on the Ab board was found to be shorted. A large quantity of solder flowed inside from sleeve thru header. <u>Corrective Action:</u> Capacitor C10 removed & replaced. (random part failure).

FMEA NO. 4.3.1		SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT TVC/HLB DNG NO. 2294819-506, 508/ 2307085-503 SHEET 88 OF 9
CRITICALITY 2/2			
FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM		RATIONALE FOR ACCEPTANCE
No output signal to the VSU. Neither video nor synchronization information is present.	Loss of camera output depicting scene information within FOV of lens assembly.	EFTLUBE HISTORY	
A1 Sync Generator Clock Divider Chain. 2294880-504	Worst Case: Loss of mission critical video.	10R - W6823 - Log #558 - TVC S/N 012-502 Y1771 - Log #560 - TVC S/N 009-502 Y1771 - Log #560 - TVC S/N 002-502 Y1771 - Log #568 - TVC S/N 009-502 Y1770 - Log #567 - TVC S/N 014-502 Y1770 - Log #567 - TVC S/N D10-502 Y1770 - Log #568 - TVC S/N 017-502 Y1729 - Log #578 - TVC S/N 020-502	Description: Flight Failure, Spacecraft Level RMS TV Camera circuit breaker popped open during flight mission STS-3.
A2 Camera Timing Logic 2294881-501			Cause: Camera low voltage supply has erratic synchronization mode at low temperature.
A3 Sync Formatter, Video Output Drive. 2294884-503			Corrective Action: All flight cameras were returned under CCA35 for rework and retest to ECN C-18B1. ECN (C-18B1) to the low voltage power supplies eliminates the erratic synchronization problem. TVC group part no. has been changed from 2294819-502 to 504 to denote cameras that contain low voltage power supply modification.
A6 Power On/Off Switching, Input Voltage Preregulators, Output Voltage Regulators. 2294885-501		IDR - Y1771 - Log #0570 - TVC S/N 008-502	Description: Flight Failure Spacecraft Level (STS-3)
A7 DC-DC Converters Primary Oscillator Driver, Secondary Rectifiers/Filters. 2294886-503		TVC not synchronized for approximately 30 minutes. This problem occurred at cold temperature. Synchronization was regained at 20°C.	
A13 Master Oscillator 7205523-1		Cause: Loss of phase lock due to thermal assymetry of the 3.58 MHz Phase detector.	
		Corrective Action: CCA 39 has been issued directing RGA to incorporate the heater and sync modifications (ECN CCT 84B1 to all) flight camera's. TVC 008 was modified accordingly. TVC group number has been updated from group 502 to 506.	
		IDR - Y1779 - Log #576 - TVC S/N 014-502	Description: Flight Failure (STS-3) Spacecraft Level
		IDR was opened to allow relay K1 - contacts 5 and 6 failure on assy 2294885-503 S/N 1018.	

ITEM NO. <u>4.3.1</u>	SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT <u>TVC/WLA</u> DWG NO. <u>2294819-506, 508/ 2307088-503</u> SHEET <u>8C</u> OF <u>9</u>
CRITICALITY <u>2/2</u>		
FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	RATIONALE FOR ACCEPTANCE
No output signal to the VSU. Neither video nor synchronization information is present.	Loss of camera output depicting scene information within FOV of lens assembly.	FAILURE HISTORY TDR - B-3521 - Log #1165 - TVC S/N 038-508 Description: Acceptance Test Failure Box Level Thermal Vac - Hot Environment Excessive supply current. Lost all DLR/camera lights and output video information. Cause: Shorted capacitor C14 on AB board. Corrective Action: C14 removed and replaced with new capacitor. Product assurance lab could not find a cause for shorted cap. (Report # B5321A) Considered random failure.
A1 Sync Generator Clock Divider Chain. 2294880-504	Worst Case: Loss of mission critical video.	
A2 Camera Timing Logic 2294881-501		
A3 Sync Formatter, Video Output Drive. 2294884-501		
A4 Power On/Off Switching. Input Voltage Preregulators. Output Voltage Regulators. 2294885-501		
A5 DC-DC Converters Primary Oscillator Driver. Secondary Rectifiers/Filters. 2294886-503		
A6 Master Oscillator 2295521-1		

ITEM NO. <u>4.3.1</u>	SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT <u>TVC/HIA</u> DWG NO. <u>2294819-506, 508/</u> <u>2302080-503</u> SHEET <u>9</u> OF <u>9</u>
FAILURE MODE AND CAUSE No output signal to the VSD. Neither video nor synchronization information is present. <u>A1</u> Sync Generator Clock Divider Chain. 2244880-504 <u>A2</u> Camera Timing Logic 2294881-501 <u>A3</u> Sync Formatter Video Output Drive. 2294884-503 <u>A4</u> Power On/Off Switching. Input Voltage Preregulators. Output Voltage Regulators. 2294885-501 <u>A5</u> DC-DC Converters Primary Oscillator Driver. Secondary Rectifiers/Filters. 2294886-501 <u>A6</u> Master Oscillator 2295527-1	FAILURE EFFECT ON FMD IIth Loss of camera output depicting scene information within FOV of lens assembly. Worst Case: Loss of mission critical video.	RATIONALE FOR ACCEPTANCE <u>OPERATIONAL EFFECTS</u> Loss of video. Possible loss of major mission objectives if RMS elbow is required. <u>CREW ACTIONS</u> If possible, continue RMS operations using alternative visual cues. <u>CREW TRAINING</u> Crew should be trained to use possible alternatives to CCTV. <u>MISSION CONSTRAINT</u> Where possible, procedures should be designed so they can be accomplished without CCTV.