2294819-506.508/

2307088-503

ÔΕ

\_\_TYC/WLA

T 1MU THEA NO. 4.3.3.1 SHUTTLE ECTV DING NO. CRITICAL ITEMS LIST CRITICALITY \_\_2/2 SHEET FAILURE MODE AND FAILURE EFFECT CAUSE ON END ITEM BATTOMALE FOR ACCEPTANCE lime base errors (jitter) in the (1) Loss of camera output **DESIGN FEATURES** synchronization information on the depicting scene intorvideo oulput line. Video informamation within fOV of The TVC/Lens Assembly is comprised of 16 electrical subassemblies; 13 subassemblies lion is present and contains the lens assembly. are RCA Astro designed and fabricated using standard printed-circuit board type of time base errors. (2) loss of camera until construction. The remaining three assemblies, high voltage power supply, oscillator, self-heating of cirand slepper motors, are vendor supplied components which have been specified and cuilty restores normal purchased according to RCA Specification Control Drawings (SCDs) prepared by engi-Al Sync Generator. operation. neering and reliability assurance. Specifications per the SCD, are prepared to Clack Divider Chain. establish the design, performance, test, qualification, and acceptance requirements Phase-tocked toop. Werst Case: for a procured piece of equipment. 2294680-564 Loss of mission critical A2 Camera Liming Logic videa. Parts, materials, processes, and design guidelines for the Shuttle CCTV program are 2294881-501. specified in accordance with RCA 2295503. This document defines the program require-All Haster Oscillator ments for selection and control of EEE parts. To the maximum extent, and consistent with availability, all parts have been selected from military specifications at the TVE JAN level, as a minimum. In addition to the overall selection criteria, a subset of **Heaters** general purpose preferred parts has been defined by this document and the RCA Government Systems Division Standard Parts List. In the case of the CMOS and ITL family of microcircuits, devices are screened and tested to the MIL-STD-883C equivalent and procured under the designations of HI-REL/3WQ and SMC 54LS from RCA-\$50 and Texas Instruments Corp. respectively. Parts not included in the above documents have been used in the design only after a nonstandard item approval form (MSJAF) has been prepared, submitted to Reliability Assurance Empineering (RAE) and approved for use in the specific application(s) defined in the MSIAF by MASA-JSC. Horst-Case Circuit Analyses have been performed and documented for all circuit designs to demonstrate that sufficient operating margins exist for all operating conditions. The analysis was worst case in that the value for each of the variable parameters was set to limits that will drive the output to a maximum (or minimum). A component application review and analysis was conducted to verify that the applied stress on each piece part by the temperature extremes specified with environmental qualification testing does not exceed the stress dending values identified in PCA 2295501. In addition, an objective examination of the design was performed through a PDR and FOR to verify that the IVC/Lens assembly met specification and contractual requirements.

<del></del>			
ENTITION AND EAST FAILURE FEECT		SHUTTLE ECTV CRITICAL ITEMS LIST	HNET
FAILURE MODE AND  CAUSE  Time base errors ([itter] in the synchronization information on the video dutput line. Video information is present and contains the time base errors.  IV( A! Sync Generator. Clock Divider Chain. Hisser-tocked toop. 2294880-504 A2 Comerator Liming togic 2294881-501 A!! Muster Oscillator  IVC Unaters	FAITURE EFFECT ON END LITH  (1) Loss of camera output depicting scene infor- matinn within FDV of lens assembly.  (2) Loss of camera until self-heating of cir- cuitry restores normal operation.  Vurst Case: Loss of mission critical video.	RATIONALE FOR ACCEPTANCE  OESIGN FEATURES (Continued)  BARE BOARD DESIGN (AI)  The design of the associated AI board is constructed from copper-clad epoxy glass sheets (NEMA G-10) Grade fR-4), connections are made through printed traces which run though surfaces. Every trace terminates at an annular resorrounds the hole in which a component lead or terminal provides a footing for the solder, ensuring good mechan performance. Its size and shape are governed by MIL-P-spacing and routing. These requirements are reiterated notes to further assure compliance. Variations between final product (due to irregularities of the etching producting notes. This prevents making defective boards (final product (due to irregularities of the etching producting notes. This prevents making defective boards (final product (due to irregularities of the etching productinal notes are dealless from a drill tape thus eliminate no lead or terminal, but serve only to electrical board layers, contain stitch bars for mechanical support. The thru holes are deilless from a drill tape thus elimin tumber reliability criterion. After drilling and etc tin-lead plated per H(L-STD-1495. This provides for each time of board assembly, even after periods of prolocution of board assembly, even after periods of prolocution of the time of board assembly, even after periods of prolocution of the time of board assembly even after periods of prolocution of the time of board assembly, even after periods of prolocution of the time of board assembly, even after periods of prolocutions are included.  All components are installed in manner which assures a Component leads are pre-tinned, allowing total melting the form of the bodies of layers.	om laminated  PER MIL-P-55617A. Circuit row point to point on the ing. The annular ring lis located. This ring ical and electrical sold and electrical sold are trace widths, specifically in drawing the artwork master and the cess) are also controlled by row good artwork. Holes which by interconnect the different thand increased reliability. The interconnect is and increased reliability. The interconnect is a specifically of controlled by and increased reliability. The interconnect is a specific to the possibility of color ring concentricity, and increased reliability. The interconnect is a specific to the possibility of color ring concentricity, and reliable soldering at the possibility. The interconnection is a specific to the possibility of solder points. All leads the possibility are staked.
		alter final assembly. The board is coaled with urethane humidity and contamination.  BOARD PLACEMENT  The Al and A3 boards are secured in the electronics assegold plated beryllium copper card guides. Connections a with blind-mated connectors. Disengagement during launce which spans the board's tree edge.	which protects against only by one made to the mother board

UNIT TVE/NLA FHEA ND. \_ 4.3.3.1 SHUTTLE CCTV DWG NO. 2294819-506,5087 CRITICAL LIENS LIST 2307098-503 ERITICALITY <u>2/2...</u> SHEET 3 OF FATTURE MORIE AND FAILURE EFFECT CAUSE OH END TIEM RATIONALE FOR ACCEPTANCE Time base errors (jitter) in the (1) Loss of camera output DESIGN FEATURES (Continued) synchronization information on the depicting scene inforvideo output line. Video informamation within FOV of MARE BOARD CONSTRUCTION (A2) lion is present and contains the lens assembly. lime base errors. (2) Loss of camera until The A2 board is of "welded wire" construction. At the bare board level this does not self-heating of cirdistinguish it from a sormal PC board except that holes which will take weld pins TVC custry restores Aormal generally are not connected to PC traces. Only those page which bring power and Al Sync Generator. pround potentials to the ICs are on PCs. An abundar ring surrounds the hole in the operation. Clock Divider Chain. board where each power and ground pin is located. These pins are then soldered to the trace like any other component lead. Aside from this feature, all design Phase-Locked Loop. Horst Case: 2294880-504 Loss of mission critical & construction techniques used in PC board layout apply. A2 Camera liming Logic video. 2294881-601 BOARD ASSEMBLY (A2) All Master Oscillator The drilled and elched boards are populated with several hundred solderable or TVC weldable pins. Power and ground pins, as well as connector pins, are solvered in Heaters. place. Discreet components (resistors, diudes, capacitors) are attached to bifurcated terminals, where they are soldered. Flatpack It's are welded, lead-by-lead to the tops of the weld pins. After welding, extra lead material is trimmed away. Circuit connections are made using #30 AMG mickel weld wire. The wire is welded to the pin surfaces on the board backside. All wire welds are done using a machine which is lape driven, thus eliminating the possibility of miswiring due to operator error. All wiring & circuit performance is tested prior to box-level installation. After successful testing, components are staked as required by drawing notes and the assembly is coated with wrethung. The board is inserted in the box on card-edge guides, in the same manner as the other PC boards. The Al3 assembly is a temperature compensated voltage controlled crystal ascillator (ICVCXO) that is purchased to a specification controlled drawing that establishes the requirements for performance, design, test, and qualification of the unit. The product assurance provisions of the document contain the identical requirements for relectronic parts and materials as the Shuttle CCTV program and must receive the approval of RCA and MASA-JSC. Mechanical and electrical integrity of the assembly is confirmed by both analysis (design reviews) and test (qualification and acceptance),

REVISED 10-14-86

THEA NO. 4.3.3.1  CRIT (CALLTY 2/2  TAILURE MODE AND		SHULTLE CCTV CRETICAL LIENS LIST	UNIT TYC/MA DWG NO. 2294819-506,508/ 2307080-501 SHFET 4 OF 9
CAUSE  Time base errors (ilter) in the synchronization information on the video output line. Video information is present and contains the time base errors.  I/C Al Sync Generator. Clock Divider Chain. Phase-torked loop. 2294880-504  A2 Camera Liming Logic 2294881-501  A11 Master Oscillator  EVC	ON END ITEM  (1) Loss of camera output depicting scene information within FOV of lens assembly.  (2) Loss of camera until self-heating of circuitry restores normal operation.  Horst Case: Loss of mission critical video.	RATIONALE FOR ACCEPTANCE  QUALIFICATION TEST  For Qualification Test Flow, see Table 2 located at the	frant of this book.

UNIT JYC/WLA ГИЕА НО. <u>4.3.3.1</u> SHUTTLE CCTV OHG NO. 2294019-506.50<mark>8</mark>/ CRITICAL ITEMS LIST 2307088-503 CREDICALITY \_2/2\_\_ SHEET FAILURE HODE AND FAILURE EFFECT CAUSE ON END THEM RATIONALE FOR ACCEPTANCE lime base errors (jitter) in the (1) loss of camera output ACCEPTANCE TEST synchronization information on the depitting scene inforvideo output line. Video informamation within FOV of The CCTV systems! MLA is subjected directly, without vibration isolators which might from is present and contains the lens assembly. be used in their normal installation, to the following testing: time base errors. (2) Loss of camera until self-heating of cir-· Vibratjan: 20-80Hz : 3 dB/Oct-rise from 0.01  $G^2/Hz$ 141 cuilry restores normal 80-350 Hz: 8.04 G<sup>2</sup>/Hz A) Sync Generator. operation. 350-750 Hz: -3 48/10 Oct-slope Clack Divider Chain. Test Duration: I Minute per Axis Phase-Locked Loop. Worst Case: Test tevel: 6.1 Gras 2294880-584 loss of mission critical AZ Camera limino Logic video. • Thermal Vacuum: In a pressure of  $IX10^{-5}$  Turn, the temperature shall be as 2294881-50 kg follows: Alb Haster Oscillator 125° f: Time to stablize equipment plus I haur [YC 25° F: Time to stablize equipment plus I hour Healers 125° F: Time to stablize equipment plus I hour The WLA may not have been subjected to the vacuum condition. for Acceptance lest flow, See Table I located at the front of this book. OPERATIONAL JESIS In order to verify that CCIV components are operational, a test must verify the health of all the command related components from the PHS (A7A1) panel switch, through the RCU, through the sync lines to the Camera/PfU, to the Camera/PTU command decoder. The test must also verify the camera's ability to produce video, the VSU's ability to route video, and the monitor's ability to display video. A similar test would be performed to verify the HOH command path. Pre-Launch on Arbiter Test/(n-flight lest . 1. fower CC1V System. 2. Via the PMS panel, select a monitor as destination and the camera under lest as source. 3. Send "Campra Power On" command from PHS panel. 4. Select "External Sync" on monitor, 5. Observe video displayed on monitor. Note that if video on monitor is synchronized (i.e., Stable raster) them this indicates that the camera is receiving composite sync from the RCU and that the camera is producing Synchronized video. 6. Send Pan. Till, Focus, Joom, DLR, AND Gamma commands and ossually feither via the monitor or direct observations verify operation. Select downlink as destination and camera under test as source. 8. Observe videa routed to committak. 9. Send "Camera Power Off" (ommand via PHS pane). 18. Repeat Steps 3 through 9 emept issue commands you the 80M command path.

4 195

This proves that the fell equipment is operational.

UNCI \_\_\_\_ [VC/W.A JMEA NO. . 4.3.3.1 2294819-506.50BZ SINTILE CCTV DWG NO. CRITICAL IFEMS LIST 2307088-503 CHITICALITY \_\_ 2/2 SHEET \_6\_\_ OF FAILURE NODE AND FAILURE EFFECT \_\_\_\_CAUSE. ON END LIEM RATIONALE FOR ACCEPTANCE Time base errors (litter) in the QA\_INSPECTION (1) loss of camera output synchronization information on the depicting scene inforvideo ontput line. Video informamation within FOY of Procurement [gntrol - The IVC/WLA EEE Parts and bardware items are procured (rom tion is present and contains the tens assembly. approved vendors and suppliers, which went the requirements set lorth in the CCIV time base errors. 121 toss of camera until contract and Quality Plan Work Statement (WS-2593176). Resident DCAS personnel self-heating of cirreview all procurement documents to establish the need for GSI on selected parts 170 cultry restores normal (PAI 517). Al Sync Generator. operation. Clack Divider Chain. Incoming Inspection and Storage - Incoming Quality inspections are made on all Phase-Locked Long. Moest Case: received materials and parts. Results are recorded by lot and retained in file by 2244880~504 Loss of mission critical drawing and control numbers for future reference and traceability. All EEE parts AZ Camera liming Logic video. are subjected to incoming acceptance tests as called for in PAI 315 - Incoming 2294881-501 Inspection lest Instructions. Incoming flight parts are further processed in All Master üscillator accordance with RCA 1846684 - Preconditioning and Acceptance Requirements for Electronic Parts, with the exception that DPA and PIND testing is not performed. ΙVC Mechanical items are inspected per PAI 316 - Incoming Inspection lastructions for Heaters mechanical items. PAI 305 - Incoming Quality Control Inspection Instruction. and PAI 612 - Procedure for Processing Incoming or Purchased Parts Designated for Flight Use. Accepted items are delivered to Material Controlled Stores and retained under specified conditions until fabrication is required. Non-conforming materials are held for Malerial Review Board (MHB) disposition. (PAI 30), PA1 IQC 531). <u> Coard Assembly & Test</u> - Prior to the start of TVC board assembly, all items are verified to be correct by stock room personnel, as the items are accumulated to form a kit. The items are verified again by the opurator who assembles the kit by checking against the as-built-parts-list (ABPL). DCAS Mandatory (nspection founts are designated for all printed circuit, wire wrap and welded wire boards, plus harness connectors for saldering wiring, crimping, solder splices and quality workmanship prior to coating of the component side of boards and sleeving of harnesses. **3VC Boards** Specific TVC board assembly and test instructions are provided in drawing notes, and applicable documents are called out in the fabrication Procedure and Record (IPR-2294819) and parts list PC2294819. These include shuttle IVE assembly notes 2593660, Process Standard RIV-566 2280801, Process Standard - Bonding Vetera Tape 2280889. Specification Solderang 2280749. Specification Make Plate Application 1960167, Specification - Crimping 2280800, Specification - Bonding and Staking 2280878, Specification - Orethane coating 2280877, Specification - lucking compound 2026116. Specification Epoxy Adbesive 2010985. Specification - Marking 2280876. Specification - Workmanship 8030015, Specification Bonding and Staking 2280875.

TVE/BLA FMEA ND. 4.3.3.1 SHUTTLE CETY OWG NO. 2294819-506.508/ CRITICAL TIEMS LIST <u> 2307088-503</u> CRITICALITY <u>\_\_2/2</u> OF FAILURE MODE AND FALLUBE EFFECT CAUSE ON END THEM BATIONALE FOR ACCUPTANCE

fine hase errors (jitter) in the symphromization information on the viden autput line. Video information is present and contains the time base errors.

140 Al Sync Generator. Clock Divider Chain. Phase-locked toop. 2294800-504

A2 Camera limino Logic 2294881-501

All Muster Oscillator

TYC Heaters (1) Loss of camera output depicting scene information within FOV of lens assembly.

(2) Loss of camera until self-heating of cir-Cuitry restores normal operation.

**Horst Case:** loss of mission critical video.

(Deunitary) MOLTZERCH

IVC Assembly and lest - An open box test is performed per IP-II-2294819, and an Acceptance Test per 19-AT-2294819, including vibration and thermal vacoum. Torques are specified and witnessed, traceability numbers are recorded and calibrated tools. are checked prior to use. RCA Quality and OCAS inspections are performed at the completion of specified FPR operations in accordance with PAI 204, PAI 205, PAI 206 and PAI 217. DCAS personnel witness IVC button-up and critical torquing.

W.A. Assembly and lest - An open box test is performed per (P-1F-2307088. Acceptance Test per IP-A1-2307088. Turques are specified and witnessed, traceability numbers are recorded and calibrated Lools are checked prior to use. RCA Quality and DCAS inspections are performed at the completion of specified FPR operations in accordance with PAI 204. PAI 205. PAI 217 and PAI 402. OCAS personnel witness MLA button-up and critical torquing.

[VC/MLA Assembly and lest - After a IVC and a WIA have been tested individually. they are mated and a final acceptance test is performed per IP-AI-2294819, including vibration and thermal vacuum environments. RCA and DCAS personnel monitor these tests and review the acceptance test data/results. These personnel also inspect for conformance after all repair, rework and refest.

Preparation for Shippent - The TVC and MLA are separated prior to shipment after fabrication and testing is complete. Each is parkaged according to CCIV tetter 8011 and 2280746. Process standard for Puckaging and Handling quidelines. All related documentation aucluding assembly drawings, Parts List, ABPL, Test Data, etc., is gathered and held in a documentation folder assigned specifically to each assembly. This fulder is retained for reference. An EIOP is prepared for each assy in arcordance with the requirements of WS-2593176. RCA QC and DCAS personnel witness crating, packaging, packing and marking, and review the EIOP for completeness and attorace.

8EVISED 10-14-86

EHFA NO. 4.3.3.1 CRETICALERY 2/2			SHUTTLE CCTV CRITICAL ITEMS EIST	UNTT <u>TYC/W/A</u> ONG NO. <u>2294819-586,508/</u> 2307008-503  SHEET <u>8</u> OF <u>9</u>
FAILURE MIDE AND  CAUST  Inme base errors (jitter) in the synchronization information on the video output line. Video information is present and contains the time base errors.  [YS A] Sync Generator.  Clock Divider Chain.  Phase-tocked Loop.  2294880-504  AZ Comera Fining Logic.  2294881-50)  A[] Master Oscillator.  [YC]  Phase-tocked Loop.	faiture effect ON FND LIEN  (1) Loss of camera autput medicting scene infor- mation within fOY of lens assembly.  (2) Loss of camera until self-heating of cir- cuitry restores normal operation.  Norst Ease: Lass of mission critical wides.	FAILURE HISTORY	SATIONALI FOR ACCEPT	
		•		

FHEA NO. 4.3.3.1 CRITICALISY 2/2		SHUTTLE CCTV CRITICAL LIENS LIST	UNIT TYC/HLA  DHG NO. 2294819-506.508/ 2307088-503  SHEET9 Of9	
FAILURE MODE AND	FAILURE EFFECT ON FNB LIEN	RATIONALE FOR ACCEPTANCE		
CAUSE  The base errors (jitter) in the probability in the deconstant on information on the deconology line. Video information is present and contains the one base errors.  Sync Generator. Clock Divider Chain. Phase-tocked Loop. 2244880-504 Camera Liuing Logic 2294881-501 J. Master Oscillator  Causers	ON END LICH  (1) toss of camera output depicting scene infor- mation within FOV of lens assembly.  (2) toss of camera until self-heating of cir- cuitry rostores normal operation.  Horst (4se: Loss of mission critical video.	DPERATIONAL EFFECTS  Loss of video. Possible loss of major mission obj  CREM ACTIONS  If possible, continue RMS operations using alternative  CREM TRAINING  Crem should be trained to use possible alternative  MISSION CONSTRAINT  Where possible, procedures should be designed so to CCTV.	jectives if RMS elbow is required. ative visual cues. es to CCTV	