

CEI  
Critical Items List

Assembly Name/Part Number: Torque Multiplier/40159 24258 of  
Reference: CEI\_TROMLT  
Prepared by: C. Hartman Approved by: R. Mithrey  
Superseding Date: 9/98 Date: 1/89 Rev: A

NAME PRN BY	CRIT	FAILURE MODE & CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
Reaction Ring Assembly 40159 24258-40 Item 5.4 Doc	071	S. ADMIN Loss of restraint strap.  CAUSE: Defective webbing or thread. Broken stitches. Worn or abraded webbing. Damage to Reaction Ring.	END ITEM: Torque Multiplier operated from strap and is lost.  O/E INTERFACE: Unable to loosen lock bolts.  MISSION: Unable to Jettison Payload. Terminate EVA.  CREW/VEHICLE: Loss of crew and vehicle.	a. DESIGN: The Restraint Strap is fabricated from one-inch Nosee webbing MIL-I-5038 specifications which is capable of withstanding a proof load of 819 lbs. The strap is stitched with size "E" Nosee thread, militar, Twisted and Bonded MIL-I-41636 specification). All cut ends of webbing are coated with KFF-F-800 resin to prevent fraying or unraveling. The cut end of the webbing is passed through the Reaction Ring, folded in a loop configuration and stitched with a 13/16" x 13/16" "Box-1" stitch pattern through all thicknesses of loop. Three additional rows of stitching are added to each end of the "Box-1" to provide further strength. Stitching is terminated by back locking 3-2 stitches to prevent seam separation. All stitching is lock stitch type 701 per FED-518-751, 7 to 10 stitches per inch.  The Reaction Ring is fabricated from 15-3 PH stainless, heat treated to H1425 condition, and passivated per DD-P-35 specifications. The Torque Multiplier is stored in a foam cushion in the Payload Bay FSA to protect it from the possibility of damage from impact.  b. TEST: Component Acceptance Test - None

540210W  
ATTACHMENT -  
Page 143 of 1

Central Items List

Assembly Name/Part Number: Torque Multiplier/Int50 20250-01  
 References: ITC 1047  
 Prepared By: L. Carlson Approved By: E. Dalbey  
 Superseding Date: 9/88 Date: 1/89 Rev: A

NAME P/N REV	CRIT	FAILURE MODE & CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
Reaction Ring Assembly Int50- 20250-01 Item 5.4 Dwg	1/1	5.4E111- Loss of restraint strap.		<p>PBA Test - None</p> <p>Certification Test - The restraint strap is fabricated from the same Nylon webbing as the EVA Waist Tether which is certified to withstand a proof load of 819 lbs without failure.</p> <p>C. INSPECTION) Components and material manufactured to ITC requirements at an approved supplier are documented from procurement through shipping by the supplier. ITC incoming receiving inspection verifies that the materials received are as identified in the procurement documents, that no damage has occurred during shipment and that supplier certification has been received which provides traceability information.</p> <p>The following NIP's are performed during the Torque Multiplier Assembly manufacturing process to assure the failure causes are precluded from the fabricated items</p> <ol style="list-style-type: none"> <li>1. Inspection of all components for damage or material degradation.</li> <li>2. Inspection of seams and stitching.</li> </ol>

540210W  
ATTACHMENT -  
PAGE 144 of 153

CH  
Critical Item Test

Assembly Manual Number: Torque Multiplier/10152 20250 01  
 Reference: Lit. 180M1  
 Prepared by: J. Norton  
 Supervising Supt: 0700  
 Prepared by: G. Mather  
 Date: 1984 Rev. A

NAME	CRIT	FAILURE MODE & CAUSE	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
:Quackin :Qsq :Assembly :10152- :20152-01 :Item 3.4 :Qsq	0/1	5. 41M1 Loss of restraint strap.		During PDA, the following inspection points are performed at the Torque Multiplier Assembly level in accordance with ITC Document 10107 70490.  1. Verify conformance to drawing. 2. Inspection for damage or material degradation.  B. FAILURE HISTORY None  C. GROUND FORWARDING During ground forwarding, in accordance with ITC Document 10107-70490, the Torque Multiplier Assembly is inspected for damage, functionally tested for proper operation.  F. OPERATIONAL USE: 1. Crew Response Pre/Post IVA - N/A IVA - If load is not lost, restrain using wrist lather.  2. Training Crew Briefing.  3. Operational Considerations Catastrophic failure of load is lost. Possible loss of crew/vehicle.

Attachment No. 10107-70490  
 Release Date  
 Page 04-23 of 04-01

SHOZ10W  
 ATTACHMENT -  
 Page 145 of 153