

ASSY NOMENCLATURE: MANIPULATOR FOOT RETRACT  
ASSEMBLY PART NO.: SED 30103160

## CRITICAL ITEMS LIST

PREPARED BY: L. HAHN & F. PERAZZO

REPORT NO. MSA/RB  
REVISION A  
DATE: 17 MAY 1986

FMEA REF	NAME, QTY & DRAWING REF DESIGNATION	OPIT	FAILURE MODE AND CAUSE	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
A2 A	Adaptive Payload Carrier (APC) Interface Mechanism  QTY (1)  DWG C95-101	2/2	A2 - Latch fails to close due to defective material, contamination or galling.	<u>END ITEM</u> Unable to close latch  <u>GFE INTERFACE</u> Unable to connect MFR to APC  <u>MISSION</u> Loss of MFR; unable to accomplish subsequent mission objectives.  <u>CREW / VEHICLE</u> None	<u>A. Design</u> Materials per tables 1 & 2 of MSFC-SPEC-522A are certified for traceability/quality. Anodic hardcoating per MIL-A-8625C on aluminum interfaces with relative motion minimizes galling and wear. Contamination caused by corrosion by products eliminated by extensive use of thermal control coating and solid (Moly di-sulfide) lubricant coating.

Grumman Corporation

## CRITICAL ITEMS LIST

GRUMMAN

ASSY Nomenclature: MANIPULATOR FOOT RESTRAINT

PREPARED BY: L. HAHN &amp; F. PERAZZO

ASSEMBLY PART NO: 560 3940150

REPORT NO. PAJ 07 R 0

REVISION - B

DATE: 6 JULY 1995

FMEA REF	NAME, QTY & DRAWING REF DESIGNATION	CRT	FAILURE MODE AND CAUSE	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
A2 A	Adaptive Payload Carrier (APC) Interface Mechanism  QTY (1)  DWG C95-101	2/2	A2 - Latch fails to close due to defective material, contamination or galling.	<u>END ITEM</u> Unable to close latch  <u>GFE INTERFACE</u> Unable to connect MFR to APC  <u>MISSION</u> Loss of MFR; unable to accomplish subsequent mission objectives.  <u>CREW / VEHICLE</u> None	<b>B. TEST HISTORY</b> 1. Acceptance test per procedure 380-94-01 at Grumman [7/7/83] before and after all tests. ATP includes functional tests of all operating functions and a general visual inspection. 2. SiliKness test per procedure 380-10-01 at Grumman [7/7/83]. Demonstrated stanchion end play less than .5 inch lateral and 2 inches longitudinal for 1 hundred pound load. 3. Vibration and shock test per procedure 380-10-01 at Grumman [7/7/83]. Demonstrated ability to withstand design levels without structural failure with no significant resonance. Several screens required the application of latches. 4. APC/MFR ultimate load tests per STS 0944 at Rockwell [9/83]. Loads applied in 10 steps, each comprising 10% of final load. Yield was observed at the ultimate load of 14 x 1ml. 5. Thermal vacuum test at JSC [7/25/84]. MFR was operated at ambient temperature, plus 224 F and -117 F (average lowest achievable chamber temp) at an average vacuum of .00006 torr. 6. Center of gravity test at JSC [12/2/84]. 7. Manoeuvrability swing test at JSC [1/9/85]. <b>C. INSPECTION</b> 1. NAVFARO inspects all production end items at completion of final assembly. 2. Anodic hard coated aluminum parts inspected for compliance to MIL-A-8825 C by DCAS. Certificate of compliance available at Grumman Bellpage. 3. Thermal Control Coating process is controlled by inspections, (post prime, cure, post coating and cure), and sample testing for coating thickness, coating adhesion, and emittance/solar absorpti- <b>D. FAILURE HISTORY</b> None per PRACA database. The MFR has been successfully utilized on five missions, STS 10, 13, 51A, 51B, and 61C. <b>E. TURNAROUND</b> Inspection per 52891A, 05-001-NAC 10 DEC 1997 includes a functional test of all MFR operating functions and a general visual inspection <b>F. OPERATIONAL USE</b> 1. Operational effect of failure: MFR could not be restored. It possibly could not be used on a second EVA if it had to be reissued. 2. Crew action: Crew could strap MFR in place using a tie-down device if available or jettison the MFR. 3. Crew training: Crew would reacquaint on any generic tie-down equipment available. 4. Mission constraints: None 5. Inflight Checkout: Crew will visually verify latch closed at end of slow operation