

ASSY NOMENCLATURE: MANIPULATOR FOOT RESTRAINT
 ASSEMBLY PART NO.: SED 30100400

CRITICAL ITEMS LIST

PREPARED BY: L. HAHN & F. PERAZZO

REPORT NO: BUS-87-RH
 REVISION: A
 DATE: 17 MAY 1988

FMEA REF	NAME, CTRY & DRAWING REF DESIGNATION	CRIT	FAILURE MODE AND CAUSE	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
BI	Vertical Stanchion Stow Latch QTY (1) Dwg C95-122	I/I	BI - Relaxation or structural failure of trigger spring; structural failure of hook (P/N C95-122-13) or trigger (P/N C95-122-11) due to defective material.	<u>END ITEM</u> Vertical stanchion may move unrestrained to deployed position. <u>GEE INTERFACE</u> APC latch may fail due to overload <u>MISSION</u> MFR may sustain damage; MFR may be unable to accomplish mission objectives. <u>CREW / VEHICLE</u> Potential loss of crew/vehicle due to impact by MFR	<u>A. Design</u> The APC interface mechanism has been designed to withstand launch loads including: shock(20g, 11 milli-sec, sawtooth pulse, 3 axes), random vibration as high as .2g50hz, and lift-off and landing static loads 8.4g's 3.0 g's, and 6.4g's in the z, y, and x axes respectively. Dynamic magnification of 2 has been included and all static loads are assumed simultaneous (worst case) and are combined with the worst case 3.3 sigma random response load to each axes. An astronaut handling load of one hundred pounds in any direction at any point was also considered. Using the above load spectrum design safety margins of 1.14 for deformation and 1.40 for failure have been achieved. All springs are corrosion resistant and will be cycled a small fraction of nominal cyclic life in the 20 mission life of the MFR. Fatigue life based upon random response loads with appropriate stress concentration factors has been established using a scatter factor of 4.0 (e.g., 80 mission fatigue life based upon S-N curves). All materials are per table 1 and 2 of MSFC-SPEC-522A, to reduce stress corrosion, and are certified for traceability/quality.

Grumman Corporation

CRITICAL ITEMS LIST

GRUMMAN

ASSEMBLY NOMENCLATURE: MANIPULATOR FOOT RESTRAINT

PREPARED BY: L HAHN & F PERAZZO

ASSEMBLY PART NO.: 860 33400100

REPORT NO: RMB-ET-R-8

REVISION A

DATE: 8 JULY 1989

FMEA REF	NAME, QTY & DRAWING REF DESIGNATION	CRT	FAILURE MODE AND CAUSE	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
B1	Vertical Stanchion Slow Latch QTY (1) Dwg C95-122	1/1	B1 - Relaxation or structural failure of trigger spring; structural failure of hook (P/N C95-122-13) or trigger (P/N C95-122-11) due to defective material.	<p>END ITEM Vertical stanchion may move un restrained in deployed position.</p> <p>GFE INTERFACE APC latch may fail due to overload</p> <p>MISSION MFR may sustain damage; MFR may be unable to accomplish mission objectives.</p> <p>CREW / VEHICLE Potential loss of crew/vehicle due to impact by MFR</p>	<p>D. TEST HISTORY</p> <ol style="list-style-type: none"> Acceptance test per procedure 300 94 01 at Grumman (7/16/83) before and after all tests. ATF includes functional tests of all operating functions and a general visual inspection. Stiffness test per procedure 300-104 01 at Grumman (7/16/83). Demonstrated stanchion end play less than .5 inch for a five pound load in any direction and deflection less than 3 inches lateral and 2 inches longitudinal for thousand pound loads. Vibration and shock test per procedure 300-59.01 at Grumman (7/16/83). Demonstrated ability to withstand design levels without structural failure with no significant resonance. Several screens required the application of loads. APCMF II ultimate load tests per STSII-0914 at Rockwell (9/83). Loads applied in 14 steps, each comprising 10% of limit load no yield was observed at the ultimate load of 14 x 1000 lb. Thermal vacuum test at JSC (7/29/84). MFR was operated at ambient temperature, plus 224 F and -137 F (average lowest achievable chamber temp) at an average vacum of .00006 torr. Center of gravity test at JSC (10/2/84) Moment of inertia swing test at JSC (10/4/85) <p>E. INSPECTION</p> <ol style="list-style-type: none"> MAVPRO inspects all production end items at completion of final assembly Anodic hard coated aluminum parts inspected for compliance to MIL-A-1625C by DCAS. Certificate of compliance on file at Grumman Bellpage. Thermal Control Coating process is controlled by inspections, (part prime, cure, post coating and cure), and sample testing for coating thickness, coating adhesion, and enhanced/duo absorption. <p>F. FAILURE HISTORY</p> <p>None (per PRACA database). The MFR has been successfully utilized on live missions, STS 11, 13, 5A, 5B, and 6C.</p> <p>G. TURNAROUND</p> <p>Inspection per 5280PIA 05601 NUC 10 DEC 1987 includes a functional test of all MFR operating functions and a general visual inspection.</p> <p>H. OPERATIONAL USE</p> <ol style="list-style-type: none"> Operational Effect of Failure - Vertical stanchion would become unlocked and possibly break off, or overload the APC latches. Probable damage to the orbiter, MFR, and payload. Crew Action - None Crew Training - None Mission Constraint - None In flight Checkout - Crew will visually verify latch closed at end of slow operation