

CRITICAL ITEMS LIST

FAILURE MODE OR SIGNAL/DIS: HST-PFR-2
 NAME / QUANTITY: Yaw and Pitch Assy/1 each
 DRAWING REFERENCE: 417708

PROJECT: HST
 LRU NAME / QUANTITY: PFR/2
 LRU PART NUMBER: 2ED03107083-204

PAGE: 1 OF 3
 SUBSYSTEM: MA
 EFFECTIVITY: ALL ORBITERS

FAILURE MODE NUMBER HST-PFR-2-4	CRITICALITY 1R/2	FAILURE EFFECT	RETENTION RATIONALE			
FUNCTION Those joints allows the crew to configure the PFR platform in a desired position by rotating the user about the horizontal plain of the platform (or yaw plain of the user) and about the users pitch plain.		END ITEM PFR loses stability, cannot be used. MISSION No effect on mission objectives if failure occurs in payload bay. CREW / VEHICLE Possible damage to orbiter.	I. Design Features to Minimize the Chance of the Failure Mode A. Design All HST PFRs were designed to an ultimate structural safety factor of 1.4. B. Tolerances Sufficient tolerances were used in the HST PFR design to prevent jamming by expansion and contraction of material due to temperature extremes or on-orbit use. C. Materials - Major Components See material list (Table B-2). II. Testing and Analysis A. Acceptance Testing 1. PIA A full pre-installation acceptance (PIA) test will be performed on each HST PFR before it is delivered to KSC to support any STS flight. The PIA will verify that the HST PFRs are functioning within tolerances and that the assembly is clean. 2. Vibration The HST PFRs were exposed to qualification level vibration loads during user initial development in support of STS-31. The test verified that the HST PFRs were free of manufacturing defects and tolerance problems. (Reference LMSC Document number H177007-501).			
FAILURE MODE AND CAUSE MODE While attached to a STS-PFR socket in the orbiter payload bay, the yaw and/or pitch joint assembly inadvertently becomes unlocked and rotates when the crew member is in the HST PFR. CAUSE(S) 1) Fatigue spring failure. 2) Linkage comes loose.						
REDUNDANCY SCREENS A - Pass B - Pass C - Pass	REMAINING PARTS 1) Crew is tethered preventing the crew from floating off.					
MISSION PHASE EVA	CONNECTIVE ACTION TIMES <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 50%;">TIME TO EFFECT</th> <th style="width: 50%;">TIME TO CORRECT</th> </tr> </thead> <tbody> <tr> <td>Minutes</td> <td>Seconds</td> </tr> </tbody> </table>			TIME TO EFFECT	TIME TO CORRECT	Minutes
TIME TO EFFECT	TIME TO CORRECT					
Minutes	Seconds					
		INTERFACE None				

HST-PFR-7

CRITICAL ITEMS LIST

REFERENCE DESIGNATION: HST-PFR-2
 NAME / QUANTITY: Yaw and Pitch Assy/1 each
 DRAWING REFERENCE: 017702

PROJECT: HST
 LRU NAME / QUANTITY: PFR/2
 LRU PART NUMBER: SE00107008-301

PAGE 2 OF 5
 SUBSYSTEM: N/A
 EFFECTIVITY: ALL ORBITERS

FAILURE MODE NUMBER HST-PFR-2-4	CRITICALITY 1R/2	FAILURE EFFECT	RETENTION RATIONALE																								
FUNCTION		END ITEM PFR loses stability, cannot be used MISSION No effect on mission objectives if failure occurs in payload bay CREW / VEHICLE Possible damage to orbiter INTERFACE None	A. Acceptance Testing (continued) The following vibration levels are per : <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: center;">Frequency (Hz)</th> <th style="text-align: center;">Slope (dB/oct)</th> <th style="text-align: center;">Constant Level G²/Hz</th> <th style="text-align: center;">Overall Grms</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">20</td> <td></td> <td style="text-align: center;">.009</td> <td style="text-align: center;">7.7</td> </tr> <tr> <td style="text-align: center;">20-45</td> <td style="text-align: center;">+7.0</td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">45-600</td> <td></td> <td style="text-align: center;">.06</td> <td></td> </tr> <tr> <td style="text-align: center;">600-2000</td> <td style="text-align: center;">-6.0</td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">2000</td> <td></td> <td style="text-align: center;">.0054</td> <td></td> </tr> </tbody> </table> B. Certification Testing 1. Thermal Vacuum The HST PFR was exposed to a cold temperature (-132°F) vacuum (1x10 ⁻⁵ torrs) environment. This test was used to check the tolerances of the linkages and locking pin. The operational requirement was -90°F (Ref. JSC-23550) 2. Functionals The HST PFR was functionally operated prior to and immediately after all acceptance/certification tests to verify that the test environment did not degrade the hardware performance.	Frequency (Hz)	Slope (dB/oct)	Constant Level G ² /Hz	Overall Grms	20		.009	7.7	20-45	+7.0			45-600		.06		600-2000	-6.0			2000		.0054	
Frequency (Hz)	Slope (dB/oct)			Constant Level G ² /Hz	Overall Grms																						
20				.009	7.7																						
20-45	+7.0																										
45-600				.06																							
600-2000	-6.0																										
2000		.0054																									
FAILURE MODE AND CAUSE																											
MODE																											
While attached to a STS-PFR socket in the orbiter payload bay, the yaw and/or pitch joint assembly inadvertently becomes unlocked and rotates when the crew member is in the HST PFR.																											
CAUSE(S)																											
1) Fatigue spring failure. 2) Linkage comes loose.																											
REDUNDANCY SCREENS	REMAINING PATHS																										
A - Pass B - Pass C - Pass	1) Crew is tethered preventing the crew from floating off.																										
MISSION PHASE	CORRECTIVE ACTION TIMES																										
	TIME TO EFFECT TIME TO CORRECT																										
EVA	Minutes Seconds																										

HST-PFR-8

CRITICAL ITEMS LIST

REFERENCE DESIGNATOR: HST-PFR-2
 NAME / QUANTITY: Yaw and Pitch Assy/ each
 DRAWING REFERENCE: J77002

PROJECT: HST
 LRU NAME / QUANTITY: PFR/2
 LRU PART NUMBER: 2803107953-301

PAGE 3 OF 5
 SUBSYSTEM: N/A
 EFFECTIVITY: ALL ORBITERS

FAILURE MODE NUMBER HST-PFR-2-4	CRITICALITY 1R/2	FAILURE EFFECT	RETENTION RATIONALE
FUNCTION These joints allows the crew to configure the PFR platform in a desired position by rotating the user about the horizontal plain of the platform (or yaw plain of the user) and about the users pitch plain.		END ITEM PFR loses stability, cannot be used	C. Certification Analysis All HST PFR components were analyzed to the following induced environments to verify that the assembly can withstand the environment levels: 1. Requirements Source a. Shock - Functional NSTS-07700 VOL. XIV b. Vibration (Fr. Levels) - Acoustics NSTS-07700 VOL. XIV c. Structures - Ult (Is = 2.0) NSTS-07700 VOL. XIV - Fracture NSTS-07700 VOL. XIV d. Acceleration - Flight MF0004-014D - Crash MIL-STD-810, Meth. 516, Proceed. 1 e. Temperature - Hot (+260°F) NSTS-07700 VOL. XIV, Appendix 7 - Cold (-80°F) JSC-23550
FAILURE MODE AND CAUSE		MISSION No effect on mission objectives if failure occurs in payload bay	
MODE While attached to the HST, the pivot and/or roll joint assembly inadvertently becomes unlocked and rotates when the crew member is in the HST PFR.			
CAUSE(S) 1) Fatigue spring failure 2) Linkage comes loose		CREW / VEHICLE Possible damage to orbiter	
REQUIREMENT SCREENS A - Pass B - Pass C - Pass			
REMAINING PARTS 1) Crew is tethered preventing the crew from floating off		INTERFACE None	
MISSION PHASE			
CORRECTIVE ACTION TIMES			
		Time to Effect	Time to Correct
EVA	Minutes	Seconds	

HST-PFR-9

CRITICAL ITEMS LIST

REFERENCE DESIGNATION: HST-PFR-2
 NAME / QUANTITY: Yaw and Pitch Army/1 each
 DRAWING REFERENCE: 4177102

PROJECT: HST
 LRU NAME / QUANTITY: PFR/2
 LRU PART NUMBER: 92001107055-301

PAGE 4 OF 5
 SUBSYSTEM: N/A
 EFFECTIVITY: ALL ORBITERS

FAILURE MODE NUMBER HST-PFR-2-4	CRITICALITY 1R/2	FAILURE EFFECT	RETENTION RATIONALE	
FUNCTION These joints allows the crew to configure the PFR platform in a desired position by rotating the user about the horizontal plane of the platform (or yaw plane of the user) and about the users pitch plane.		END ITEM PFR loses stability, cannot be used	III. Inspection A. Manufacturing 1. The HST PFR components were inspected prior to build-up for conformance to their applicable drawings. 2. All fracture critical piece parts were and will be inspected as described on their applicable drawings. B. Assembly 1. HST PFR will be cleaned and inspected to the levels described in JSC 5322B. Once cleaned, the HST PFR will be bagged to prevent any contamination from entering the unit. C. Testing 1. The hardware was fully inspected for any signs of loose parts as a part of the pre/post functional tests performed prior to and immediately after all certification and acceptance tests (reference LMSC H177097-501).	
FAILURE MODE AND CAUSE MODE While attached to the HST, the pivot and/or roll joint assembly inadvertently becomes unlocked and rotates when the crew member is in the HST PFR. CAUSE(S) 1) Fatigue spring failure 2) Lintage comes loose		MISSION No effect on mission objectives if failure occurs in payload bay		
REUNDANCY SCREENS A - Pass B - Pass C - Pass		CREW / VEHICLE Possible damage to orbitler		
REMAINING PATHS 1) Crew is tethered preventing the crew from floating off		INTERFACE None		
MISSION PHASE		CORRECTIVE ACTION TIMES		
		TIME TO EFFECT		TIME TO CORRECT
EVA		Minutes		Seconds

HST-PFR-10

CRITICAL ITEMS LIST

REFERENCE DESIGNATION: HST-PFR-2
 NAME / QUANTITY: Yaw and Pitch Assembly each
 DRAWING REFERENCE: 4177108

PROJECT: HST
 LRU NAME / QUANTITY: PFR2
 LRU PART NUMBER: 30233007050-301

PAGE 5 OF 5
 SUBSYSTEM: N/A
 EFFECTIVITY: ALL ORBITERS

FAILURE MODE NUMBER HST-PFR-2-4	CRITICALITY 1R/2	FAILURE EFFECT	RETENTION RATIONALE
FUNCTION These joints allows the crew to configure the PFR platform in a desired position by rotating the user about the horizontal plain of the platform (or yaw plain of the user) and about the users pitch plain		END ITEM PFR loses stability, cannot be used MISSION No effect on mission objectives if failure occurs in payload bay CREW / VEHICLE Possible damage to orbiter	IV. Failure History A. None, HST PFR flew on STS-31, but was not used during the mission. V. Operations A. <u>Effects of Failure</u> Loss of stability, Possible damage to orbiter. B. <u>Crew Actions</u> None C. <u>Training</u> Crew must be tethered during operation in the HST PFR. D. <u>Mission Constraints</u> None E. <u>Inflight Check-Outs</u> None
FAILURE MODE AND CAUSE MODE While attached to the HST, the pivot and/or roll joint assembly inadvertently becomes unlocked and rotates when the crew member is in the HST PFR. CAUSES: 1) Fatigue spring failure 2) Linkage comes loose			
REUNDANCY SCREENS A - Pass B - Pass C - Pass	REMAINING FAILURE 1) Crew is tethered preventing the crew from floating off		
MISSION PHASE	CORRECTIVE ACTION TIMES TIME TO EFFECT TIME TO CORRECT		
EVA	Minutes	Seconds	INTERFACE None

HST-PFR - 11