

CRITICAL ITEMS LIST

PAGE 1 OF 6
SUBSYSTEM TOOL BOX
EFFECTIVITY ALL ORDERS

REFERENCE DESIGNATOR: TBA-1
NAME / QUANTITY: PFR SOCKET (1)
DRAWING REFERENCE: 10480-90479

PROJECT: HST
LRU NAME / QUANTITY: QUAD POD ASBY (1)
LRU PART NUMBER: 10411-20214-01

FAILURE MODE NUMBER HST-TBA-1-1	CRITICALITY 1R/2	FAILURE EFFECT	RETENTION RATIONALE			
FUNCTION The portable foot restraint (PFR) socket is used to restrain the PFR so that the crew will have a work platform at the tool box.		ENVIRONMENT Cannot remove the PFR from the PFR socket. The quad pod cannot support the PFR loads during landing.	DESIGN I. Design Feature to Minimize the Chance of the Failure Mode A. Design All tool box components were designed to a structural safety factor of 2.0. B. Tolerances Sufficient tolerances will be used in the socket design to prevent jamming by expansion and contraction of material due to temperature extremes or on-orbit use. C. Materials - Major Components 1. Pip Pin - MS17990C621 2. Socket - CRES 15-5 PHH11050 II. Testing and Analysis A. Acceptance Testing 1. PDA A full pre delivery acceptance (PDA) test will be performed on the tool box assembly before it is delivered to JSC for the beginning of the certification process. The PDA will verify that the pip pin and contingency handle are operating correctly and that the assembly is clean. 2. Vibration The flight tool box will be exposed to acceptance vibration loads while it is in flight configuration. The test will verify that the pip pin will withstand the vibration loads.			
FAILURE MODE AND CAUSE MODE Cannot remove the PFR from the PFR socket for landing.						
CAUSE(S) 1.) Pip pin is jammed in the socket, cannot remove PFR. 2.) Galling between socket and PFR. 3.) Contamination.						
REDAUNDANCY SCREENS A - Pass B - N/A C - Pass	REPAIRING PATHS 1.) Use contingency release handle at the pivot point.					
MISSION PHASE EVA	CORRECTIVE ACTION TIMES <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 50%;">TIME TO EFFECT</th> <th style="width: 50%;">TIME TO CORRECT</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">Hours</td> <td style="text-align: center;">Minutes</td> </tr> </tbody> </table>		TIME TO EFFECT	TIME TO CORRECT	Hours	Minutes
TIME TO EFFECT	TIME TO CORRECT					
Hours	Minutes					
		MISSION Mission objectives are complete.				
		CREW / VEHICLE Possible damage to the orbiter if the PFR becomes loose in the payload bay.				
		INTERFACE PFR is stuck in the socket and cannot be removed.				

PREPARED BY: J.F. PARK

REVISION: BASIC

SUPERSEDED DATE: NONE

DATE: 2/20/98

HST-TBA - 1

CRITICAL ITEMS LIST

PAGE 2 OF 6
SUBSYSTEM TOOL BOX
EFFECTIVITY ALL ORBITERS

REFERENCE DESIGNATOR: TBA-1
NAME / QUANTITY: PFR SOCKET (1)
DRAWING REFERENCE: 10100-20170

PROJECT: HST
LRU NAME / QUANTITY: QUAD POD ASBY (1)
LRU PART NUMBER: 10101-20214-01

FAILURE MODE NUMBER HST-TBA-1-1	CRITICALITY 1R/2	FAILURE EFFECT	RETENTION RATIONALE																											
FUNCTION The portable foot restraint (PFR) socket is used to restrain the PFR so that the crew will have a work platform at the tool box.		SND ITEM Cannot remove the PFR from the PFR socket. The quad pod cannot support the PFR loads during landing.	DESIGN A. <u>Acceptance Testing (continued)</u> The following vibration levels are per SMD memo ES42-92-134: <table border="1" style="margin: 10px auto; border-collapse: collapse;"> <thead> <tr> <th>Frequency (Hz)</th> <th>Slope (dB/oct)</th> <th>Constant Level G²/Hz</th> <th>Cycle/Grms</th> </tr> </thead> <tbody> <tr> <td>20-60</td> <td>+3.0</td> <td rowspan="3">.04</td> <td rowspan="3">6.1</td> </tr> <tr> <td>60-350</td> <td rowspan="2">-3.0</td> </tr> <tr> <td>350-2000</td> </tr> <tr> <td>20-45</td> <td>+10.0</td> <td rowspan="2">.08</td> <td rowspan="2">7.7</td> </tr> <tr> <td>45-600</td> <td rowspan="2">-6.0</td> </tr> <tr> <td>600-2500</td> <td></td> </tr> <tr> <td>20-70</td> <td>+4.0</td> <td rowspan="2">.05</td> <td rowspan="2">7.0</td> </tr> <tr> <td>70-600</td> <td rowspan="2">-6.0</td> </tr> <tr> <td>600-2000</td> <td></td> </tr> </tbody> </table> 3. <u>Pip Pin Program</u> All Pip Pins used in the HST hardware will be exposed to a separate dedicated acceptance test program to assure the project that the pip pins are at acceptable conditions which will help prevent a failure on-orbit.	Frequency (Hz)	Slope (dB/oct)	Constant Level G ² /Hz	Cycle/Grms	20-60	+3.0	.04	6.1	60-350	-3.0	350-2000	20-45	+10.0	.08	7.7	45-600	-6.0	600-2500		20-70	+4.0	.05	7.0	70-600	-6.0	600-2000	
Frequency (Hz)	Slope (dB/oct)			Constant Level G ² /Hz	Cycle/Grms																									
20-60	+3.0			.04	6.1																									
60-350	-3.0																													
350-2000																														
20-45	+10.0	.08	7.7																											
45-600	-6.0																													
600-2500																														
20-70	+4.0	.05	7.0																											
70-600	-6.0																													
600-2000																														
FAILURE MODE AND CAUSE MODE Cannot remove the PFR from the PFR socket for landing.		MISSION Mission objectives are complete.	CREW / VEHICLE Possible damage to the orbiter if the PFR becomes loose in the payload bay.																											
CAUSE(S) 1.) Pip pin (MS17960C621) is jammed in the socket, cannot remove PFR. 2.) Galling between socket and PFR. 3.) Contamination.				INTERFACE PFR is stuck in the socket and cannot be removed.																										
REDUNDANCY SCREENS A - Pass B - N/A C - Pass	REPAIRING PATHS 1.) Use contingency release handle at the pivot point.																													
MISSION PHASE	CORRECTIVE ACTION TIMES																													
	TIME TO EFFECT	TIME TO CORRECT																												
EVA	Hours	Minutes																												

PREPARED BY: J. F. PARK

REVISION: BASIC

SUPERSEDING DATE: NONE

DATE: 11/00/82

HST-TBA - 2

CRITICAL ITEMS LIST

REFERENCE DESIGNATOR: TBA-1
 NAME / QUANTITY: PFR SOCKET (1)
 DRAWING REFERENCE: 18104-30172

PROJECT: IMV
 LRU NAME / QUANTITY: QUAD POD ASSY (1)
 LRU PART NUMBER: 18101-30214-01

PAGE 3 OF 8
 SUBSYSTEM: TOOL BOX
 EFFECTIVITY: ALL ORDERS

FAILURE MODE NUMBER HST-TBA-1-1	CRITICALITY 1FU2	FAILURE EFFECT	RETENTION RATIONALE
FUNCTION The portable foot restraint (PFR) socket is used to restrain the PFR so that the crew will have a work platform at the tool box.		END ITEM Cannot remove the PFR from the PFR socket. The quad pod cannot support the PFR loads during landing.	DESIGN A. <u>Acceptance Testing (continued)</u> 3. Pip Pin Program (continued) c. <u>Vibration</u> All pip pins will be vibration tested to standard acceptance level vibration loads to screen for any workmanship defects. d. <u>Functional</u> All pip pins will be functionally operated and operation loads recorded prior to and immediately after all acceptance level testing to determine if there has been any adverse effects due to the test environment. B. <u>Certification Testing</u> 1. Thermal Vacuum The Tool Box will be exposed to the following thermal vacuum environment. Pip pin location, PFR interface with socket, and contingency handle operation will be a part of the test plan. a. <u>Temperature</u> - Cold Side Only (amb. to -80°F) b. <u>Pressure</u> - ATM to 1x10 ⁻⁵ torr
FAILURE MODE AND CAUSE MODE Cannot remove the PFR from the PFR socket for landing.		MISSION Mission objectives are complete.	
CAUSE(S) 1.) Pip pin (MS17990C821) is jammed in the socket, cannot remove PFR. 2.) Galling between socket and PFR. 3.) Contamination.		CREW / VEHICLE Possible damage to the orbiter if the PFR becomes loose in the payload bay.	
REDUNDANCY SCREENS A - Pass B - N/A C - Pass	REPAIRING ACTION 1.) Use contingency release handle at the pivot point.	INTERFACE PFR is stuck in the socket and cannot be removed.	
MISSION PHASE	CORRECTIVE ACTION TIMES		
	TIME TO EFFECT	TIME TO CORRECT	
EVA	Hours	Minutes	

PREPARED BY: J. F. PARK

REVISION: BAWC

SUPERSEDING DATE: NONE

DATE: 11/20/92

HST-TBA - 3

CRITICAL ITEMS LIST

PAGE 4 OF 6
SUBSYSTEM TOOL BOX
EFFECTIVITY, ALL DRAWINGS

REFERENCE DESIGNATOR: TBA-1
NAME / QUANTITY: PFR SOCKET (1)
DRAWING REFERENCE: M198-30173

PROJECT: IST
LRU NAME / QUANTITY: OMAD POD ASSY (1)
LRU PART NUMBER: 10461-38214-01

FAILURE MODE NUMBER HST-TBA-1-1	CRITICALITY 1R/2	FAILURE EFFECT	RETENTION RATIONALE																												
FUNCTION The portable foot restraint (PFR) socket is used to restrain the PFR so that the crew will have a work platform at the tool box.		END ITEM Cannot remove the PFR from the PFR socket. The quad pod cannot support the PFR loads during landing.	DESIGN B. <u>Certification Testing (continued)</u> 2. <u>Functionals</u> The tool box components like the PFR socket pin pin and contingency handle will be functionally operated prior to and immediately after all certification test to verify that the test environment does not degrade the hardware performance. C. <u>Certification Analysis</u> The PFR socket assembly will be analyzed to the following induced environments to verify that the assembly can withstand the environment levels: <table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">1. <u>Requirements</u></td> <td style="width: 50%;">Source</td> </tr> <tr> <td style="padding-left: 20px;">a. <u>Shock</u></td> <td></td> </tr> <tr> <td style="padding-left: 40px;">- Functional</td> <td>NSTS-07700 VOL. XIV</td> </tr> <tr> <td style="padding-left: 20px;">b. <u>Vibration (FL Levels)</u></td> <td></td> </tr> <tr> <td style="padding-left: 40px;">- Acoustics</td> <td>NSTS-07700 VOL. XIV</td> </tr> <tr> <td style="padding-left: 40px;">- Modal</td> <td>JSC-14046</td> </tr> <tr> <td style="padding-left: 20px;">c. <u>Structural</u></td> <td></td> </tr> <tr> <td style="padding-left: 40px;">- UR. (Is = 2.0)</td> <td>NSTS-07700 VOL. XIV</td> </tr> <tr> <td style="padding-left: 40px;">- Fracture</td> <td>NSTS-07700 VOL. XIV</td> </tr> <tr> <td style="padding-left: 20px;">d. <u>Acceleration</u></td> <td></td> </tr> <tr> <td style="padding-left: 40px;">- Flight</td> <td>WF0004-0140</td> </tr> <tr> <td style="padding-left: 40px;">- Crash</td> <td>MIL-STD-810D, Method 516, Procedure 1</td> </tr> <tr> <td style="padding-left: 20px;">e. <u>Temperature</u></td> <td></td> </tr> <tr> <td style="padding-left: 40px;">- Hot (+250°F)</td> <td>IST S/AD (10181-10081A)</td> </tr> </table>	1. <u>Requirements</u>	Source	a. <u>Shock</u>		- Functional	NSTS-07700 VOL. XIV	b. <u>Vibration (FL Levels)</u>		- Acoustics	NSTS-07700 VOL. XIV	- Modal	JSC-14046	c. <u>Structural</u>		- UR. (Is = 2.0)	NSTS-07700 VOL. XIV	- Fracture	NSTS-07700 VOL. XIV	d. <u>Acceleration</u>		- Flight	WF0004-0140	- Crash	MIL-STD-810D, Method 516, Procedure 1	e. <u>Temperature</u>		- Hot (+250°F)	IST S/AD (10181-10081A)
1. <u>Requirements</u>	Source																														
a. <u>Shock</u>																															
- Functional	NSTS-07700 VOL. XIV																														
b. <u>Vibration (FL Levels)</u>																															
- Acoustics	NSTS-07700 VOL. XIV																														
- Modal	JSC-14046																														
c. <u>Structural</u>																															
- UR. (Is = 2.0)	NSTS-07700 VOL. XIV																														
- Fracture	NSTS-07700 VOL. XIV																														
d. <u>Acceleration</u>																															
- Flight	WF0004-0140																														
- Crash	MIL-STD-810D, Method 516, Procedure 1																														
e. <u>Temperature</u>																															
- Hot (+250°F)	IST S/AD (10181-10081A)																														
FAILURE MODE AND CAUSE MODE Cannot remove the PFR from the PFR socket for landing.		MISSION Mission objectives are complete.																													
CAUSE(S) 1.) Pin pin (MS17990C821) is jammed in the socket, cannot remove PFR. 2.) Galling between socket and PFR. 3.) Contamination.																															
REBUNDANCY SCREENS A - Pass B - N/A C - Pass																															
REMAINING PATHS 1.) Use contingency release handle at the pivot point.		CREW / VEHICLE Possible damage to the orbiter if the PFR becomes loose in the payload bay.																													
MISSION PHASE																															
INTERFACE PFR is stuck in the socket and cannot be removed.																															
REBUNDANCY SCREENS		CONRECTIVE ACTION TIMES																													
MISSION PHASE																															
EVA		<table style="width: 100%; border-collapse: collapse;"> <tr> <th style="width: 50%;">TIME TO EFFECT</th> <th style="width: 50%;">TIME TO CORRECT</th> </tr> <tr> <td>Hours</td> <td>Minutes</td> </tr> </table>	TIME TO EFFECT	TIME TO CORRECT	Hours	Minutes																									
TIME TO EFFECT	TIME TO CORRECT																														
Hours	Minutes																														

PREPARED BY: J. F. PARK

REVISION: BASIC

SUPERSEDING DATE: NONE

DATE: 06/93

HST-TBA - 4

CRITICAL ITEMS LIST

PAGE 6 OF 6
SUBSYSTEM TOOL BOX
EFFECTIVITY ALL PRINTERS

REFERENCE DESIGNATOR: TBA-1
NAME/QUANTITY: PFR SOCKET (1)
DRAWING REFERENCE: 10190-20678

PROJECT: HST
(KIT NAME/QUANTITY) QUAD POD ASSY (1)
LOW PART NUMBER: 10191-20214-01

FAILURE MODE NUMBER HST-TBA-1-1	CRITICALITY 1R/2	FAILURE EFFECT	RETENTION RATIONALE		
FUNCTION The portable foot restraint (PFR) socket is used to restrain the PFR so that the crew will have a work platform at the tool box.		END ITEM Cannot remove the PFR from the PFR socket. The quad pod cannot support the PFR loads during landing.	DESIGN III. Inspection A. Manufacturing <ol style="list-style-type: none"> 1. The PFR socket assembly components will be inspected prior to build-up for conformance to their applicable drawings. 2. All fracture critical piece parts will be inspected as described on their applicable drawings. 3. The pip pin will be inspected upon delivery. D. Assembly <ol style="list-style-type: none"> 1. Exterior assemblies will be cleaned and inspected to the levels described in section 3.53.5 of the HST S/AD (10191-10081A). Once cleaned, the tool box will be completely bagged to prevent any contamination from entering the PFR socket assembly. C. Testing <ol style="list-style-type: none"> 1. The assembly will be fully inspected and functionally operated during PDAs and PIAs 2. The hardware will be fully inspected for any signs of galling as a part of the pre/post functional tests performed prior to and immediately after all major certification and acceptance testing. 		
FAILURE MODE AND CAUSE MODE Cannot remove the PFR from the PFR socket for landing.					
CAUSE(S) 1.) Pip pin (MS17990C621) is jammed in the socket, cannot remove PFR. 2.) Galling between socket and PFR. 3.) Contamination.					
REUNDANCY SCREENS A - Pass B - N/A C - Pass	REPAIRING PATHS 1.) Use contingency release handle at the pivot point.				
MISSION PHASE		MISSION Mission objectives are complete.			
CORRECTIVE ACTION TIMES					
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th style="width: 50%;">TIME TO EFFECT</th> <th style="width: 50%;">TIME TO CORRECT</th> </tr> <tr> <td style="text-align: center;">Hours</td> <td style="text-align: center;">Minutes</td> </tr> </table>				TIME TO EFFECT	TIME TO CORRECT
TIME TO EFFECT	TIME TO CORRECT				
Hours	Minutes				
EVA		CREW / VEHICLE Possible damage to the orbiter if the PFR becomes loose in the payload bay.			
		INTERFACE PFR is stuck in the socket and cannot be removed.			

PREPARED BY: J. F. PARK

REVISION: BASIC

SUPERSEDING DATE: NONE

DATE: 12/23/92

HST-TBA - 5

CRITICAL ITEMS LIST

PAGE 8 OF 6
SUBSYSTEM: TOOL BOX
EFFECTIVITY: ALL ORBITERS

REFERENCE DESIGNATOR: TBA-1
NAME / QUANTITY: PFR SOCKET (1)
DRAWING REFERENCE: W150-3878

PROJECT: HST
LRU NAME / QUANTITY: QUAD POD ASBY (1)
LRU PART NUMBER: W151-38814-01

FAILURE MODE NUMBER HST-TBA-1-1	CRITICALITY 1R/2	FAILURE EFFECT	RETENTION RATIONALE
FUNCTION The portable foot restraint (PFR) socket is used to restrain the PFR so that the crew will have a work platform at the tool box.		END ITEM Cannot remove the PFR from the PFR socket. The quad pod cannot support the PFR loads during landing.	DESIGN IV. Failure History A. There have been no failures associated with the HST tool box quad pod PFR socket. V. Operations A. <u>Effects of Failure</u> Cannot remove the PFR from the PFR socket. The quad pod cannot support the PFR loads during landing. B. <u>Crew Actions</u> To activate the redundant hardware, the crew will remove the contingency release handle by hand or with an EVA wrench. The handle actuation will release the central shaft at the pivot that will allow the PFR and socket to be removed from the quad pod. C. <u>Training</u> As part of the certification testing, crews will activate the redundant systems during the thermal vacuum tests. Additional training will occur in the WETF. D. <u>Mission Constraints</u> The PFR must be removed prior to landing. E. <u>Initial Check-Outs</u> None.
FAILURE MODE AND CAUSE MODE Cannot remove the PFR from the PFR socket for landing.			
CAUSE(S) 1.) Pip pin (MS17990C821) is jammed in the socket, cannot remove PFR. 2.) Galling between socket and PFR. 3.) Contamination.			
REDUNDANCY SCREENS A - Pass B - N/A C - Pass	REMEDIAL ACTION 1.) Use contingency release handle at the pivot point.		
MISSION PHASE		MISSION Mission objectives are complete.	
INTERFACE PFR is stuck in the socket and cannot be removed.			
CORRECTIVE ACTION TIMES			
	TIME TO EFFECT	TIME TO CORRECT	
EVA	Hours	Minutes	

PREPARED BY: J.F. PARK

REVISION: BAIRC

SUPERSEDING DATE: NONE

DATE: 11/06/92

HST-TBA - 6