

CRITICAL ITEMS LIST

PAGE 1 OF 2

REFERENCE DESIGNATOR: UARS
 NAME/QUANTITY: Quick Release Pin/1
 DRAWING REFERENCE: ST20P1583

PROJECT: UARS
 LRU NAME/QUANTITY: PFR Quick Pin Assembly
 LRU PART NUMBER: 10159-10037-02

SUBSYSTEM: EEV Payload Bay Attach.
 EFFECTIVITY: ALL ORBITERS

FAILURE MODE NO. UARS-FM-001	CRITICALITY 2/ER	FAILURE EFFECT	RETENTION RATIONALE
FUNCTION			
Held inserted PFA in position.		END ITEM None for this failure alone, if knob also fails the assembly will not be properly configured for loading and doors cannot be closed.	A. Design Sufficient interface tolerances are used to ensure proper operation and are based on manufacturer's specifications and required thermal tolerances.
FAILURE MODE AND CAUSE			
Jaws closed in deployed position. Cause: 1. Galling 2. Contamination		MISSION None	Shank and Spindle are made of 17-4PH or 15-7MO stainless and the socket that it interfaces with is made of stainless steel.
			B. Test/Analysis Assembly will be functionally cycled to ensure proper operation. Pins have been thermally tested at -120 degrees F and function has been verified per (TPS # 1b590054).
REDUNDANCY SCREENS	REMAINING PATHS		
A - Pass B - N/A C - Pass	First failure unable to remove clamp.	CREW/VEHICLE Possible damage to orbiter with second failure during landing. Unable to close Payload Bay doors if failure of both knob and pin occur which would result in loss of vehicle.	C. Inspection All piece parts are inspected for conformance to the applicable drawings before and after any special process.
MISSION PHASE	TIME TO EFFECT	TIME TO CORRECT	
EVA	Hours	Minutes	PPA (PreDelivery Acceptance) will be performed on all end items. Pins are verified functionally at PPA by inserting them into end item and checking that they lock and unlock.

PREPARED BY: R. Bruno

REVISION:

ISSUING DATE

DATE

REVISION HISTORY

ECP/PLS
2000-05-22

CRITICAL ITEMS LIST

PAGE 2 OF 2

REFERENCE DESIGNATOR: UARS
 NAME/QUANTITY: Quick Release Pin/1
 DRAWING REFERENCE: ST2HP15B3

PROJECT: UARS
 LAU NAME/QUANTITY: PDR Payload Bay Attitude
 LAU PART NUMBER: 10159-10037-02
 SUBSYSTEM: ALL ORBITERS
 EFFECTIVITY: ALL ORBITERS

FAILURE MODE NO. UARS-FM-001	Criticality 2/IR	FAILURE EFFECT	RETENTION RATIONALE
FUNCTION	Held inserted PDR in position.	END ITEM None for this failure alone, if knob also fails the assembly will not be properly configured for loading and doors cannot be closed.	C. Inspection (cont.) All piece parts are cleaned and processed in IIC Cleaning, Packaging, Handling, Shipping, and Storage Procedures for Space Shuttle Crew Equipment; Document #10107-70009.
FAILURE MODE AND CAUSE	Jaws closed in deployed position. Cause: 1. Galling 2. Contamination	MISSION None	D. Failure History A quick release pin failure has been observed during vibration testing for CITA. A swaged pin that held the T-handle in place came loose and the pin failed.
REDUNDANCY SCREENS			E. Ground Turnaround PDA-PIA will be performed on all end items.
A - Pass B - N/A C - Pass			F. Operational Use 1. Operational Effect of Failure None, for this failure alone. 2. Crew Action None 3. Crew Training None 4. Mission Constraints None 5. Inflight Detection None
MISSION PHASE	TIME TO EFFECT	TIME TO CORRECT	5040377 ATTACHMENT PAGE 42 OF 48
EVA	Hours	Minutes	

PREPARED BY: R. Brum REVISION: -

UARS - 2

DATE

DATE