

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL HARDWARE
 NUMBER: M5-6MB-2265-G-I

SUBSYSTEM NAME: ELECTRICAL POWER GENERATION - CRYO, GENERIC
 REVISION : 9 09/09/92

	PART NAME VENDOR NAME	PART NUMBER VENDOR NUMBER
LRU	: MID PCA 1	V070-764400
LRU	: MID PCA 2	V070-764430
SRU	: DIODE	JANTXV1N4246

- PART DATA -

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:
 DIODE, ISOLATION, 1 AMP - H2 MANIFOLD 1 AND 2 ISOLATION VALVES - OPEN
 POSITION

REFERENCE DESIGNATORS: 40V76A25A1CR23
 : 40V76A25A1CR25
 : 40V76A26A1CR23
 : 40V76A26A1CR25

QUANTITY OF LIKE ITEMS: 4
 FOUR, TWO PER H2 MANIFOLD VALVE CIRCUIT

FUNCTION:
 PROVIDES CIRCUIT ISOLATION FROM GROUND INITIATED COMMANDS AND CONDUCTS CREW
 INITIATED COMMANDS CONTROLLING OPENING OF THE H2 MANIFOLD 1 AND 2 ISOLATION
 VALVES.

PRINT DATE: 09/09/92

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL FAILURE MODE
 NUMBER: M5-6MB-2265-G-01

SUBSYSTEM: ELECTRICAL POWER GENERATION - CRYO, GENERIC
 LRD MID PCA 1
 ITEM NAME: DIODE

REVISION# 9 09/09/92
 CRITICALITY OF THIS
 FAILURE MODE: 2/2

FAILURE MODE:
 OPEN, FAILS TO CONDUCT

MISSION PHASE:
 OO ON-ORBIT

VEHICLE/PAYLOAD/KIT EFFECTIVITY:	102	COLUMBIA
	:	103 DISCOVERY
	:	104 ATLANTIS
	:	105 ENDEAVOUR

CAUSE:
 STRUCTURAL FAILURE (MECHANICAL STRESS, VIBRATION), ELECTRICAL STRESS, THERMAL STRESS, PROCESSING ANOMALY

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

REDUNDANCY SCREEN A) N/A
 B) N/A
 C) N/A

PASS/FAIL RATIONALE:

- A)
- B)
- C)

PRINT DATE: 09/09/92

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL FAILURE MODE
 NUMBER: M5-6MB-2265-G-01

 - FAILURE EFFECTS -

(A) SUBSYSTEM:

LOSS OF ABILITY TO CONDUCT THE H2 MANIFOLD VALVE "OPEN" SWITCH COMMAND.

(B) INTERFACING SUBSYSTEM(S):

LOSS OF ABILITY TO MANUALLY OPEN THE H2 MANIFOLD WITH THE PANEL SWITCH.

(C) MISSION:

POSSIBLE LOSS OF MISSION DUE TO ASSOCIATED MANIFOLD VALVE FAILING CLOSED RESULTING IN ONE TANK BEING ISOLATED TO A SINGLE FUEL CELL. MISSION TERMINATED WHEN THE HYDROGEN IN THAT TANK IS CONSUMED.

(D) CREW, VEHICLE, AND ELEMENT(S):

NO EFFECT - FIRST FAILURE

 - DISPOSITION RATIONALE -

(A) DESIGN:

REFER TO APPENDIX F, ITEM NO. 3 - DIODE

(B) TEST:

REFER TO APPENDIX F, ITEM NO. 3 - DIODE

DIODE IS FUNCTIONALLY VERIFIED IN FLIGHT. PERFORM GROUND TURNAROUND TEST WHEN VALID VERIFICATION IS UNOBTAINABLE IN FLIGHT OR AFTER LRU REPLACEMENT

(C) INSPECTION:

REFER TO APPENDIX F, ITEM NO. 3 - DIODE

(D) FAILURE HISTORY:

REFER TO APPENDIX F, ITEM NO. 3 - DIODE

(E) OPERATIONAL USE:

CREW WILL REMOVE ASSOCIATED TANK FROM PAIRED HEATER OPERATION

PRINT DATE: 09/09/92

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL FAILURE MODE
NUMBER: M5-6MB-2265-G-01

- APPROVALS -

PRODUCT ASSURANCE MGR	:	T. J. EAVENSON	:	<u>T. J. Eavenson 9/15/92</u>
PRODUCT ASSURANCE ENG	:	T. K. KIMURA	:	<u>T. K. Kimura 9/15/92</u>
DESIGN ENG TEAM LEADER	:	G. M. ANDERSON	:	<u>G. M. Anderson 9.15.92</u>
DESIGN ENGINEERING	:	T. D. NGUYEN	:	<u>T. D. Nguyen 9/15/92</u>
NASA RELIABILITY	:		:	<u>Mark 765 [unclear] 9/16/92</u>
NASA SUBSYSTEM MANAGER	:		:	<u>James L. [unclear] 12/16/92</u>
NASA EPD&C RELIABILITY	:		:	<u>James L. [unclear] 12/16/92</u>
NASA QUALITY ASSURANCE	:		:	<u>Mark 765 [unclear] 10/20/92</u>
NASA EPD&C SUBSYS MGR	:		:	<u>James L. [unclear] for FA 12/14/92</u>