## CRITICAL ITEMS LIST

PROJECT: SRMS ASS'Y NOMENCLATURE: FEEU SYSTEM: ELECTRICAL S. 63151111 ASS'Y PAR: 51140F1174-38-5

	THEA REF.	FHEA REV.	NAME OTT & DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURI : FFECT UN END ITEM	HOUR / FUNC. RATIONALE FOR ACCEPTANCE 2/1R CRITICALITY SCREENS: A-PASS, B-PASS, C-PASS
	3570	2	HOTOR DRIVE QIT-1 SCHEMATIC 2263764 AND 2563765	MODE: ONE OR MORE POWER SWITCHES FAIL SHORTED.  CAUSE (S): (1) PARTS FAILURE ORIVER. (2) PARTS FAILURE COMMUTATION/ SWITCHING LOGIC.	MOTOR MAY MOT DRIVE. THEREFORE SYSTEM WILL DE ENDPERATIVE IN ALL PRIME MODES. ARM WILL IMP DUNING CAPTURE SEQ. EE FUSES WILL BLOW AT SHOULDER. WORST CASE  UNEXPECTED PATIOND MOTION. INCOMPLETE CAPTURE/RELEASE SEQUENCE. UMABLE TO RELEASE ACTION REQ. REDUNDANT PATHS REMAINING BACKUP EE RELEASE.	DESIGN FEATURES  DISCRETE SEMICOMOUCIOR DEVICES SPECIFIED TO AT LEAST THE TX LEVEL OF MIL'S-19500. ALL DEVICES ARE SUBJECTED TO RE-SCREEMING BY AN INDEPENDANT IEST MOUSE. SAMPLES OF ALL PROCURED LOTS/DATE CODES ARE SUBJECTED TO DESTRUCTIVE PHYSICAL AMALYSIS (OPA) TO VERIFY THE INTEGRITY OF THE MANUFACTURING PROCESSES. DEVICE STRESS LEVELS ARE, DERATED IN ACCORDANCE WITH SPAR-RMS-PA.003 AND VERIFIED BY DESIGN REVIEW.  THE DESIGN UPILIZES PROVEN CIRCUIT TECHNIQUES AND IS IMPLEMENTED USING CMOS LOGIC DEVICES.  CMOS DEVICES OPERATE AT LOW POWER AND HENCE DO NOT EXPERIENCE SIGNIFICANT OPERATING STRESSES. THE TECHNOLOGY IS MATURE, AND DEVICE RELIABILITY HISTORY IS WELL DOCUMENTED. ALL STRESSES ARE ADDITIONALLY REDUCED BY DERATING THE APPORTIATE PARAMETERS IN ACCORDANCE MITH SPAR-RMS-PA.003. SPECIAL HANDLING PRECAUTIONS ARE USED AT ALL STAGES OF MANUFACTURE TO PRECLUDE DAMAGE/STRESS DUE TO ELECTROSTATIC DISCHARGE.  ALL RESISTORS AND CAPACITORS USED IN THE DESIGN ARE SELECTED FROM ESTABLISHED RELIABILITY (FX) TYPES. LIFE EXPECIANCY IS INCREASED BY ENSURING THAT ALL ALLOWABLE STRESS LEVELS ARE DERATED IN ACCORDANCE MITH SPAR-MS-PA.003. ALL CERMMIC AND ELECTROLYTIC CAPACITORS ARE ROUTINELY SUBJECTED TO RADIOGRAPHIC INSPECTION.  THE POWER SUITCHES ARE BASE MOUNTED FOR THERMAL DISSIPATION. THE POWER SUITCHES ARE BASE MOUNTED FOR THERMAL DISSIPATION. THE POWER SUITCHES ARE BASE MOUNTED FOR THERMAL DISSIPATION. THE POWER SUITCHES PER MISSION.
ı		t	<u> </u>	I	L	

PREPARED BY:

MFWG

SUPERCEDING DATE: D6 OCT B7

APPROVED BY:

DATE: 24 JUL 91

CIL REV: 2

CRITICAL ITEMS LIST

PROJECT: SAMS ASS'Y NOMENCLATURE: EEEU

SYSTEM! ELECTRICAL SUBSYSTEM
ASS'Y P/H: 51140F174-38-5 SHEET: 2

	FMEA REF.	FMEA REV.	HAME, GTY, & DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END LIEN	HDWA / FUNC. 2/18 CRETICALITY	RATIONALE FOR ACCEPTANCE SCREENS: A-PASS, B-PASS, C-PASS
	3570	2	MOTOR DRIVE GIY-1 SCHEMATIC 2263764 AND 2563765	MODE: DHE OR MORE POWER SWITCHES FAIL SHORTED.  CAUSE(9): CAUSE(5): CAUSE(1): CAUSE(1)	HOTOR MAY NOT DRIVE. THEREFORE SYSTEM WILL BE INOPERATIVE IN ALL PRIME MODES. ARM WILL LIMP DURING CAPTURE SEQ. EE FUSES WILL BLOW AT SHOULDER.  WORST CASE WHENPECTED PAYLOAD MOTION. INCONPLETE CAPTURE/RELEASE SEQUENCE. UMABLE TO RELEASE PAYLOAD. CREW ACTION REQ.  REDUNDANT PATHS REMAINING BACKUP EE RELEASE,	ENVIRONMENTAL  O VIGRATION:  O THERMAL:  THE EEEU 19 II EXPOSED TO TH (VIBRATION AN  THE END EFFEC TESTS (TPST8) WHICH VERTFIE  OUALIFICATION:  O VIBRATION:  O VIBRATION:  O THERMAL:  O HUMIDITY:  O EMC:  FLIGHT CHECKO PORS OPS CHEC	LEVEL AND DURATION REFERENCE TABLE 6  +70 DEGREES C 10 -25 DEGREES C (1 1/2 CYCLES)  NTEGRATED INTO THE EMD EFFECTOR AND IS FURTHER EE HOD EFFECTOR ACCEPTANCE TEST ENVIRONMENTS D THERMAL VACUUM).  FOR ASSEMBLY IS PART OF THE INTEGRATED RMS SYSTEM RMS STRONGBACK TEST AND TP552 FLAT FLOOR TEST)  S THE ABSENCE OF THE FAILURE MODE.  LEVEL AND DURATION - REFERENCE TABLE 6  20G/11MS - 3 AXES (6 DIRECTIONS)  +81 DEGREES C TO -36 DEGREES C (6 CYCLES)  T X 10+*-6 TORR  TESTED IN THE EMD EFFECTOR HUMIDITY TEST.  MIL-STO-461 AS MODIFIED BY SL-E-0002 (TESTS CEOT, CEOS, CSO1, CSO2, CSO6, REOT, REOZ (M/B) RSOT).  MIT  XXLIST (ALL VENICLES) JSC 16987
-	PREPARED B	T: E	IFWG	SUPERCEDING DAT	e: No ori'at'	APPROVED BY:	DATE: 24 JUL 91 CIL REV: 2

## CRITICAL ITEMS LIST

PROJECT: SRHS

ASS'Y NOMENCLATURE: FEEU

SYSTEM: ELECTRICAL SUBSYSTEM
ASS'Y P/N: \$1140F1174-38-5 SHEET: 3

FMEA REF.	FMEA REV.	NAME QTY & DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	HDUR / FUNC. RATIONALE FOR ACCEPTANCE 2/1R CRITICALITY SCREENS: A-PASS, B-PASS, C-PASS
3570	2	MOTOR DRIVE QTY-1 SCHEMATIC 2263764 AND 2563765	MODE: ONE OR MORE POMES SYITCHES FAIL SHORTED.  CAUSE(S): CAUSE(S): (1) PARTS FAILURE ORIVER. (2) PARTS FAILURE COMMUTATION/ SWITCHING LOGIC.	MOTOR MAY NOT DRIVE. THEREFORE SYSTEN WILL BE INOPERATIVE IN ALL PRIME MODES. ARM WILL LIMP DURING CAPTURE SEQ. EE FUSES WILL BLOW AT SHOULDER. WORST CASE UNEMPECTED PAYLOAD MOTION. INCOMPLETE CAPTURE/RELEASE SEGUENCE. UNABLE TO RELEASE PAYLOAD. CREW ACTION REO. REDUNDANT PATHS REMAINING BACKUP EE RELEASE.	UNITS ARE MANUFACIURED UNDER DOCUMENTED QUALITY CONTROLS. THESE CONTROLS ARE EMERCISED THROUGHOUT DESIGN PROCURENENT, PLANNING, RECEIVING, PROCESSING, FABRICATION, ASSEMBLY, RÉSING AND SIPPING OF THE UNITS. MANDATORY INSPECTION POINTS ARE EMPLOTED AT VARIOUS STAGES OF FABRICATION ASSEMBLY AND TEST, GOVERNHENT SQURCE IMSPECTION IS INVOKED AT VARIOUS CONTROL LEVELS.  EEE PARTS IMSPECTION IS PERFORMED AS REQUIRED BY SPAR-RMS-PA.003. EACH EEE PART IS QUALIFIED AT THE PART LEVEL TO THE REQUIREMENTS OF THE APPLICABLE SPECIFICATION. ALL EEE PARTS ARE 100X SCREEMED AND BURNED IN, AS A MINHUM, AS REQUIRED BY SPAR-RMS-PA.003, DT THE SUPPLIER. ADDITIONALLY, EEE PARTS ARE 100X RE-SCREEMED IN ACCORDANCE WITH REQUIREMENTS, BY AN INDEPENDENT SPAR APPROVED TESTING FACILITY. DPA 13 PERFORMED AS REQUIRED BY A.003 ON A RANDOMLY SELECTED 5X OF PARTS, MAKINENS PIECES, MINHUMM 3 PIECES FOR EACH LOT NUMBER/DATE CODE OF PARTS RECEIVED.  WIRE IS PROCUMED TO SPECIFICATION MIL-U-22759 OR HIL-W-B1381 AND INSPECTED AND TESTED TO NASA JSCHOOOD STANDARD HUMBER 95A.  RECEIVING INSPECTION VERIFIES THAT ALL PARTS RECEIVED ARE AS 10ENTIFIED IN THE PROCUMENENT PROVIDENTS, THAT MO PHYSICAL DANAGE HAS OCCURRED TO PARTS DURING SHIPEMENT, THAT THE RECEIVING DOCUMENTS PROVIDE ADEQUATE TRACEABLITY INFORMATION AND SCREENING DATA CLEARLY IDENTIFIES ACCEPTABLE PARTS.  PARTS ARE INSPECTED THROUGHOUT MANUFACTURE AND ASSEMBLY AS APPROPRIATE TO THE MANUFACTURING STAGE COMPLETED. THESE THSPECTIONS INCLUDE,  PRINTED CIRCUIT BOARD IMSPECTION FOR CORRECT SOLDERING, MIRE LOOPING, STRAPPING, ETC. OPERATORS AND INSPECTORS ARE TRAINED AND ADEQUACY OF PLATED THROUGH HOLES,  COMPONENT MOUNTING INSPECTION FOR ADEQUATE PROCESSING IS PERFORMED USING ULTRAVIOLET LIGHT TECHNIQUES.  POST P.C. 8D. INSTALLATION INSPECTION, CHECK FOR CORRECT BOARD INSTALLATION, ALIGNMENT OF BOARDS, PROPER CONNECTOR CONTACT MATING, MIRE ROULTING, STRAPPING OF MIRES ETC.,  PRE-ACCEPTANCE TEST INSPECTION, WHICH INCLUDES AN AUDIT OF LOWER TIER INSPECTION COMPLETION, AS BUILT CONFIGURATION VERIFICAT

PREPARED BY:

MFMG

SUPERCEDING DATE: 06 OCT 87

APPROVED BY:

DATE: 24 JUL 91

CIL REV: 2

CRITICAL ITEMS LIST

PROJECT: SRMS ASS'Y NOMENCLATURE: EEEU

SYSTEM: ELECTRICAL SUBSYSTEM ASS'Y P/R: 51140F1174-38-5

MOTOR DRIVE OF CR MORE STREAM	B-PASS, C-PASS	C. RATIONALE FOR ACC  Y SCREENS: A-PASS, B-	FAILURE EFFECT ON END 11EM	FAILURE MODE AND CAUSE	NAME, DIY, & DRAWING REF. DESIGNATION	FMEA REV.	FMEA REF.
	H INCLUDES VERIFICATION OF ST EQUIPMENT CALIBRATION/ FIGURATION IS CONVENED BY ITH ENGINEERING, SUPPLIER AS APPLICABLE, PRIOR TO THE START OF ANY IFICATION).  AMBIENT PERFORMANCE, AR/GOVERNMENT REP  RE ASSY - INSPECTIONS INCLUDE ENT OF PUSHBACK CONTACTS, WIRING ETC. AND POWER-UP DURE 11P-251D.  IICH INCLUDES AN AUDIT OF AS BUILT CONFIGURATION POINT).  AMBIENT, VIBRATION INADATORY INSPECTION POINT).  FERNATION OF MECHANICAL ARM I EQUIPMENT TO FORM THE SRMS. PHASE OF INTEGRATION WHICH IRING CHECKS, WIRING ROUTING, PUSH BACK CONTACTS ETC.	T READINESS REVIEW (TRR) WHICH PERSONNEL, TEST DOCUMENTS, TEST NATION STATUS AND HARDWARE COMFITT ASSURANCE IN COMJUNCTION WIT IS BILLIT, CONFIGURATION CONTROL, HE GOVERNMENT REPRESENTATIVE, PRULE TESTING (ACCEPTANCE OR QUALIFOTANCE TESTING (ACCEPTANCE OR QUALIFOTANCE TESTING (ATP) INCLUDES AMIAL AND VIBRATION TESTING, (SPARATION OF UNIT TO END EFFECTOR DING CHECKS, CONNECTERS FOR BENAL, CLEANLINESS, INTERCONNECT WITO SPAR INSPECTION TEST PROCEDURACE TESTING (ATP) INCLUDES, AND THE TESTING, CSPAR/GOVERNMENT OF PARCE CONNECTORS FOR BENAL VAC TESTING, (SPAR/GOVERNMENT OF TROUBLESS AND THE FLIGHT CABIN IS CETTONS ARE PERFORMED AT EACH PURCHES GROUNDING CHECKS, THRU WIRK REACE CONNECTORS FOR BENT OR PURSUES SYSTEMS TESTING - STRONGBACK AND ORMANCE TEST. (SPAR/GOVERNMENT)	MOTOR MAY NOT ORIVE. THEREFORE SYSTEM WILL BE INDPERATIVE IN ALL PRIME MODES. ARM WILL LEMP DURING CAPTURE SEO. EE FUSES WILL BLOW AT SHOULDER. WORST CASE UNEMPECTED PATLOAD MOTION. INCOMPLETE CAPTURE/RELEASE SEQUENCE. UHABLE TO RELEASE SEQUENCE. UHABLE TO RELEASE SEQUENCE. REDUNDANT PATHS REMAINING BACKUP EE	MODE: ONE OR MORE POWER SUITCHES FAIL SHORTED. CAUSE(S): (1) PARTS FAILURE DRIVER. (2) PARTS FAILURE COMMUTATION/ SWITCHING	MOTOR DRIVE GIT-1 SCHEMATIC 2263764 AND	2	3370
						1	

CRITICAL ITEMS LIST

PROJECT: SRHS
ASS'Y NOMENCLATURE: ELEU

SYSTEM: ELECTRICAL SUBSYSTEM
ASS'Y P/R: 51120F1174-3E-5 SHEET: 5

FMEA MEF.	FMEA REV.	NAME GTY & DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	HDWR / FUNC. 2/1R CRITICALITY	RATIONALE FOR ACCEPTANCE SCREENS: A-PASS, B-PASS, C-PASS	
3570	2	MOTOR DRIVE DTY-1 SCHEMATIC 2263764 AND 2563765	MODE: ONE OR MORE POWER SWITCHES FAIL SHORTED.  CAUSE(S): CAUSE (S): CAUSE (S	MOTOR MAY NOT DRIVE. THEREFORE SYSTEM WILL BE INOPERATIVE IN ALL PRIME MODES. ARM WILL LIMP DURING CAPTURE SEG. SEGUES WILL BLOW AT SHOULDER. WORST CASE UMEXPECTED PAYLOAD MOTION. INCOMPLETE CAPTURE/RELEASE SEGUENCE. UMABLE TO RELEASE PAYLOAD. CREW ACTION REQ. REDUMDANT PATHS REMAINING BACKUP EE RELEASE.	MODE ON THE	BEEN NO FAILURES ASSOCIATED WITH THIS FAILURE SRMS PROGRAM.	
PALPARED 0	IT: !	1FWG	SUPERCEDING DATE	E: NO OC! 01	APPROVED BY:	DATE: 24 JUL 91	CIL REV: 2

$\sim$
~
$\alpha$
Ξ.
_
11
_
Г
п
•••
С
٠.
- 1
•
=
ñ
Z
_

FMEA FM REF. RE		FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	HDWR / FUNC. RATTOMALE FOR ACCEPTANCE 2/1R CRITICALITY SCREENS: A-PASS, B-PASS, C-PASS
3570 2	MOTOR DRIVE GTV-1 SCHEMATIC 2263764 AMD 2563765	MODE: ONE OR MORE POWER SWITCHES FAIL SHORTED.  CAUSE(S): (A) PARTS FAILURE DRIVER. (2) PARTS FAILURE COMMUTATION/ SWITCHING LOGIC.	MOTOR MAY HOT DRIVE. THEREFORE SYSTEM WILL BE INOPERATIVE IN ALL PRIME MODES. ARM WILL LIMP DURING CAPTURE SEQ. EE FUSES WILL BLOW AT SHOULDER.  WORST CASE UNEXPECTED PAYLOAD MOTION. INCOMPLETE CAPTURE/RELEASE SEQUENCE. UNABLE TO RELEASE PAYLOAD. CREW ACTION REQ.  REDUNDANT PATHS REMAINING  DACKUP EE RELEASE.	CPERATIONAL EFFECTS  EE DOSS MOT DEBATE HOMINALLY WHEN COMMANDED. ARM REMAINS LEMP UNTIL EE MODE SWITCH 1S TURNED OFF DURING AM AUTO CAPTURE SECURACE.  CREW ACTION  FOR ANY OFF HOMINAL OPERATION OF THE EE, THE EE MODE SWITCH SHOULD BE TURNED OFF. ATTEMPT TO CAPTURE IN THE ALTERNATE MODE. 1F THE SHARES REMAIN OPEN, MANEUVER ARM AUAY FROM PATIOND. IF SHARES ARE PARTIALLY CLOSED, ATTEMPT RELEASE USING A PRIMARY EE MODE. 1F SHARES OPEN, MANEUVER ARM AUAY FROM THE PATUAD. IF SHARES OPEN, MANEUVER ARM AUAY FROM THE PATUAD. HOMELYER ON THE PATUAD. HOMELY COMPILER AWAY FROM PATUAD. HE SHARES CANNOT BE OPEND. IN ANY MODE, EVA CAM BE USED TO RELEASE THE PAYLOAD OR THE ARM/PAYLOAD COMBINATION CAN BE JETTISOMED.  CREW TRAINING  CREW THAINING  CREW THAINING AN OPERATIONS.  MISSION CONSTRAINT  WHEN CAPTURING A FREE FLYING PAYLOAD, THE EE MUST BE FAR ENOUGH AWAY FROM STRCUTURE TO PROMIBITE CONTACT REGARDLESS OF PAYLOAD ROTATIONS.  HISSION CONSTRAINT  WERE CAPTURING A FREE FLYING PAYLOAD, THE EE MUST BE FAR ENOUGH AWAY FROM STRCUTURE TO PROMIBITE CONTACT REGARDLESS OF PAYLOAD ROTATIONS.  HIS EMODE SWITCH SHOULD BE PLACED BACK IN THE OFF POSITION IMMEDIATELY AFTER THE SPEC DRIVE TIME HAS ELAPSED.  OMRSD OFFLINE  VERTEY NOMINAL OPERATION OF END EFFECTOR.  VERTEY CORRECT TIME FOR CLOSE FLAG AND RIGID FLAG TO CHANGE STATE.  OMRSD ONLINE TURNAROUND  VERTEY HOMINAL OPERATION OF END EFFECTOR.  VERTEY CORRECT TIME FOR CLOSE FLAG AND RIGID FLAG TO CHANGE TO GREY.  VERTEY CORRECT TIME FOR CLOSE FLAG AND RIGID FLAG TO CHANGE TO GREY.