REVISEO 5-7-87

FMEA RO. N 5.10 CRITICALITY 2/2		SHUTTLE ECTV CHITECAL TIENS LIST	DNIT Cable DNG NO. 2293288-502, 503 LSSUED 10-14-86 SHEET 1 OF 5	
FATLURE HODE AND FATLURE EFFECT ON END ITEM		RATIONALE FOR ACCEPTANCE		
.ass af HTR ATM (TVC)	No videa	DESIGN FEATURES		
lpen No video Worst Case: Loss of mission critical video.		The MS Bulkhead cable is a 60-inch long assembly, 17-wire assembly originating at the cargo bay and bulkhead. The cable provides power and commands to cargo bay camera stack and returns yiden to the bulkhead position. The video and sync wires are shielded #24 Twinax twisted-pair wires. The cable design is taken from the successfully flown Apollo program. The design is a cable-connector assembly in which the wire terminations are protected from excessive flexture at the joint between the wire and the connector terminal. The load concentration is moved away from the conductor connection and distributed axially along the length of the conductors encapsulated is a potted-taper profile. This technique also protects the assembly from dirt and entrapped moisture which could cause problems in space. The cable and its components meet the applicable requirements of NASA, Military and RCA specifications. These requirements include: • General/Hechanical/Electrical Features • Design and Construction • Materials • Terminal Solderability • Environmental		
		 Qualification Marking and Serialization Traceability and Documentation 		

4 140

1-78 x 6411

FMEA NO. W 5.10 CRITICALITY 2/2		SHUTTLE CCTV CRITICAL ITEMS LIST	UNIT Cable DN6 NO. 2293288-502, 503 ISSUED T0-14-86 SHEET 2 OF 5		
FAILURE MODE AND FAILURE EFFECT CAUSE ON END ITEM		RATIONALE FOR ACCEPTANCE	RATIONALE FOR ACCEPTANCE		
iss of HTR RTN (TVC)	No video	DUALIFICATION TEST	•		
→ EΠ	Norst Case: Loss of missiun critical video.	Qualified by 1.) similarity to previous successful space qualification tests of CCTV LRUs. ACCEPTANCE TEST The cable acceptance test consists of an obmmeter check connection is present and intact. Results are recorded INPERALIDIAL TEST The following tests verify that CCTV components are operated to the Camera/PTU command decoder are proper. The test ability to produce video, the VSU's ability to route vidisplay video. A similar test verifies the MOM command Pre-taunch on Orbiter Test/In-Flight Test 1. Power CCTV System. 2. Select a monitor via the PHS panel, as destination source. 3. Send "Camera Power On" command from PHS panel. 4. Select "External Sync" on monitor. 5. Observe video displayed on monitor. If video on a stable raster), then this indicates that the camer from the RCU and that the camera is producing sync. 6. Send Pan, Tilt, Focus, Zoom, ALC, and Gamma command anonitor or direct observation) verify proper oper. 7. Select Downlink as destination and camera under to Ouserve video routed to downlink. 9. Send "Camera Power Dff" command via PHS panel. 10. Repeat Steps 3 through 9 except issue commands viproves that the CCTV equipment is operational if	to assure that each wire i on data sheets. erable and that the commands from the sync lines to the Camera/PTU, its also verify the camera's ideo and the munitor's ability to i path. mention is synchronized (i.e., ra is receiving composite sync chronized video. ds and visually (either via the ation. est as source.		

REVISED 5-7-87

FMEA NO. M 5,10 CHITICALITY 2/2		SHUTTLE CCTV CRITICAL TIEMS LIST	ONIT Cable DH6 NO. 229378B-502, 503 1SSUEO 10-14-B6 SHEET 3 OF 5
FATEURE MODE AND CAUSE	FATLURE EFFECT ON END 13EM	RATIONALE FUR ACT	CEPTANCE
oss of HTA RTN (TVC)	No video Worst Case:	QA/INSPECTION Procurement Control - Mire, connectors, solder,	etc. are procured from approved vendors
	loss of mission critical video.	and suppliers which meet the requirements set for Plan Work Statement (WS-2593)76). Incoming Inspection & Storage - Incoming Quality materials and parts. Hesuits are recorded by it control numbers for future reference and traceal Material Controlled Stores and retained under spaceful fabrication is required. Non-conforming material (MUB) disposition. (PAI-307, PAI 19C-53).	y inspections are made on all received it and retained in file by drawing and pility. Accepted items are delivered to secified conditions until cable
		Assembly & Test - Prior to the start of assembly by stock room personnel as the items are accumuly verified again by the operator who assembles the as-built-parts-list (ABPL).	lated to form a kit. The items are
		Specific instructions are given in assembly draw called out in the Fabrication Procedure and Reconcess Standard crimping flight connector contaplicing of standard interconnecting wire using Process Standard marking of parts or assemblies material and test procedure (TP-AT-2293288). Quant the completion of key operations.	ord (FPR-2293288). These are 2280900 - acts, 2280801 - Process Standard in-line Baychem solder sleeves, 2280876 - with epoxy colors, 2280876. Potting
		Preparation for Shipment - When fabrication and packaged according to 2200746, Process Standard A)) related documentation including assembly dris gathered and held in a documentation folder assembly. This folder is retained for reference	for Packaging and Handling Guidelines. awings, Parts List, ABPL, Test Data, etc. assigned specifically to each cable

FNEA NO. W 5.30		SHUTTLE COTY CRITICAL ITEMS LIST	UNIT CAD TO DMG NO. 22932H8-502, 503 ISSUED TO-14-86 SHEET 4 OF 5		
FATLURE NOVE AND CAUSE	ON END TYEM	RATIONALE FOR ACC	RATIONALE FOR ACCEPTANCE		
ass of HTR RTW (TVC)	No video	FAILURE HISTORY			
lpen	Worst Case: Loss of mission critical video.	There have been no reported failures during RCA	testing, pre-flight or flight.		
. ·			•		
ı					
		· · · · · · · · · · · · · · · · · · ·			
•					

REVISED 5-7-87

FREA NO. N 5.10 CRITICALITY 2/2		SHUTTLE COTV CRITTCAL ITEMS LIST	ONIT Cable OWG NO. 2293288-502, 503 ISSUED T0-14-86 SHEET 5 OF 5	
FATUURE MODE AND FATUURE EFFECT ON END ITEM		AATIONALE FOR ACCEPTANCE		
Loss of HTM RTM (TVC)	Na video	OPERATIONAL EFFECTS	•	
Open .	Horst Case: Loss of mission critical video.	Loss of video. Possible loss of major mission of other required cameras.	bjectives due to loss of RMS cameras or	
	CITICAL VINCES	<u>CREW ACTIONS</u> If possible, continue RMS operations using after	mate udeupl ever	
		CREW TRAINING	Tate Visual Lues.	
		Crew should be trained to use possible alternate	es to CCTV.	
	·	MISSION CONSTRAINT		
		Where possible procedures should be designed so	they can be accomplished without CCTV.	
·				
		·		
			. •	
		·		
	ેલ કેલ નહે	2	•	
	*	·		