PAGE:

PRINT DATE: 11/07/88

SHUTTLE CRITICAL ITEMS LIST - OPRITER

MUMBER: 06-131-0204-X

SUBSTITUTE BANG: ARS COOLING

EXVISION : 11/07/88

CLASSIFICATION

XXXX

PART NUMBER

LPO 6RU

CABIN PAN & DERRIS TRAP VALWE, CHECK, FAN OUTLET

MC621-0008-0311

5V755546

QUARTITY OF LIKE ITEMS: 2 ONE IN EACH OF TWO FAN FLOW PATHS

DESCRIPTION/FUNCTION: TWO VALVES, ONE BACE IN THE FLOW PATH OF EACH CABIN AIR CIRCULATION FAN TO PERMIT FLOW THROUGH AN OPERATING FAN AND PREVENT BACK-FLOW THROUGH NON-OPERATING FAN.

550230 A ATTACEMENT -Page 11 of 241

١R

= 12 XI\* (

### SHUTTLE CRITICAL ITEMS LIST - ORBITER

SUBSYSTEM : ATMOSPHERIC REVIT. FREA NO 06-18 -0104 -1 REV:08/11/65

ASSEMBLY : FAN & DEBRIS TRAP CRIT. FUNC: :MC621-0008-0311 P/W RI

CRIT. HDW: P/N VENDOR: SV755546 HAM STL VEHICLE 102 104 103

QUANTITY : 2 EFFECTIVITY: x

ONE IN EACH OF THE FAN PHASE(S): PL LO X OO X DO X LS

:FLOW PATHS

PREPARED BY:

APPROVED BY KINDES DES N. X. DUONG

N. L. STEISSLINGER AREL

MAGE D. STOICA QÍ

REDUNDANCY SCREEN: A-PASS B-H/A C-FASE SSH THE THE REL 10 mg 10

QE (

ITEM:

. CHECK VALVE - FAN OUTLET

FUNCTION:

TWO VALVES, ONE EACH IN THE FLOW PATH OF EACH CABIN AIR CIRCULATION FAN to permit flow through an operating fam and prevent back-flow through NON-OPERATING FAN.

PAILURE MODE:

CLOSED

CAUSE(S):

PHYSICAL BINDING/JAMMING, CONTAMINATION

EFFECT(S) ON:

- (A) SUBSYSTEM (B) INTERFACES (C) HISSION (D) CREW/VEHICLE
- (A) LOSS OF REDUNDANCY AIR FLOW IS BLOCKED THROUGH ONE OF TWO CABIN FA FLOW PATHS.
- (B) NO EFFECT.
- (C) POSSIBLE EARLY MISSION TERMINATION FOR FIRST FAILURE.
- (D) NO EFFECT.
- (E) FUNCTIONAL CRITICALITY EFFECT FAILURE IN THE ACTIVE FLOW PATH WILL CAUSE LOSS OF ALL AIR FLOW. POTENTIAL LOSS OF CREW/VEHICLE DUE TO LOSS OF FLIGHT DECK AVIONICS COOLING. SCREEN B IS N/A BECAUSE CHECK VALVE IS IN STANDBY UNTIL ACTIVATION OF REDUNDANT FLOW PATH.

#### DISPOSITION & RATIONALE:

(A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE ELSTORY (E) OPERATIONAL USE

(A) DESIGN

VALVE HOUSING IS CONSTRUCTED OF ALUMINUM WITH STAINLESS STEEL BIFILER Spring and fiberglass flappers. The check valve is normally closed unde NO FLOW CONDITIONS IN ANY ATTITUDE. MULTIVANE FLAPPER, DUAL STAINLESS STEEL SPRING LOADED CLOSED, UPSTREAM 40/70 MICRON FILTER, FLAPPER HINGES and mounts drilled at assembly, flapper material - glass reinforced

# SHUTTLE CRITICAL ITEMS LIST - ORBITER

SUBSYSTEM :ATMOSPHERIC REVIT. FMEA NO 06-18 -0104 -1 REV:08/12/

POLYMER, METALLIC PARTS - SCREW. DESIGN OPERATING LIFE OF THE CHECK VALVE IS A MINIMUM OF TO,000 CYCLES. DESIGN INTERNAL LEAKAGE IN THE REVERSE FLOW DIRECTION IS 0.01 LB/MIN MAX AT 70 DEG F AND 12 INCHES OF WATER DELTA PRESSURE.

## (B) DESIGN

ACCEPTANCE TEST - EXAMINATION OF PRODUCT, CHECK VALVE LEAKAGE TESTED AT 10 INH20 GN2 PRESSURE, TOTAL LEAKAGE 0.1 LB/MIN MAX.

QUALIFICATION TEST - CHECK VALVES ARE SUBJECTED TO THE FOLLOWING AS PARTICLE CABIN FAN ASSEMBLY - VIBRATION SPECTRUM OF 20 TO 150 HZ INCREASE AT 6 DE/OCTAVE TO 0.09 G\*\*2/HZ, CONSTANT AT 0.09 G\*\*2/HZ FROM 150 TO 9 HZ, DECREASING AT 9 DE/OCTAVE FROM 900 TO 2000 HZ FOR 48 MIN/AXIS IN 1 ORTHOGONAL AXES. SHOCK - THREE TERMINAL SAWTOOTH PULSES OF 20G PEAR AMPLITUDE AND 11 MS DURATION APPLIED IN BOTH DIRECTIONS ALONG EACH OF THREE ORTHOGONAL AXES. TEMPERATURE/MUNIDITY TESTS AT 100% MUMIDITY AND TEMPERATURE CYCLED BETWEEN 60 AND 120F FOR 120 HOURS.

IN-VEHICLE TESTING - CASIN FAN DELTA-P WOULD INDICATE A BLOCKAGE IN THE FLOW PATH WHEN THE FAN WITH THE FAILED CLOSED CHECK VALVE IS TURNED ON

OPERSO - VALVES ARE CYCLED EACH TIME THE CABIN FANS ARE TURNED ON AND CI IN SUPPORT OF VEHICLE COOLING. PERFORMANCE OF THE CABIN FANS IS VERIFI DURING EACH TURNAROUND. CABIN FAN DELTA-P IS CONTINUOUSLY MONITORED SERVES AS AN INDICATION OF VALVE FAILURE. ALSO VERIFIED AS A CONTINGENCY UPON LRU REPLACEMENT.

### (C) INSPECTION

RECEIVING INSPECTION
INCOMING PARTS ARE VISUALLY INSPECTED FOR MATERIAL AND PROCESS
GERTIFICATION.

CONTAMINATION CONTROL PART CLEANLINESS IS MAINTAINED AND VERIFIED TO H.S. REQUIREMENTS.

# ASSEMBLY/INSTALLATION

TORQUE APPLICATION IS VERIFIED BY INSPECTION PER H.S. PROCEDURES. EPO APPLIED TO SHAFT POSTS PROVIDING A REDUNDANT LOCKING INSURANCE ON ALIGNMENT OF CENTER LINE OF SHAFT HOLIS IN POST IS CHECKED. PROOF PRESSURE TEST OF THE OUTLET HEADER AND CHECK VALVES ARE VERIFIED BY INSPECTION. INSPECTION VERIFIES LEAK TEST PER REQUIREMENT.

CRITICAL PROCESSES ANODIZING IS VERIFIED BY INSPECTION.

#### TESTING

ATP TEST IS VERIFIED BY INSPECTION.

#### RANDLING/PACKAGING

PACKAGING PROCEDURES AND REQUIREMENT FOR SHIPMENT IS VERIFIED BY INSPECTION.

SS0230A ATTACHMENT -Page 13 of 241

# SHUTTLE CRITICAL ITEMS LIST - ORBITER

SUBSYSTEM : ATMOSPHERIC REVIT.

FMEA NO 06-18 -0304 -3

REV: 08/11/

(D) FAILURE HISTORY
NO FAILURE HISTORY APPLICABLE TO CLOSED FAILURE MODE. THE FAN CHECK
VALVE HAS SUCCESSFULLY PERFORMED WITHOUT FAILURE THROUGH THE DURATION O
THE SHUTTLE PROGRAM.

(2) OPERATIONAL USE TES.