PAGE: 120 PRINT DATE: 08/25/95

FAILURE MODES EFFECTS ANALYSIS (FMEA) - CRITICAL HARDWARE

NUMBER: M8-1MR-BM007-X

1

9/1/85

SUBSYSTEM NAME: MECHANICAL - EDS

PART NAME PART NUMBER

REVISION:

PART NAME PART NUMBER
VENDOR NAME VENDOR NUMBER

LRU : GUIDE RING ASSEMBLY 33U.6271.011-05

NPO-ENERGIA 33U.6271.011-05

SAU : MECH, GUIDE RING BALLSCREW 33U.5365.011-05 NPO-ENERGIA 33U.6365.011-05

PART DATA

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS: GUIDE RING BALLSCREW INTERCONNECTING MECHANISM

REFERENCE DESIGNATORS:

QUANTITY OF LIKE ITEMS: 3 THREE (ONE PER BALLSCREW PAIR)

FUNCTION:

LOCATED AT THE APEX OF EACH BALLSCREW PAIR, THE BALLSCREW INTERCONNECTING MECHANISM PROVIDES A KINEMATIC CONNECTION BETWEEN THE GUIDE RING AND THE REMAINING ELEMENTS OF THE DOCKING MECHANISM. THE MECHANISM PROVIDES LOCKING OF BOTH BALLSCREW RODS TO PREVENT THEM FROM ROTATING AND UNLOCKING OF BOTH BALLSCREW RODS TO ALLOW THEM TO OPERATE TOGETHER.

SERVICE IN BETWEEN FLIGHT AND MAINTENANCE CONTROL: VISUAL INSPECTION, SERVICEABILITY CONTOL, DOCKING WITH CALIBRATING DOCKING MECHANISM.

MAINTAINABILITY

REPAIR METHOD - NONE (REPAIRING IN MANUFACTURING CONDITIONS ONLY).

REFERENCE DOCUMENTS: 33U.8365.011-05

33U.8271.011-05

.PAGE: 127

PRINT DATE: 08/25/95

FAILURE MODES EFFECTS ANALYSIS (FMEA) - CIL FAILURE MODE

NUMBER: M8-1MR-8M007-02

REVISIONA

241/25

SUBSYSTEM NAME: MECHANICAL - EDS

LRU: GUIDE RING ASSEMBLY

CRITICALITY OF THIS

ITEM NAME: MECHANISM, BALLSCREW INTERCONNECTING FAILURE MODE: 1R2

FAILURE MODE:

BROKEN

MISSION PHASE:

00

ON-ORBIT

VEHICLE/PAYLOAD/KIT EFFECTIVITY: 104 ATLANTIS

GEAR/SHAFT FAILURE DUE TO MATERIAL DEFECT, MANUFACTURE DEFECT, EXCESSIVE EXTERNAL LOADS, VIBRATION, MECHANICAL SHOCK

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

CRITICALITY 1R2 DURING INTACT ABORT ONLY (AVIONICS ONLY)? N/A

REDUNDANCY SCREEN

A) PASS

B) PASS

C) PASS

PASS/FAIL RATIONALE:

METHOD OF FAULT DETECTION:

INSTRUMENTATION - THE CORRESPONDING DOCKING RING INDICATORS ON THE DOCKING CONTROL PANEL WILL ILLUMINATE TO INDICATE RING POSITION AND ALIGNMENT. VISUAL OBSERVATION - INABILITY TO MOVE THE DOCKING RING; POTENTIAL MOMENT CREATED BETWEEN VEHICLES ABOUT ONE POINT ON THE RING.

- FAILURE EFFECTS -

(A) SUBSYSTEM:

ONE BALLSCREW OF THE PAIR IS ALLOWED TO POTATE INDEPENDENTLY OF THE OTHER AND WILL NOT BE ABLE TO RESTRAIN AXIAL LOADS. LOSS OF CAPABILITY TO ALIGN THE DOCKING RING. LOADS EXPERIENCED DURING CAPTURE WILL COLLAPSE. THE DOCKING RING AT THE POINT ON THE RING WHERE FAILURE OF THE BALLSCREW INTERCONNECTING MECHANISM OCCURRED.

(B) INTERFACING SUBSYSTEM(S):

POTENTIAL DAMAGE TO ORBITER STRUCTURE IF ORBITERMIR COLLIDE DUE TO THIS FAILURE AND WORKAROUND IS NOT IMPLEMENTED.



PAGE: 128

PRINT DATE: 08/25/95

FAILURE MODES EFFECTS ANALYSIS (FMRA) - CIL FAILURE MODE

NUMBER: M8-1MR-BM007-02

(C) MISSION:

LOSS OF DOCKING RING ALIGNMENT WILL PRECLUDE DOCKING CAPABILITIES
 RESULTING IN LOSS OF ORBITERMIR MISSION OBJECTIVES.

(D) CREW, VEHICLE, AND ELEMENT(S):

FIRST FAILURE (BROKEN BALLSCREW INTERCONNECTING MECHANISM) COLLAPSE OF THE DOCKING RING AT ONE POINT ON THE RING DURING CAPTURE COLLD CAUSE A MOMENT BETWEEN ORBITER AND MIR.

(E) FUNCTIONAL CRITICALITY EFFECTS:

N/A

DESIGN CRITICALITY (PRIOR TO OPERATIONAL DOWNGRADE, DESCRIBED IN F): 1/1

(F) RATIONALE FOR CRITICALITY CATEGORY DOWNGRADE; SECOND FAILURE (INABILITY TO OPEN CAPTURE LATCHES OR PERFORM SEPARATION) INABILITY TO CIRCUMVENT THE MOMENT CREATED BETWEEN ORBITER AND MIR. POTENTIAL COLLISION BETWEEN BOTH VEHICLES RESULTING IN POSSIBLE LOSS OF

-DISPOSITION RATIONALE-

(A) DESIGN:

CREW AND VEHICLE.

A BROKEN BALLSCREW INTERCONNECTING MECHANISM IS CONSIDERED TO BE VERY REMOTE BASED ON THE FOLLOWING: THE USE AND EXPERIENCE OF TRIS MECHANISM ON PREVIOUS DEVELOPMENTS; PRELIMINARY STRENGTH ANALYSIS OF STRUCTURAL ELEMENTS AND PARTS; THE CHOICE OF STAINLESS STEELS AS THE MATERIAL HAD PERFORMED WELL IN OPERATIONAL USE; THE CALCULATION OF TOLERANCES AND DIMENSIONAL CIRCUITS; THE CHOICE OF SPECIAL BEARINGS SUITABLE FOR OPERATIONAL CONDITIONS; AND THE USE OF A SPRING MECHANISM TO REDUCE SPACING BETWEEN GEARS TO REDUCE THE POSSIBILITY OF GEAR TEETH DAMAGE OR BREAKAGE DUE TO EXCESSIVE LOADS.

(B) TEST:

DOCKING MECHANISM ACCEPTANCE TESTS:

 VIBRORESISTENT TEST - APDS SUBJECTED TO THE FOLLOWING VIBRATION LEVELS FOR 2 MINUTES PER AXIS:

FREQUENCY (HZ)	SPECTORAL DENSITY ACCELERATION
FROM 20 TO 80	INCREASING, 3DB OCTAVE TO 0.04G2/HZ
FROM 90 TO 350	PERMANENT 0.04G ² /HZ
FROM 350 TO 2000	DECREASING 3DB OCTAVE WITH 0.04GF/HZ

SUBSEQUENT TO THIS TEST AN ENGINEERING INSPECTION IS PERFORMED TO IDENTIFY BROKEN OR LOOSE HARDWARE.

2. DOCKING MECHANISM CHECKOUT (STATIC) TEST - RING IS EXTENDED AND RETRACTED AS NECESSARY TO FULLY TEST ITS OPERATION DURING A SINGLE DOCKING. FORCE IS APPLIED TO THE RING TO SIMULATE LOADS THAT CAN OCCUR DURING RING CAPTURE AND MATING OF THE TWO MECHANISMS. ATTENUATION SYSTEM CHARACTERISTICS IS DETERMINED WHEN THE RING IS DEFLECTED AND ROTATED DURING THIS TEST. THIS TEST WILL VERIFY



PAGE: 129

PRINT DATE: 08/25/95

FAILURE MODES EFFECTS ANALYSIS (FMEA) - CIL FAILURE MODE

NUMBER: M8-1MR-BM007-02

PROPER OPERATION OF THE BALLSCREW INTERCONNECTING MECHANISMS UNDER LOAD AND NO-LOAD CONDITIONS.

- 3. THERMO VACUUM TEST DOCKING OF THE MECHANISM IS THERMALLY CYCLED, UNDER LOAD CONDITIONS, FROM +20°C TO -50°-55°C TO +50°+55°C TO +20°C IN A VACUUM AT 10°-4 TO 10°-5 TORA. DWELL AT EACH TEMPERATURE AND BETWEEN OPERATIONS AT EACH TEMPERATURE IS A MINIMUM OF 60 MINUTES AFTER STABILIZATION. OPERATIONS INCLUDES PERFORMING DOCKING WHICH IS ACCOMPLISHED AT A SPEED OF 0.15M/SEC BETWEEN THE SIMULATOR AND MOVEABLE PLATFORM (CONTAINING THE DOCKING MECHANISM). PROPER OPERATION OF THE BALLSCREW INTERCONNECTING MECHANISMS IS VERIFIED FOR A TEMP RANGE OF -50°C/-55°C TO 50°C/-55°C.
- 4. CONTROLLED DOCKING TEST CONTROLLED DOCKING IS PERFORMED TO VERIFY PROPER DOCKING CAPABILITIES UNDER LOAD CONDITIONS. A PULL TEST OF ASSEMBLIES WITH THE DOCKING MECHANISM ASSEMBLY IS PERFORMED DURING THIS TEST. THESE TESTS WILL VERIFY PROPER OPERATION OF THE BALLSCREW INTERCONNECTING MECHANISMS.

DOCKING MECHANISM QUALIFICATION TESTS:

- 1. OPERATIONAL CAPABILITY TEST WITH DOCKING RING IN IT'S INITIAL POSITION FORCE IS APPLIED TO THE RING TO SIMULATE LOADS THAT CAN OCCUR DURING RING CAPTURE AND MATING OF THE TWO MECHANISMS. ATTENUATION SYSTEM CHARACTERISTICS IS DETERMINED WHEN THE RING IS DEFLECTED AND ROTATED DURING THIS TEST. THIS TEST WILL VERIFY PROPER OPERATION OF THE BALLSCREW INTERCONNECTING MECHANISMS UNDER LOAD CONDITIONS.
- 2. TRANSPORTABILITY STRENGTH TEST SHIPPING LOADS ARE SIMULATED ON A VIBRATING TABLE TO VERIFY THAT THE DOCKING MECHANISM WILL NOT BE DAMAGED DURING SHIPMENT. THIS TEST IS CONDUCTED UNDER THE CONDITIONS CONTAINED IN THE FOLLOWING TABLE.

ı	VIERATION	VIBRATION		FREQUENCY SUBBANO, HZ					TOTAL TEST	
١	ACCELER	ACCELER	5-7	7-15	15-30 30-40 40-60 DURATION				LTION (
١	DIRECTION	AMPLITUDE		TEST DURATION, MIN					MIN	
I	ALONG X-AXIS	1.4%	_	4	-	1	-	_	4	
Ί		1.2	76	93	32	61	39	5	7	
Ιİ	ALONG Y-AXIS	1.1	1		7	-	1	-	" 4	
Ί		1:0	19	16	. 2	10	. 7	~	53	
ıl	ALONG Z-AXIS	1.1		4		_	_	-	4	
Ί		1.0	32	40	. 16	26	18	2	10	

SUBSEQUENT TO THIS TEST AN INSPECTION IS PERFORMED TO IDENTIFY BROKEN OR LOOSE HARDWARE AND AN OPERATIONAL CAPABILITY TEST, AS DEFINED IN QTP #1 ABOVE, IS PERFORMED TO VERIFY PROPER BALLSCREW INTERCONNECTING MECHANISM OPERATIONS DURING RING MOVEMENT.

3. SHOCK AND SAWTOOTH LOADING STRENGTH TEST - DOCKING MECHANISM IS SUBJECTED TO 20G TERMINAL SAWTOOTH SHOCK PULSES IN EACH AXIS, 3 PULSES IN EACH DIRECTION FOR A TOTAL OF 6 PULSES/AXIS. AFTER COMPLETION AN INSPECTION IS PERFORMED TO IDENTIFY BROKEN OR LOOSE HARDWARE AND AN OPERATIONAL CAPABILITY TEST IS CONDUCTED, AS



FAILURE MODES EFFECTS ANALYSIS (FMEA) — CIL FAILURE MODE -- NUMBER: Ma-1MR-BM007- 02

DEFINED IN QTP #1 ABOVE, TO VERIFY PROPER BALLSCREW INTERCONNECTING MECHANISM OPERATIONS DURING RING MOVEMENT.

4. VIBRATION STRENGTH TEST - APDS SUBJECTED TO THE FOLLOWING VIBRATION LEVELS IN EACH AXIS FOR A 400 SECOND DURATION.

FREQUENCY (HZ)	SPECTORAL DENSITY ACCELERATION
FROM 20 TO 80	INCREASING, 3DB OCTAVE TO 0.067G2/HZ
FROM BO TO 350	CONSTANT 0.067G2/HZ
FROM 350 TO 2000	DECREASING 3DB OCTAVE WITH 0.067G2/HZ

SUBSECUENT TO THIS TEST AN ENGINEERING INSPECTION IS PERFORMED TO IDENTIFY BROKEN OR LOOSE HARDWARE AND AN OPERATIONAL CAPABILITY TEST, AS DEFINED IN QTP #1 ABOVE, IS PERFORMED TO VEHIFY PROPER BALLSCREW INTERCONNECTING MECHANISM OPERATIONS DURING RING MOVEMENT.

- 5. APDS SERVICEASILITY TEST IN A SIX-DEGREE-OF-FREEDOM DYNAMIC TEST-THE SIX-DEGREE-OF-FREEDOM DYNAMIC TEST VERIFIES APDS DOCKING AND UNDOCKING OPERATIONS UNDER CLOSE-TO-FULL-SCALE CONDITIONS. STATIC MOTION OF ENTITIES IS SMULATED UNDER SPECIFIC INERTIAL AND GEOMETRICAL PARAMETERS FOR VARIOUS INITIAL CONDITIONS FOR MIRVSHUTTLE DOCKING. A TOTAL OF 2D DOCKINGS IS PERFORMED. BALLSCREW INTERCONNECTING MECHANISM OPERATION VERIFIED BY EXTENSION OF DOCKING RING TO INITIAL POSITION AND ABSORPTION OF ENERGY OF RELATIVE MOVEMENT DURING EACH DOCKING. SUBSEQUENT TO THIS TEST AN ENGINEERING INSPECTION IS PERFORMED TO IDENTIFY BROKEN OR LOOSE HARDWARE AND AN OPERATIONAL CAPABILITY TEST, AS DEFINED IN CITY #1 ABOVE. IS PERFORMED TO VERIFY PROPER BALLSCREW......
- 6. TARGET SERVICE LIFE TEST TESTS ARE PERFORMED TO VERIFY PROPER DOCKING AND UNDOCKING OPERATIONS OVER ITS LIFE OF 100 DOCKINGS. PROPER OPERATION OF THE BALLSCREW INTERCONNECTING MECHANISMS VERIFIED DURING 100 DOCKING AND UNMATING CYCLES (FOR MC821-0087-1001/- 2001 UNITS ONLY). FOR MC821-0087-2001, 4001, & -5001 UNITS PROPER OPERATION VERIFIED DURING 388 CYCLES (44 VACUUM/LOAD CYCLES, 16 LOAD CYCLES, & 324 NO-LOAD CYCLES). THESE TESTS INCLUDE RING EXTENSION, RETRACTION, AND ALIGNMENT, SUBSEQUENT TO THIS TEST AN ENGINEERING INSPECTION IS PERFORMED TO IDENTIFY BROKEN OR LOCSE HARDWARE AND AN OPERATIONAL CAPABILITY TEST, AS DEFINED IN CITP #1 ABOVE, IS PERFORMED TO VERIFY PROPER BALLSCREW INTERCONNECTING MECHANISM FUNCTIONING DURING RING MOVEMENT AND DOCKING OPERATIONS.
- 7. COLD AND HEAT RESISTANCE TEST DOCKING OF THE MECHANISM IS THERMALLY CYCLED FROM +20°C TO -50'-55°C TO +50'+55°C TO +20°C IN A VACUUM AT 10°-5 TO 10°-5 TORR.: DWELL AT EACH TEMPERATURE AND BETWEEN OPERATIONS AT EACH TEMPERATURE IS A MINIMUM OF 60 MINUTES AFTER STABILIZATION. FIVE CYCLES WERE PERFORMED AGAINST THE GUIDE RING EXTEND AND FINAL POSITION MECHANICAL STOPS FOR 10 SECONDS EACH. DURING EACH DOCKING, AS SHOWN IN THE FOLLOWING TABLE, A FAILED BALLSCREW INTERCONNECTING MECHANISM WOULD BE DETECTED.



FAILURE MODES EFFECTS ANALYSIS (FMEA) — CIL FAILURE MODE NUMBER: M6-1MR-5M007- 02

SEQ	DOCKING RATE.	SIMULATOR ROTATIONAL ANGLE		TEMP	VO: 74.65	PRESS INTEGRITY
NO.	M/S	PITCH	ROLL	-c	VOLTAGE VOLTS	CHECKOUT
1	0.10	O°	O _o	25 +/-10	23	YES
	<u> </u>					
2	0.10	O°	4°	25 +/-10	34	NO.
3	0.12	4°	4*	25 +/-10	27	NO.
4*	<u> </u>			+80+/-5		YES
4	0.10	4 °	o	+50+/-5	27	YES
5'			<u> </u>	-(60+/-5)		YES
5	0.10	4*	_0-	-(30+/-5)	27	YES
6'				+60+/-5		YES
6	0.12	0.	4*	+50+/-5	23	YES
7"				-(60+/-5)		YËŞ
7	0.10	o,	4°	-(30 +/-5)	23	YES
6*				+60+/-5		YES
8	0.12	4 °	4º	50 +/-5	34	YEŞ
6*			1 —	-(60+/-5)		YES
9	0.12	4°	4°	-(30 +/-6)	34	YES
10*				+60+/-5		YES
10	0,10	4*	0°	+50+/-5	27	YES
111				-(60+/-5)		YES
11	0.10	<u> </u>	4*	-(30 +/-5)	27	YES
12"	1 - 1	_		+60+/-5		YES
12"	0.10	<u>0-</u>	4°	+50+/-5	27	YES
13"				-(80+/-5)		YES
13*	0.12	4"	4°	-(30 +/-5)	27	YES
14"			 	+60+/-5		YES
14"	0.12	4"	4*	+50+/-5	27	YES
15"	0.12		40	+25+/-10	29	YES

"MC821-0087-2001, -4001, & -5001 ONLY

AFTER COMPLETION AN INSPECTION IS PERFORMED TO IDENTIFY BROKEN OR LOOSE HARDWARE AND AN OPERATIONAL CAPABILITY TEST, AS DEFINED IN QTP #1 ABOVE, IS PERFORMED TO VERIFY PROPER BALLSCREW INTERCONNECTING MECHANISM FUNCTIONING DURING RING MOVEMENT AND DOCKING OPERATIONS.

a. CONTROL DISASSEMBLY - UPON COMPLETION OF ALL QUAL TESTING THE DOCKING MECHANISM IS DISMANTLED AND ALL BALLSCREW INTERCONNECTING MECHANISM OPERATING SURFACES ARE CHECKED FOR EVIDENCE OF WEAR OR FAILURE.

OMRSD - TURNARQUIND CHECKOUT TESTING IS ACCOMPLISHED IN ACCORDANCE WITH OMRSD.

(C) INSPECTION:

RECEIVING INSPECTION

RAW MATERIAL IS VERIFIED BY INSPECTION TO ASSURE COMPLIANCE WITH THEIR SPECIFICATIONS ON A CERTAIN % OF THE BATCH AT THE INPUT CONTROL.



PRINT DATE: 29,08.95

PAGE: 132

FAILURE MODES EFFECTS ANALYSIS (FMEA) — CIL FAILURE MODE
NUMBER: M8-1MR-BM007-02

CONTAMINATION CONTROL

CORROSION PROTECTION PROVISIONS AND CONTAMINATION CONTROL VERIFIED BY INSPECTION. CHECK OF ROOM CLEANLINESS; PARTS WASHING AND OTHER OPERATIONS OF THE TECHNOLOGICAL PROCESS WHICH PROVIDES CLEANLINESS ARE VERIFIED BY INSPECTION.

CRITICAL PROCESSES

ANODIZING, HEAT TREATING, CHEMICAL PLATING, AND SQLDERING VERIFIED BY INSPECTION.

ASSEMBLY/INSTALLATION

ADJUSTMENTS AND TUNING ACCORDING TO TECHNICAL REQUIREMENTS OF THE DRAWINGS ARE VERIFIED BY INSPECTION. QUALITY CONTROL OF COATINGS AND FABRICATION OF BALLSCREW INTERCONNECTING MECHANISM (INCLUDING GEAR/BEARING MATING) IS VERIFIED BY INSPECTION.

TESTING

ATP/QTP/DMRSD TESTING VERIFIED BY INSPECTION.

HANDLING/PACKAGING

HANDLING/PACKAGING PROCEDURES AND REQUIREMENT FOR SHIPMENT VERIFIED BY INSPECTION.

(D) FAILURE HISTORY:

DATA ON TEST FAILURES, UNEXPLAINED ANOMALIES, AND OTHER FAILURES EXPERIENCED DURING GROUND PROCESSING OF ODS DOCKING MECHANISMS CAN BE FOUND IN PRACA DATA BASE.

(E) OPERATIONAL USE:

CENTERING SPRING MECHANISM WILL LIMIT ROTATION OF ONE BALLSCREW, PROVIDING SOME RESTRAINT AGAINST RING COLLAPSE. HOWEVER, IF A BROKEN BALLSCREW INTERCONNECTING MECHANISM RESULTS IN A MOMENT BETWEEN BOTH VEHICLES, DURING DOCKING, CREW COULD OPEN CAPTURE LATCHES AND FIRE APPROPRIATE ORBITER RCS JETS TO PERFORM SEPARATION.

- APPROVALS -

DESIGN ENGINEER
DESIGN MANAGER
NASA SS/MA
NASA SUBSYSTEM MANAGER

M. NIKOLAYEVA A. SOUBCHEV

.

Proprietary Data