PAGE: 1 PRINT DATE: 03/29/96

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL HARDWARE

NUMBER: 04-1A-0119 -X

SUBSYSTEM NAME: ELECTRICAL POWER GENERATION; FUEL CELL

REVISION: 2

12/18/89

PART DATA

PART NAME

VENDOR NAME

PART NUMBER

**VENDOR NUMBER** 

LRU

: VALVE, WATER PRESSURE RELIEF

AERODYNE

MC284-0431-0001

3039-4-000

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS: VALVE, WATER PRESSURE RELIEF.

REFERENCE DESIGNATORS:

40V45RV170

40V45RV270 40V45RV370

QUANTITY OF LIKE ITEMS: 3

THREE

FUNCTION:

1,6 10.

RELIEVES EXCESS WATER PRESSURE FROM FUEL CELLS.

PRINT DATE: 03/27/96

PAGE 2

FAILURE MODES EFFECTS ANALYSIS FMEA - CIL FAILURE MODE

NUMBER: 04-1A-0119-02

REVISION#:

3

03/25/96

SUBSYSTEM NAME: ELECTRICAL POWER GENERATION: FUEL CELL

LRU: VALVE, WATER PRESSURE RELIEF

CRITICALITY OF THIS

ITEM NAME: VALVE, WATER PRESSURE RELIEF

FAILURE MODE: 2/2

FAILURE MODE:

FAILS OPEN: INTERNAL LEAKAGE

MISSION PHASE:

PL PRE-LAUNCH

LO LIFT-OFF

OO ON-ORBIT

VEHICLE/PAYLOAD/KIT EFFECTIVITY:

102 COLUMBIA

DISCOVERY 103

ATLANTIS 104

ENDEAVOUR 105

CAUSE:

MECHANICAL SHOCK, VIBRATION, PHYSICAL BINDING/JAMMING, CONTAMINATION.

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

REDUNDANCY SCREEN

A) N/A

B) N/A

C) N/A

PASS/FAIL RATIONALE:

A)

₽)

C)

9.

- FAILURE EFFECTS -

(A) SUBSYSTEM:

NO EFFECT - OVERBOARD RELIEF OF PRODUCT WATER FROM SINGLE FUEL CELL.

PAGE: 3

### FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL FAILURE MODE

NUMBER: 04-1A-0119-02

500 B

### (B) INTERFACING SUBSYSTEM(S):

NO EFFECT - REDUCED WATER QUANTITY SUPPLIED TO ECLSS.

### (C) MISSION:

EFFECTS DEPENDENT ON MISSION. WATER VENTING MAY INTERFERE WITH MISSION/PAYLOAD OBJECTIVES.

### (D) CREW, VEHICLE, AND ELEMENT(S):

NO EFFECT.

### (E) FUNCTIONAL CRITICALITY EFFECTS:

NONE.

### -DISPOSITION RATIONALE-

### (A) DESIGN:

RÉLIEF VALVE IS CONSTRUCTED OF STAINLESS STEEL AND THE VALVE MECHANISM IS PROTECTED BY A 45 MICRON FILTER.

THE SLIDING SURFACES ARE DESIGNED TO BE SUFFICIENTLY SMOOTH AND WEAR RESISTANT TO PRECLUDE PARTICLE GENERATION FROM INTERFERING WITH THE FUNCTION OF THE VALVE.

THE VALVE IS DESIGNED TO TOLERATE THE VIBRATION AND SHOCK LEVELS ASSOCIATED WITH THE SERVICE ENVIRONMENT.

### (B) TEST:

CERTIFICATION INCLUDED PROOF PRESSURE, EXTERNAL LEAKAGE, CRACK-FULL FLOW-RESEAT PRESSURES, INTERNAL LEAKAGE, VACUUM INTEGRITY, SALT FOG, VIBRATION, ACCELERATION, SHOCK, THERMAL CYCLES, OPERATING LIFE, AND BURST PRESSURE.

ACCEPTANCE TESTS INCLUDE PROOF PRESSURE, LEAKAGE, VACUUM INTEGRITY, FUNCTIONAL VERIFICATION, AND CLEANLINESS.

OMRSO: WATER RELIEF VALVE CRACK AND RESEAT PRESSURES ARE VERIFIED OMOP.

### (C) INSPECTION:

PRINT DATE: 03/27/96

PAGE: 4

## FAILURE MODES EFFECTS ANALYSIS (FMEA) - CIL FAILURE MODE NUMBER: 04-1A-0119- 02

### RECEIVING INSPECTION

TEST REPORTS AND RECORDS ARE MAINTAINED CERTIFYING MATERIALS AND CHEMICAL/METALLURGICAL PROPERTIES. VISUAL AND DIMENSIONAL EXAMINATION IS PERFORMED ON INCOMING PARTS.

### CONTAMINATION CONTROL

PROPER OPERATION AND MAINTENANCE OF A CLASS 100,000 CLEAN ROOM IS VERIFIED BY QC. PART CLEANLINESS LEVEL 200 IS CERTIFIED BY INSPECTION. A PARTICLE COUNT EXAMINATION OF 50ML SAMPLES IS MADE UNDER 50X MAGNIFICATION, RECORDED, AND VERIFIED BY INSPECTION.

#### ASSEMBLY/INSTALLATION

DIMENSIONAL AND SURFACE CHECKS OF INLET AND OUTLET HOUSINGS AND BELLOWS ARE VERIFIED AND RECORDED BY INSPECTION. PREASSEMBLY CLEANING BY WASH AND RINSE, VAPOR DEGREASING, AND ULTRASONIC CLEANINGLIS VERIFIED BY INSPECTION. THE INLET FILTER IS EXAMINED UNDER 50X MAGNIFICATION. MASS SPECTROMETER LEAK CHECKS AND 10X VISUAL EXAMINATIONS OF ELECTRON BEAM WELDS ARE VERIFIED BY INSPECTION:

### CRITICAL PROCESSES

ALL CRITICAL PROCESSES AND CERTIFICATIONS ARE MONITORED AND VERIFIED BY INSPECTION, CRITICAL PROCESSES ARE WELDING, COATING, AND CLEANING.

### TESTING

ATP IS OBSERVED AND VERIFIED BY QC, INCLUDING PROOF PRESSURE/EXTERNAL LEAKAGE, VACUUM INTEGRITY, INTERNAL LEAKAGE, AND COMPONENT OPERATION.

### HANDLING/PACKAGING

IN-PROCESS OPERATIONS ARE VERIFIED BY QC TO PROTECT PARTS AND PRECLUDE MISHANDLING. PARTS ARE VERIFIED TO BE PACKAGED AND TRANSPORTED IN ACCORDANCE WITH APPLICABLE REQUIREMENTS. SHUTTLE HARDWARE, INCLUDING RAW MATERIAL, IS SEGREGATED FROM OTHER STOCK IN INSPECTION.

### (D) FAILURE HISTORY:

CURRENT DATA ON TEST FAILURES, FLIGHT FAILURES, UNEXPLAINED ANOMALIES, AND OTHER FAILURES EXPERIENCED DURING GROUND PROCESSING ACTIVITY CAN BE FOUND IN THE PRACA DATA BASE.

THERE HAVE BEEN NO ACCEPTANCE TEST, QUALIFICATION TEST, FIELD OR FLIGHT FAILURES ASSOCIATED WITH THIS FAILURE MODE.

# (E) OPERATIONAL USE:

NO CREW ACTION AFTER FAILURE.

04.44 70

PRINT DATE: 03/27/96

PAGE: 5

FAILURE MODES EFFECTS ANALYSIS (FMEA) ~ CIL FAILURE MODE NUMBER: 04-1A-0119-02

- APPROVALS -

PAE MANAGER

PRODUCT ASSURANCE ENGR : L. X. DANG

DESIGN ENGINEERING

NASA SSMA

NASA SUBSYSTEM MANAGER :

D. F. MIKULA

: MUSTIN, LLOYD

Alex 12-12-13-28

Princed & Wignes 6/16/97